



南方摩哆 SOUTHERN MOTOR

Business Reg. No: 234147/00L
Block 1006, Bukit Merah Lane 2. #01-10, Singapore 159762
Tel: 6273-0369 (3 Lines) Fax: 6274-6614

11th October 2019

AXA Insurance Singapore Pte Ltd
8 Shenton Way #24-01
AXA Tower
SINGAPORE (068811)

Dear Sirs,

RE: Cost of repair for Yamaha MT-09 - FBP802U

1pcs pf Handle bar ⁹ X NN		S\$ 220.00 X	Rasul
1pcs of Hand Guard (LH,RH) <i>scd</i>		380.00	
2pc of Signal Light <i>br</i>		240.00	Hp 2000068
1pc of Windscreen <i>scd</i>		320.00	
1pc of Tank <i>bt</i>	7834.50	1,400.00	4 days
1pc of Tank Cover (LH) <i>scd</i>	56.00	180.00	
1pc of Tank Cover (RH) <i>scd</i>	395.00	180.00	L/S
1pc of Radiator <i>bt</i>		950.00	
1pcs of Box <i>bt</i>		850.00	
1pcs of Crash Bar <i>bt</i>	8279.50	450.00	14/10/19 @ 15%
1pcs of Sport Light <i>scd</i>	20%	250.00	
2pcs of Mirror <i>mis</i> (1pc)		190.00	Ready after repair
1pcs of Brake Lever & Clutch Lever <i>scd</i>	6623.60	180.00	
1pcs of Mudguard <i>cut</i>		240.00	
1pcs of Helmet <i>scd</i>	4/8-6,600	350.00	
1pcs of Side Stand <i>repair</i>		180.00 X	
1pcs of Front Footrest X NN		58.00 X	
1pcs of Side Fairing (LH) <i>scd</i>		180.00	
1pcs of Side Fairing (RH) <i>scd</i>		180.00	
1pcs of Coolant Water <i>scd</i>		50.00 s/n - 50	
1pcs of Exhaust Pipe <i>bt</i>		1,900.00	8705
1pcs of Master Pump <i>scd</i>		380.00	10%
		9,308.00	7834.50
		930.80	
		8,377.20	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Yours Faithfully,

Southern Motor

Less 10%

Nett
Alignment Fork
Front Number Plate
Transport
Labour

150.00 60
12.00 *scd* - 10 } 395
45.00
380.00 280
S\$ 8,964.20