

11/01/2019

ASS. REC. BY:

REF:

CS/CT219018071/11y3

112

Special Instruction:

SUIVBY: Taufiqh

ASSIGNMENT (Office)

From (Person): Ong chin kiat of CT2 Date/Time: 14.10.19 12.39 PM

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLC 7437U Insured: GBE 1640X

at Workshop m/s Hitachi Capital Tel: 64663022

of NO 8 Fourth Lot Yang Road

Policy No: DMCVSN 30789419033 Claim No: SNM19D204825102

Sum Insured: Excess:

Make of Veh: D.O.A. 8.10.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 14.10.2019 4.47 PM Person Contacted: Ah Hao Vehicle IN (OUT)

Date/Time	Action/Instruction (✓) Estimate
	GBE 1640X : X
	SLC 7437U : X

ASS. REC. BY: Tan Jhe

REF: LONG CT1

ASSIGNMENT

From: _____ Date: 15.10.2019

Estimated Cost: _____

OD / TP / NS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: G4 8801-m

at Workshop m/s: MAJOR WAY CAR CARE

of 10A4 Lower Delta Road

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Est. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS my 3pm

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLL74374 Regn: 2016 my

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Toyota Athis cc 1598

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 217409 T/Radio: Insured / Std / NI / NA

Eng/No: 217409

C/No: MROS3KE41W454579

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205 K5 R66

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Michelin

Front R/Bal: 6 mm

L/Bal: 6 mm

D.O.A. _____ D.O.I. 15/10/190

Survey held at Hitech Capital

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or *

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>23/1/20</u>	<u>\$3855.25, 6 days, email to Jiong Hoo (Red \$2799.50, 42%)</u>

RECEIVED 29 JAN 2020

Date/Time, File Pass to? : Prell. Report

: Final Report

Date/Time, File Return to? 29/1/20 Typist

Report Form: _____

Lump Sum / T.E.B. : PIP \$3855.25

Days Of Repair: 6

Resurvey No. of Trip: 3

- Add Fee:
- Site Insp (\$ _____)
 - Interview (\$ _____)
 - Tech. Invs (\$ _____)
 - Weekend (\$ _____)

Survey Fee:	
Transportation:	
S + PS \$	
Photo	
Other	
TOTAL	<u>220</u>

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Oct 2019		14 Oct 2019 16:39 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured:	PRINTEC PTE LTD, Co. Reg. No.: 197902751N								
Main Claimant:	HITACHI CAPITAL ASIA PACIFIC PTE LTD, Co. Reg. No.: 199400399N								
Vehicle Reg. No.:	SLC7437U	Date of Loss:	08/10/2019 11:00 - :59 [40 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D204825C02	Policy/Cover Note No.:	DMCVSN30789419033						
Vehicle Reg. No. (Insured):	GBE1640X	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Hitachi Capital Asia Pacific Pte. Ltd (HQ) No 8 Fourth Lok Yang Road, 629705 Pioneer - Tel: 64663022								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 23/10/2019]								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Yvonne Wong (LKK Auto)

From: Taufikh (LKKAuto)
Sent: Thursday, January 23, 2020 11:00 AM
To: 'JiongHow, Ng'
Cc: 'Vonn, LM Siow'; 'Jamilah, Binte MohdKassim'; Yvonne Wong (LKK Auto)
Subject: RE: SLC7437U / GBE1640X

Hi Jiong How,

COR \$3855.25 , 6 days.

Regards
Taufikh
Lkk Auto

From: JiongHow, Ng [mailto:jionghow.ng@hcspl.com.sg]
Sent: Friday, 10 January 2020 5:31 PM
To: Taufikh (LKKAuto)
Cc: Vonn, LM Siow; Jamilah, Binte MohdKassim
Subject: SLC7437U / GBE1640X

Dear Taufikh,

Please confirm COR @ \$3855.25 Before GST

Before paint have already WhatsApp to you

6 days repair

Regards

Ng Jiong How
Motor Claims Advisor
Auto Servicing
Total Vehicle Solutions Department

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre (Automobile Leasing & Workshop)
8 Fourth Lok Yang Road Singapore 629705
t: 6833 6282
e: jionghow.ng@hcspl.com.sg
w: www.hitachi-capital.com.sg

HITACHI
Inspire The Next

DISCLAIMER:

This email and/or any files and/or attachments transmitted are PRIVATE & CONFIDENTIAL and may be LEGALLY PRIVILEGED. This email is intended solely for the attention and use of the name addressee(s). If you are not a named addressee, you must not use, disseminate, forward, print or copy this email and all its contents/attachments. If you have received this email in error, please notify the sender immediately by email and delete it from your system.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/10/2019 09:10
Date Of Accident	08/10/2019 11:00
Exact Location Of Accident	21 KENG KEE RD THYE HONG CENTRE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLC7437U
Insured/Policyholder	
Name Of Registered Owner	HITACHI CAPITAL ASIA PACIFIC PTE LTD
Co Reg No	199400399N
Email Address	JUNTAIYO@HCSPL.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-64663022

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 CLASSIC CVT (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MSD/VPCP/19-000825-00
Cover Note Number	

Driver

Name of Driver	ABDUL SHUKOR BIN ABDUL
NRIC No	S2165775A
Date Of Birth	20/04/1957
Occupation	OUTDOOR
Date Of Driving Pass	14/08/1997
Driving Experience	22 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-93664823
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 828 JURONG WEST STREET 81 #04-462
Postcode	640823
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - LESSEE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE1640X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	CHOW KOK YONG
NRIC/Passport Number	S0224705D
Contact Number	98167112
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Driver's

On the 2/10/19 at about 11:00am, I was stopped along Thye Hong Centre carpark and was heading to the east. Suddenly vehicle B came out from that parking lot and hit onto my vehicle right side parking.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NBC/PW No.:

**Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre**

No. 8 Fourth Lok Yang Road Singapore 629705
Tel : 64663022 Fax : 68966591
Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE

China Taiping

QUOTE NO :
ACCIDENT DATE : 08/10/2019@1100HRS
VRN : SLC7437U
MODEL : Toyota Altis
TP VRN : GBE1640X

ATTN: MOTOR CLAIMS DEPT

Qty S\$ Unit S\$ Amt S\$ Labor

PARTS REPLACEMENT

1. Body Repair

1 Front Door RH	1	\$ 1,100.00	\$ 1,100.00	bl ✓
2 Front Door Outer Handle RH	1	\$ 143.00	\$ 143.00	R ✓
3 Front Door Outer Handle Cap RH	1	\$ 96.00	\$ 96.00	R ✓
4 Front Door Sticker RH	1	\$ 66.00	\$ 66.00	re ✓
5 Front Door Chrome Moulding RH	1	\$ 133.00	\$ 133.00	?
6 Front Door Regulator RH	1	\$ 305.00	\$ 305.00	?
7 Front Door Regulator Motor RH	1	\$ 355.00	\$ 355.00	?
8 Rear Door RH	1	\$ 1,079.00	\$ 1,079.00	bl ✓
9 Rear Door Outer Handle RH	1	\$ 143.00	\$ 143.00	X
10 Rear Door Outer Handle Cap RH	1	\$ 65.00	\$ 65.00	X
11 Rear Door Stickers RH	1	\$ 62.00	\$ 62.00	re ✓
12 Rear Door Regulator RH	1	\$ 305.00	\$ 305.00	X
13 Rear Door Regulator Motor RH	1	\$ 850.00	\$ 850.00	Y
14 Rocker Panel Outer RH	1	\$ 371.00	\$ 371.00	R ✓

Discount -25%

*Ren bumper - R ✓
Ren RH fender - R ✓*

\$ (1,268.25)

TOTAL \$ 3,804.75

2. Labor Charges

1 Remove, repair and replace parts for affected areas	925	\$ 1,250.00
2 Spray paint on the affected areas	1000	\$ 1,250.00
3 Remove & Refit Door Window Glass To Faciliate Repair	80	\$ 150.00
4 Dismantle and transfer door fitting & mechanism to new door	120	\$ 200.00

Sub Total : \$ 2,850.00

Grand Total : \$ 6,654.75
Add 7% GST : \$ 465.83
Nett Total : \$ 7,120.58

No. of repair days:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications 5 allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

*Tan Jun 97495749/67418234
- WP - 15/10/19
Resurvey before paint
sure thantam
5-6 days*

Parts - \$2307.00
 -25% - \$576.75

\$1730.25

labour - \$2125.00
 \$3855.25*

Hitachi Capital Asia Pacific Pte. Ltd.
 Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
 Tel : 64663022 Fax : 68966591
 Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE

China Taiping

QUOTE NO :
 ACCIDENT DATE : 08/10/2019@1100HRS
 VRN : SLC7437U
 MODEL : Toyota Altis
 TP VRN : GBE1640X

ATTN: MOTOR CLAIMS DEPT

Qty S\$ Unit S\$ Amt S\$ Labor

PARTS REPLACEMENT

1. Body Repair

1 Front Door RH	1	\$ 1,100.00	\$ 1,100.00	bl ✓
2 Front Door Outer Handle RH	1	\$ 143.00	\$ 143.00	Ry ✓
3 Front Door Outer Handle Cap RH	1	\$ 96.00	\$ 96.00	Ry ✓
4 Front Door Sticker RH	1	\$ 66.00	\$ 66.00	new ✓
5 Front Door Chrome Moulding RH	1	\$ 133.00	\$ 133.00	X } fun X
6 Front Door Regulator RH	1	\$ 305.00	\$ 305.00	X } fun
7 Front Door Regulator Motor RH	1	\$ 355.00	\$ 355.00	X }
<hr/>				
8 Rear Door RH	1	\$ 1,079.00	\$ 1,079.00	bl ✓
9 Rear Door Outer Handle RH	1	\$ 143.00	\$ 143.00	X ny
10 Rear Door Outer Handle Cap RH	1	\$ 65.00	\$ 65.00	X ny
11 Rear Door Stickers RH	1	\$ 62.00	\$ 62.00	new ✓
12 Rear Door Regulator RH	1	\$ 305.00	\$ 305.00	X ny
13 Rear Door Regulator Motor RH	1	\$ 850.00	\$ 850.00	X ny
14 Rocker Panel Outer RH	1	\$ 371.00	\$ 371.00	Ry ✓

Discount -25%

Rear bumper - Ry
 Rear RH fender - Ry

\$ (1,268.25)

TOTAL

\$ 3,804.75

2307
 1730.25

2. Labor Charges

1 Remove, repair and replace parts for affected areas	925	\$ 1,250.00
2 Spray paint on the affected areas	1000	\$ 1,250.00
3 Remove & Refit Door Window Glass To Faciliate Repair	80	\$ 150.00
4 Dismantle and transfer door fitting & mechanism to new door	120	\$ 200.00

2125

1730.25

2125

\$3855.25*

6 days*

Sub Total : \$ 2,850.00

Grand Total : \$ 6,654.75
 Add 7% GST : \$ 465.83
 Nett Total : \$ 7,120.58

No. of repair days: 5

Tan Jun 97495749 / 67410224
 WP 15/10/19
 Resuming before paint
 sure thank you
 5-6 days

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19018071/TIYF3N2
Date: 31/01/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN30789419033
Claimant Vehicle No : SLC7437U **Insured Vehicle No :** GBE1640X
 Date of Loss: 08/10/2019 Nature of Claim: TP **Claim No:** SNM19D204825C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLC7437U**
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A) Engine No: 1ZR562646
 Reg. Date: 25/05/2016 (Man. Year: 2016) Chassis No: MR053REH104548579
 Colour: Grey Odometer: 217409 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
 Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm
 Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,804.75	1,730.25	2,074.50	54.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,850.00	2,125.00	725.00	25.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,654.75	3,855.25	2,799.50	42.07
+ GST 7.00/7.00% (S\$)	465.83	269.87	195.96	42.07
Nett Amount (S\$)	7,120.58	4,125.12	2,995.46	42.07

INSPECTION

Date of Assignment: 14/10/2019
 Date Inspected: 15/10/2019 Inspected At: Hitachi Capital Asia Pacific Pte. Ltd (HQ)
 No 8 Fourth Lok Yang Road
 Singapore 629705
 Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 31 Jan 2020)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLC7437U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Bent	1,100.00 FL	*1,100.00 FL
2	1		*FRONT DOOR OUTER HANDLE RH	Repair	143.00 FL	*- FL
3	1		*FRONT DOOR OUTER HANDLE CAP RH	Repair	96.00 FL	*- FL
4	1		*FRONT DOOR STICKER RH	Necessary	66.00 FL	*66.00 FL
5	1		*FRONT DOOR CHROME MOULDING RH	Not Necessary	133.00 FL	*- FL
6	1		*FRONT DOOR REGULATOR RH	Not Necessary	305.00 FL	*- FL
7	1		*FRONT DOOR REGULATOR MOTOR RH	Not Necessary	355.00 FL	*- FL
8	1		*REAR DOOR RH	Bent	1,079.00 FL	*1,079.00 FL
9	1		*REAR DOOR OUTER HANDLE RH	Not Necessary	143.00 FL	*- FL
10	1		*REAR DOOR OUTER HANDLE CAP RH	Not Necessary	65.00 FL	*- FL
11	1		*REAR DOOR STICKERS RH	Necessary	62.00 FL	*62.00 FL
12	1		*REAR DOOR REGULATOR RH	Not Necessary	305.00 FL	*- FL
13	1		*REAR DOOR REGULATOR MOTOR RH	Not Necessary	850.00 FL	*- FL
14	1		*ROCKER PANEL OUTER RH	Repair	371.00 FL	*- FL
15	1		*REAR BUMPER (NPA)	Repair	0.00 FL	*- FL
16	1		*REAR RH FENDER (NPA)	Repair	0.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	5,073.00	2,307.00
- List Item Discount on L Items 25.00/25.00% (S\$)	1,268.25	576.75
Total Parts (S\$)	3,804.75	1,730.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE,REPAIR AND REPLACE PARTS FOR AFFECTED AREAS	New	1,250.00	925.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	1,250.00	1,000.00
3	REMOVE & REFIT DOOR WINDOW GLASS TO FACILITATE REPAIR	New	150.00	80.00
4	DISMANTLE AND TRANSFER DOOR FITTING & MECHANISM TO NEW DOOR	New	200.00	120.00
Gross Labour Cost (\$\$)			2,850.00	2,125.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >