

ASS. REC. BY:

REF: CS/FC119018073/Uqf3n2

Special Instruction:

Survivor: Marcus

ASSIGNMENT (Office)

From (Person): MAY chua

of

FC1

Date/Time: 14.10.19 4.16p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SME 2076M

Insured:

SHD 3210A

at Workshop m/s RICO 60 Auto

Tel:

9187 8064

of 8 Kaki Bukit Ave 4 #02-24

Policy No:

Claim No:

D19006501 MP5H

Sum Insured:

Excess:

Make of Veh:

D.O.A. 7.10.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 14.10.19 4.34p.m

Person Contacted:

Shanelle

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHD 3210A CC3/A2618012180/T1103/2 DOA: 29/06/2018
	SME 2076M: X
16/10/19 @ 3.12pm	revised to May chua by email.

ASS. REC. BY:

REF: FC1

Marcus

ASSIGNMENT

From:

Date:

15.10.2019

Veh No:

SME 2076M

Yr Regn:

210

Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

CA/

Make:

Mercedes 3

C.C.

1598

Colour:

white

A/C:

Insured / Std / NI / NA

Sp. Reading

183497

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JM6B2102/A0133311

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: Nil / ☒ SRim / ☐ STD A/Rim or

Tyre Size:

F:

R:

MIC
205/55R16BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

7/10/19

D.O.I.

15/10/19

Survey held at

Des. of Damages: ☐ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ UIC / ☐ Rooftop or *

Rear n/s.

The UIC / Chassis frame / Body Structure affected due to collision.

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SME 2076M

at Workshop m/s:

RICO 60 Auto

of

B Kaki Bukit Ave 4 #02-24

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

\$13800

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

P

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

30

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

mg

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

deptok.

LIA 10636 4wh A24 3164

8/10/19 4/5 @ 3000 confirmed with John Ured @ 13060. 36, 88%.

* MV: B13.8K (04A);

U/A: B10636;

RV: B3164

RECEIVED 10 OCT 2019

Date/Time, File Pass to?



: Preli. Report

1) 18/10 11am



: Final Report

Date/Time, File Return to?

2)

Rep. Form:

71

Lump Sum / F.R. / C.

3000

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Insp (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Other

TOTAL

15x15 = 225

170 + 225

50

50

49

544



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19006501MFSH

Date: 16 October 2019

Our Ref: CS/FCI19018073/Uqf3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SME 2076M

Please be informed that we had conducted the inspection of the abovementioned vehicle on 15/10/2019 at the premises of M/s RICO 60 AUTO, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>11,920.00 (SN+LABOUR ONLY)</u>
Revised Estimate Amount	: S\$ <u>1,580.00</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the rear n/s portion.



Yours faithfully

CHUA KANG SENG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	10-10-2019	Our Ref No. D19006501MFSH
Accident Date	07-10-2019	Claim Type. Third Party
Insured Vehicle	SHD3210A	Third Party Vehicle. SME2076M
Survey Location	8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT	
Contact Person.	SHANELLE LIM	
Contact No.	62866060/ 91878064	Fax No. 62867060
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	RICO 60 AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 16 October 2019 3:12 PM
To: 'CWS Motor Claims'; SUR
Cc: 'May Chua'
Subject: RE: SURVEY ASSESSMENT - D19006501MFSH/1
Attachments: CSFCI19018073Uqf3.pdf

Dear May,

Enclosed herewith preliminary advice of SME 2076M.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Monday, 14 October 2019 4:35 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'May Chua' <maychua@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19006501MFSH/1

Dear Sir/Madam,

Thank you for your assignment.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Sent: Monday, 14 October, 2019 4:16 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; May Chua <maychua@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19006501MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

sgCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

Spend \$30 to qualify
NOW TILL 15 NOV 2019
[MON - FRI, 6PM - 10PM]

CLICK TO FIND OUT MORE

MAZDA 3

Price Range

Depreciation

2010

Vehicle Type

Submit

Advanced Search

Home » Used Cars » D&L Auto Trading » Mazda 3 2.0A Luxury

Mazda 3 2.0A Luxury

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price

\$15,800

Depreciation

N.A.

Reg Date

10-Feb-2010
(3mths 25days COE left)

Mileage

118,000 km (12.2k /yr)

Manufactured

2009

Road Tax

\$1,212 /yr

Transmission

Auto

Dereg Value

\$12,405 as of today (change)

OMV

\$23,592

COE

\$19,000

ARF

\$23,592

Engine Cap

1,999 cc

Power

108.0 kW (144 bhp)

Curb Weight

1,324 kg

No. of Owners

2

Type of Vehicle

Mid-Sized Sedan

Features

Powerful 2.0L DOHC 16V VVT Engine, 144BHP, 5 Speed Auto Steptronic, Traction Control, Paddle Shifters, Airbags, 4XABS Disc Brakes, Keyless Entry/Start View specs of the Mazda 3 Sedan (2009-2014)

Accessories

Genuine Leather, New 17" Sport Rims, New Tyres, AUX/USB Audio, Steering Controls, Fog Lights, Solar Film, Reverse Sensors, Retractable Side Mirrors

Description

Guaranteed Accident Free, High OMV \$24K, Beautiful Leather Interior, Extremely Well Maintained, Wear & Tear Parts Fully Replaced, Guaranteed Loan For Bad Credit/Ex Bankruptcy, View After Lunch Till 11PM Daily, Please Call To Arrange Viewing.

Category

PARF Car

Status

Available

Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more

Posted on: 31-Aug-2019 | Last Updated on: 14-Sep-2019

Upfront Payment

» more Financial info

Transfer Fee

\$25

Down Payment

\$4,740 (change)

Maximum 70% Loan

1st Instalment

\$3,714

Based on 2.98% interest rate

Products and Services

» View All

Compare



Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Company

D&L Auto Trading

» dealer's price list

» 20 vech sold | 26 vech available

Address

200 Jalan Sultan #04-20

Search cars nearby this location

Location

Textile Centre

Office No

62960188

Contact Person(s)

Darren Low

96236322



We're revving up our celebrations for our first-year milestone



Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Mercedes-Benz E-Class E200 Exclusive.



Exclusive Model! by C&C High
Car, 100% Accident Free, Low
Mileage Done, AMG Noms
Direct Owner. StarAd



Browse by Category

6 vehicles

Mazda 3



To get alerted when new vehicles are added

Sort by Date Posted

20 results/page

Advanced Search



Search Selection

Mazda 3



Mazda 3 1.6A Luxury (New 5-yr COE)

\$30,800

\$6,150 /yr

26-Jan-2010

1,598 cc

-

Sedan

Available

Luxury Model, Best Priced Unit In The Market! Very Well Maintained, Smooth And Responsive Drive With Quiet Undercarriage. Call For A Viewing Appointment Today!

Mayfair Motoring

Posted: 07-Oct-2019

Tags: 2010 Mazda 3, 2010 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda



Mazda 3 1.6A Luxury (New 5-yr COE)

\$30,800

\$6,150 /yr

20-Jan-2010

1,598 cc

-

Sedan

Available

Full Loan Available At \$800 Plus, We Can Help To Convert To Z10 Usage If Needed. In House Loan Or Bank Loan Available! Fast, Easy And Flexible Loan Approval! We Are sgCarMart Premium Dealer! Buy With Confidence! Viewing And Test Drive Available Daily Including...

88 Motor Trading

Posted: 05-Oct-2019

Tags: 2010 Mazda 3, 2010 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda



Mazda 3 1.6A Luxury (New 5-yr COE)

\$32,999

\$6,590 /yr

12-Jan-2010

1,598 cc

148,000 km

Sedan

Available

1 Owner Just Arrival! Sporty White In Black Color Mazda 3 SDN Luxury! Very Well Maintained By Careful Owner And 100% Accident Free, Stable Good Road Holding, Nice Dash Board! The Car In Original Paint Condition Since Day One! Road Tax Till Jan 2020! Call Us Now, D...

Posted: 26-Sep-2019

Tags: 2010 Mazda 3, 2010 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda



Mazda 3 2.0A

\$21,555

\$8,730 /yr

25-Nov-2010

1,999 cc

153,000 km

Sedan

Available

1 Owner Just Arrival! Sporty Red In Black Color Mazda 3 2.0 SDN! Very Well Maintained By Careful Owner And 100% Accident Free, Stable Good Road Holding, Fully Maintain Agent Trans Eurokas Mazda. The Car In Original Paint Condition Since Day 1. High PARF At \$1...

Posted: 22-Sep-2019

Tags: 2010 Mazda 3, 2010 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda



Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



Mazda 3 1.6A Luxury (New 5-yr COE)

\$31,700

\$6,330 /yr

11-May-2010

1,598 cc

164,000 km

Sedan

Available

Well Maintained, Mint Condition. Ideal For Short Term Usage With Low Depreciation.

Posted: 19-Sep-2019

Tags: 2010 Mazda 3, 2010 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda



Mazda 3 2.0A Luxury

\$15,800

N.A

10-Feb-2010

1,999 cc

118,000 km

Sedan

Available

Guaranteed Accident Free, High OMV \$24K, Beautiful Leather Interior, Extremely Well Maintained, Wear & Tear Parts Fully Replaced, Guaranteed Loan For Bad Credit/Ex Bankruptcy, View After Lunch Till 11PM Daily, Please Call To Arrange Viewing.

Posted: 31-Aug-2019

Tags: 2010 Mazda 3, 2010 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda

Save this search criteria, to get email alerts whenever a match is found.

Compare

Make

Model

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status


> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	233X
Vehicle Details	
Vehicle No.:	SME2076M
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Oct 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 1.6L SDN
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	Z6837775
Chassis No.:	JM6BL10Z1A0133311
Maximum Power Output:	77.0 kW (103 bhp)
Open Market Value:	\$20,056.00
Original Registration Date:	05 Feb 2010
First Registration Date:	05 Feb 2010
Transfer Count:	1
Actual ARF Paid:	\$20,056.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Feb 2020
PARF Rebate Amount:	\$10,028.00
Intended COE Rebate Details	
COE Expiry Date:	04 Feb 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$19,989.00
COE Rebate Amount:	\$608.00
Total Rebate Amount:	\$10,636.00

The information contained herein is correct as at 15 Oct 2019

OK



not Alif
here
2/58
at
15/10/8

ATTN:		15/10/11	
NO.	DESCRIPTION - PARTS	QTY	PRICE
1	REAR WINDSCREEN MOULDING 11 X	1	
2	BOOTLID 11 X	1	
3	BOOTLID LOGO (MAZDA) 11 X	1	
4	BOOTLID EMBLEM (MAZDA 3) 11 X	1	
5	BOOTLID THIRD BRAKE LAMP 11 X	1	
6	BOOTLID SWITCH 11 X	1	
7	BOOTLID LAMP (L+R) 11 X	2	
8	BOOTLID INNER TRIM 11 X	1	
9	BOOTLID INNER TRIM HANDLE 11 X	1	
10	BOOTLID DAMPER (L+R) 11 X	1	
11	BOOTLID HINGE (L+R) 11 X	2	
12	BOOTLID STOPPER (L+R) 11 X	2	
13	BOOTLID INNER LOCK 11 X	1	
14	BOOTLID INNER LOCK CATCH 11 X	1	
15	BOOTLID WEATHERSTRIP 11 X	1	
16	TAIL LAMP (L+R) n/s? n/s one 1pc	2	
17	TAIL LAMP PANEL (L+R) 11 X	2	
18	REAR BUMPER D15	1	
19	REAR BUMPER RETAINER (L+R) n/s 1pc	2	
20	REAR BUMPER REINFORCEMENT BAR n/s 1pc	1	
21	REAR BUMPER BRACKET (L+R) 11 X	2	
22	REAR BUMPER BEAM n/s X	1	
23	REAR BUMPER SPONGE n/s X	1	
24	REAR BUMPER CARPLATE LAMP (L+R) 11 X	2	
25	REAR BUMPER LOWER n/s X	1	
26	REAR BUMPER LOWER REFLECTOR (L+R) n/s one 1pc	2	
27	REAR BUMPER UNDERCOVER n/s X	1	
28	REAR FENDER (L+R) 12 X	2	
29	REAR FENDER INNER TRIM (L+R) 11 X	2	
30	REAR FENDER COWLING (L+R) 11 X	2	
31	END PANEL Body 1pc	1	
32	END PANEL TOP GARNISH 11 X	1	
33	SPAREWHEEL PANEL 11 X	1	
34	SPAREWHEEL PANEL TOP BOARD 11 X	1	
35	EXHAUST PIPE 12 X	1	
36	EXHAUST GASKET 11 X	1	
37	EXHAUST BRACKET (L+R) 11 X	2	
38	EXHAUST HEAT SHIELD 11 X	1	
SUBTOTAL			\$ -

		LESS 10%		\$	-
		PARTS TOTAL		\$	-
	SPECIAL NETT		QTY	PRICE	
1	REAR WINDSCREEN SEALANT 11X		1	\$	120.00
2	BOOTLID INNER TRIM CLIPS 11X		10	\$	100.00
3	TAIL LAMP CLIPS 11X		4	\$	80.00
4	REAR BUMPER CLIPS 11X 50		10	\$	100.00
5	REAR BUMPER REVERSE SENSOR SET ?		2	\$	300.00
6	REAR CARPLATE 11X		1	\$	120.00
7	REAR CARPLATE FRAME 11X		1	\$	120.00
8	REAR FENDER SEALANT 11X		1	\$	120.00
9	REAR FENDER INNER TRIM CLIPS 11X		20	\$	200.00
10	REAR FENDER COWLING CLIPS 11X		20	\$	200.00
11	END PANEL SEALANT ?		1	\$	120.00
12	END PANEL TOP GARNISH CLIPS 11X		10	\$	100.00
13	SPAREWHEEL PANEL SEALANT 11X		1	\$	120.00
14	SPARE TYRE 11X		1	\$	600.00
15	SPARE RIM 11X		1	\$	800.00
		SPECIAL NETT TOTAL		\$	3,200.00
	LABOUR		QTY	PRICE	
1	TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK&REALIGN 600		1	\$	3,600.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA 750		1	\$	2,400.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA 30		1	\$	250.00
4	TO RNR REAR WINDSCREEN 11X		1	\$	400.00
5	TO RNR REAR BOOT MECHANISM 11X		1	\$	400.00
6	TO RNR UPHOLSTERY,GARNISH AND ATTACHMENT PARTS 80		1	\$	400.00
7	TO RNR REVERSE SENSOR & CHECK FUNCTION. 50		1	\$	120.00
8	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS 11X		1	\$	250.00
9	TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION 20		1	\$	150.00
10	TO DO DIAGNOSIS AND RESET , REPROGRAM OR CODING FAULT CODE. 11X		1	\$	400.00
11	TO DO WATER LEAK TEST . 11X		1	\$	100.00
12	TO RNR FUEL TANK TO ASSIST WORK LOAD 11X		1	\$	250.00
		TOTAL		\$	8,720.00
		GRAND TOTAL COST		\$	11,920.00

LKK Auto Consultants hereby notify the Repairs of the following:

- Damage and before/after spray painting
- To use damaged part(s) during resurvey
- This resurvey is subject to confirmation
- This resurvey is on a "Without Prejudice" basis
- No claim modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

L - 1530



Rico 60 Auto Services Pte Ltd. Blk 8, Kaki Bukit Avenue 4, #02-24
Premier @ Kaki Bukit Singapore 415875, Email: claims@rico60.com
Tel: 6286 6060, FAX: 6286 7060

VEHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

SME 2076 M
MAZDA 3

NOT Affm
hmr
1/5 #3000/
H.M.
15/10/18
Zhang Hui

NO.	DESCRIPTION - PARTS	QTY	PRICE	
1	REAR WINDSCREEN MOULDING 11 X	1	\$168.00	X
2	BOOTLID 11 X	1	\$1272.00	X
3	BOOTLID LOGO (MAZDA) 11 X	1	\$64.00	X
4	BOOTLID EMBLEM (MAZDA 3) 11 X	1	\$58.00	X
5	BOOTLID THIRD BRAKE LAMP 11 X	1	\$321.00	X
6	BOOTLID SWITCH 11 X	1	\$106.00	X
7	BOOTLID LAMP (L+R) 11 X	2	\$496.00	X
8	BOOTLID INNER TRIM 11 X	1	\$156.00	X
9	BOOTLID INNER TRIM HANDLE 11 X	1	\$89.00	X
10	BOOTLID DAMPER (L+R) 11 X	2	\$327.00	X
11	BOOTLID HINGE (L+R) 11 X	2	\$286.00	X
12	BOOTLID STOPPER (L+R) 11 X	2	\$36.00	X
13	BOOTLID INNER LOCK 11 X	1	\$253.00	X
14	BOOTLID INNER LOCK CATCH 11 X	1	\$84.00	X
15	BOOTLID WEATHERSTRIP 11 X	1	\$122.00	X
16	TAIL LAMP (L+R) 11 X 19c N/scre \$993.40	2	\$1986.80	1PC
17	TAIL LAMP PANEL (L+R) 11 X	2	\$208.00	X
18	REAR BUMPER D15	1	\$973.00	X
19	REAR BUMPER RETAINER (L+R) N/scre 1PC \$38.00	2	\$76.00	1PC
20	REAR BUMPER REINFORCEMENT BAR 11 X 10/20/20	1	\$385.00	X
21	REAR BUMPER BRACKET (L+R) 11 X	2	\$96.00	X
22	REAR BUMPER BEAM 11 X	1	NIL	X
23	REAR BUMPER SPONGE 11 X	1	NIL	X
24	REAR BUMPER CARPLATE LAMP (L+R) 11 X	2	\$126.00	X
25	REAR BUMPER LOWER 11 X	1	\$390.00	X
26	REAR BUMPER LOWER REFLECTOR (L+R) 11 X 1PC \$71.40	2	\$142.80	1PC
27	REAR BUMPER UNDERCOVER 11 X	1	\$248.90	X
28	REAR FENDER (L+R) 11 X	2	\$1858.00	X
29	REAR FENDER INNER TRIM (L+R) 11 X	2	\$486.00	X
30	REAR FENDER COWLING (L+R) 11 X	2	\$164.00	X
31	END PANEL 2 30/30 409.30	1	\$635.00	X
32	END PANEL TOP GARNISH 11 X	1	\$198.00	X
33	SPAREWHEEL PANEL 11 X	1	\$1347.00	X
34	SPAREWHEEL PANEL TOP BOARD 11 X	1	\$176.00	X
35	EXHAUST PIPE 11 X	1	\$879.00	X
36	EXHAUST GASKET 11 X	1	\$39.00	X
37	EXHAUST BRACKET (L+R) 11 X	2	\$78.00	X
38	EXHAUST HEAT SHIELD 11 X	1	\$169.90	X
			P: \$3095.80	
			-20% = \$2476.64	
			SUBTOTAL	\$ -

14600.40

		(202 LESS 10%)	\$	-
		PARTS TOTAL	\$	-
SPECIAL NETT		QTY	PRICE	
1	REAR WINDSCREEN SEALANT 11X	1	\$	120.00
2	BOOTLID INNER TRIM CLIPS 11X	10	\$	100.00
3	TAIL LAMP CLIPS 11X	4	\$	80.00
4	REAR BUMPER CLIPS 11X 50	10	\$	100.00
5	REAR BUMPER REVERSE SENSOR SET 11X	2	\$	300.00
6	REAR CARPLATE 11X	1	\$	120.00
7	REAR CARPLATE FRAME 11X	1	\$	120.00
8	REAR FENDER SEALANT 11X	1	\$	120.00
9	REAR FENDER INNER TRIM CLIPS 11X	20	\$	200.00
10	REAR FENDER COWLING CLIPS 11X	20	\$	200.00
11	END PANEL SEALANT 30 11X	1	\$	120.00
12	END PANEL TOP GARNISH CLIPS 11X	10	\$	100.00
13	SPAREWHEEL PANEL SEALANT 11X	1	\$	120.00
14	SPARE TYRE 11X	1	\$	600.00
15	SPARE RIM 11X	1	\$	800.00
SN: #100				
SPECIAL NETT TOTAL			\$	3,200.00
LABOUR		QTY	PRICE	
1	TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK&REALIGN 600	1	\$	3,600.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA 750	1	\$	2,400.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA 30	1	\$	250.00
4	TO RNR REAR WINDSCREEN 11X	1	\$	400.00
5	TO RNR REAR BOOT MECHANISM 11X	1	\$	400.00
6	TO RNR UPHOLSTERY, GARNISH AND ATTACHMENT PARTS 80	1	\$	400.00
7	TO RNR REVERSE SENSOR & CHECK FUNCTION. 50	1	\$	120.00
8	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS 11X	1	\$	250.00
9	TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION 20	1	\$	150.00
10	TO DO DIAGNOSIS AND RESET, REPROGRAM OR CODING FAULT CODE. 11X	1	\$	400.00
11	TO DO WATER LEAK TEST. 11X	1	\$	100.00
12	TO RNR FUEL TANK TO ASSIST WORK LOAD 11X	1	\$	250.00
L: #1530				
Total: #4106.64				
-20%: #3300				
TOTAL			\$	8,720.00
GRAND TOTAL COST			\$	11,920.00

P-2870-10

202

P-2296.08


S.N 100.00

L-1530.00

3926.08

3144

25060.36



VEHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

SME 2076 M
MAZDA 3

ATTN:			
NO.	DESCRIPTION - PARTS	QTY	PRICE
1	REAR QUARTER PANEL (LH) 2 X	1	
	SUBTOTAL		\$ -
	LESS 10%		\$ -
	PARTS TOTAL		\$ -
	SPECIAL NETT	QTY	PRICE
1	EXHAUST CHROME TIP 11	1	\$ 1,000.00
	SPECIAL NETT TOTAL		\$ 1,000.00
	LABOUR	QTY	PRICE
	TOTAL		#REF!
	GRAND TOTAL COST		#REF!



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19018073/Uqf3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 21-10-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3210A	Veh. Inspected	SME 2076M	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19006501MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	14/10/2019	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 3 (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	JM6BL10Z1A0133311	Colour	WHITE	
Odometer	183497	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	MICHELIN	6 mm	
L/H Front Tyre	205/55 R16	MICHELIN	6 mm	
R/H Rear Tyre	205/55 R16	PIRELLI	6 mm	
L/H Rear Tyre	205/55 R16	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/10/2019	Inspection Date	15/10/2019	
Survey held at	RICO 60 AUTO SERVICES PTE LTD 8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SME 2076M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	168.00	-
1	BOOTLID	NOT NECESSARY	1,272.00	-
1	BOOTLID LOGO (MAZDA)	NOT NECESSARY	64.00	-
1	BOOTLID EMBLAM (MAZDA 3)	NOT NECESSARY	58.00	-
1	BOOTLID THIRD BRAKE LAMP	NOT NECESSARY	321.00	-
1	BOOTLID SWITCH	NOT NECESSARY	106.00	-
2	BOOTLID LAMP (L+R)	NOT NECESSARY	496.00	-
1	BOOTLID INNER TRIM	NOT NECESSARY	156.00	-
1	BOOTLID INNER TRIM HANDLE	NOT NECESSARY	89.00	-
2	BOOTLID DAMPER (L+R)	NOT NECESSARY	327.00	-
2	BOOTLID HINGE (L+R)	NOT NECESSARY	286.00	-
2	BOOTLID STOPPER (L+R)	NOT NECESSARY	36.00	-
1	BOOTLID INNER LOCK	NOT NECESSARY	253.00	-
1	BOOTLID INNER LOCK CATCH	NOT NECESSARY	84.00	-
1	BOOTLID WEATHERSTRIP	NOT NECESSARY	122.00	-
2	TAIL LAMP (L+R)	N/S CRACKED	1,986.80	993.40
2	TAIL LAMP PANEL (L+R)	NOT NECESSARY	308.00	-
1	REAR BUMPER	DISTORTED	973.00	973.00
2	REAR BUMPER RETAINER (L+R)	N/S BENT	76.00	38.00
1	REAR BUMPER REINFORCEMENT BAR	DENTED / BENT	385.00	385.00
2	REAR BUMPER BRACKET (L+R)	NOT NECESSARY	96.00	-
1	REAR BUMPER BEAM (NPA)	NO SUCH PARTS	-	-
1	REAR BUMPER SPONGE (NPA)	NO SUCH PARTS	-	-
2	REAR BUMPER CARPLATE LAMP (L+R)	NOT NECESSARY	126.00	-
1	REAR BUMPER LOWER	NOT FITTED	390.00	-
2	REAR BUMPER LOWER REFLECTOR (L+R)	N/S CRACKED	142.80	71.40
1	REAR BUMPER UNDERCOVER	NOT FITTED	248.90	-
2	REAR FENDER (L+R)	TO REPAIR SEE LABOUR	1,858.00	-
2	REAR FENDER INNER TRIM (L+R)	NOT NECESSARY	486.00	-
2	REAR FENDER COWLING (L+R)	NOT NECESSARY	164.00	-

Report Ref No. CS/FCI19018073/Uqf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	END PANEL	BADLY DENTED	635.00	409.30
1	END PANEL TOP GARNISH	NOT NECESSARY	198.00	-
1	SPARE WHEEL PANEL	NOT NECESSARY	1,347.00	-
1	SPARE WHEEL PANEL TOP BOARD	NOT NECESSARY	176.00	-
1	EXHAUST PIPE	TO REPAIR SEE LABOUR	879.00	-
1	EXHAUST GASKET	NOT NECESSARY	39.00	-
2	EXHAUST BRACKET (L+R)	NOT NECESSARY	78.00	-
1	EXHAUST HEAT SHIELD	NOT NECESSARY	169.90	-
	LESS 10% DISCOUNT		-1,460.04	-
	LESS 20% DISCOUNT		-	-574.02
			13,140.36	2,296.08
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	120.00	-
10	BOOTLID INNER TRIM CLIPS (SN)	NOT NECESSARY	100.00	-
4	TAILLAMP CLIPS (SN)	NOT NECESSARY	80.00	-
10	REAR BUMPER CLIPS (SN)	NECESSARY	100.00	50.00
2	SET REAR BUMPER REVERSE SENSOR (SN)	NOT NECESSARY	300.00	-
1	REAR CARPLATE (SN)	NOT NECESSARY	120.00	-
1	REAR CARPLATE FRAME (SN)	NOT NECESSARY	120.00	-
1	REAR FENDER SEALANT (SN)	NOT NECESSARY	120.00	-
20	REAR FENDER INNER TRIM CLIPS (SN)	NOT NECESSARY	200.00	-
20	REAR FENDER COWLING CLIPS (SN)	NOT NECESSARY	200.00	-
1	END PANEL SEALANT (SN)	NECESSARY	120.00	50.00
10	END PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	100.00	-
1	SPAREWHEEL PANEL SEALANT (SN)	NOT NECESSARY	120.00	-
1	SPARE TYRE (SN)	NOT NECESSARY	600.00	-
1	SPARE RIM (SN)	NOT NECESSARY	800.00	-
			3,200.00	100.00
	<u>LABOUR</u>			
	TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD,KNOCK & REALIGN.INCLUSIVE OF THE REPAIR OF REAR FENDER (L+R) AND EXHAUST PIPE.		3,600.00	600.00

Report Ref No. CS/FCI19018073/Uqf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA.		2,400.00	750.00
	TO RUST PROOF ACCIDENT AFFECTED AREA.		250.00	30.00
	TO RNR REAR WINDSCREEN.	NOT NECESSARY	400.00	-
	TO RNR REAR BOOT MECHANISM.	NOT NECESSARY	400.00	-
	TO RNR UPHOLSTERY,GARNISH AND ATTACHMENT PARTS.		400.00	80.00
	TO RNR REVERSE SENSOR & CHECK FUNCTION.		120.00	50.00
	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS.	NOT NECESSARY	250.00	-
	TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION.		150.00	20.00
	TO DO DIAGNOSIS AND RESET,REPROGRAM OR CODING FAULT CODE.	NOT NECESSARY	400.00	-
	TO DO WATER LEAK TEST.	NOT NECESSARY	100.00	-
	TO RNR FUEL TANK TO ASSIST WORK LOAD.	NOT NECESSARY	250.00	-
			8,720.00	1,530.00
	GRAND TOTAL		25,060.36	3,926.08
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,000.00

Report Ref No. CS/FCI19018073/Uqf3n2

MARKET VALUE: \$13,800.00 (EST)-LTA REIMBURSEMENT VALUE: \$10,636.00=NETT VALUE: \$3,164.00

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.