

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Steve (LKK) OD - Not Authorise (Revert)
: 15/10/19, 1.00pm 3 days
: EXCESS - ?
: P/P
: Ry Refz spj

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PROFESSIONAL AUTOMOTIVE DETAILING

CERAMIC WORKS QUATATION

Date: 17 October 2019
IVS 10036

ISSUED TO

NAME : ATTICUS LOW
Address :

Contact : 97927926
Email : ATTICUSLOWKC@YAHOO.COM.SG
Car Model : AUDI A4
Car Plate Number : SLT3704K

ISSUED BY

Ceramic Works LLP
13 Kaki Bukit Road 4
#01-29 Bartley Biz Centre
Singapore 417807
Contact : (+65) 8189 3233
Website : ceramicworks.sg

Description

TO COAT ACCIDENT AFFECTED AREA

DECONTAMINATING FOAM WASH

MULTISTEP POLISHING

COAT ACCIDENT AFFECTED AREA

\$ 490.00

Sub - Total \$ 490.00

Total S\$ \$ 490.00

Terms and Conditions

*All payment due upon receipt of Invoice.

*No refund or transfer of packages purchased unless otherwise stated.

*Cheque to be crossed and made payable to "Ceramic Works LLP".

*By providing your contact number with us, you hereby kindly consent Ceramic Works LLP to contact you via SMS and phone for any form of marketing or promotion events from us, notwithstanding your number maybe listed on the Do Not Call Registry.



OPTI-SHINE PTE. LTD. Reg No. 201227486G

25 Kaki Bukit Road 4 #06-47 Synergy@KB Singapore 417800
Tel: +65 6635 5656 Fax: +65 6635 4646 Mobile: +65 8661 8747
Email: sales@opti-shine.com Website: www.opti-shine.com

Invoice / Cash Sale

NO.: OS- 13196

Name : Atticus Low Date : 31/10/2017
Address : _____ Mobile : 97927926
Email : atticuslowkc@yahoo.com.sg

Vehicle No.	Model	Remarks
SLT3704K	Audi A4	com.sg

S. No	Description	Amount	
		\$	CTS
1)	Signature Protection Treatment Titanium Package 3 sessions within 24 months 1st Session Done on 31/10/2017 5 Years Warranty	1250	00
2)	Sunshade	70	00
TOTAL		1320	00

 **Opti-Shine**
Professional Car Grooming | Paint Protection System

JOHN YEO
8777 0006
john@opti-shine.com




www.opti-shine.com


OPTI-SHINE PTE LTD
25 Kaki Bukit Road 4
#06-47 Synergy @ KB
Singapore 417800
T: 6635 5656
F: 6635 4646
Reg No: 201227486G

Terms and Conditions:

- By providing your contact number on this form, you give us permission to call you in response to this request and other marketing activities via sms and phone even if your contact number is listed in the Do Not Call Registry. Your privacy is important to us. We will never sell, trade or share your personal information with any third party organization.
- The above agreement and payment are not refundable or transferable.
- Unless otherwise stated, the expiry date of package shall be for a period of 24 months from date of agreement.
- Cheques should be crossed and made payable to **OPTI-SHINE PTE. LTD.**
- Funds transfer should be made to OCBC Current Account No. 533827366001 and proof of transfer to be emailed to sales@opti-shine.com for our reference.
- All Payments are due upon receipt of this invoice.


OPTI-SHINE PTE. LTD.

Professional Car Grooming | Paint Protection System


Customer's Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 15779

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1235/2019/NS
Date : 14-Oct-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Steve

3 days - ok - jb - 29 Jan 20

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Atticus Low Kok Cheong
Address : 10 Hougang St 32
#08-24
Singapore 534037
Telephone : (HP) +65 97927926
Type of Claim : Own damage Claim
Policy No. : 170069824-01
Vehicle No : **SLT 3704 K**
Model Code : Audi A4 Sedan 1.4 TFSI S
Model / Year : 26/10/2017
Engine No : CVN 045413
Chassis No : WAUZZZF41JA022951
Mileage :
Date In :
Estimated By : Johnny Boo / Allan Wu
Accident Date : 12-Oct-19
Place of Accident : HDB Car Park Behind Blk 122 Bukit Merah Lane 1 Car Lot 150

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLT 3704 K

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rhs front door's multi-lock system and power window devices. Inspect for damages.	S/N \$	280.00	\$ 280.00 /
2	To dismantle rhs front door panel trim. To remove and renew rhs wing mirror assy.	S/N \$	300.00	
3	To dismantle and renew rhs front door. Re-organise crash management components. Reinstall all parts removed.	\$	1,050.00	\$ 500.00 /
4	To respray rhs front door, rhs rear door, door handle and rhs wing mirror cover.	\$	2,500.00	\$ 600.00 /
6	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00 /
	SUB TOTAL LABOUR CHARGES	:	\$ 4,322.00	\$ 1,572.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLJ 8411 M

S/N	Parts Description	Damaged Parts & Prices		
			S/Nett	Remarks
1	FRONT DOOR - RH	\$	2,152.00	\$ 1,721.60 ✓
2	FRONT DOOR OUTER SEAL - RH	NEC \$	185.00	\$ 147.60 ✓
3	BONDING AGENT	NEC \$	45.00	\$ 35.92 ✓
4	CLEANING SOLUTION	NEC \$	65.00	\$ 52.00 ✓
5	FRONT DOOR ATTACHMENT PARTS	\$	488.00	
6	FRONT DOOR CATCH	\$	96.00	
7	DOOR HANDLE TRIM PLATE - DRIVER DOOR	\$	80.00	
8	DOOR HANDLE SENSOR - RH	\$	208.00	
9	EXTERIOR DOOR HANDLE - RH	\$	35.00	
10	LOCK CYLINDER - DRIVER DOOR	\$	492.00	
11	DOOR MOUNTING BAR - DRIVER DOOR	\$	149.00	
12	WINDOW REGULATOR - RH	\$	250.00	
13	WINDOW REGULATOR MOTOR - RH	\$	278.00	
14	EXTERIOR MIRROR MOUNTING - RH	2 \$	824.00	
15	MIRROR CAP - RH	\$	220.00	
16	MIRROR GLASS - RH	\$	1,553.00	
17	WINDOW SLOT SEAL - RH	\$	280.00	
18	TYRE PRESSURE DATA PLATE	\$	35.00	\$ 27.36 ✓
19	SUNDRIES	\$	300.00	\$ 4.08 ✓
20				
	TOTAL SPARE PARTS CHARGES	:	\$ 7,735.00	\$ 1,988.56
	TOTAL LABOUR CHARGES	:	\$ 4,322.00	\$ 1,572.00
	GRAND TOTAL CHARGES	:	\$ 12,057.00	\$ 3,560.56

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/1235/2019/NS

12-Oct-19

TROY GOH

1 of 1

SLT 3704 K

A4 SEDAN 1.4 TFSI S

Quantity	Description	Unit Price	Amount
Labours			
1	To reapply paint coating for accident affected area. <i>MC</i>	\$ 490.00	
GRAND TOTAL		\$ 490.00	

For Premium Automobiles Pte Ltd

claim insured letter K/V first

Authorised Signature

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLT 3704 K

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1235/2019/NH

3rd March 2020

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SLT 3704 K, Audi A4 SEDAN 1.4 TFSI S-TRONIC.

With reference to the above-mentioned vehicle, no. **SLT 3704 K**, claimant, **MR. ATTICUS LOW KOK CHEONG**, please find the related document per attached.

1. A copy of the Original invoice no. 85014919 – S\$ 3809.80.
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – SLT 3704 K

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6886 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 13:37

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014919 Date : 28/02/2020 Order : SLT3704K Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SLT3704K (V 34967) Regn Date: 26/10/2017 Mileage: 43914 WIP No.: 15779

Model: A4 SEDAN 1.4 TFSI S tronic Chassis: WAUZZZF41JA022951 Engine: CVN 045413 Dept: U

You have been assisted by :- UB-Nora (11)

	Details	Qty	Unit Price	Amount
S	BODYWORK M: TO REMOVE AND TRANSFER RHS FRONT DOOR'S MULTI LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	280.00	1.00	280.00
S	BODYWORK M: TO DISMANTLE AND RENEW RHS FRONT DOOR. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	500.00	1.00	500.00
S	BODYWORK M: TO RESPRAY RHS FRONT DOOR AND DOOR HANDLE	600.00	1.00	600.00
S	BODYWORK M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A8W0831052D DOOR	1.00	2152.00	1,721.60
X	A8W0837912A SEAL	1.00	184.50	147.60
X	A8W2837240 GRU CLEANING SOL AP	1.00	65.00	52.00
X	A8W0837878 COVER AP	1.00	5.10	4.08
X	A8W0010502C LABEL	1.00	34.20	27.36
X	AD 355205A2 BONDAGENT	1.00	44.90	35.92

Parts 1,988.56
Labour 0.00
Sublet 1,572.00
Menus 0.00
Lubricant 0.00

Sub-Total 3,560.56

7% GST 249.24

Grand Total 3,809.80



7/2

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLT 3704 K

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1235/2019/KK
18 October 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages


RE: CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A4 SEDAN 1.4 TFSI
Vehicle Chassis No. : WAUZZZF41JA022951
Vehicle Regn No. : **SLT 3704 K**
Vehicle Mileage : 42425 KM
Vehicle Owner : Mr. Atticus Low Kok Cheong
Certificate No : 1700069824-01
Own Damage Excess : \$ 0.00 (Inclusive GST)
Accident Date : 12 Oct 2019
Place : HDB Carpark Behind Blk 122 Bukit Merah Lane 1 Car Lot 150
Repair Cost : \$ 3809.80
WIP No. : 15779
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time : 18.06 pm
Date : 18/10/2019

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Oct 2019		15 Oct 2019 11:08 Edit Adj Rpt	\$3,560.56 Edit Estimates	\$3,560.56 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LOW KOK CHEONG ATTICUS, ID: S7222513I, Tel: +6597927926, Email: ATTICUSLOWKC@YAHOO.COM.SG		
Vehicle Reg. No.:	SLT3704K	Date of Loss:	12/10/2019 08:00 - :59 [23 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 0731916492SG	Policy/Cover Note No.:	1700069824 (Comprehensive)
		Excess:	S\$0.00
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Azlan, Syazairdina] syazairdina.azlan@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 24/10/2019]		
Driver/Custodian:	LOW KOK CHEONG ATTICUS (47 / Male), NRIC: S7222513I, Tel: +6597927926 Email: ATTICUSLOWKC@YAHOO.COM.SG		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (29/10/2019): Alert - Adj Mandate Maintained - SLT3704K - Claim Handler: Azlan, Syazairdina
- AIG_SG (15/10/2019): Alert - Adj Mandate Approved (S\$4634.00) - SLT3704K - Claim Handler: Azlan, Syaz...
- AIG_SG (15/10/2019): SLT3704K / OD / 12/10/2019 / Coverage & Excess update

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLT3704K (0731916492SG)

OD

Oct 12 2019 8:00AM

[LOW KOK CHEONG ATTICUS]

Premium Automobiles Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio				View View in Browser	
Video				1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	12/10/19 18:06	Video - Accident [Linked Accident Report Documents]	1	Load MP4	
2	12/10/19 18:06	Video - Accident [Linked Accident Report Documents]	1	Load MP4	
Assessment Reports				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	15/10/19 16:07	Adjuster Immediate Advice	1	Load HTM	
2	21/10/19 09:08	Adjuster Immediate Advice	1	Load HTM	
Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	15/10/19 17:20	General View	1	Load JPG	☒
2	15/10/19 17:20	General View	1	Load JPG	☒
3	15/10/19 17:20	General View	1	Load JPG	☒
4	15/10/19 17:20	General View	1	Load JPG	☒
5	15/10/19 17:20	General View	1	Load JPG	☒
6	15/10/19 17:20	General View	1	Load JPG	☒
7	15/10/19 17:20	General View	1	Load JPG	☒
8	15/10/19 17:20	General View	1	Load JPG	☒
9	15/10/19 17:20	General View	1	Load JPG	☒
10	15/10/19 17:20	General View	1	Load JPG	☒
11	15/10/19 17:20	General View	1	Load JPG	☒
12	15/10/19 17:20	General View	1	Load JPG	☒
13	15/10/19 17:20	General View	1	Load JPG	☒
14	15/10/19 17:20	General View	1	Load JPG	☒
15	15/10/19 17:20	Odometer Reading	1	Load JPG	☒
16	15/10/19 17:20	Chassis Number	1	Load JPG	☒
17	15/10/19 17:20	General View	1	Load JPG	☒
18	15/10/19 17:20	General View	1	Load JPG	☒
19	15/10/19 17:20	General View	1	Load JPG	☒
20	15/10/19 17:20	General View	1	Load JPG	☒
21	15/10/19 17:20	General View	1	Load JPG	☒
22	29/01/20 19:01	Reinspection Photo	1	Load JPG	☒
23	29/01/20 19:01	Reinspection Photo	1	Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	15/10/19 15:17	GIA REPORT	1	Load PDF	
2	15/10/19 15:18	Driving Licence	1	Load PDF	

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
3	15/10/19 15:19	Certificate of Insurance		Load PDF
4	15/10/19 15:19	ESTIMATE		Load PDF
5	21/10/19 08:59	SUPP		Load PDF
6	23/10/19 15:15	INV OPTI SHINE		Load PDF
7	19/03/20 16:41	DISCHARGE VOUCHER		Load PDF
8	19/03/20 16:41	WORKSHOP INVOICE		Load PDF

Linked Accident Report Documents

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	12/10/19 18:06	Video - Accident		Load MP4
2	12/10/19 18:06	Video - Accident		Load MP4
Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	06/12/19 18:53	Accident Statement		Load HTM
2	06/12/19 18:54	Accident Statement		Load HTM
3	06/12/19 18:54	Accident Statement		Load HTM
4	06/12/19 18:55	Accident Statement		Load HTM
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	12/10/19 18:01	Police Report		Load JPG
2	12/10/19 18:02	Police Report		Load JPG
3	12/10/19 18:02	Police Report		Load JPG
4	12/10/19 18:11	Accident Photo		Load JPG
5	12/10/19 18:11	Accident Photo		Load JPG
6	12/10/19 18:11	Accident Photo		Load JPG
7	12/10/19 18:11	Accident Photo		Load JPG
8	12/10/19 18:11	Accident Photo		Load JPG
9	12/10/19 18:11	Accident Photo		Load JPG
10	12/10/19 18:11	Accident Photo		Load JPG
11	12/10/19 18:11	Accident Photo		Load JPG
12	12/10/19 18:11	Accident Photo		Load JPG
13	12/10/19 18:11	Accident Photo		Load JPG
14	12/10/19 18:11	Accident Photo		Load JPG
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	12/10/19 18:01	Sketch Plan		Load JPG
2	12/10/19 18:01	Sketch Plan #2		Load JPG

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19018119/EYD3S2
Date: 19/03/2020

REFERENCE

Insured/Claimant: LOW KOK CHEONG ATTICUS Policy No: 1700069824
Date of Loss: 12/10/2019 Nature of Claim: OD Claim No: 0731916492SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLT3704K
Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A) Engine No: CVN045413
Reg. Date: 26/10/2017 (Man. Year: 2017) Chassis No: WAUZZZF41JA022951
Colour: Black Odometer: 42353 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$110,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm
Front Right Side: Pirelli 5 mm Rear Right Side: Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,735.00	1,988.56	5,746.44	74.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,322.00	1,572.00	2,750.00	63.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,057.00	3,560.56	8,496.44	70.47
+ GST 7.00/7.00% (S\$)	843.99	249.24	594.75	70.47
Nett Amount (S\$)	12,900.99	3,809.80	9,091.19	70.47

INSPECTION

Date of Assignment: 15/10/2019
Date Inspected: 15/10/2019 Inspected At: 281 Alexandra Road
Estimated Period of Repair: 3.0 days Repairer: Premium Automobiles Pte Ltd

Adjuster: CHEN TSUE YEE

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR - RH	Dented	2,152.00 FS	*1,721.60 FS
2	1		*FRONT DOOR OUTER SEAL - RH	Necessary	185.00 FS	*147.60 FS
3	1		*BONDING AGENT	Necessary	45.00 FS	*35.92 FS
4	1		*CLEANING SOLUTION	Necessary	65.00 FS	*52.00 FS
5	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	488.00 FS	*- FS
6	1		*FRONT DOOR CATCH	Not Necessary	96.00 FS	*- FS
7	1		*DOOR HANDLE TRIM PLATE - DRIVER DOOR	Not Necessary	80.00 FS	*- FS
8	1		*DOOR HANDLE SENSOR - RH	Not Necessary	208.00 FS	*- FS
9	1		*EXTERIOR DOOR HANDLE - RH	Not Necessary	35.00 FS	*- FS
10	1		*LOCK CYLINDER - DRIVER DOOR	Not Necessary	492.00 FS	*- FS
11	1		*DOOR MOUNTING BAR - DRIVER DOOR	Not Necessary	149.00 FS	*- FS
12	1		*WINDOW REGULATOR - RH	Not Necessary	250.00 FS	*- FS
13	1		*WINDOW REGULATOR MOTOR - RH	Not Necessary	278.00 FS	*- FS
14	2		*EXTERIOR MIRROR MOUNTING - RH	Not Necessary	824.00 FS	*- FS
15	1		*MIRROR CAP - RH	Not Necessary	220.00 FS	*- FS
16	1		*MIRROR GLASS - RH	Not Necessary	1,553.00 FS	*- FS
17	1		*WINDOW SLOT SEAL - RH	Not Necessary	280.00 FS	*- FS
18	1		*TYRE PRESSURE DATA PLATE	Necessary	35.00 FS	*27.36 FS
19	1		*SUNDRIES	Necessary	300.00 FS	*4.08 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	7,735.00	1,988.56
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER RHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	New	280.00	280.00
2	TO DISMANTLE RHS FRONT DOOR PANEL TRIM. TO REMOVE AND RENEW RHS WING MIRROR ASSY.	New	300.00	0.00
3	TO DISMANTLE AND RENEW RHS FRONT DOOR. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	1,050.00	500.00
4	TO RESPRAY RHS FRONT DOOR, RHS REAR DOOR, DOOR HANDLE AND RHS WING MIRROR COVER.	New	2,500.00	600.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
Gross Labour Cost (S\$)			4,322.00	1,572.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >