

ASS. REC. BY:

REF:

CS/7M319018126/KV8312

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Dillen Senthilan

of

TMI

Date/Time: 09 October 2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMP 448 D

Insured:

SKK 2450H

at Workshop m/s

Lim Tan Motor

Tel:

6452 0893

of BIK 176 Sin Ming Drive #03-09/10

Policy No: MH001443

Claim No: M1907906

Sum Insured:

Excess:

Make of Veh:

D.O.A. 25/09/2019

(Client's Record)

18/10/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

15.10.19

11.57A.M

Person Contacted:

Venus

Vehicle IN (OUT)

Date/Time

Action/Instruction (✓) Estimate

SKK 2450H : X

SMP 448D : X

21/10/19

Send preli revised via merimen

6/11

81675-20 Cabman (Red 1123.60, 409)

ASS. REC. BY:

REF: Tm1

ASSIGNMENT

From: _____ Date: 12.10.2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: smp 448D

at Workshop m/s- Lim Tan Motor

of BIK 176 SH Ming Drive #03-09

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: 9300m

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 1.3.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS smp

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: smp 448D

Yr Regn: 09 15

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda

c.c

1317

Colour: M. Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 3314

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GK3

3417217

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175 / 70 R 4

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 9 mm

R/Bal. 9 mm

L/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 23/9/19

D.O.I. 18/10/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or *.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 06 NOV 2019

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 6/11 - typist

Report Form: Mr. Men

Lump Sum / L.P. / 1675.20

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

250

11

261

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Tokio Marine Insurance Singapore Ltd
20 McCallum Street
#09-01 Tokio Marine Centre
Singapore 069046From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Dillen Senthilan so Selvarajoo

Date: 21 Oct 2019

Preliminary Advice

Insured Vehicle No	: SKK2450H	Accident Date	: 25/09/2019
TP Vehicle No	: SMP448D	Assignment Date	: 15/10/2019
Make	: HONDA FIT	Est. Duration of Repair	: 4
Date of Inspection	: 18/10/2019		
Inspection At	: LIM TAN MOTOR		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,798.80
Revised Amount	:S\$	1,675.20
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,675.20

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments : The above survey was conducted on a 'Without Prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Oct 2019		15 Oct 2019 11:29 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	PRIME CAR RENTAL & TAXI SERVICES PTE LTD, Co. Reg. No.: 199606293Z								
Main Claimant:	NEO JIA JIA, ID: S8408659B								
Vehicle Reg. No.:	SMP448D	Date of Loss:	25/09/2019 15:00 - :59						
Claim Type:	TP / M1907906	Policy/Cover Note No.:	MH001443 (TP, Fire & Theft) Coverage: 15/10/2018 - 14/10/2019						
Vehicle Reg. No. (Insured):	SKK2450H	Policy No. (Claimant):	5112228131						
		Excess:	S\$1,500.00						
Repairer:	Lim Tan Motor Pte Ltd (HQ) Blk 176 Sin Ming Drive #03-09/10, Sin Ming Auto Care, 575721 Sin Ming - Tel: 6452 0893								
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Dillen Senthilan so Selvarajoo]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 24/10/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 659B

Vehicle Details

Vehicle No.: SMP448D
Vehicle to be Exported: Yes
Intended Deregistration Date: 26 Sep 2019
Vehicle Make: HONDA
Vehicle Model: FIT 1.3GF CVT
Primary Colour: Silver
Manufacturing Year: 2019
Engine No.: L13B3931709
Chassis No.: GK33417217
Maximum Power Output: 73.0kW (97 bhp)
Open Market Value: \$16,017.00
Original Registration Date: 06 Sep 2019
First Registration Date: 06 Sep 2019
Transfer Count: 0
Actual ARF Paid: \$6,017.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 05 Sep 2029
PARF Rebate Amount: \$4,512.00

Intended COE Rebate Details

COE Expiry Date: 05 Sep 2029
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$27,000.00
COE Rebate Amount: \$21,600.00
Total Rebate Amount: \$26,112.00

The information contained herein is correct as at 26 Sep 2019

OK

ESTIMATE TO REPAIR

VEHICLE NO. : SMP448D
MAKE : HONDA
MODEL : FIT 1.3GF CVT
YEAR : 2019
CHASSIS NO : GK33417217

SURVEYOR NAME : LKK Iscaneth
DATE OF SURVEY :
TIME OF SURVEY : 18 OCT 2019

DATE : 1-Oct-19
DATE OF ACCIDENT : 25-Sep-19
THIRD PARTY REF : SKK2450H
THIRD PARTY REF : TOKIO MARINE INSURANCE SINGAPORE LTD

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	rear bumper				\$ 580.00
2 pcs	rear bumper retainer		\$ 13.50		\$ 27.00
10 pcs	rear bumper clips		\$ 3.50		\$ 35.00
1 pc	tail gate				\$ 814.00
1 pc	tail gate fit emblem				\$ 35.00
1 pc	rear windscreen moulding				\$ 120.00
					\$ 1,611.00
	less 20%				\$ 322.20
					\$ 1,288.80
1 tube	rear windscreen sealant	S.Nett			\$ 40.00
1 pc	rear number plate	S.Nett			\$ 40.00
	To putty & spray paint.				\$ 680.00
	To transfer tail gate fitting.				\$ 80.00
	To remove & refix rear windscreen glass.				\$ 120.00
	To anti-rust.				\$ 50.00
	Labour charges.				\$ 500.00
TG/VL	TOTAL				\$ 2,798.80

Not Authorized
Repairing BY PAIM
4 days

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Lim Tan Motor Pte Ltd
Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
Tel: 65-64520893 Fax: 65-64559127 Email: admund@lkm.sg
Co. Reg No. 199307277D GST Reg No. M2-0019085-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without prior written consent of Lim Tan Motor Pte Ltd

ESTIMATE TO REPAIR

VEHICLE NO. : SMP448D
MAKE : HONDA
MODEL : FIT 1.3GF CVT
YEAR : 2019
CHASSIS NO : GK33417217

SURVEYOR NAME : Lkk Kenneth
DATE OF SURVEY : 18 OCT 2019
TIME OF SURVEY :

DATE : 1-Oct-19
DATE OF ACCIDENT : 25-Sep-19
THIRD PARTY REF : SKK2450H
THIRD PARTY REF : TOKIO MARINE INSURANCE SINGAPORE LTD

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	rear bumper				\$ 580.00 X
2 pcs	rear bumper retainer		\$ 13.60		\$ 27.00 X
10 pcs	rear bumper clips		\$ 3.60		\$ 36.00 X
1 pc	tail gate				\$ 814.00 ✓
1 pc	tail gate fit emblem				\$ 35.00 ✓
1 pc	rear windscreen moulding				\$ 120.00 ✓
				969.00	\$ 1,611.00
				193.80	\$ 322.20
	less 20%				\$ 1,288.80
1 tube	rear windscreen sealant	S Nett		275.20	\$ 40.00 ✓
1 pc	rear number plate	S Nett		SN 40.00	\$ 40.00 X
	To putty & spray paint.			860.00	\$ 680.00 4001
	To transfer tail gate fitting.			1675.20	\$ 80.00 601
	To remove & refix rear windscreen glass.				\$ 120.00 ✓
	To anti-rust.				\$ 50.00 301
	Labour charges.				\$ 500.00 2501
TG/VL	TOTAL				\$ 2,798.80

Not Authorized
Return By Paint
4 days

APPROVED

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI19018126/KVF3N2

Date: 11/11/2019

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MH001443
Claimant Vehicle No :	SMP448D	Insured Vehicle No :	SKK2450H
Date of Loss:	25/09/2019	Nature of Claim:	TP
		Claim No:	M1907906

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP448D	Engine No:	L13B3931709
Make & Model:	HONDA FIT, 1.3 GF CVT (A)	Chassis No:	GK33417217
Reg. Date:	06/09/2019 (Man. Year: 2019)	Odometer:	3314 km
Colour:	Metallic Grey		
Engine Capacity:	1317 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,368.80	815.20	553.60	40.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,430.00	860.00	570.00	39.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,798.80	1,675.20	1,123.60	40.15
+ GST 7.00/7.00% (S\$)	195.92	117.26	78.66	40.15
Nett Amount (S\$)	2,994.72	1,792.46	1,202.26	40.15

INSPECTION

Date of Assignment: 15/10/2019

Date Inspected: 18/10/2019 Inspected At:

Lim Tan Motor Pte Ltd (HQ)
Blk 176 Sin Ming Drive #03-09/10, Sin
Ming Auto Care
Singapore 575721

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 11 Nov 2019)
Parts: 143	HONDA FIT 1.3 GF CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMP448D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	580.00 FL	*- FL
2	2		*REAR BUMPER RETAINER	Serviceable	27.00 FL	*- FL
3	10		*REAR BUMPER CLIPS	Not Necessary	35.00 FL	*- FL
4	1		*TAIL GATE	Bent	814.00 FL	*814.00 FL
5	1		*TAIL GATE FIT EMBLEM	Necessary	35.00 FL	*35.00 FL
6	1		*REAR WINDSCREEN MOULDING	Necessary	120.00 FL	*120.00 FL
7	1		*TUBE REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
8	1		*REAR NUMBER PLATE	Serviceable	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	1,691.00	1,009.00
- List Item Discount on L Items 20.00/20.00% (S\$)	322.20	193.80
Total Parts (S\$)	1,368.80	815.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PUTTY & SPRAY PAINT	New	680.00	400.00
2	TO TRANSFER TAIL GATE FITTING	New	80.00	60.00
3	TO REMOVE & REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
4	TO ANTI-RUST	New	50.00	30.00
5	LABOUR CHARGES	New	500.00	250.00
Gross Labour Cost (\$\$)			1,430.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >