

ASS. REC. BY:

Assigner: Kenneth

REP: C8/EGI 19018130/Kyd3

Special Instruction:

Meimer

ASSIGNMENT (Office)

From (Person): Pauline soh

of EGI

Date/Time: 15/10/19 @ 11:11am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKW 5334C

Insured:

XE 844X

at Workshop in:

Tong Luek

Tel:

6250 0088

of

160 Sin Ming Drive # 07-01 / 06

Policy No:

Claim No:

CDMFG19001908

Sum Insured:

Excess:

Make of Veh:

D.O.A.

10/10/2001

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 12:15pm 15/10/19

Person Contacted:

Candy

Vehicle IN/OUT

Date/Time

Action/Instruction

Island /

SKW 5334C-X

XE 844X-X

18/10

Seat Preli via Meimer

Hidden
Photo O.K

ASS. REC. BY:

REF:

2112/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4-5 days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKW5334C

Yr Regn:

11, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

M. C180

c.c.

1595

Colour:

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading:

48066

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WDD2050402R110165

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NII / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

225/50R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

10/10/19

D.O.I.

15/10/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

File pass to

24/12

PIP \$9174-70 (Red \$4461-90, 32%)

RECEIVED 17 JAN 2020

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

17/1/20 Typist

Report Format:

Lump Sum / I.B.I. (\$) :

PIP \$9174-70

Days Of Repair:

5

Resurvey No. of Trip:

3

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

350
11

361

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 18 Oct 2019

Preliminary Advice

Insured Vehicle No	: XE844X	Accident Date	: 11/10/2019
TP Vehicle No	: SKW5334C	Assignment Date	: 15/10/2019
Make	: TOYOTA COROLLA ALTIS	Est. Duration of Repair	: 5.00
Date of Inspection	: 15/10/2019		
Inspection At	: TONG LUCK AUTO PTE LTD (HQ) 160 SIN MING DRIVE, #07-01 SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,466.63
Revised Amount	:S\$	5,008.90
Check Items (Estimated)	:S\$	3,973.00
Total	:S\$	8,981.90

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :The above survey was conducted on a without "prejudice" basis

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	18 Oct 2019 17:54 Edit Reg		15 Oct 2019 00:00 Edit Adj Rpt		Last:IA 18 Oct 2019 18:04		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]
Insured:	QI FENGYONG, ID: 0 72649419	
Main Claimant:	-	
Vehicle Reg. No.:	SKW5334C	Date of Loss: 11/10/2019 00:00 - :59 [47 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:
Vehicle Reg. No. (Insured):	XE844X	Policy No. (Claimant):
		Excess:
Repairer:	Tong Luck Auto Pte Ltd (HQ) 160 Sin Ming Drive, #07-01 Sin Ming AutoCity, 575722 Sin Ming - Tel: 6250 0088	
Handling Insurer:	ERGO Insurance Pte. Ltd. (HQ) - Tel: 6829 9199	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 24/10/2019]	

ASSOCIATED MAIL RECEIVED	View All Compose Case Mail
There are no mail for this case.	

ALL ASSOCIATED TASKS	View All Search Tasks Create New Task Complete
Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?	
No results.	

Nivitha (LKK Auto)

From: ERGO Insurance Pte. Ltd. (Claims Department) <claims@ergo.com.sg>
Sent: Tuesday, 15 October 2019 11:11 AM
To: Operation / Yu Ching; Admin-D (LKKAuto (admin-d@lkkauto.com); Admin A (admin-a@lkkauto.com); Mei Kwan (LKKAuto (Meikwan@lkkauto.com)
Cc: Ivy Yong; Phoebe Xie
Subject: RE: Claims ref no. (P) CDMFG19001908 ACCIDENT INVOLVING VEHICLE NO.: SKW5334C & XE844X ON 11/10/2019 ALONG WOODLANDS AVE 12 TOWARDS BKE

Hi LKK,

Please conduct this survey request.

(Note: Survey vehicle only)

Kindly inform us if you are not able to attend it.

***** NOTE:** Please assist to quote our claims ref no. as the subject matter, when forwarding the Preliminary Reports / Survey Reports.

Thank you.

Date Classification : Confidential, C3

Warmest Regards,
Pauline Soh
ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-05 Suntec Tower Five
Singapore 038985
DID: +65 6829 9194
pauline.soh@ergo.com.sg

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

From: Operation / Yu Ching [mailto:operation@lkkauto.com.sg]
Sent: Monday, October 14, 2019 11:02 AM
To: ERGO Insurance Pte. Ltd. (Claims Department); Pauline Soh
Cc: Ivy Yong; Phoebe Xie
Subject: RE: Claims ref no. (P) CDMFG19001908 ACCIDENT INVOLVING VEHICLE NO.: SKW5334C & XE844X ON 11/10/2019 ALONG WOODLANDS AVE 12 TOWARDS BKE

Dear Pauline,

We hereby confirm and agreed to nominate LKK Auto Consultants Pte Ltd to conduct the joint pre-repair surveyor as a Single Joint Expert

Thanks & regards,
Yu Ching



Tong Luck Auto Pte Ltd

160 Sin Ming Drive
#07-01/06 Sin Ming Autocity
Singapore 575722
Tel: 6250 0088 Fax: 6250 5545
Email: operation@tlauto.com.sg

From: ERGO Insurance Pte. Ltd. (Claims Department) <claims@ergo.com.sg>

Sent: Monday, 14 October, 2019 9:57 AM

To: operation@tlauto.com.sg; Pauline Soh <pauline.soh@ergo.com.sg>

Cc: Ivy Yong <ivy.yong@ergo.com.sg>; Phoebe Xie <phoebe.xie@ergo.com.sg>

Subject: FW: Claims ref no. (P) CDMFG19001908 ACCIDENT INVOLVING VEHICLE NO.: SKW5334C & XE844X ON 11/10/2019 ALONG WOODLANDS AVE 12 TOWARDS BKE

Dear Candy,

Please refer to our list of surveyors :

1	AIS	Automobile Inspection Services Pte Ltd
2	FTA	FormTeam Consultancy Pte Ltd
3	IAS	Infiniti Appraisal Service
4	JPK	JP Knights Pte Ltd
5	LBS	L.B.S Auto Consultants Pte Ltd
6	LKK	LKK Auto Consultants Pte Ltd
7	PS	Priority Services
8	VAC	Vicom Ltd
9	AJAX	AJAX Inspection Services Pte Ltd
10	QRM	Quantum Risk Management (S) Pte Ltd
11	AA	Appraisal Associate

Date Classification : Confidential, C3

Warmest Regards,
Pauline Soh
ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-05 Suntec Tower Five
Singapore 038985
DID: +65 6829 9194
pauline.sohi@ergo.com.sg

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd will not be liable for any loss or damage thereby caused.

From: Operation / Candy Ong [<mailto:operation@tlauto.com.sg>]
Sent: Friday, October 11, 2019 4:29 PM
To: ERGO Insurance Pte. Ltd. (Claims Department)
Subject: RE: ACCIDENT INVOLVING VEHICLE NO.: SKW5334C & XE844X ON 11/10/2019 ALONG WOODLANDS AVE 12 TOWARDS BKE

Dear All,

We have our client's instruction to notify you the above accident

Please find attached documents for your information and necessary action

The vehicle is now garage at our workshop

Kindly let us have your surveyor list and arrange for the PRI survey of our client's vehicle at an earlier date

Best Regards,
Candy Ong
Tong Luck Auto Pte Ltd

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	778Z
Vehicle Details	
Vehicle No.:	SKW5334C
Vehicle to be Exported:	Yes
Intended Deregistration Date:	18 Oct 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C180 AVANTGARDE (R17 LED)
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	27491030452169
Chassis No.:	WDD2050402R110165
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$35,294.00
Original Registration Date:	03 Nov 2015
First Registration Date:	03 Nov 2015
Transfer Count:	0
Actual ARF Paid:	\$36,412.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Nov 2025
PARF Rebate Amount:	\$27,309.00
Intended COE Rebate Details	
COE Expiry Date:	02 Nov 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$60,789.00
COE Rebate Amount:	\$36,719.00
Total Rebate Amount:	\$64,028.00

The information contained herein is correct as at 18 Oct 2019

OK



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : XE844X

CLAIM TYPE : THIRD PARTY

TP INS. CO. : ERGO INSURANCE PTE LTD

ACCIDENT DATE : 11/10/2019

TP VEH REG NO : XE844X

ESTIMATE

NO : QUOT201910-000029(00)

DATE : 11/10/2019

POLICY NO : 999995580

VEH REG NO : SKW5334C

MAKE/MODEL : MERCEDES BENZ C180
AVANTGARDE (R17 LED)

CHASSIS NO : WDD2050402R110165

ENGINE NO : 27491030452169

REG. DATE : 2015

15/10/19

Not Notified
Primary B4pain

5 days

\$ 9174.70

Estimate Repair Cost to Vehicle No : SKW5334C

Description	Quantity	Unit Price	Amount
		SS	SS

NET PRICE

1 Bootlid	1	2,155.00	2,155.00	✓
2 Bootlid weatherstrip	1	205.00	205.00	✗
3 Bootlid centre logo	1	49.00	49.00	—
4 Bootlid 'C180' emblem	1	92.00	92.00	—
5 Bootlid 'C & C' emblem	1	38.00	38.00	—
6 Bootlid trimboard clips	10	10.00	100.00	—
7 Rear end panel	1	1,433.00	1,433.00	✗ R
8 Rear bumper	1	1,656.00	1,656.00	✓
9 Rear bumper reinforcement	1	660.00	660.00	✓
10 Rear bumper inner frame	1	120.00	120.00	✗
11 Rear bumper sensors	4	185.00	752.00	✗
12 Rear bumper sensor seals	6	12.00	72.00	—
13 Rear bumper clips	15	9.00	135.00	—
14 Rear bumper lower spoiler	1	222.00	222.00	✓
15 Rear bumper lower chrome	1	260.00	260.00	✓
16 Rear bumper towing cover	1	52.00	52.00	—
17 Rear bumper lower spoiler clips	10	9.00	90.00	—
			8,091.00	
		Less 10%	809.10	
			7,281.90	

LABOUR

18 To remove and refix rear bumper sensor, reset all faulty code	1	100.00	100.00	601
19 To check and rectify wiring system	1	80.00	80.00	201
20 To panel beat and straighten rear floorboard panel, rear chassis frame, to cut and weld rear end panel including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00	5001
21 To putty and spray same on affected areas	1	1,200.00	1,200.00	5001
22 To apply rust proofing on repaired and replaced panels	1	120.00	120.00	7603
			2,500.00	

TOTAL SS 9,781.90

ADD GST @ 7% 684.73

GRAND TOTAL SS 10,466.63

SINGAPORE DOLLAR TEN THOUSAND FOUR HUNDRED SIXTY-SIX AND CENTS SIXTY-THREE ONLY



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : XE844X

CLAIM TYPE : THIRD PARTY

TP INS. CO. : ERGO INSURANCE PTE LTD

ACCIDENT DATE : 11/10/2019

TP VEH REG NO : XE844X

ESTIMATE

NO : QUOT201910-000029(00)

DATE : 11/10/2019

POLICY NO : 999995580

VEH REG NO : SKW5334C

MAKE/MODEL : MERCEDES BENZ C180
AVANTGARDE (R17 LED)

CHASSIS NO : WDD2050402R110165

ENGINE NO : 27491030452169

REG. DATE : 2015

*Not Notified
Repair B4 pain*

4-5 days

Estimate Repair Cost to Vehicle No : SKW5334C

Description	Quantity	Unit Price	Amount
		<u>S\$</u>	<u>S\$</u>
NET PRICE			
1 Bootlid	1	<i>As</i> 2,155.00	2,155.00 ✓
2 Bootlid weatherstrip	1	205.00	205.00 7X
3 Bootlid centre logo	1	49.00 <i>As</i>	49.00 —
4 Bootlid 'C180' emblem	1	92.00 <i>As</i>	92.00 —
5 Bootlid 'C & C' emblem	1	38.00 <i>As</i>	38.00 —
6 Bootlid trimboard clips	10	10.00 <i>As</i>	100.00 —
7 Rear end panel	1	1,433.00	1,433.00 7R
8 Rear bumper	1	<i>As</i> 1,656.00	1,656.00 ✓
9 Rear bumper reinforcement	1	660.00	660.00 7✓
10 Rear bumper inner frame	1	120.00	120.00 7X
11 Rear bumper sensors	4	188.00	752.00 7X
12 Rear bumper sensor seals	6	12.00 <i>As</i>	72.00 —
13 Rear bumper clips	15	9.00 <i>As</i>	135.00 —
14 Rear bumper lower spoiler	1	222.00 <i>As</i>	222.00 ✓
15 Rear bumper lower chrome	1	<i>Sub As</i> 260.00	260.00 ✓
16 Rear bumper towing cover	1	52.00 <i>As</i>	52.00 —
17 Rear bumper lower spoiler clips	10	9.00 <i>As</i>	90.00 —
			8,091.00
			Less 10%
			809.10
			7,281.90
LABOUR			
18 To remove and refix rear bumper sensor, reset all faulty code	1	100.00	100.00 601
19 To check and rectify wiring system	1	80.00	80.00 201
20 To panel beat and straighten rear floorboard panel, rear chassis frame, to cut and weld rear end panel including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00 796
21 To putty and spray same on affected areas	1	1,200.00	1,200.00 5001
22 To apply rust proofing on repaired and replaced panels	1	120.00	120.00 796
			2,500.00
TOTAL			S\$ 9,781.90
ADD GST @ 7%			684.73
GRAND TOTAL			S\$ 10,466.63

SINGAPORE DOLLAR TEN THOUSAND FOUR HUNDRED SIXTY-SIX AND CENTS SIXTY-THREE ONLY



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : XE844X

CLAIM TYPE : THIRD PARTY

TP INS. CO. : ERGO INSURANCE PTE LTD

ACCIDENT DATE : 11/10/2019

TP VEH REG NO : XE844X

ESTIMATE

NO : QUOT201910-000029(00)

DATE : 11/10/2019

POLICY NO : 999995580

VEH REG NO : SKW5334C

MAKE/MODEL : MERCEDES BENZ C180
AVANTGARDE (R17 LED)

CHASSIS NO : WDD2050402R110165

ENGINE NO : 27491030452169

REG. DATE : 2015

Estimate Repair Cost to Vehicle No : SKW5334C

Description	Quantity	Unit Price	Amount
		S\$	S\$
SUPPLEMENTARY			
NET PRICE			
1 Front safety belt - RH	1	698.00 <i>Tm</i>	698.00 ✓
2 Rear safety belt - RH / LH	2	420.00 <i>Tm</i>	840.00 ✓
3 Air bag control unit	1	945.00 <i>M</i>	945.00 ✓
			2,483.00
		Less 10%	248.30
			2,234.70
LABOUR			
4 To transfer damaged bootlid interior mechanism to new bootlid	1	80.00	80.00 <i>601</i>
5 To remove and refit front & rear safety belt and air bag control unit	1	680.00	680.00 <i>2501</i>
6 To dismantle and refit console box to enable to replace airbag control unit	1	280.00	280.00 <i>1201</i>
7 To reprogram air bag control module and reset fault code	1	580.00	580.00 <i>4501</i>
			1,620.00
TOTAL			S\$ 3,854.70
ADD GST @ 7%			269.83
GRAND TOTAL			S\$ 4,124.53

SINGAPORE DOLLAR FOUR THOUSAND ONE HUNDRED TWENTY-FOUR AND CENTS FIFTY-THREE ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE

AutoSoon Pte Ltd

176 Sin Ming Drive #01-10
Sin Ming Autocare Singapore 575721
Tel No. 6452 6657 Fax No. 6451 4618
Email : autosoon1@gmail.com
UEN: 200709808N GST Reg No: 200709808N

Tax Invoice No: AS 851341
PO Number:
Date: NOVEMBER 11, 2019
Car Plate No: SKW 5334 C
Mercedes Benz C180
Chassis:
Remark: Notes
Mileage: 48062

TONG LUCK AUTO PTE LTD
160 SIN MING DRIVE #07-01 SIN MING AUTOCITY SINGAPORE 575722
PHONE: 6250 0088 FAX: 6250 5545

S.No	Quantity	Particular	Unit Price	Amount (SGD)
1	1	LABOUR To Reprogram CPAC Control Module Assy and reset Airbag fault code	450.00	450.00
2	1	Labour to troubleshoot wiring harness and rewiring Rear Parking Sensor Assy		

Sub Total	450.00
GST 7%	31.50
Total	481.50
Paid Amount	0.00
Total Due	481.50

Terms of Payment: Cash

Customer's Signature/Co. Stamp

I/We agree to pay all work and parts required for the repairs described above at your retail charge. All goods shall remain the property of the seller until paid for in full. I have read and accept your terms and conditions.

For AutoSoon Pte Ltd





TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118 FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : XE844X

CLAIM TYPE : THIRD PARTY

TP INS. CO. : ERGO INSURANCE PTE LTD

ACCIDENT DATE : 11/10/2019

TP VEH REG NO : XE844X

ESTIMATE

NO : QUOT201910-000029(00)

DATE : 11/10/2019

POLICY NO : 999995580

VEH REG NO : **SKW5334C**

MAKE/MODEL : MERCEDES BENZ C180
AVANTGARDE (R17 LED)

CHASSIS NO : WDD2050402R110165

ENGINE NO : 27491030452169

REG. DATE : 2015

Estimate Repair Cost to Vehicle No : SKW5334C

Description	Quantity	Unit Price	Amount
		S\$	S\$

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI19018130/KYD3N2
Date: 20/01/2020

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:
Claimant Vehicle No : SKW5334C **Insured Vehicle No :** XE844X
Date of Loss: 10/10/2019 **Nature of Claim:** TP **Claim No:** CDMFG19001908

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKW5334C**
 Make & Model: MERCEDES-BENZ C180, 1.6 Avantgarde (R17 LED) (A) Engine No: 27491030452169
 Reg. Date: 03/11/2015 (Man. Year: 2015) Chassis No: WDD2050402R110165
 Colour: Metallic Grey Odometer: 48060 km
 Engine Capacity: 1595 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50R17 Rear Tyre Size: 225/50R17
 Front Left Side: Pirelli 9 mm Rear Left Side: Pirelli 9 mm
 Front Right Side: Pirelli 9 mm Rear Right Side: Pirelli 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,516.60	7,184.70	2,331.90	24.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,120.00	1,990.00	2,130.00	51.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,636.60	9,174.70	4,461.90	32.72
+ GST 7.00/7.00% (S\$)	954.56	642.23	312.33	32.72
Nett Amount (S\$)	14,591.16	9,816.93	4,774.23	32.72

INSPECTION

Date of Assignment: 15/10/2019
 Date Inspected: 15/10/2019 Inspected At: Tong Luck Auto Pte Ltd (HQ)
 160 Sin Ming Drive, #07-01 Sin Ming AutoCity
 Singapore 575722
 Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Jan 2020)

Parts: 143 MERCEDES-BENZ C180 1.6 Avantgarde (R17 LED) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKW5334C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	2,155.00 FN	*2,155.00 FN
2	1		*BOOTLID WEATHERSTRIP	Serviceable	205.00 FN	*- FN
3	1		*BOOTLID CENTRE LOGO	Necessary	49.00 FN	*49.00 FN
4	1		*BOOTLID C180 EMBLEM	Necessary	92.00 FN	*92.00 FN
5	1		*BOOTLID C&C EMBLEM	Necessary	38.00 FN	*38.00 FN
6	10		*BOOTLID TRIMBOARD CLIPS	Necessary	100.00 FN	*100.00 FN
7	1		*REAR END PANEL	Repair	1,433.00 FN	*- FN
8	1		*REAR BUMPER	Buckled	1,656.00 FN	*1,590.00 FN
9	1		*REAR BUMPER REINFORCEMENT	Bent	660.00 FN	*645.00 FN
10	1		*REAR BUMPER INNER FRAME	Serviceable	120.00 FN	*- FN
11	4		*REAR BUMPER SENSORS	Serviceable	752.00 FN	*- FN
12	6		*REAR BUMPER SENSOR SEALS	Necessary	72.00 FN	*72.00 FN
13	15		*REAR BUMPER CLIPS	Necessary	135.00 FN	*135.00 FN
14	1		*REAR BUMPER LOWER SPOILER	Dented	222.00 FN	*222.00 FN
15	1		*REAR BUMPER LOWER CHROME	Scratched/Dented	260.00 FN	*260.00 FN
16	1		*REAR BUMPER TOWING COVER	Dented	52.00 FN	*52.00 FN
17	10		*REAR BUMPER LOWER SPOILER CLIPS	Necessary	90.00 FN	*90.00 FN
18	1		*FRONT SAFETY BELT-RH	Jammed	698.00 FN	*698.00 FN
19	2		*REAR SAFETY BELT-RH/LH	Jammed	840.00 FN	*840.00 FN
20	1		*AIR BAG CONTROL UNIT	Necessary	945.00 FN	*945.00 FN

F=Franchise part. N=NettItemDisc.

Sub Total (S\$)	10,574.00	7,983.00
- Nett Item Discount on N Items 10.00/10.00% (S\$)	1,057.40	798.30
Total Parts (S\$)	9,516.60	7,184.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIX REAR BUMPER SENSOR,RESET ALL FAULTY CODE	New	100.00	60.00
2	TO CHECK AND RECTIFY WIRING SYSTEM	New	80.00	20.00
3	TO PANEL BEAT AND STRAIGHTEN REAR FLOORBOARD PANEL,REAR CHASSIS FRAME,TO CUT AND WELD REAR END PANEL INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY,TO REFIT AND ADJUST THE SAME	New	1,000.00	500.00
4	TO PUTTY AND SPRAY SAME ON AFFECTED AREAS	New	1,200.00	500.00
5	TO APPLY RUST PROOFING ON REPAIRED AND REPLACED PANELS	New	120.00	30.00
6	TO TRANSFER DAMAGED BOOTLID INTERIOR MECHANISM TO NEW BOOTLID	New	80.00	60.00
7	TO REMOVE AND REFIT FRONT & REAR SAFETY BELT AND AIR BAG CONTROL UNIT	New	680.00	250.00
8	TO DISMANTLE AND REFIT CONSOLE BOX TO ENABLE TO REPLACE AIRBAG CONTROL UNIT	New	280.00	120.00
9	TO REPROGRAM AIR BAG CONTROL MODULE AND RESET FAULT CODE	New	580.00	450.00
Gross Labour Cost (S\$)			4,120.00	1,990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >