

VOLKSWAGEN CENTRE SINGAPORE

17 Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation Non binding - Preview

Page 1/2

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Mr
TEO
WEE KWAN, EDWARD
14 UPPER BOON KENG ROAD
#17-959
Singapore 380014

Document no.
Document date 14-10-2019
Customer no. 5211043795
Customer GST-ID 201009404M
Dealer 39999
Job order number 2019002328/ 1
Job order date 14-10-2019
Service Advisor EDMUND, HUI HUANG GOH

License plate	Model code	First registration	VIN	Model	Mileage
SGT301T	5G13HZ	14-10-2016	VWVZZZAUZH055322	Golf 1.4 CLBM 92 TSI D7F	2,121

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Diagnostic and Programming	1	pcs.	480 360.00 ✓	#1	360.00	385.20
	Check Short Circuit / Harness Repair	1	pcs.	200 200.00 ✓	#1	200.00	214.00
5G6807417APGRU	Cover For Bumper Primed	1	pcs.	1,080.14 ✓	#1	1,080.14	1,155.75
5G0998492 GRU	1 Set Sensor Brackets Pri	1	pcs.	19.87 ✓	#1	19.87	21.26
5G0919491	Sensor Bracket	2	pcs.	13.21 ✓	#1	26.42	28.27
5G0919491A	Sensor Bracket	1	pcs.	13.21 ✓	#1	13.21	14.13
5G0919492A	Sensor Bracket	1	pcs.	13.21 ✓	#1	13.21	14.13
D 822150A1	Bonding Agent For Plastic	1	pcs.	56.90 ✓	#1	56.90	60.88
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	74.29 ✓	#1	74.29	79.49
5G0807305D	Bumper	1	pcs.	572.31 ?	#1	572.31	612.37
	(REINFORCEMENT)						
5G6807393	Guide Piece	1	pcs.	34.51 X	#1	34.51	36.93
	(BUMPER BRACKET LHS)						
5G6807394	Guide Piece	1	pcs.	34.51 ?	#1	34.51	36.93
	(BUMPER BRACKET RHS)						
5G6807394A	Guide Piece	1	pcs.	34.51 X	#1	34.51	36.93
	(BUMPER RETAINER LHS)						
5Q0919275B GRU	Sensor Primed	1	pcs.	164.62 m/s ✓	#1	329.24	352.29
5G0853675BA2ZZ	Inscription Bright Chrome	1	pcs.	58.66 ✓	#1	58.66	62.77
5G0853687 2ZZ	Inscription Bright Chrome	1	pcs.	66.63 ✓	#1	66.63	71.29
	(GOLF)						
5G0945096M	Taillight	1	pcs.	276.08 X	#1	276.08	295.41
	(RIGHT OUTER)						
5G0945094AD	Taillight With Rear Fog L	1	pcs.	252.43 X	#1	252.43	270.10
	(RIGHT INNER)						
	LABOUR	1.5	hrs	840.00 1260 ✓	#1	3,360.00	3,595.20
	Spray Painting	2	hrs	800.00 1600 ✓	#1	3,200.00	3,424.00

Quotation valid till 21-10-2019

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	560.00	9,502.92	7%	704.40	10,062.92	10,767.32
Total	560.00	9,502.92		704.40	10,062.92	10,767.32

Customer

Service Advisor

VOLKSWAGEN CENTRE SINGAPORE

17 Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 2/2

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Mr
TEO
WEE KWAN, EDWARD
14 UPPER BOON KENG ROAD
#17-959
Singapore 380014

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor
14-10-2019
5211043795
201009404M
39999
2019002328/ 1
14-10-2019
EDMUND, HUI HUANG
GOH

License plate	Model code	First registration	VIN	Model	Mileage
SGT301T	5G13HZ	14-10-2016	WVWZZZAUZH055322	Golf 1.4 CLBM 92 TSI D7F	2,121

-----VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).-----

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanpin 97495744
up'
17/10/19 e Han
Resurvey before paint
04 days
sure/Markus.w