



MELB (WINNER): 7/11/19

* SCENE VIDEO *

Letter of Claims Request for direct settlement.

97373292

We are submitting a claim on behalf of our customer TEO WEE KWAN, EDWARD
NRIC 57234151A insured of vehicle SGT 301T against
your insured vehicle number SKR 2162 C (ALG)
On the accident dated on 11-10-19 (ddmmYYYY) along TURNING OFF
TELOK BLANGAH RD TO HARBOURFRONT AVE.

Dated this 14 OCT 2019 (day) of _____ (month) 2019 .

Charmaine Kong
Volkswagen Group Singapore
Accident Claims Dept.
charmaine.kong@vw.com.sg
DID : 63057176/ 63057299
HP: 92361399

VOLKSWAGEN CENTRE SINGAPORE

17 Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

1/2

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Mr
TEO
WEE KWAN, EDWARD
14 UPPER BOON KENG ROAD
#17-959
Singapore 380014

Document no.
Document date 14-10-2019
Customer no. 5211043795
Customer GST-ID 201009404M
Dealer 39999
Job order number 2019002328/ 1
Job order date 14-10-2019
Service Advisor EDMUND, HUI HUANG
GOH

License plate	Model code	First registration	VIN	Model	Mileage
SGT301T	5G13HZ	14-10-2016	WVWZZZAUZH055322	Golf 1.4 CLBM 92 TSI D7F	2,121

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Diagnostic and Programming	1	pcs.	360.00	#1	360.00	385.20
	Check Short Circuit / Harness Repair	1	pcs.	200.00	#1	200.00	214.00
5G6807417APGRU	Cover For Bumper Primed	1	pcs.	1,080.14	#1	1,080.14	1,155.75
5G0998492 GRU	1 Set Sensor Brackets Pri	1	pcs.	19.87	#1	19.87	21.26
5G0919491	Sensor Bracket	2	pcs.	13.21	#1	26.42	28.27
5G0919491A	Sensor Bracket	1	pcs.	13.21	#1	13.21	14.13
5G0919492A	Sensor Bracket	1	pcs.	13.21	#1	13.21	14.13
D 822150A1	Bonding Agent For Plastic	1	pcs.	56.90	#1	56.90	60.88
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	74.29	#1	74.29	79.49
5G0807305D	Bumper	1	pcs.	572.31	#1	572.31	612.37
	(REINFORCEMENT)						
5G6807393	Guide Piece	1	pcs.	34.51	#1	34.51	36.93
	(BUMPER BRACKET LHS)						
5G6807394	Guide Piece	1	pcs.	34.51	#1	34.51	36.93
	(BUMPER BRACKET RHS)						
5G6807394A	Guide Piece	1	pcs.	34.51	#1	34.51	36.93
	(BUMPER RETAINER LHS)						
5Q0919275B GRU	Sensor Primed	2	pcs.	164.62	#1	329.24	352.29
5G0853675BA2ZZ	Inscription Bright Chrome	1	pcs.	58.66	#1	58.66	62.77
5G0853687 2ZZ	Inscription Bright Chrome (GOLF)	1	pcs.	66.63	#1	66.63	71.29
5G0945096M	Taillight	1	pcs.	276.08	#1	276.08	295.41
	(RIGHT OUTER)						
5G0945094AD	Taillight With Rear Fog L	1	pcs.	252.43	#1	252.43	270.10
	(RIGHT INNER)						
	LABOUR	4	pcs.	840.00	#1	3,360.00	3,595.20
	Spray Painting	4	pcs.	800.00	#1	3,200.00	3,424.00

Quotation valid till 21-10-2019

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	560.00	9,502.92	7%	704.40	10,062.92	10,767.32
Total	560.00	9,502.92		704.40	10,062.92	10,767.32

Customer

Service Advisor

VOLKSWAGEN CENTRE SINGAPORE

17 Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page	2/2
Document no.	
Document date	14-10-2019
Customer no.	5211043795
Customer GST-ID	201009404M
Dealer	39999
Job order number	2019002328/ 1
Job order date	14-10-2019
Service Advisor	EDMUND, HUI HUANG GOH

Company	Customer Details:
AIG ASIA PACIFIC INSURANCE P/L	Mr
78 Shenton Way	TEO
#07-16 AIG Building	WEE KWAN, EDWARD
Singapore 079120	14 UPPER BOON KENG ROAD
	#17-959
	Singapore 380014

License plate	Model code	First registration	VIN	Model	Mileage
SGT301T	5G13HZ	14-10-2016	WVWZZZAUZHW055322	Golf 1.4 CLBM 92 TSI D7F	2,121

-----VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).-----
