

ASS. REC. BY:

REF: CS/FCI 19018138/K9F3A2

Special Instruction:

Surveyor: KendallASSIGNMENT (Office)From (Person): Sithora

of

FCIDate/Time: 15.10.19 1.01 p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLM 422E

Insured:

SHC 7382R

at Workshop m/s

Poon Sang Snow

Tel:

96169634

of

Blk 160 sm ming Driv #05-13

Policy No:

Claim No:

D19 006572 MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 12.10.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

15.10.19 1.15 p.m

Person Contacted:

AlbertVehicle IN/OUT

Date/Time	Action/Instruction (<input checked="" type="checkbox"/>) Estimate
	<u>SLM 422E - X</u>
	<u>SHC 7382R - NS/INC 18022977/19622 ROA - 20/12/2018</u>
<u>16/10/19 @ 3.20 p.m</u>	<u>revised to Sithora by email.</u>
<u>21/10</u>	<u>Cl Lys @ 370d email & confirmed (Red \$ 10475.70, 74%)</u>

ASS. REC. BY:

REF: 1-021

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 896k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SIM 4228 Yr Regn: 07, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Harrier c.c. 1986

Colour: M.P. White A/C: Insured / Std / NI / NA

Sp. Reading: 58775 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 25460 - 0076738

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: 235/55R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 2 mm

L/Bal. 2 mm

D.O.A. 12/10/19

Rear

R/Bal. 3 mm

L/Bal. 3 mm

D.O.I. 15/10/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 / File pass to

RECEIVED 22 OCT 2019

Date/Time, File Pass to?

☐

: Prel. Report

1) 20/10 11:15

☐

: Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 5

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S - RS. SI

Parking

Others

TOTAL

4x15 = 60

170 + 60

50

50 + 50

20

400

Report Format :

Lump Sum / I.B.A. (\$) 3700



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19006572MESH

Date: 16 October 2019

Our Ref: CS/FCI19018138/Kqf3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLM 422E

Please be informed that we had conducted the inspection of the abovementioned vehicle on 15/10/2019 at the premises of M/s POON SIANG SEOW and have the following to report:-

Workshop Estimate Amount	: S\$ 14,175.70 .
Revised Estimate Amount	: S\$ 4,565.43 .
"Check" Items Amount	: S\$ 989.93 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages
at the rear o/s portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	14-10-2019	Our Ref No. D19006572MFSH
Accident Date	12-10-2019	Claim Type. Third Party
Insured Vehicle	SHC7382R	Third Party Vehicle. SLM422E
Survey Location	BLK 160 SIN MING DRIVE #05-13	
Contact Person.	ALBERT	
Contact No.	64537511/ 96169634	Fax No. 0
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	POON SIANG SEOW	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 16 October 2019 3:20 PM
To: 'CWS Motor Claims'; SUR
Cc: 'Sithara'
Subject: RE: SURVEY ASSESSMENT - D19006572MFSH/1
Attachments: CSFCI19018138Kqf3.pdf

Dear Sithara,

Enclosed herewith preliminary advice of SLM 422E.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Tuesday, 15 October 2019 1:17 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19006572MFSH/1

Dear Sir/Madam,

Thank you for your assignment.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Sent: Tuesday, 15 October, 2019 1:01 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19006572MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 077H

Vehicle Details

Vehicle No.: SLM422E
Vehicle to be Exported: Yes
Intended Deregistration Date: 15 Oct 2019
Vehicle Make: TOYOTA
Vehicle Model: HARRIER PREMIUM 2.0 A
Primary Colour: White
Manufacturing Year: 2016
Engine No.: 3ZRB771558
Chassis No.: Z5U600076738
Maximum Power Output: 111.0 kW (148 bhp)
Open Market Value: \$31,188.00
Original Registration Date: 21 Jul 2016
First Registration Date: 21 Jul 2016
Transfer Count: 0
Actual ARF Paid: \$30,664.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 20 Jul 2026
PARF Rebate Amount: \$22,998.00

Intended COE Rebate Details

COE Expiry Date: 20 Jul 2026
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$38,610.00
COE Rebate Amount: \$26,113.00
Total Rebate Amount: \$49,111.00

The information contained herein is correct as at 14 Oct 2019

OK

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate No S119V07798 /VPZ /R03

Form MZ406C

Date of Issue: 20-Jun-2019

1. Index Mark and Registration No. of Vehicle: SLM422E

2. Chassis number of Vehicle: ZSL6000076738

3. Name of Policyholder: EVERGREEN RENT A CAR PTE. LTD.

4. Effective date of Commencement of Insurance for the purpose of the Act: 21-JUL-2019 00:00

5. Date of Expiry of Insurance: 20-JUL-2020 23:59

6. Persons or Classes of Persons entitled to drive*:

Any person who is driving on the Policyholder's order or with their permission or to whom the vehicle is hired.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

7. Limitations as to use*:

- A) Use for carriage of passengers or goods in connection with the Policyholder's business.
- B) Use for social, domestic, pleasure and business purposes of any person to whom the vehicle is hired.
- C) Use for the carriage of passengers for hire or reward under Private Hire Vehicle (PHV) by the person to whom the vehicle is hired.

8. Policy does not cover:

- A) Use for racing, pace-making, reliability trial or speed-testing.
- B) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle.

*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings.

I/We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

For and on behalf of
LIBERTY INSURANCE PTE LTD
Approved Insurers



Authorised Signature

For Information only:

COVERAGE:	Comprehensive, Unlimited Windscreen
SUM INSURED (S\$):	MARKET VALUE AT THE TIME OF LOSS
EXCESS (S\$):	Section 1 S\$1,500.00, Additional Excess for Young, Elderly & Inexperienced Drivers, S\$3,000.00, Windscreen Excess S\$100.00
FINANCE COMPANY:	SING INVESTMENTS & FINANCE LTD
PRODUCER NAME:	PACIFIC INSURANCE BROKERS PTE LTD



方 商 昭 噴 漆 POON SIANG SEOW

Sin Ming Autocity, No. 160 Sin Ming Drive, #05-13, Singapore 575722.
Tel: 6453 7511 Fax: 6453 8046 Email: sitti1@singnet.com.sg Regn. No. 05396600K

*Not withstanding
L1 Imp @ 37000/-
Paying After Paint
5 days*

Evergreen Rent A Car Pte Ltd
Blk 159 Sin Ming Road
#01-07 Amtech Building
Singapore 575825

Dear sir
Estimate cost of repair to vehicle no.SLM 422E
To supply

1. Rear tail gate
2. Rear tail gate badge harrier
3. Rear tail gate damper x2
4. Rear tail gate rubber
5. Rear tail gate lock
6. Rear w/s molding
7. Tail lamp x2
8. Rear tail gate reflector x2
9. Rear bumper *1343.00*
10. Rear bumper sensor
11. Rear bumper retainer x2
12. Rear bumper lower cover
13. Rear bumper reflector x2
14. Rear bumper sponge
15. Rear bumper reinforcement
16. Exhaust box
17. Rear panel *258*
- Labour charges
- Rust proofing
- Panel beating
- Spray painting
- Total

<i>Bt</i>	1,515.60	✓
<i>Mr</i>	69.80	✓
<i>Sn</i>	940.00	X
<i>Sn</i>	381.90	X
<i>Mr</i>	970.00	X
<i>Mr</i>	350.00	✓
<i>Sn</i>	1,120.00	X
<i>Sn</i>	980.00	X
<i>CM</i>	1,568.90	✓
<i>Shant</i>	350.00	<i>2000</i>
<i>Dit</i>	180.00	✓
<i>Net</i>	389.60	✓
<i>Sn</i>	160.00	X
<i>CM</i>	181.90	✓
<i>Mr</i>	458.00	✓
<i>h</i>	1,580.00	X
<i>R</i>	680.00	✓
	100.00	<i>501</i>
	1,200.00	<i>600</i>
	1,000.00	<i>660</i>
	<i>14,175.70</i>	



Your faithfully

for




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19018138/Kqf3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 25-10-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 7382R	Veh. Inspected	SLM 422E
Policy No.		Coverage (\$)	0.00
Claim No.	D19006572MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	15/10/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA HARRIER (A)	c.c	1986
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	ZSU600076738	Colour	METALLIC PEARL WHITE
Odometer	58775	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/55 R18	BRIDGESTONE	2 mm
L/H Front Tyre	235/55 R18	BRIDGESTONE	2 mm
R/H Rear Tyre	235/55 R18	BRIDGESTONE	3 mm
L/H Rear Tyre	235/55 R18	BRIDGESTONE	3 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	12/10/2019	Inspection Date	15/10/2019
Survey held at	POON SIANG SEOW No.160 SIN MING DRIVE #05-13 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 422E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR TAIL GATE	BENT	1,515.60	1,515.60
1	REAR TAIL GATE BADGE HARRIER	NECESSARY	69.80	69.80
2	REAR TAIL GATE DAMPER	SERVICEABLE	940.00	-
1	REAR TAIL GATE RUBBER	SERVICEABLE	381.90	-
1	REAR TAIL GATE LOCK	TO REPAIR SEE LABOUR	970.00	-
1	REAR W/S MOULDING	NECESSARY	350.00	350.00
2	TAIL LAMP	SERVICEABLE	1,120.00	-
2	REAR TAIL GATE REFLECTOR	SERVICEABLE	980.00	-
1	REAR BUMPER	CRACKED	1,568.90	1,343.00
2	REAR BUMPER RETAINER	DISTORTED	180.00	180.00
1	REAR BUMPER LOWER COVER	DENTED	389.60	389.60
2	REAR BUMPER REFLECTOR	SERVICEABLE	160.00	-
1	REAR BUMPER SPONGE	CRACKED	181.90	181.90
1	REAR BUMPER REINFORCEMENT	BENT	458.00	458.00
1	EXHAUST BOX	TO REPAIR SEE LABOUR	1,580.00	-
1	REAR PANEL	TO REPAIR SEE LABOUR	680.00	-
	LESS 25% DISCOUNT		-	-1,121.98
			11,525.70	3,365.92
SPECIAL NETT ITEMS				
1	REAR BUMPER SENSOR (SN)	SHORTED	350.00	200.00
			350.00	200.00
LABOUR				
	RUST PROOFING.		100.00	50.00
	PANEL BEATING. INCLUSIVE OF REPAIR OF REAR TAIL GATE LOCK, EXHAUST BOX AND REAR PANEL.		1,200.00	660.00
	SPRAY PAINTING.		1,000.00	600.00
			2,300.00	1,310.00
GRAND TOTAL			14,175.70	4,875.92

Report Ref No. CS/FCI19018138/Kqf3n2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,700.00
---	--	--	----------

Report Ref No. CS/FCI19018138/Kqf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part does so at his or her own risk.