

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 349D**AAD1910-084**

Not Authorised
1/ Sep @ 1200hr

Vehicle No.: 14 OCT 2019
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration :

SHD 349D

VF1ABL15AUC282349

RENAULT

LATITUDE

11.10.19

III

17/5/2016

PART			LIST		
1	1	BUMPER COVER REAR	\$	<i>Re/Red</i> 561.70	✓
2	1	BUMPER LOWER REAR	\$	<i>Re</i> 411.90	✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>Re</i> 98.10	} X
4	1	BUMPER BRACKET SIDE RH REAR	\$	<i>Re</i> 82.10	
5	1	BUMPER RETAINER RH REAR	\$	<i>Re</i> 59.80	
6	1	BUMPER REFLECTOR RH	\$	<i>Re</i> 16.60	
7	1	BUMPER BRACKET SIDE LH REAR	\$	<i>Re</i> 80.80	
8	1	BUMPER RETAINER LH REAR	\$	<i>Re</i> 54.20	
9	1	BUMPER REFLECTOR LH	\$	<i>Re</i> 16.60	
10	1	BUMPER BEAM REAR	\$	<i>Re</i> 547.80	
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>Re</i> 114.50	
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>Re</i> 100.90	
13	1	OUTER PANEL REAR (End Panel)	\$	<i>Re</i> 745.80	
14	1	OUTER PANEL REAR (End Panel) TRIM	\$	<i>Re</i> 404.56	
15	1	TAILLAMP RH	\$	<i>Re</i> 313.10	
16	1	TAILLAMP PANEL RH	\$	<i>Re</i> 401.40	
17	1	TAILLAMP LH	\$	<i>Re</i> 401.40	
18	1	TAILLAMP PANEL LH	\$	<i>Re</i> 401.40	
19	1	BOOT REAR	\$	<i>Re</i> 1,677.20	
20	1	BOOT FINISHER	\$	<i>Re</i> 344.70	
21	1	BOOT WHEATERSTRIP	\$	<i>Re</i> 178.20	
22	1	BOOT REFLECTOR LAMP LH	\$	<i>Re</i> 277.70	
23	1	BOOT REFLECTOR LAMP RH	\$	<i>Re</i> 277.70	
24	1	BOOT BADGE 'RENAULT'	\$	<i>Re</i> 82.40	
25	1	BOOT BADGE	\$	<i>Re</i> 95.80	
26	1	BOOT STRUT LH	\$	<i>Re</i> 145.10	

Trans-cab Auto Services Pte Ltd**AAD1910-084**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 349D

27	1	BOOT STRUT RH	\$	SH	145.10	}	X	
28	1	BOOT HINGE LH	\$	N	254.20			
29	1	BOOT HINGE RH	\$	N	253.80			
30	1	BOOT INNER TRIM BOARD	\$	SH	611.00			
31	1	BOOT SWITCH	\$	SH	113.00			
32	1	BOOT LOCK	\$	N	246.60			
33	1	BOOT LOCK CATCH	\$	N	41.70			
34	1	FENDER PANEL REAR LH	\$	N	1,933.20			
35	1	WHEELARCH REAR LH	\$	SH	275.40	}	X	
36	1	FENDER PANEL INNER TRIM REAR LH	\$	SH	671.45			
37	1	EXHAUST CAP REAR	\$	SH	125.40			
TOTAL			\$		12,562.31			
10%			\$		1,256.23			
			\$		11,306.08			

Special Nett

1	1SET	PARKING AID	\$	SH	700.00	X
2	1SET	REAR BUMPER CLIP	\$	na	66.00	✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	na	33.00	✓
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10	1	BOOT STICKER "Trans-cab"	\$	na	30.00	} X
11	1	BOOT STICKER "6555-3333"	\$	na	30.00	
12	1	EXHAUST MOUNTING REAR	\$	SH	16.00	
13	1	REAR LEFT TYRE	\$	SH	300.00	
14	2	REAR WINDSCREEN SEALANT	\$	na	80.00	
15	1	WINDSCREEN MOULDING	\$	na	100.00	
16	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
17	1	BOOT INNER TRIM CLIP	\$	na	45.00	
18	1SET	BOOT FINISHER CLIP	\$	na	24.20	}
19	1	TAILLAMP CLIP LH	\$	na	5.00	

Trans-cab Auto Services Pte Ltd**AAD1910-084**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 349D

20	1	TAILLAMP CLIP RH	\$	5.00	} X
21	1	Rear Bumper Protector	\$	nn 100.00	
22	1SET	FENDER WHEELARCH REAR LH CLIP	\$	35.00	
23	1	FENDER INNER TRIM CLIP LH	\$	28.00	
24	1	REAR LEFT TYRE RIM	\$	380.00	
TOTAL			\$	2,225.20	
TOTAL PARTS			\$	13,531.28	

LABOUR

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	5 380.00	X
To Rust-Proofing Of The Affected Areas.	\$	5 170.00	X
To Check Electrical Lighting Concerned.	\$	5 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	5 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	2001
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 170.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	nn 170.00	X

Trans-cab Auto Services Pte Ltd**AAD1910-084**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 349D

To check steering geometry and computer wheel alignment	\$	na	220.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	4	380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	4	380.00	X
Putty and spray painting of the affected portion.	\$		6,000.00	22d
To repair and realign rear exhaust pipe.	\$	7	170.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	4	380.00	X
TOTAL	\$		15,100.00	
Over All Total	\$		28,631.28	

LUMP SUM (REPAIR DAY)~~20 DAYS~~

2 day,

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: