

REPAIR ESTIMATE*

VEHICLE NO : SHC 118J

DATE 14/10/2019 15:17

MAKE :

MODEL : HYUNDAI IONIQ

LKK/RAM

Lke

CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Fender (RH) x Repair			\$ 490.70
	Front Fender Shield (RH) x nn			\$ 114.70
	Front Fender Retainer x ?			\$ 41.40
	Emblem-Blue Drive (RH) nec			\$ 26.60
	Front Wheel Hub Cap (RH) x ND			\$ 346.40
	Frt Bumper x nn (Repair)			
	SUB TOTAL			\$ 1,019.80
	LESS 20%			\$ 203.96
	DISCOUNTED TOTAL			\$ 815.84
	Labour Charge			
	Panel Beating			\$ 560.00 \$480
	Spray Painting Charge			\$ 500.00 \$400
	Tuff Kote			\$ 50.00 x nn
	Frt Wheel Alignment			\$ 120.00 x nn
	TOTAL LABOUR			\$ 1,230.00
	ESTIMATE TOTAL			\$ 2,045.84
<p><u>LKK Auto Consultants</u> hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p>				
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				

Ram (LKK)
14/10/19 1600hrs
Part by Part
aft repair photo
Parasuram@LKKAuto.com
68622778 HP

Repair by: 2dys