

CC4/11119018143/T1pb3.

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Oct 2019)

Parts: M1-MPV TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJW7417X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT DOOR RH	25.00	0.00	*1,345.00 FL
Sub Total (S\$)						1,345.00
- List Item Discount on L Items (S\$)						336.25
Total Parts (S\$)						1,008.75

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			11.00 ✓
1	1	OD/TP Case (Insurer)	
Sub Total (S\$)			11.00 ✓

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REMOVE AND REPLACE ACCIDENT DAMAGED PARTS. REALIGN ALL CONNECTION.	New	200.00 ✓
2	SPRAY PAINT FRONT DOOR RH	New	200.00 ✓
Gross Labour Cost (S\$)			2) 400.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS
< END OF ESTIMATES >

1) PARTS 1008.75
 2) MISC 11.00
 3) LABOUR 400.00
 1419.75
 - 283.95 less 20%
 1135.80.

Lump sum \$ 1100.00 *

Please advice. Thank You
 Billy UAW.

Tanfer 97495749
 'wp'
 04/11/19 @ 1145

Lumpsum
 Resume after repair.
 02 days
 sure / hands on

1/5 \$ 1100, 2 days

E-mail to Billy 14/11/19