

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

INDIA INTERNATIONAL INSURANCE PTE LTD

64, Cecil Street #04/05

IOB BUILDING

S,pore 049711

Accident date:13/10/2019

Date:14/10/2019

Estimate cost to repair vel: SLR 9523L (BMW 325i) claims under vel: SHD 4964B.

1pce bonnet	\$1,249.30	✓ BT	1050.30
1pce bonnet emblem	72.50	X SUC	
12pcs bonnet insulator clips \$10 1 (set)	120.00	✓ nec	30
1pce front left fender	667.50	X SUC	
	\$2,109.30		
Less 10%	210.93		
	\$1,898.37		
To dismantle/renew accident portion 1 day	500.00	220	
To spray paint 1ps	1,000.00	250	
Total:	\$3,398.37		

h/s report
without prejudice
Manager after paint
853/1883
Hock Ann
2 day
10.40 AM
22/10/19
Hock Ann @ 11/11/19

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____