

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST1900339
Date: 14 Oct 2019
Veh Reg No: SLJ9301C
Make/Model: AUDI A4 1.4 TFSI S
TRONIC
Chasis No: WAUZZZF42HA056388
Reg. Date: 29/12/2016
Your Ref No: SLT5466J

Claim Type: Third Party
Accident Date: 07/10/2019
TP Veh Reg No: SLT5466J

Vic

Estimate Repair Cost to Vehicle No :SLJ9301C

Quantity	Description	List Price	Amount
		SS	SS
	List Price		
1	1 PC REAR BUMPER <i>rehd</i>	2,015.00	✓
2	1 PC REAR BUMPER REINFORCEMENT <i>Bent</i>	819.00	✓
3	2 PCS REAR BUMPER BRACKET <i>na</i>	138.80	✓
4	1 PC REAR BUMPER LOWER GARNISH <i>cut</i>	326.50	✓
5	4 PCS REVERSE SENSORS <i>2 pieces dmd</i>	4282.10 924.00	✓ 462
6	1 PC BOOT LID <i>Repr</i>	4067.99	2,470.00 x
7	1 PC BOOT LID LOGO	112.50	✓
8	1 PC BOOTLID "A4" EMBLEM <i>3 pc</i>	86.60	✓
9	1 PC BOOTLID "TFSI" EMBLEM	86.60	✓
10	1 PC BOOT LID LOCK	446.00	+
11	1 PC BOOT LID LOCK CHECKER <i>3 pc</i>	91.00	+
12	1 PC BOOT LID RUBBER	284.50	+
	<i>1 pc rear bumper top beam</i>	235.10	✓
	<i>1 set " " clips</i>	60.00	✓
	Labour		
13	1 TO CHECK WIRING <i>na</i>	50.00	30
14	1 TO REMOVE AND REFIT REVERSE SENSOR	100.00	60
15	1 TO SPRAY UNDERSEAL	80.00	x
16	1 (REAR) TO SPRAY PAINTING	950.00	500
17	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	950.00	400
18	1 TO REMOVE AND REFIT INNER TRIM	100.00	50
		2,230.00	2,230.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 07/10/2019
TP Veh Reg No: SLT5466J

Estimate No: EST1900339
Date: 14 Oct 2019
Veh Reg No: SLJ9301C
Make/Model: AUDI A4 1.4 TFSI S
TRONIC
Chasis No: WAUZZZF42HA056388
Reg. Date: 29/12/2016
Your Ref No: SLT5466J

Estimate Repair Cost to Vehicle No :SLJ9301C

Quantity	Description	List Price	Amount
		SS	SS
		Total	S\$ 9,250.45
		Add GST @ 7%	647.53
		Total Amount Payable	S\$ 9,897.98

TOTAL: SINGAPORE DOLLAR NINE THOUSAND EIGHT HUNDRED NINETY SEVEN AND CENTS NINETY EIGHT ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE

<u>LKK Auto Consultants</u> hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:
--

Adrian Lj
2/s 14/10/15.

04 Days.

total: 5137.99
4/s 4.1K.

4.1K.