

ASS. REC. BY:

REF: CS/PC1 19018153/ Kyf3<sup>2</sup>

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Ming Chien San San

of

PC1

Date/Time: 15.10.19 2.13 p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLD 90946

Insured:

SHA 3964

at Workshop m/s

Lai Huat

Tel:

64538110

of

160 Sin Ming Drive #04-01

Policy No:

Claim No:

D19006553 MP54

Sum Insured:

Excess:

Make of Veh:

D.O.A.

11.10.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

"mp"

H.O.D. Endorsement:

Date/Time:

15.10.19 2.29 p.m

Person Contacted:

Jenny

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

SLD 90946 - X

SHA 03964 - X

22/10/19

Sent Preli by email

ASS. REC. BY:

REF: FCI

## ASSIGNMENT

From:

Date:

17.10.2019

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLD 9094 G

at Workshop n/s

Lai Hwa (Meng Ka)

of

160 Sin ming drive #04-01/02

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

Bal. or Market Value:

\$466

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLD 9094G

Yr Regn:

10, 12

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Peugeot

508

C.C.

1588

Colour

M. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

164762

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VI-380.5 FVA CL 055250

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

235/45R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

9

mm

Rear

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

11/10/19

D.O.I.

17/10/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

&amp; M

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

17/12

L/S \$12500/- (Red \$7113-12, 36%)

RECEIVED 17 FEB 2020

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

31/1/20 Typist

Rep. Form:

Comp. Sum. (B/C)

\$12500/-

Days Of Repair:

6

Resurvey No. of Trip:

3

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

9x15=135

135+70=305

305

50

50+50

48

503

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	14-10-2019	<b>Our Ref No.</b> D19006553MFSH
<b>Accident Date</b>	11-10-2019	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHA0396H	<b>Third Party Vehicle.</b> SLD9094G
<b>Survey Location</b>	160 SIN MING DRIVE #04-01/#04-02/#07-03SIN MING AUTOCITY	
<b>Contact Person.</b>	JENNY LIM	
<b>Contact No.</b>	64538110/ 0	<b>Fax No.</b> 64596267
<b>Survey Type</b>	DIRECT SETTLEMENT:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

<b>Cc : Workshop</b>	LAI HUAT (MENG KEE) MOTOR PTE LTD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	MERINA CHIA SAN SAN	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

## Yvonne Wong (LKK Auto)

---

**From:** Yvonne Wong (LKK Auto)  
**Sent:** Tuesday, October 22, 2019 10:22 AM  
**To:** 'CWS Motor Claims'  
**Cc:** 'Merina Chia'  
**Subject:** SURVEY ASSESSMENT - D19006553MFSH/1  
**Attachments:** SLD9094G DOA 11102019 REVERT.pdf

Dear Sir/ Madam

Enclosed preliminary revised of vehicle SLD9094G  
Date of survey : 17/10/2019  
Number of days : 6 days

Thank you.

Best Regards,

**Yvonne Wong (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [yvonne.wong@lkkauto.com](mailto:yvonne.wong@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Tuesday, October 15, 2019 2:24 PM  
**To:** 'CWS Motor Claims' <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Cc:** 'Merina Chia' <[MerinaChia@msfirstcapital.com.sg](mailto:MerinaChia@msfirstcapital.com.sg)>  
**Subject:** RE: SURVEY ASSESSMENT - D19006553MFSH/1

Dear Sir/Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

**Summer Lee** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** CWS Motor Claims <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>  
**Sent:** Tuesday, 15 October, 2019 2:13 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** CWS Motor Claims <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; Merina Chia <[MerinaChia@msfirstcapital.com.sg](mailto:MerinaChia@msfirstcapital.com.sg)>  
**Subject:** PRI: SURVEY ASSESSMENT - D19006553MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

**Note: All the accident reports are uploaded into CWS for your perusal.**

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19006553MFSH

Date: 22 Oct 2019

Our Ref: CS/FCI19018153/Kyf3

The Motor Claims Department  
MS First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SLD9094G**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 17/10/2019 at the premises of M/s LAI HUAT (MENG KEE) MOTOR PTE LTD. and have the following to report:-

Workshop Estimate Amount	: S\$ <u>13,476.02</u>
Revised Estimate Amount	: S\$ <u>8,663.19</u>
"Check" Items Amount	: S\$ <u>1,883.62</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

**Description of Damage:**

The vehicle sustained damages at the rear & front portion.



Yours faithfully

KONG SENG CHEONG  
Licensed Appraiser

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	11/10/2019 16:52
Date Of Accident	11/10/2019 07:55
Exact Location Of Accident	PIE TOWARDS TUAS
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLD9094G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TEO KAH BOON
NRIC No	S8015210H
Email Address	KABOOMED@GMAIL.COM
Mobile Phone No	(LOCAL) +65-81571515
Alternative Phone No	OTHERS-81571515
<b>Vehicle Particulars</b>	
Manufacturer	PEUGEOT
Model	508 1.6 TURBO ALLURE PLUS
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3017081902
Cover Note Number	

### Driver

Name of Driver	TEO KAH BOON
NRIC No	S8015210H
Date Of Birth	25/05/1980
Occupation	INDOOR
Date Of Driving Pass	20/04/2001
Driving Experience	18 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81571515
Fax Number	
Contact Number	OTHERS-81571515
Email Address	KABOOMED@GMAIL.COM

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SKH8288L

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address


Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)





## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

It was Friday (11 Oct) morning at 7:55am. It was sunny and road condition was dry.

I was driving on the right-most lane of PIE going towards Tug (just past Stevens Rd exit).

Car C for reasons unknown to me jammed brake and Car B did not have time to react and rear-ended Car C.

I immediately jammed my brakes (Car A) and managed to stop behind Car B. However, this happened in a matter of seconds and Car D (taxi) behind me ~~also~~ could not react in time and rear-ended me. This collision caused my car - ~~Car A~~ (Car A) to lurch forward, and rear-ending Car B as a result. This is clearly shown in my video footage (both front and rear) of my ~~car~~ in-car camera as submitted. There were ~~so~~ 2 more cars behind Car D (taxi) that stopped after the accident but I ~~did not~~ do not know if they were involved in any collision.

~~I did not~~ After taking some photos, and exchanging particulars with Car B and Car D (taxi), ~~so~~ I proceeded to drive off.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date &amp; Time:

11 OCT 2019

Driver's Signature

(If driver is not the policyholder)

Date &amp; Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

MOTOR PRIVATE CAR

**CERTIFICATE OF INSURANCE**

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)  
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960  
Road Transport Act, 1987 (Malaysia)  
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Cov. Type: C  
**PLM 326912**

ORIGINAL

CERTIFICATE No.

DMPCSN3017081902

Engine No : 10FJBX1560479

ChasNo: VF38D5FVACL055250

1. Index Mark and Registration  
Number of Vehicle

SLD9094G

2. Name of Policy Holder

TEO KAH BOON

3. Effective date of the Commencement of  
Insurance for the purposes of the Regulations,  
Ordinance or Enactment

01 April 2019

Named Drivers Ex Sect. I ..... S\$500.00

Additional Ex Other than Named Drivers:

Ex Sect. I - Age <= 25 ..... S\$3,000.00

Ex Sect. I - Age >= 26 ..... S\$500.00

\* Age as at date of accident

EX ON WINDSCREEN ..... S\$100.00

5. Persons or Classes of Persons entitled to drive\*

(a) The Policyholder.

(b) Any other person who is driving on the Policyholder's order or with his permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use.\*

Use for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover use for hire or reward tuition driving test racing pace-making, reliability trial, speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

Excess whichever is applicable for losses occurring outside Singapore (Constructive Total Loss/Theft) will be doubled.

One time Waiver of Excess for the first S\$1,000 will apply to the Insured and Named Drivers in the event of Own Damage Claim at our Authorised Workshops for each Policy Year.

HIRE PURCHASE CO. : SING INVESTMENTS & FINANCE LTD AS HP OWNER

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act 1987 (Malaysia), are not to be included under these headings.

**I/We hereby Certify** that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please see reverse

For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Issued By:

Authorised Officer

Authorised Signatory

# 来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267  
GST No: M2-0128609-3  
UEN: 199407592C

## ESTIMATE

EST. No ..... EST0023522  
Teo Kah Boon

Page ..... 1 of 2  
Your ref. .... TP-SHA 396H MS FC  
Job No. .... 70944  
Our ref. .... 19.10.25  
Payment .....  
Date ..... 14/10/2019

Attn .....

Vehicle No .... SLD 9094G  
Vehicle Model Peugeot 508  
Accident on ... 11/10/2019

*Not Authorized*  
*11/10/19*  
*Repair After Paint*  
*6 days*

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts - Nett item:					
1.00	Pc	Front bonnet	2,007.60		2,007.60
1.00	Pc	Front radiator grille	499.60		499.60
1.00	Pc	Front radiator grille chrome moulding	477.77		477.77
1.00	Pc	Front bumper	1,600.76		1,600.76
1.00	Pc	Front bumper lower grille	200.70		200.70
1.00	Pc	Front logo emblem	69.60		69.60
1.00	Pc	Front bumper reinforcement	670.77		670.77
7.00	Pcs	Front bumper top clips	16.17		113.19
1.00	Pc	Front engine under cover	433.75		433.75
1.00	Pc	Rear boot lid	1,997.60		1,997.60
1.00	Pc	Rear bumper	1,469.70		1,469.70
1.00	Pc	Rear bumper lower garnish	433.90		433.90
1.00	Pc	Rear bumper reinforcement	599.70		599.70
1.00	Pc	Rear number plate lamp LH	89.70		89.70
1.00	Pc	Rear number plate lamp RH	89.70		89.70
1.00	Pc	Rear bumper lower garnish chrome moulding	199.60		199.60
1.00	Pc	Rear 508 emblem	70.77		70.77

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary part(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by: \_\_\_\_\_  
Date: \_\_\_\_\_

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

# 来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267  
GST No: M2-0128609-3  
UEN: 199407592C

## ESTIMATE

EST. No .....: EST0023522  
Teo Kah Boon

Page .....: 2 of 2  
Your ref. ....: TP-SHA 396H MS FC  
Job No. ....: 70944  
Our ref. ....: 19.10.25  
Payment .....  
Date .....: 14/10/2019

Attn .....

Vehicle No ....: SLD 9094G  
Vehicle Model : Peugeot 508  
Accident on ...: 11/10/2019

Quantity	Unit	Description	Unit price	Disc. pct.	Amount	
Special nett item:						
1.00	Pc	Front number plate	35.00		35.00	CM ✓
1.00	Pc	Rear number plate	35.00		35.00	CM ✓
1.00	Pc	Rear bumper top plate	100.00		100.00	Bu ✓
Labour & Misc:						
1.00		To transfer rear parking sensor	50.00		50.00	Et ✓
1.00		To straighten front body, to remove and renew above parts	650.00		650.00	Sp ✓
1.00		To spray paint	700.00		700.00	✓
Sub-Total					12,594.41*	
GST 7.00%					881.61	
Total					S\$ 13,476.02	

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."



ky

# 来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267  
GST No: M2-0128609-3  
UEN: 199407592C

## ESTIMATE

EST No EST0023522  
Teo Kah Boon

Page 1 of 2  
Your ref TP-SHA 396H MS FC  
Job No 70944  
Our ref 19 10 25  
Payment  
Date 14/10/2018

Attn

Vehicle No SLD 90943  
Vehicle Model Peugeot 508  
Accident on 11/10/2018

*Not Authorized*  
*11 Sep @ 12,500k*  
*Repair After Paint*  
*6 days*

Quantity	Unit	Description	Unit price	Disc pct	Amount
Supply of Parts - Nett item.					
1.00	Pc	Front bonnet	2,007.60		By 2,007.60
1.00	Pc	Front radiator grille	499.60		CM 499.60
1.00	Pc	Front radiator grille chrome moulding	477.77		CM 477.77
1.00	Pc	Front bumper	1,600.76		By 1,600.76
1.00	Pc	Front bumper lower grille	200.70		By 200.70
1.00	Pc	Front logo emblem	69.60		By 69.60
1.00	Pc	Front bumper reinforcement	670.77		By 670.77
7.00	Pcs	Front bumper top clips	16.17		By 113.19
1.00	Pc	Front engine under cover	133.75		By 133.75
1.00	Pc	Rear boot lid	1,097.60		By 1,097.60
1.00	Pc	Rear bumper	1,469.70		By 1,469.70
1.00	Pc	Rear bumper lower garnish	433.90		By 433.90
1.00	Pc	Rear bumper reinforcement	599.70		By 599.70
1.00	Pc	Rear number plate lamp LH	89.70		By 89.70
1.00	Pc	Rear number plate lamp RH	89.70		By 89.70
1.00	Pc	Rear bumper lower garnish chrome moulding	199.60		CM 199.60
1.00	Pc	Rear 508 emblem	70.77		By 70.77

58

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大致修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

# 来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267  
GST No: M2-0128609-3  
UEN: 199407592C

## ESTIMATE

EST. No EST0023522  
Teo Kah Boon

Page 2 of 2  
Your ref TP-SHA 396H MS FC  
Job No 70944  
Our ref 19.10.25  
Payment  
Date 14/10/2019

Attn

Vehicle No SLD 9094G  
Vehicle Model Peugeot 508  
Accident on 11/10/2019

Quantity	Unit	Description	Unit price	Disc pct	Amount
		Special nett item:			
1.00	Pc	Front number plate	35.00		CM 35.00 ✓
1.00	Pc	Rear number plate	35.00		CM 35.00 ✓
1.00	Pc	Rear bumper top plate	100.00		BL 100.00 ✓
		Labour & Misc:			
1.00		To transfer rear parking sensor	50.00		50.00 ✓
1.00		To straighten front body, to remove and renew above parts	650.00		650.00 600 ✓
1.00		To spray paint	700.00		700.00 ✓

Sub-Total 12,594.41  
GST 7.00% 881.61  
Total S\$ 13,476.02  
19613-128

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

# 来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267  
GST No: M2-0128609-3  
UEN: 199407592C

## SUPPLEMENTARY

## ESTIMATE

EST No EST0023522  
Teo Kah Boon

Page 1 of 1  
Your ref TP-SHA 396H MS FC  
Job No 70944  
Our ref 19.10.25  
Payment  
Date 21/10/2019

Attn

Vehicle No SLD 9094G  
Vehicle Model Peugeot 508  
Accident on 11/10/2019

Quantity	Unit	Description	Unit price	Disc pct	Amount
Supply of Parts - Nett item.					
SUPPLEMENTARY ITEM					
1.00	Pc	Front support panel	588.75		588.75
1.00	Pc	Front headlamp LH	2,677.33		2,677.33
1.00	Pc	Front headlamp RH	2,677.33		2,677.33
1.00	Pc	Air con condenser	1,075.30		1,075.30

58

CM  
ms CM  
ms CM  
R

Sub-Total 7,018.71  
GST 7.00% 491.31  
Total S\$ 7,510.02

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."




**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19018153/Kyf3s2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 17-02-2020	
		Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SHA 396H	Veh. Inspected	SLD 9094G
Policy No.		Coverage (\$)	0.00
Claim No.	D19006553MFSH	Excess (\$)	0.00
Assign From	MERINA CHIA SAN SAN	Assign Date	15/10/2019
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	PEUGEOT 508 (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	VF38D5FVACL055250	Colour	METALLIC BLACK
Odometer	164762	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	235/45 R18	GOODYEAR	9 mm
L/H Front Tyre	235/45 R18	GOODYEAR	9 mm
R/H Rear Tyre	235/45 R18	GOODYEAR	9 mm
L/H Rear Tyre	235/45 R18	GOODYEAR	9 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	11/10/2019	Inspection Date	17/10/2019
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722		
<b>5a. Remarks</b>			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>6 Working Days</b>	





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 9094G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT BONNET	BENT	2,007.60	2,007.60
1	FRONT RADIATOR GRILLE	CRACKED	499.60	499.60
1	FRONT RADIATOR GRILLE CHROME MOULDING	CRACKED	477.77	477.77
1	FRONT BUMPER	BUCKLED	1,600.76	1,600.76
1	FRONT BUMPER LOWER GRILLE	DENTED	200.70	200.70
1	FRONT LOGO EMBLEM	NECESSARY	69.60	69.60
1	FRONT BUMPER REINFORCEMENT	BENT	670.77	670.77
7	FRONT BUMPER TOP CLIPS @ \$16.17	NECESSARY	113.19	113.19
1	FRONT ENGINE UNDER COVER	SERVICEABLE	433.75	-
1	REAR BOOT LID (DENTED)	NOT CONSISTENT WITH THE IMPACT	1,997.60	-
1	REAR BUMPER	BUCKLED	1,469.70	1,469.70
1	REAR BUMPER LOWER GARNISH	DENTED	433.90	433.90
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	599.70	-
1	REAR NUMBER PLATE LAMP LH	SERVICEABLE	89.70	-
1	REAR NUMBER PLATE LAMP RH	SERVICEABLE	89.70	-
1	REAR BUMPER LOWER GARNISH CHROME MOULDING	CRACKED	199.60	199.60
1	REAR 508 EMBLEM	NECESSARY	70.77	70.77
1	FRONT SUPPORT PANEL (ADDITIONAL)	CRACKED	588.75	588.75
1	FRONT HEADLAMP LH (ADDITIONAL)	MTG CRACKED	2,677.33	2,677.33
1	FRONT HEADLAMP RH (ADDITIONAL)	MTG CRACKED	2,677.33	2,677.33
1	AIR CON CONDENSER (ADDITIONAL)	BENT	1,075.30	1,075.30
	LESS 5% DISCOUNT		-	-741.64
			18,043.12	14,091.03
<b>SPECIAL NETT ITEMS</b>				
1	FRONT NUMBER PLATE (SN)	CRACKED	35.00	35.00
1	REAR NUMBER PLATE (SN)	CRACKED	35.00	35.00
1	REAR BUMPER TOP PLATE (SN)	BUCKLED	100.00	100.00
			170.00	170.00

Report Ref No. CS/FCI19018153/Kyf3s2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	TO TRANSFER REAR PARKING SENSOR.		50.00	50.00
	TO STRAIGHTEN FRONT BODY, TO REMOVE AND RENEW ABOVE PARTS. INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT.		650.00	600.00
	TO SPRAY PAINT.		700.00	700.00
			1,400.00	1,350.00
<b>GRAND TOTAL</b>			<b>19,613.12</b>	<b>15,611.03</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>12,500.00</b>

Report Ref No. CS/FCI19018153/Kyf3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.