



TeamWork Garage Pte Ltd  
 53 Ubi Avenue 1 #01-23/24 Spore 408934  
 Paya Ubi Industrial Park  
 Tel : 6844 2475  
 E-mail : claims@teamworkgarage.com  
 Register number : 201015366H  
 REPAIR PERFORMA INVOICE

AIG INSURANCE

Vehicle number	SKG2261H
Make / Model	TOYOTA ESTIMA
Chassis number	ACR507056208
Accident date	14/10/2019
Reference	1910-11

Qty Particulars Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS			
1	FRONT BUMPER	1380	1745.60 de ✓
2	FRONT BUMPER SIDE RETAINER	12940	259.80 LH de ✓ CHK AM
1	FRONT BUMPER REINFORCEMENT	394.20	471.90 ? bt ✓
1	FRONT BUMPER SPONGE	69.20	163.80 ? Cra ✓
1	FRONT BUMPER LOWER GRILLE		295.00 X AM
1	FRONT GRILLE		364.00 X AM
2	FRONT HEADLAMP	204348	5083.40 LH de ✓ RHY AM
2	FRONT HEADLAMP CONTROL UNIT	510	RH X AM 1620.00 *? LH - dis ✓
1	FRONT LH FOG LAMP		269.90 de ✓
1	FRONT LH FOG LAMP COVER		194.00 de ✓
1	FRONT TOW COVER		81.91 de ✓
1	FRONT BONNET	796.50	1890.50 bt ✓
2	FRONT BONNET HINGE		189.20 R ✓
1	FRONT BONNET OUTER GARNISH		311.50 X AM
1	FRONT BONNET EMBLEM		96.70 X AM
1	FRONT FENDER	685	1032.50 bt ✓
1	FRONT FENDER INNER SHIELD	175	243.20 de ✓
1	FRONT LH DOOR		1998.50 X AM
1	FRONT LH SHOCK ABSORBER		449.20 X AM
1	FRONT LH KNUCKLE ARM	421	594.20 P bt ✓
1	FRONT LH KNUCKLE ARM BEARING	125	321.40 ? bt ✓
1	FRONT LH LOWER ARM		514.10 X AM
1	FRONT SUPPORT PANEL		811.40 R ✓
1	FRONT SUPPORT PANEL TOP GARNISH		201.60 AM ✓
1	AIRDUCT		186.50 X AM
			19389.81
	Less 25%		4847.45
	Subtotal		14542.36
	Balance C/F		14542.36

7280.01  
 5460.00

<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
	Balance B/F	14542.36
1 SET	FRONT BUMPER CLIP	50.00 <i>30 net</i>
1 SET	FRONT GRILLE CLIP	60.00 <i>20 x un</i>
1 SET	FRONT SUPPORT PANEL TOP GARNISH CLIP	60.00 <i>x un</i>
1 SET	FRONT FENNDER INNER SHIELD CLIP	60.00 <i>20 net</i>
1	FRONT LH RIM	600.00 <i>x un</i>
	Subtotal	830.00 <i>50.</i>
	Balance C/F	15372.36
S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
	Balance B/F	15372.36
1	CHECK FRONT & REAR WIRING AND LIGHTING SYSTEM	150.00 <i>30</i>
2	REMOVE AND REFIT GARNISH , LINING AND TRIM FOR REPAIR	200.00 <i>40</i>
3	TO REMOVE AND REFIT FRONT UNDERCARRAIGE	350.00 <i>120<sup>2</sup> phk</i>
4	TO CONDUCT WHEEL ALIGNMENT	150.00 <i>80.</i>
5	PANEL BEATING ON AFFECTED AREAS	1600.00 <i>700</i>
6	SPRAY PAINTING ON AFFECTED AREAS	1600.00 <i>800</i>
7	APPLY ANTI-RUST ON AFFECTED AREAS	200.00 <i>30</i>
	Subtotal	4250.00 <i>1800.</i>
	Grand total	19622.36

Tanghin 92495449  
WP

15/10/19 @ 1130

kur p s u r

Resurvey before paint.

5 days.

sur@lkhauto.com

7310

4/5 @ 5850

\* 5 days

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: