



**TeamWork Garage Pte Ltd**  
 53 Ubi Avenue 1 #01-23/24 Spore 408934  
 Paya Ubi Industrial Park  
 Tel : 6844 2475  
 E-mail : claims@teamworkgarage.com  
 Register number : 201015366H  
**REPAIR PERFORMA INVOICE**

**AIG INSURANCE**

Vehicle number	SKG2261H
Make / Model	TOYOTA ESTIMA
Chassis number	ACR507056208
Accident date	14/10/2019
Reference	1910-11

Qty Particulars Unit Price - SGD \$

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT BUMPER	1745.60 <i>de ✓</i>
2	FRONT BUMPER SIDE RETAINER	259.80 <i>LH-de ✓, RHA</i>
1	FRONT BUMPER REINFORCEMENT	471.90 <i>?</i>
1	FRONT BUMPER SPONGE	163.80 <i>?</i>
1	FRONT BUMPER LOWER GRILLE	295.00 <i>X</i>
1	FRONT GRILLE	364.00 <i>?</i>
2	FRONT HEADLAMP	5083.40 <i>LH-a ✓ RHY</i>
2	FRONT HEADLAMP CONTROL UNIT	1620.00 <i>*?</i>
1	FRONT LH FOG LAMP	269.90 <i>dir ✓</i>
1	FRONT LH FOG LAMP COVER	194.00 <i>dir ✓</i>
1	FRONT TOW COVER	81.91 <i>de ✓</i>
1	FRONT BONNET	1890.50 <i>bt ✓</i>
2	FRONT BONNET HINGE	189.20 <i>Ry</i>
1	FRONT BONNET OUTER GARNISH	311.50 <i>X</i>
1	FRONT BONNET EMBLEM	96.70 <i>X</i>
1	FRONT FENDER	1032.50 <i>bt ✓</i>
1	FRONT FENDER INNER SHIELD	243.20 <i>de ✓</i>
1	FRONT LH DOOR	1998.50 <i>X</i>
1	FRONT LH SHOCK ABSORBER	449.20 <i>X</i>
1	FRONT LH KNUCKLE ARM	594.20 <i>?</i>
1	FRONT LH KNUCKLE ARM BEARING	321.40 <i>?</i>
1	FRONT LH LOWER ARM	514.10 <i>X</i>
1	FRONT SUPPORT PANEL	811.40 <i>Ry ✓</i>
1	FRONT SUPPORT PANEL TOP GARNISH	201.60 <i>X</i>
1	AIRDUCT	186.50 <i>X</i>
		19389.81
	Less 25%	4847.45
	Subtotal	14542.36
	Balance C/F	14542.36

<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
	Balance B/F	14542.36
1 SET	FRONT BUMPER CLIP	50.00 <i>30 new</i>
1 SET	FRONT GRILLE CLIP	60.00 <i>20?</i>
1 SET	FRONT SUPPORT PANEL TOP GARNISH CLIP	60.00 <i>x</i>
1 SET	FRONT FENNDER INNER SHIELD CLIP	60.00 <i>20 new</i>
1	FRONT LH RIM	600.00 <i>x</i>
	Subtotal	830.00
	Balance C/F	15372.36
S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
	Balance B/F	15372.36
1	CHECK FRONT & REAR WIRING AND LIGHTING SYSTEM	150.00 <i>30</i>
2	REMOVE AND REFIT GARNISH ,LINING AND TRIM FOR REPAIR	200.00 <i>40</i>
3	TO REMOVE AND REFIT FRONT UNDERCARRAIGE	350.00 <i>120? pick</i>
4	TO CONDUCT WHEEL ALIGNMENT	150.00 <i>80.</i>
5	PANEL BEATING ON AFFECTED AREAS	1600.00 <i>700.</i>
6	SPRAY PAINTING ON AFFECTED AREAS	1600.00 <i>800</i>
7	APPLY ANTI-RUST ON AFFECTED AREAS	200.00 <i>30.</i>
	Subtotal	4250.00
	Grand total	19622.36

Tanpin 97495749  
-WP-

15/10/19 @ 1130

humpson

Resurvey before paint.

5 days.

sur@lkhauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: