LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd. 6 Temasek Boulevard #18-01 Suntec Tower 4 Singapore 038986 From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Date: 15 Oct 2019

Preliminary Advice

Insured Vehicle No : SJZ4463R

TP Vehicle No : SLH9037B Accident Date : 13/10/2019

Make : TOYOTA PRIUS Assignment Date : 15/10/2019

Date of Inspection : 14/10/2019 Est. Duration of Repair : 2Days

Inspection At : ESTEEM PERFORMANCE PTE LTD

Point of Impact / General Description of Damages

The vehicle sustained impact / damagesO/S Rear... portion and parts claimed are consistent to the accident.

| Repairer's Estimate (Gross) | :S\$ | 2,502.85 |
|-----------------------------|------|----------|
| Revised Amount | :S\$ | 430.00 |
| Check Items (Estimated) | :S\$ | 112.28 |
| Total | :S\$ | 542.28 |

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$
Pre-Accident Value :S\$
COE / PARF Rebate :S\$
Salvage Value :S\$
Margin for Repair :S\$

Remarks

| (|) |) The vehicle is repairable at our adjusted amount. We have also | confirmed excess and policy coverage. |
|---|---|--|---------------------------------------|
| | | Kindly let us have your authorisation. | |
| | | | |

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments :We have not authorized repairs.