



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLH 9037 B

Not Authorized

Parts	(a) Cost / List Price Items	\$	2,043.80
	Plus/Less 25%	\$	510.95
	Total of Cost / List	\$	1,532.85
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items		
Total Parts Cost		\$	1,532.85
Labour		\$	970.00
Total		\$	2,502.85

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

The above total will be subjected to 7% G.S.T.

Name of Surveyor

:

Kenneth

Company

:

LKK

Survey conducted on

:

14/10/18

at

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : *02* day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ _____

(e) Signature of surveyor

:

Lc

Date:

14/10/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.

Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLH 9037 B**
Make & Model : **TOYOTA PRIUS**
Chassis No : **JTDKB3FU403537886**

Submit By : **SERENCE**
Year Manufacture : **2016**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear bumper	1	\$497.50		X
2	Rear bumper clip	10	\$40.00		X
3	Rear bumper side retainer LH	1	\$112.70		X
4	Rear bumper side retainer RH	1	\$112.70		X
5	Rear bumper reinforcement	1	\$398.90		X
6	Rear bumper lower garnish centre	1	\$582.60		X
7	Rear bumper lower garnish LH	1	\$149.70		X
8	Rear bumper lower garnish RH	1	\$149.70		?
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Labour