

ASS. REC. BY:

REF:

CS/INC19018160/ET9302

Special Instruction:

Surveyor: SteveASSIGNMENT (Office)

CWS

From (Person): Theresa Vimalaof INCDate/Time: 15 October 2019

Estimated Cost:

Bill to:

OF / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: GBD 3120YInsured: GBB 3923Hat Workshop m/s Jwfi International PTE LTDTel: 6703 8916of 10 Amk industrial park 2A #03-08 AUTOPoint (568047)

Policy No:

Claim No: MT/1062604-002

Sum Insured:

Excess:

Make of Veh:

D.O.A. 16/09/2019

(Client's Record)

"wp"

CA / REV / REP. / REV 24 HRS

H.O.D. License:

Date/Time: 15/10/2019 @ 02:45pmPerson Contacted: ZuhriVehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	GBD 3120Y: x
	GBB 3923H: x
	Change workshop to Jwfi.

Summer Lee (LKK Auto)

From: Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>
Sent: Wednesday, 16 October, 2019 9:07 AM
To: assignments
Subject: RE: TP CASES FARMED OUT TO LKK ON 15/10/2019

Hi Lkk, here is the list of the OIC names etc...

With Regards

Theresa Vimala
Senior Administrator
Motor Insurance
www.income.com.sg

income
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

in with you

From: Theresa Vimala D/O Balagangadharan
Sent: Tuesday, 15 October 2019 10:07 AM
To: assignments <assignments@lkkauto.com>
Cc: Teng Ken Leong <kenleong.teng@income.com.sg>; Thio Tse Kiat <tsekiat.thio@income.com.sg>; Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>
Subject: RE: TP CASES FARMED OUT TO LKK ON 15/10/2019

Dear LKK,

Please assist to survey the following vehicles .

SN	OIC	Claim No.	Survey Date	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	SERENE	MT/1066803-001	15/10/2019	SLD3925Z	BAN CHOON MOTOR WORKS	3 PIONEER ROAD NORTH #01-14/15 SINGAPORE 628457	Perlin / 62641191		SIW7966C	7/10	
2	CHARLOTTE	MT/1064715-002	15/10/2019	GY8801M	MOTORWAY CAR CARE CENTRE PTE LTD	1094 LOWER DELTA ROAD MOTORWAY BUILDING SINGAPORE 169205	Annie Tew / 6571 9642	10:00-12:00	SKQ8849X	30/9	
3	JEFF	MT/1064107-002	15/10/2019	XE4320P	VFIX AUTO PTE LTD	26 CHIA PING ROAD SINGAPORE 619977	Weng Sheng / 6455 2957	14:00-16:00	SIH7384K	26/9	Owner waiting
4	JEFF	MT/1066455-002	15/10/2019	SIW7856L	AUTO INSURE PTE LTD	6 MARSILING LANE	Sam Goh / 9743 6363		SIW9804D	11/10	
5	DAVID	MT/1066634-001	15/10/2019	SLN3940B	AUTO INSURE PTE LTD	6 MARSILING LANE	Geraldine Lim / 9743 6363		SGR6525K	10/10	
6	HELENA	MT/1059149-002	15/10/2019	SCG6128D	TAN CHONG MOTOR SALES PTE LTD	913 BUKIT TIMAH ROAD SINGAPORE 589623	ZUHRI / 67038916	10:00-12:00	SKZ7039B	22/8	Owner waiting
7	HUEY HUEY	MT/1062604-002	15/10/2019	G8D3120Y	TAN CHONG MOTOR SALES PTE LTD	913 BUKIT TIMAH ROAD SINGAPORE 589623	ZUHRI / 67038916	10:00-12:00	G8B3923H	16/9	Owner waiting

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

With Regards

Theresa Vimala
Senior Administrator
Motor Insurance
T +65 6430 7898
www.income.com.sg

income
made different



in with
you

At Income, we are 'In with You' on Performance, Growth,
Innovation and Impact. These attributes reflect what we promise
as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

Steve Chen (LKK Auto)

From: JWG CLAIMS <jwg.claims@yahoo.com>
Sent: Monday, December 09, 2019 7:02 PM
To: Steve Chen (LKK Auto)
Subject: Re: Finalization for vehicle number GBD3120Y
Attachments: 3120.pdf

Dear Steve,

Offer accepted.

Thank you.

Warmest Regards,
JWG INTERNATIONAL PTE. LTD.

10, Ang Mo Kio Ind Park 2A
#03-08 AMK AutoPoint
Singapore 568047

TEL: 6909 8882 | FAX: 6909 9592

On Wednesday, 4 December 2019, 09:28:10 am GMT+8, Steve Chen (LKK Auto) <stevechen@lkkauto.com> wrote:

Dear Kelvin,

Kindly refer our finalize \$3500 (L/S, before GST). 5 repair days.

Kindly confirm.

Thanks

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	300B
Vehicle Details	
Vehicle No.:	GBD3120Y
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Nov 2019
Vehicle Make:	NISSAN
Vehicle Model:	NV350 PANEL VAN 2.5 5MT 5DR EURO V
Primary Colour:	Grey
Manufacturing Year:	2014
Engine No.:	YD25354917A
Chassis No.:	JN1MC2E26Z0002963
Maximum Power Output:	-
Open Market Value:	\$23,914.00
Original Registration Date:	30 Aug 2014
First Registration Date:	30 Aug 2014
Transfer Count:	0
Actual ARF Paid:	\$1,196.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 Aug 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$37,959.00
COE Rebate Amount:	\$18,122.00
Total Rebate Amount:	\$18,122.00

The information contained herein is correct as at 20 Nov 2019

OK

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

RECORDS MANAGEMENT CENTRE

TAX INVOICE

Our Ref No: GR-19-163471

Date of Request: 04/10/2019

Your Ref No: Online Purchase

Tan Chong Motor Sales Pte Ltd
911, Bukit Timah Road
Singapore 589622

Dear Sir/Madam,

Enquiry Date 04/10/2019
Enquiry By Eric Koh Yong Lang
TP Vehicle No. GBB3923H
Accident Date 16/09/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ [X] GIRO ☐ [] Cash ☐ [] Cheque

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-19-163471
Date of Request: 04/10/2019

Your Ref No: Online Purchase

Tan Chong Motor Sales Pte Ltd
911, Bukit Timah Road
Singapore 589622

Dear Sir/Madam,

Enquiry Date 04/10/2019
Enquiry By Eric Koh Yong Lang
TP Vehicle No. GBB3923H
Accident Date 16/09/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
GBB3923H	NTUC Income Insurance Co-operative Ltd	13/02/2019-12/02/2020	

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	300B
Vehicle Details	
Vehicle No.:	GBD3120Y
Vehicle to be Exported:	Yes
Intended Deregistration Date:	15 Oct 2019
Vehicle Make:	NISSAN
Vehicle Model:	NV350 PANEL VAN 2.5 5MT 5DR EURO V
Primary Colour:	Grey
Manufacturing Year:	2014
Engine No.:	YD25354917A
Chassis No.:	JN1MC2E26Z0002963
Maximum Power Output:	-
Open Market Value:	\$23,914.00
Original Registration Date:	30 Aug 2014
First Registration Date:	30 Aug 2014
Transfer Count:	0
Actual ARF Paid:	\$1,196.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 Aug 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$37,959.00
COE Rebate Amount:	\$18,489.00
Total Rebate Amount:	\$18,489.00

The information contained herein is correct as at 15 Oct 2019

OK

96450019

SURVEYOR

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/09/2019 11:46
Date Of Accident	16/09/2019 10:30
Exact Location Of Accident	GATE 363 ALEXANDRA TERRACE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBD3120Y
Insured/Policyholder	
Name Of Registered Owner	HENG BEE & CO
Co Reg No	B04493300B
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-98554565
Vehicle Particulars	
Manufacturer	NISSAN
Model	NV350-2.5 D PANEL VAN (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800098433-01
Cover Note Number	
Driver	
Name of Driver	LOO HUI CHI
NRIC No	S1304856H
Date Of Birth	10/07/1958
Occupation	OUTDOOR
Date Of Driving Pass	09/07/1982
Driving Experience	37 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98554565
Fax Number	
Contact Number	
EMail Address	STEPHEN_1007@HOTMAIL.COM

Address	377 UPPER ALJUNIED ROAD
Postcode	367862
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER THE ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBB3923H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	TEW TAI KUAYE
NRIC/Passport Number	
Contact Number	98242568
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

Vehicle No: GRD 3120Y

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

 **恒美公司**
Heng Bee & Company
No. 377, Upper Aljunied Road
Singapore 367602
Tel: 6285 2476

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

(A) My Vehicle No: GBO 3120Y

Accident Location: GATE 3, 63 ALEXANDRA TERRACE

Accident Date: 16/9/19

Time: 10.30 am/pm

- Brief Details Of Accident -

A white lorry (G8B3923H) reversed out from the carpark and hit against the rear of my van, it moved forward and reversed again and hit the rear of my van again. The hit twice caused damages to the left rear of my van, the left rear side light is now broken. The driver, Mr Teo Tai Kuay, offered a \$300/- settling fee which I do not accept and I decided to report to insurance.

- Other Vehicle Involve Details -

(B) Veh No: G8B 3923H Hp: 98242568 Pax: Driver Name: TEW TAI KUAYE

(C) Veh No: Hp: Pax: Driver Name: (S0418855R)

DECLARATION 恒美公司

We declare the foregoing particulars are true in every respect.
 No. 377, Upper Selegie Road
 Singapore 367862
 Tel: 6235 3478

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No:

JWG INTERNATIONAL PTE. LTD.

Co. & GST Reg. No.: 201837488H

Blk 10, Ang Mo Kio Ind Park 2A,

#03-08 AMK AutoPoint,

Singapore 568047

H/P: 9069 7882 Fax: 6909 9592

E-Mail: jwg.claims@yahoo.com

DATE : 18/11/19

VEHICLE NO : GBD 3120 Y
MODEL : NISSAN NV350
CHASSIS NO : JN1MC2E26Z0002963

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER / OR	1	\$ -	\$ 900.75 -
2	REAR BUMPER SIDE RETAINER LH / OR	1	\$ -	\$ 68.00 -
3	REAR BUMPER BRACKET LH X NAI	1	\$ -	\$ 88.00 -
4	REAR BUMPER BEAM X NAI	1	\$ -	\$ 153.40 -
5	REAR FENDER LH / OR	1	\$ -	\$ 2370.00 -
6	REAR FENDER INNER PANEL LH X NAI	1	\$ -	\$ 504.00 -
7	REAR WHEEL HOUSING LH X NAI	1	\$ -	\$ 554.00 -
8	REAR END PANEL X NAI	1	\$ -	\$ 158.40 -
9	REAR END PANEL SIDE PANEL LH X NAI	1	\$ -	\$ 964.80 -
10	REAR FENDER AIR DUCT LH X NAI	1	\$ -	\$ 75.30 -
11	TAILLAMP LH / OR	1	\$ -	\$ 419.60 -
12	TAILLAMP PANEL LH X NAI	1	\$ -	\$ 232.00 -
13	TAILLAMP CLIPS LH X NAI	1	\$ -	\$ 10.00 -
14	REAR BOOTLID X NAI	1	\$ -	\$ 2090.00 -
15	REAR BOOTLID EMBLEM - NV350 X NAI	1	\$ -	\$ 75.00 -
16	REAR BOOTLID EMBLEM - URVAN X NAI	1	\$ -	\$ 75.00 -
17	REAR BOOTLID LOGO X NAI	1	\$ -	\$ 75.00 -
18	REAR BOOTLID CENTER CHROME X NAI	1	\$ -	\$ 385.00 -

TOTAL PRICE \$ 9198.25 -
LESS 10% \$ -
SUB TOTAL PRICE \$ 8278.425

667.20 /
44.20 /

Parts \$3,758.35
Less 10% \$3,382.51
224.80 /

3306.20
-10%
2975.58

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE X NAI	1	\$ 80.00	\$ 80.00
2	REAR BOOTLID STICKER - 6 PAX X NAI	1	\$ 50.00	\$ 50.00
3	REAR BOOTLID STICKER - 70KM/H X NAI	1	\$ 50.00	\$ 50.00
4	REVERSE SENSOR X NAI	1	\$ 250.00	\$ 250.00
5	REAR END PANEL SEALANT X NAI	1	\$ 100.00	\$ 100.00
6	SPARE WHEEL PANEL SEALANT X NAI	1	\$ 100.00	\$ 100.00

7	REAR BUMPER CLIPS / MC	1	\$ 100.00	\$ 100.00
8	REAR FENDER COWLING CLIPS X NAI	1	\$ 100.00	\$ 100.00
9	REAR FENDER INNER TRIM CLIPS X NAI	1	\$ 100.00	\$ 100.00
10	BOOTLID INNER TRIM CLIPS X NAI	1	\$ 100.00	\$ 100.00
11	REAR END PANEL TOP GARNISH CLIPS X NAI	1	\$ 100.00	\$ 100.00

TOTAL \$ 1,130.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,600.00	800
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	500
3	TUFF COAT	\$ 250.00	30
4	WIRING CHECK	\$ 180.00	30
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	20
6	TO RNR REAR WINDSCREEN TO ASSIST WORK LOAD	\$ 250.00	X
7	TO RNR REAR BOOT MECHANISM TO ASSIST WORK LOAD	\$ 200.00	X
8	TO CHECK WHEEL ALIGNMENT	\$ 150.00	X
9	TO CHECK WIRING LAYOUT AND TAILLAMP FUNCTION	\$ 80.00	X
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 250.00	X

TOTAL \$ 4,440.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 1,130.00
TOTAL LABOUR COST : \$ 4,440.00
TOTAL REPAIR COST : \$ 5,570.00

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

KELVIN WO

KELVIN WO
HP 9069 7882

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

WHL Pm L
Steve (LKK) 20/11/19, 11.30 am
8312 8813 5 cky 5
13148.436 L/S, Ry AC sy

P-2975-58
N-30
L-1380
4385-58
L/S-3508-46
= 3500

30 ✓
S/N \$100.00
30 ✓

Labour \$1380.00
Total \$4,862.51
L/S \$3,890.00
≈ \$3,850.00

1380

JWG INTERNATIONAL PTE. LTD.

Co. & GST Reg. No.: 201837488H

Blk 10, Ang Mo Kio Ind Park 2A,

#03-08 AMK AutoPoint,

Singapore 568047

H/P: 9069 7882 Fax: 6909 9592

E-Mail: jwg.claims@yahoo.com

DATE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

VEHICLE NO : GBD 3120 Y
MODEL : NISSAN NV350
CHASSIS NO : JN1MC2E26Z0002963

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER / OK	1	\$ -	\$ 900 -
2	REAR BUMPER SIDE RETAINER LH / OK	1	\$ -	\$ -
3	REAR BUMPER BRACKET LH X	1	\$ -	\$ -
4	REAR BUMPER BEAM X	1	\$ -	\$ -
5	REAR FENDER LH / OK	1	\$ -	\$ -
6	REAR FENDER INNER PANEL LH X	1	\$ -	\$ -
7	REAR WHEEL HOUSING LH X	1	\$ -	\$ -
8	REAR END PANEL X	1	\$ -	\$ -
9	REAR END PANEL SIDE PANEL LH X	1	\$ -	\$ -
10	REAR FENDER AIR DUCT LH X	1	\$ -	\$ -
11	TAILLAMP LH / OK	1	\$ -	\$ -
12	TAILLAMP PANEL LH X	1	\$ -	\$ -
13	TAILLAMP CLIPS LH X	1	\$ -	\$ -
14	REAR BOOTLID X	1	\$ -	\$ -
15	REAR BOOTLID EMBLEM - NV350 X	1	\$ -	\$ -
16	REAR BOOTLID EMBLEM - URVAN X	1	\$ -	\$ -
17	REAR BOOTLID LOGO X	1	\$ -	\$ -
18	REAR BOOTLID CENTER CHROME X	1	\$ -	\$ -

TOTAL PRICE \$ -
LESS 10% \$ -
SUB TOTAL PRICE \$ -

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE X	1	\$ 80.00	\$ 80.00
2	REAR BOOTLID STICKER - 6 PAX X	1	\$ 50.00	\$ 50.00
3	REAR BOOTLID STICKER - 70KM/H X	1	\$ 50.00	\$ 50.00
4	REVERSE SENSOR X	1	\$ 250.00	\$ 250.00
5	REAR END PANEL SEALANT X	1	\$ 100.00	\$ 100.00
6	SPARE WHEEL PANEL SEALANT X	1	\$ 100.00	\$ 100.00

7	REAR BUMPER CLIPS / MC	1	\$ 100.00	\$ 100.00
8	REAR FENDER COWLING CLIPS X	1	\$ 100.00	\$ 100.00
9	REAR FENDER INNER TRIM CLIPS X	1	\$ 100.00	\$ 100.00
10	BOOTLID INNER TRIM CLIPS X	1	\$ 100.00	\$ 100.00
11	REAR END PANEL TOP GARNISH CLIPS X	1	\$ 100.00	\$ 100.00

TOTAL \$ 1,130.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,600.00	800
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	500
3	TUFF COAT	\$ 250.00	30
4	WIRING CHECK	\$ 180.00	30
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	20
6	TO RNR REAR WINDSCREEN TO ASSIST WORK LOAD	\$ 250.00	X
7	TO RNR REAR BOOT MECHANISM TO ASSIST WORK LOAD	\$ 200.00	X
8	TO CHECK WHEEL ALIGNMENT	\$ 150.00	X
9	TO CHECK WIRING LAYOUT AND TAILLAMP FUNCTION	\$ 80.00	X
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 250.00	X

TOTAL \$ 4,440.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 1,130.00
TOTAL LABOUR COST : \$ 4,440.00
TOTAL REPAIR COST : \$ 5,570.00

WHL RNL
Steve (LKK) 20/11/19, 11.30 am
8322 8813 5 days
L/S, Ry AC SJ

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

KELVIN WO

KELVIN WO
HP 9069 7882

TAN CHONG MOTOR SALES PTE. LTD.

911, BUKIT TIMAH ROAD

SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4594091
REFERENCE : INS/IC/2HR/0484/2019
DATE : 07-OCT-2019

Keep
REC

NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

73 BRAS BASAH ROAD #05-01

NTUC TRADE UNION HOUSE

S(189556)

TEL : 65947060

FAX : 63381504

ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : M/S HENG BEE & CO
ADDRESS : 377 UPPER ALJUNIED ROAD

S(367862)

TELEPHONE NO :

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

~~CAR AT WORKSHOP~~ / CAR NOT AT WORKSHOP

KINDLY REVERT TO ME ASAP

EMAIL : zuhri@tanchong.com

OFFICE : 67038916 FAX : 64697472

7.10.2019
15.10.2019

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-GBD3923H
VEHICLE NO : GBD3120Y
MODEL CODE : MVL2RDRE26KW3GBR-D
MODEL/YEAR : NISSAN NV350 PANEL VAN MT EURO 5
ENGINE NO : YD25354917A
CHASSIS NO : JN1MC2E26Z0002963
MILEAGE : 1 KM
DATE IN : 07/10/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 16/09/2019

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

X

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO GBD3120Y

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RPI	PERFORM RUST PROOFING & TREATMENT FOR 2X AFFECTED PANEL	120.00	60
2 RSI	R/INSTALL REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	/
3 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	50.00	X
4 ZZ/001	CHECK LIGHTING	48.00	/
5 ZZ/002	REPAIR RR END PANEL, RR FENDER LH SIDE & TAILGATE RENEW RR BUMPER COVER	980.00	420
6 ZZ/003	S/PAINT RR BUMPER, TAILGATE, RR FENDER LH SIDE RR END PANEL	1000.00	750
TOTAL LABOUR CHARGES		2253.00	

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

X

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBD3120Y

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS
1	70KM/H / <i>APC</i>	70KM/H		9.00
2	EMBLEM-REAR / <i>APC</i>	90890-JX00A	64.90	
3	EMBLEM-BACK DOO / <i>APC</i>	90892-3XY0A	64.90	
4	EMBLEM-BACK DOO / <i>APC</i>	90890-3XY0A	110.00	
5	LAMP COMB RR, LH / <i>BR</i>	26555-3XA0B	224.80	
6	CLIP(1.3X10) / <i>APC</i>	01553-05933	13.00	
7	FACE-RR BUMPER / <i>BR</i>	85022-3XA0A	667.20	
8	SUNDRIES	NPN		40.00 <i>20</i>
SUB TOTAL			1144.80	0.00 49.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			228.96	0.00 0.00
GRAND TOTAL			915.84	0.00 49.00
OVERALL TOTAL			964.84	

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO GBD3120Y

TOTAL LABOUR CHARGES	2253.00
TOTAL SPARE PARTS CHARGES	964.84
GRAND TOTAL	3217.84 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	STEVE (LKK)
SURVEYED DATE	:	15/10/19
AUTHORIZED DATE	:	5 dly
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	PIP

Ry BEL smy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19018160/Etf3e2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 13-12-2019



ATTN : HUEY HUEY

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBB 3923H	Veh. Inspected	GBD 3120Y
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1062604-002	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	15/10/2019

2. Vehicle Particulars & Condition

Make & Model	NISSAN NV350	c.c	2488
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JN1MC2E26Z0002963	Colour	GREY
Odometer	136289 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/80 R15	YOKOHAMA	5 mm
L/H Front Tyre	195/80 R15	YOKOHAMA	5 mm
R/H Rear Tyre	195/80 R15	YOKOHAMA	5 mm
L/H Rear Tyre	195/80 R15	YOKOHAMA	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	16/09/2019	Inspect Date / Time	20/11/2019 (11:24 AM)
Survey held at	JWG INTERNATIONAL PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A #03-08 AMK AUTOPOINT SINGAPORE 568047		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 3120Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	BROKEN	900.75	667.20
1	REAR BUMPER SIDE RETAINER LH	BROKEN	68.00	44.20
1	REAR BUMPER BRACKET LH	NOT NECESSARY	88.00	-
1	REAR BUMPER BEAM	NOT NECESSARY	153.40	-
1	REAR FENDER LH	DENTED	2,370.00	2,370.00
1	REAR FENDER INNER PANEL LH	NOT NECESSARY	504.00	-
1	REAR WHEEL HOUSING LH	NOT NECESSARY	554.00	-
1	REAR END PANEL	NOT NECESSARY	158.40	-
1	REAR END PANEL SIDE PANEL LH	NOT NECESSARY	964.80	-
1	REAR FENDER AIR DUCT LH	NOT NECESSARY	75.30	-
1	TAILLAMP LH	BROKEN	419.60	224.80
1	TAILLAMP PANEL LH	NOT NECESSARY	232.00	-
1	TAILLAMP CLIPS LH	NOT NECESSARY	10.00	-
1	REAR BOOTLID	NOT NECESSARY	2,090.00	-
1	REAR BOOTLID EMBLEM - NV350	NOT NECESSARY	75.00	-
1	REAR BOOTLID EMBLEM - URVAN	NOT NECESSARY	75.00	-
1	REAR BOOTLID LOGO	NOT NECESSARY	75.00	-
1	REAR BOOTLID CENTER CHROME	NOT NECESSARY	385.00	-
	LESS 10% DISCOUNT		-919.83	-330.62
			8,278.42	2,975.58
SPECIAL NETT ITEMS				
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	80.00	-
1	REAR BOOTLID STICKER - 6PAX (SN)	NOT NECESSARY	50.00	-
1	REAR BOOTLID STICKER - 70KM/H (SN)	NOT NECESSARY	50.00	-
1	REVERSE SENSOR (SN)	NOT NECESSARY	250.00	-
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	100.00	-
1	SPARE WHEEL PANEL SEALANT (SN)	NOT NECESSARY	100.00	-
1	REAR BUMPER CLIPS (SN)	NECESSARY	100.00	30.00
1	REAR FENDER COWLING CLIPS (SN)	NOT NECESSARY	100.00	-
1	REAR FENDER INNER TRIM CLIPS (SN)	NOT NECESSARY	100.00	-

Report Ref No. CS/INC19018160/Etf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOTLID INNER TRIM CLIPS (SN)	NOT NECESSARY	100.00	-
1	REAR END PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	100.00	-
			1,130.00	30.00
	LABOUR			
	PANEL BEATING, REMOVAL AND REPLACING PARTS.		1,600.00	800.00
	TO SPRAY PAINT AFFECTED AREA.		1,400.00	500.00
	TUFF COAT.		250.00	30.00
	WIRING CHECK.		180.00	30.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		80.00	20.00
	TO RNR REAR WINDSCREEN TO ASSIST WORK LOAD.	NOT NECESSARY	250.00	-
	TO RNR REAR BOOT MECHANISM TO ASSIST WORK LOAD.	NOT NECESSARY	200.00	-
	TO CHECK WHEEL ALIGNMENT.	NOT NECESSARY	150.00	-
	TO CHECK WIRING LAYOUT AND TAILLAMP FUNCTION.	NOT NECESSARY	80.00	-
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS RESET MEMORIES TO SPECIFICATION ETC.	NOT NECESSARY	250.00	-
			4,440.00	1,380.00
	GRAND TOTAL		13,848.42	4,385.58
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			3,500.00

Report Ref No. CS/INC19018160/Etf3e2

CHEN TSUE YEE

Automotive Assessor

K.K. LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.