

21/10/2019

ASS. REC. BY:

REF:

CS/INC 19018161/EV312

Special Instruction:

Surveyor: Steve

ASSIGNMENT (Office)

From (Person): Theresa Vimala

of

INC

Date/Time: 15 October 2019

Estimated Cost:

Bill to:

OD/BS/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SCG 61280

Insured: SKZ 7039B

at Workshop m/s Tan Chong Motor Sales Pte Ltd

Tel: 6703 8916

of 913 Bukit Timah Road

Policy No:

Claim No: MT/1039149-002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 22/08/2019

"wp"

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 15/10/2019 @ 02:45pm

Person Contacted: Zubri

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SCG 61280 NA/INC 19018161/24 DCA 22/08/2019
	SKZ 7039B: NA/INC 19018161/24 DCA 22/08/2019
20/11/19	@ 1228pm Zubri said vehicle has not send in for repair
23/1/2020	To re-open and submit final report - \$1494.96

Pls pass to typist, after re-open

23/1/2020

23/1/20 reopen ref only, let close date 5/2/19


Surveyor Stere REF: _____

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 5CG 61280 Yr Regn: 30/5/17
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or 1997
 Make: NISSAN Qashqai c.c. 1497
 Colour Grey A/C: Insured / Std / NI / NA
 Sp. Reading 62672 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/N: SJNFBAJ1141945450
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modl: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 225/45R19
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front 5 mm Rear 5 mm
 R/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 22/8/19 D.O.I. 15/10/19 1312pm
 Survey held at Tan Chy, Bukit Timah
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

23/1/20 MV 81K
Finalize \$1494.96, 3 days (Zuhri) (Red 919.28, 389)
 RECEIVED 25 NOV 2019

Date/Time, File Pass to? ☒ : Proll. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) 25/11 - typist

Report Format :

Lump Sum / I.B.I. (\$) _____

Days Of Repair: 3

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech Invs (\$)
☐ : Weekend (\$)

Survey Fee: _____

Transportation: _____

) \$ + RS. - SI

) Photos

) Others

TOTAL

240

240

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/ZHR/0448/2019
DATE : 13-SEP-2019

NTUC INCOME INSURANCE CO-OPERATIVE LIMITED
73 BRAS BASAH ROAD #05-01
NTUC TRADE UNION HOUSE
S(189556)
TEL : 65947060
FAX : 63381504
ATTN: MOTOR CLAIM MANAGER

OWNER'S NAME : MR TAN YOKE HONG (CHEN YUFENG)
ADDRESS : 2B HONG SAN WALK
#13-08
S(689048)
TELEPHONE NO : 97822985

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TPSK27039B
VEHICLE NO : SCG6128D
MODEL CODE : FDRARBEJ11EWAFJJ-
MODEL/YEAR : NISSAN QASHQAI 2.0
ENGINE NO : MR20457488W-J11WW
CHASSIS NO : SJNFBAJ11U1945450
MILEAGE : 1 KM
DATE IN : 13/09/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 13/09/2019

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

CAR AT WORKSHOP / CAR NOT AT WORKSHOP

KINDLY REVERT TO ME ASAP

EMAIL : zuhri@tanchong.com

OFFICE : 67038916 FAX : 64697472

13.09.19

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SCG6128D

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RSI	R/INSTALL OR RENEW REVERSE SENSOR, NECS ADJUSTMENT FUNCTION TEST	110.00	/
2	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	50.00	X
3	ZZ/001	CHECK LIGHTING	48.00	/
4	ZZ/002	REPAIR RR END PANEL & RENEW RR BUMPER	560.00	280
5	ZZ/003	S/PAINT RR END PANEL & RR BUMPER (2 TONE)	600.00	350
TOTAL LABOUR CHARGES			1368.00	

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SCG6128D

S/NO PARTS DESCRIPTION		PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
			NETT	LIST	S/NETT	
1	SENSOR ASSY	28438-HV03A			232.00	? X NN
2	SUNDRIES	NPN			50.00	20 / MC
3	BRACKET-BUMPER RH	85220-4EA0A	38.90			? X NN
4	BRACKET-BUMPER LH	85221-4EA0A	38.90			? X NN
5	FINISHER-REAR B	85071-4EA0A	18.80			X NN
6	CLI(1.3X10)	01553-05933	13.00			/ MC
7	CANOE RIVET(7.1X2)	76882-0M000	14.20			/ MC
8	CLIP(8X3)	85284-JD00A	24.00			/ MC
9	CROMMET(2.7X4)	63846-3V000	10.80			/ MC
10	FASCIA-RR BUMP	85022-4EA0H	796.70			/ CAT
SUB TOTAL			955.30	0.00	282.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			191.06	0.00	0.00	
GRAND TOTAL			764.24	0.00	282.00	
OVERALL TOTAL			1046.24			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SCG6128D

TOTAL LABOUR CHARGES	1368.00
TOTAL SPARE PARTS CHARGES	1046.24
GRAND TOTAL	2414.24 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	Steve (LKK)
SURVEYED DATE	:	15/10/19
AUTHORIZED DATE	:	3 dy
EXCESS CLAUSE	:	P/P
LIABILITY	:	Ry BCL Sp
REMARKS	:	

LKK Auto Consultants hence notify
the Repairer of the following:

- * To resurvey before/after spray painting
- * To display damaged part(s) during resurvey
- * Parts prices are subject to confirmation
- * Third party survey is on a "Without Prejudice" basis
- * No illegal modification(s) is allowed
- * Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PLS NOTE : This estimate is based on visual inspection of the
affected vehicle. Should we require further labour
charges & spare parts in the process of repairs, we
shall inform you accordingly.

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/2HR/0448/2019
DATE : 13-SEP-2019

DS => Steve

NTUC INCOME INSURANCE CO-OPERATIVE LIMITED
73 BRAS BASAH ROAD #05-01
NTUC TRADE UNION HOUSE
S(189556)
TEL : 65947060
FAX : 63381504
ATTN: MOTOR CLAIM MANAGER

ZHR

OWNER'S NAME : MR TAN YOKE HONG (CHEN YUFENG)
ADDRESS : 2B HONG SAN WALK
#13-08
S(689048)
TELEPHONE NO : 97822985

Recommend Repair

3 Pays

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TPSK27039B
VEHICLE NO : SCG6128D
MODEL CODE : FDRARBZJ11EWAFJJ-
MODEL/YEAR : NISSAN QASHQAI 2.0
ENGINE NO : HR20457488W-J11WW
CHASSIS NO : SJNFBAJ11U1945450
MILEAGE : 1 KM
DATE IN : 13/09/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 13/09/2019

L0/R = \$110 x 3 days

= \$330 + GST

= \$353.10

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SCG6128D

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RSI	R/INSTALL OR RENEW REVERSE SENSOR, NECS ADJUSTMENT FUNCTION TEST	110.00	110.00 /
2 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	50.00	.00
3 ZZ/001	CHECK LIGHTING	48.00	48.00 /
4 ZZ/002	REPAIR RR END PANEL & RENEW RR BUMPER	560.00	280.00 /
5 ZZ/003	S/PAINT RR END PANEL & RR BUMPER (2 TONE)	600.00	350.00 /
TOTAL LABOUR CHARGES		1368.00	788.00

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SCG6128D

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
		NETT	LIST	S/NETT	
1 SENSOR ASSY	28438-HV03A			232.00	X
2 SUNDRIES	NPN			20.00	OK /
3 BRACKET-BUMPER RH	85220-4EA0A	38.90			X
4 BRACKET-BUMPER LH	85221-4EA0A	38.90			X
5 FINISHER-REAR B	85071-4EA0A	18.80			X
6 CLI(1.3X10)	01553-05933	13.00			OK /
7 CANOE RIVET(7.1X2)	76882-0M000	14.20			OK /
8 CLIP(8X3)	85284-JD00A	24.00			OK /
9 CROMMET(2.7X4)	63846-5V000	10.80			OK /
10 FASCIA-RR BUMP	85022-4EA0H	796.70			OK /
SUB TOTAL		858.70	0.00	20.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		171.74	0.00	0.00	
GRAND TOTAL		686.96	0.00	20.00	
OVERALL TOTAL		706.96			✓

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SCG6128D

NETT ITEM	858.70
LESS 20.00%)	-171.74
NETT AMOUNT	686.96

LIST ITEM	0.00
LESS 30.00%)	0.00
LIST AMOUNT	0.00

SPECIAL NETT ITEM	20.00
LESS .00%)	0.00
SPECIAL NETT AMOUNT	20.00

TOTAL LABOUR CHARGES	788.00
TOTAL SPARE PARTS CHARGES	706.96

TOTAL CHARGES	1494.96
ADD 7 % GST	104.65

GRAND TOTAL	1599.61
-------------	---------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref : CS/INC19018161/Evf3e2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date : 04-12-2019

189556

ATTN : HELENA

Code : INC

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	SKZ 7039B	Veh. Inspected	SCG 6128D
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1059149-002	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	15/10/2019

2. Vehicle Particulars & Condition

Make & Model	NISSAN QASHQAI	c.c	1997
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	SJNFBAJ11U1945450	Colour	GREY
Odometer	62672	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R19	BRIDGESTONE	5 mm
L/H Front Tyre	225/45 R19	BRIDGESTONE	5 mm
R/H Rear Tyre	225/45 R19	BRIDGESTONE	5 mm
L/H Rear Tyre	225/45 R19	BRIDGESTONE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	22/08/2019	Inspection Date	15/10/2019
Survey held at	913 BUKIT TIMAH ROAD		
Repairer	TAN CHONG MOTOR SALES PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCG 6128D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BRACKET-BUMPER RH (N)	NOT NECESSARY	38.90	-
1	BRACKET-BUMPER LH (N)	NOT NECESSARY	38.90	-
1	FINISHER-REAR B (N)	NOT NECESSARY	18.80	-
10	CLI @\$1.30 (N)	NECESSARY	13.00	13.00
2	CANOE RIVET @\$7.10 (N)	NECESSARY	14.20	14.20
3	CLIP @\$8.00 (N)	NECESSARY	24.00	24.00
4	CROMMET @\$2.70 (N)	NECESSARY	10.80	10.80
1	FASCIA-RR BUMP (N)	CUT	796.70	796.70
	LESS 20% DISCOUNT		-191.06	-171.74
			764.24	686.96
SPECIAL NETT ITEMS				
1	SENSOR ASSY (SN)	NOT NECESSARY	232.00	-
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
			282.00	20.00
LABOUR				
	R/INSTALL OR RENEW REVERSE SENSOR, NECS ADJUSTMENT FUNCTION TEST.		110.00	110.00
	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA.	NOT NECESSARY	50.00	-
	CHECK LIGHTING.		48.00	48.00
	REPAIR RR END PANEL & RENEW RR BUMPER.		560.00	280.00
	S/PAINT RR END PANEL & RR BUMPER (2 TONE).		600.00	350.00
			-	-
			-	-
			-	-
			-	-
			1,368.00	788.00
GRAND TOTAL			2,414.24	1,494.96
RECOMMENDED COST OF REPAIRS (CONFIRMED)				1,494.96

Report Ref No. CS/INC19018161/Evf3e2



Report Ref No. CS/INC19018161/Evf3e2

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.