

ASS. REC. BY:

REF: CS/INC1901869/T2sf302 Special Instruction:

Surveyor: TaufikASSIGNMENT (Office)From (Person): Theresa Vimala of INC Date/Time: 15 October 2019

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLD 39252 Insured: SW 7966Cat Workshop m/s Ban Chuan Motor Works Tel: 62641191of 3 Pioneer Road North #01-14/15Policy No: _____ Claim No: MT/1066803-001

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 7/10/2019

(Client's Record)

"up"

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 15/10/2019 @ 02:09pm Person Contacted: Pertin Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SLD 39252 x</u>
	<u>SW 7966C CC6/A2G11003694/A434292 DOA 24/10/2019</u>

Tanji

REF: INC

ASS. REG. BY:

ASSIGNMENT

From: _____ Date: 15.10.2019

Estimated Cost: _____

CD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLD 39252

at Workshop m/s: Ban Chuan Motor

of 3 Pioneer Road North #01-14/15

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

N/S	O/S

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR. Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLD 39252 Yr Regn: 2016 / June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda Vezel c.c. 1496

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 88245 T/Radio: Insured / Std / NI / NA

Eng/No: 88445

C/No: R4 11110137

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size: F: 2.5/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front: _____ Rear: C

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 15/10/2019 4pm

Survey held at Ban Chuan

Des. of Damages: Frt Rest / O/S / N/S / UIC / Rooftop or +.

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

23/10/19 Confirmed HS \$ 4,600/- @ 6 days with Tanji
(\$ 3,899.42 Ret - 46%)

RECEIVED 23 OCT 2019

23/10/2019

Date/Time, File Pass to?

23/10/19

1) Typist

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.R. / : 4,600/- HS

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs 15

☐ Weekend 15

Survey Fee:

Transportation:

3 + RS. \$

Photos

Covers

TOTAL

250

Summer Lee (LKK Auto)

From: Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>
Sent: Wednesday, 16 October, 2019 9:07 AM
To: assignments
Subject: RE: TP CASES FARMED OUT TO LKK ON 15/10/2019

Hi Lkk, here is the list of the OIC names etc...

With Regards

Theresa Vimala
Senior Administrator
Motor Insurance
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

Find out more at Income.com.sg/careers

in with you

From: Theresa Vimala D/O Balagangadharan
Sent: Tuesday, 15 October 2019 10:07 AM
To: assignments <assignments@lkkauto.com>
Cc: Teng Ken Leong <kenleong.teng@income.com.sg>; Thio Tse Kiat <tsekiat.thio@income.com.sg>; Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>
Subject: RE: TP CASES FARMED OUT TO LKK ON 15/10/2019

Dear LKK,

Please assist to survey the following vehicles .

SN	OIC	Claim No.	Survey Date	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	SERENE	MT/1066803-001	15/10/2019	SLD39752	BAN CHOON MOTOR WORKS	3 PIONEER ROAD NORTH #01-14/15 SINGAPORE 628457	Perlin / 62641191		51W7966C	7/10	
2	CHARLOTTE	MT/1064715-002	15/10/2019	GY8801M	MOTORWAY CAR CARE CENTRE PTE LTD	1094 LOWER DELTA ROAD MOTORWAY BUILDING SINGAPORE 169205	Annie Tew / 6571 9642	10-00-12:00	SKQ8849X	30/9	
3	JEFF	MT/1064107-002	15/10/2019	XE4320P	VFIX AUTO PTE LTD	26 CHIA PING ROAD SINGAPORE 619977	Weng Sheng / 6455 2957	14:00-16:00	SIH7384K	26/9	Owner waiting
4	JEFF	MT/1066455-002	15/10/2019	51W7856L	AUTO INSURE PTE LTD	6 MARSILING LANE	Sam Goh / 9743 6363		51V9804D	11/10	
5	DAVID	MT/1066634-001	15/10/2019	5LN3940B	AUTO INSURE PTE LTD	6 MARSILING LANE	Geraldine Lim / 9743 6363		SGR6525K	10/10	
6	HELENA	MT/1059149-002	15/10/2019	SCG6128D	TAN CHONG MOTOR SALES PTE LTD	913 BUKIT TIMAH ROAD SINGAPORE 589623	ZUHRI / 67038916	10-00-12:00	SKZ7039B	22/8	Owner waiting
7	HUEY HUEY	MT/1062604-002	15/10/2019	GBD3120V	TAN CHONG MOTOR SALES PTE LTD	913 BUKIT TIMAH ROAD SINGAPORE 589623	ZUHRI / 67038916	10-00-12:00	GBB3923H	16/9	Owner waiting

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

With Regards

Theresa Vimala
Senior Administrator
Motor Insurance
T +65 6430 7898
www.income.com.sg

income
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Business
Owner ID: 132A

Vehicle Details

Vehicle No.: SLD3925Z
Vehicle to be Exported: Yes
Intended Deregistration Date: 31 Oct 2019
Vehicle Make: HONDA
Vehicle Model: VEZEL 1.5X A
Primary Colour: White
Manufacturing Year: 2015
Engine No.: L15B4030139
Chassis No.: RU11110137
Maximum Power Output: 96.0 kW (128 bhp)
Open Market Value: \$20,106.00
Original Registration Date: 15 Jun 2016
First Registration Date: 15 Jun 2016
Transfer Count: 0
Actual ARF Paid: \$10,149.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 14 Jun 2026
PARF Rebate Amount: \$7,611.00

Intended COE Rebate Details

COE Expiry Date: 14 Jun 2026
COE Category: A - Car up to 1600cc & 97kW
(130bhp)
COE Period(Years): 10
QP Paid: \$47,020.00
COE Rebate Amount: \$31,137.00
Total Rebate Amount: \$38,748.00

The information contained herein is correct as at 16 Oct 2019

Business
Regn No
53329132A

OK

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Wednesday, 23 October 2019 4:14 pm
To: perlin
Cc: SUR
Subject: RE: SLD 3925 Z - Finalization

Dear Perlin,

Confirmed final fig \$ 4,600.00 (lump sum) @ 6 days of repairs

Kindly send Final invoice and all supporting documents to NTUC INCOME.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: perlin <banchoon@singnet.com.sg>

Sent: Tuesday, 22 October 2019 11:21 am

To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: SLD 3925 Z - Finalization

Dear Taufikh

Attached herewith are vehicle no. SLD 3925 Z revised and supplementary quotations together with after spray paint photos for your finalization.

Thanks & Regards.

Perlin

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/10/2019 11:32
Date Of Accident	07/10/2019 08:15
Exact Location Of Accident	SLE TOWARDS BKE (LP 331-329)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLD3925Z
Insured/Policyholder	
Name Of Registered Owner	RAMLAN BIN SANJAR
NRIC No	S2182683I 546X
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90671890
Alternative Phone No	OFFICE-90671890

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5091924181-02 (CLASSIC)
Cover Note Number	

Driver

Name of Driver	RAMLAN BIN SANJAR
NRIC No	S2182683I
Date Of Birth	27/02/1962
Occupation	INDOOR
Date Of Driving Pass	20/02/1991
Driving Experience	28 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90671890
Fax Number	
Contact Number	OFFICE-90671890
Email Address	NOEMAIL

Address	733 WOODLANDS CIRCLE #09-101
Postcode	S730733
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PAID DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACHED SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	SENT TO WORKSHOP
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJW7966C
Vehicle Make/Model/Colour	MIT LANCER
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	RAZIB
NRIC/Passport Number	
Contact Number	88350257 / 88927076
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

EDAC PUNTI LANCAR (P) LTD
611 Bukit Batok Street 23
Singapore 659445
Tel: 6560 0012 Fax: 6539 0722
Email: vachb@singnet.com.sg

- 9 DEC 2019



Policyholder's Signature

Date & Time: 9/10/19 11:45 am



Driver's Signature

(If driver is not the policyholder)

Date & Time: 9/10/19 11:45 am

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 7/10/19 at about 8:30am as I was travelling along SLE towards BKE, the car in front of me make an emergency brake. So in the event, I also have to make an emergency brake. However the car bhd me SJW 7966C did not manage to brake in time thus hitting the back of my car SLD 3925Z.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature

Date & Time: 7/10/19 1145 am



Driver's Signature

(If driver is not the policyholder)

Date & Time: 7/10/19 1145 am

IDAC (Singapore) Ltd.
511 Bukit Batok Street 21
Singapore 659543
Tel: 6500 2212 Fax: 6500 0722
Email: vecbb@singnet.com.sg

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



萬 春 摩 哆 BAN CHOON MOTOR WORKS

Blk 3, Pioneer Road North #01-14/15 Singapore 628457

Tel: 6264 1191 Fax: 6261 1324

E-mail: banchoon@singnet.com.sg

Business Reg./GST Reg. No. 351915/00A

GST Regn No. 35191500A

14/10/2019

NTUC Income Insurance Co-Operative Ltd
1 Maritime Square
#10-01 Harbourfront Centre
Singapore 099253

Attn: Motor Claims Dept.

Dear Sir/Madam

QUOTATION FOR REPAIRS OF VEHICLE NO. SLD 3925 Z

MODEL: HONDA VEZEL

DATE OF ACCIDENT: 07/10/2019

YOUR INSURED VEHICLE NO. SJW 7966 C

1 pc	Rear boot cover	\$	1,050.00	bt
1 pc	VEZEL emblem		43.00	re
1 pc	HONDA emblem		15.70	re
1 pc	Rear boot rubber		96.80	hi
1 pc	Rear windscreen inner seal		120.00	re
1 pc	Rear boot inner lock		157.10	bt
1 pc	Rear boot cardboard		253.40	de
2 pcs	Rear boot reflectors @ \$264.60 each		529.20	crs
2 pcs	Taillamps @ \$428.70 each		857.40	? ✓ crs
1 pc	Rear bumper		810.00	de
1 pc	Rear bumper lower garnish		190.00	? X un
2 pcs	Rear bumper side reflectors @ \$141.10 each		282.20	44-X 2H-cr
2 pcs	Rear bumper side retainers @ \$17.50 each		35.00	? X un
1 pc	Rear bumper undercover		195.00	? X un
1 pc	End panel		411.90	bt
1 pc	End panel top garnish		92.30	de
1 pc	Floor panel - p luo to *		668.80	Rx
1 pc	Cargo box		186.90	? X un
1 pc	Spare tyre top cardboard		206.20	X un
1 pc	Rear windscreen top moulding		120.00	re
		\$	6,320.90	
	Less: 20% discount		1,264.18	
		\$	5,056.72	
1 roll	Rear windscreen gum		40.00	SN re
1 pc	Rear number plate		35.00	SN X un
1 pc	Reverse sensors		280.00	SN 200 un

LABOUR CHARGES:

- To dismantle and reassemble of rear windscreen
- To dismantle and reassemble of petrol tank
- To knocking and straightening of all necessary damaged parts.
 - To changing of above part.
- To putty and spray painting on accident damaged parts.

120.00	✓	
100.00	x	nn
1,600.00	800	700
1,200.00	800	900
<u>\$ 8,431.72</u>		

Yours faithfully,

Reinhold

8499.72
[Signature]
16/10/19
Tauphin 97495749
UP
15/10/19 @ 4pm
Lump sum
Revery after repair
@ 6 days
Suo e l'habitat wu


LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



萬 春 摩 哆

BAN CHOON MOTOR WORKS

Blk 3, Pioneer Road North #01-14/15 Singapore 628457

Tel: 6264 1191 Fax: 6261 1324

E-mail: banchoon@singnet.com.sg

Business Reg./GST Reg. No. 35191500A

GST Regn No. 35191500A

14/10/2019

NTUC Income Insurance Co-Operative Ltd

1 Maritime Square

#10-01 Harbourfront Centre

Singapore 099253

Attn: Motor Claims Dept.

Dear Sir/Madam

QUOTATION FOR REPAIRS OF VEHICLE NO. SLD 3925 Z

MODEL: HONDA VEZEL

DATE OF ACCIDENT: 07/10/2019

YOUR INSURED VEHICLE NO. SJW 7966 C

1 pc	Rear boot cover	\$	1,050.00	bt
1 pc	VEZEL emblem		43.00	na
1 pc	HONDA emblem		15.70	na
1 pc	Rear boot rubber		96.80	twi
1 pc	Rear windscreen inner seal		120.00	na
1 pc	Rear boot inner lock		157.10	tl
1 pc	Rear boot cardboard		253.40	de
2 pcs	Rear boot reflectors @ \$264.60 each		529.20	cwa
2 pcs	Taillamps @ \$428.70 each		857.40	?
1 pc	Rear bumper		810.00	de
1 pc	Rear bumper lower garnish		190.00	7x
2 pcs	Rear bumper side reflectors @ \$141.10 each		282.20	LH-? 1KH-62
2 pcs	Rear bumper side retainers @ \$17.50 each		35.00	?
1 pc	Rear bumper undercover		195.00	?
1 pc	End panel		411.90	bt
1 pc	End panel top garnish		92.30	de
1 pc	Floor panel		668.80	de
1 pc	Cargo box		186.90	?
1 pc	Spare tyre top cardboard		206.20	x
1 pc	Rear windscreen top moulding		120.00	na
		\$	6,320.90	4697.90
	Less: 20% discount		1,264.18	939.56
		\$	5,056.72	3758.32
1 roll	Rear windscreen gum		40.00	SN
1 pc	Rear number plate		35.00	SN x
1 pc	Reverse sensors		280.00	SN 200nw

LABOUR CHARGES:

To dismantle and reassemble of rear windscreen
To dismantle and reassemble of petrol tank
To knocking and straightening of all necessary damaged parts.
To changing of above part.
To putty and spray painting on accident damaged parts.

Yours faithfully,

Patino

	120.00 ✓
	100.00 x
	1,600.00 700
	1,200.00 900
\$	<u>8,431.72</u>
	5718.32
	+ 66.00
	<u>5786.32</u>

Taughin 97495749
WP'

15/10/19 @ 4pm

Lumpsum

Recovery after repair

@ 6 days

Sure to be satisfied



萬 春 摩 哆

BAN CHOON MOTOR WORKS

Blk 3, Pioneer Road North #01-14/15 Singapore 628457

Tel: 6264 1191 Fax: 6261 1324

E-mail: banchoon@singnet.com.sg

Business Reg./GSTReg. No. 351915/00A

22/10/2019

NTUC Income Insurance Co-Operative Ltd
1 Maritime Square
#10-01 Harbourfront Centre
Singapore 099253

Attn: Motor Claims Dept.

Dear Sir/Madam

SUPPLEMENTARY QUOTATION FOR VEHICLE NO. SLD 3925 Z

MODEL: HOND VEZEL

DATE OF ACCIDENT: 0710/2019

YOUR INSURED VEHICLE NO. SJW 7966 C

1 pc Buzzer assy, smart
Less: 20% discount

\$	85.00
	17.00
\$	<u>68.00</u>

A. Cua

Yours faithfully,

Petindoxe




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT				
NTUC INCOME INSURANCE CO-OPERATIVE LTD		Ref: CS/INC19018169/T1sf3n2		
73 BRAS BASAH ROAD		Date: 24-10-2019		
#05-01 NTUC TRADE UNION HOUSESINGAPORE				
189556				
ATTN: SERENE		Code: INC		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJW 7966C	Veh. Inspected	SLD 3925Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	MT/1066803-001	Excess (\$)	0.00	
Assign From	THERESA VIMALA	Assign Date	15/10/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	RU11110137	Colour	WHITE	
Odometer	88245 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	SUMITOMO	6 mm	
L/H Front Tyre	215/60 R16	SUMITOMO	6 mm	
R/H Rear Tyre	215/60 R16	SUMITOMO	6 mm	
L/H Rear Tyre	215/60 R16	SUMITOMO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/10/2019	Inspect Date / Time	15/10/2019 (04:00 PM)	
Survey held at	BAN CHOON MOTOR WORKS 3 PIONEER ROAD NORTH #01-14/15 SINGAPORE 628457			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 3925Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT COVER	BENT	1,050.00	1,050.00
1	VEZEL EMBLEM	NECESSARY	43.00	43.00
1	HONDA EMBLEM	NECESSARY	15.70	15.70
1	REAR BOOT RUBBER	TWISTED	96.80	96.80
1	REAR WINDSCREEN INNER SEAL	NECESSARY	120.00	120.00
1	REAR BOOT INNER LOCK	BENT	157.10	157.10
1	REAR BOOT CARDBOARD	DEFORMED	253.40	253.40
2	REAR BOOT REFLECTORS @\$264.60	CRACKED	529.20	529.20
2	TAILLAMPS @\$428.70	CRACKED	857.40	857.40
1	REAR BUMPER	DEFORMED	810.00	810.00
1	REAR BUMPER LOWER GARNISH	NOT NECESSARY	190.00	-
2	REAR BUMPER SIDE REFLECTORS @\$141.10	O/S CRACKED / N/S NOT NECESSARY	282.20	141.10
2	REAR BUMPER SIDE RETAINERS @\$17.50	NOT NECESSARY	35.00	-
1	REAR BUMPER UNDERCOVER	NOT NECESSARY	195.00	-
1	END PANEL	BENT	411.90	411.90
1	END PANEL TOP GARNISH	DEFORMED	92.30	92.30
1	FLOOR PANEL	TO REPAIR SEE LABOUR	668.80	-
1	CARGO BOX	NOT NECESSARY	186.90	-
1	SPARE TYRE TOP CARDBOARD	NOT NECESSARY	206.20	-
1	REAR WINDSCREEN TOP MOULDING	NECESSARY	120.00	120.00
1	BUZZER ASSY,SMART (ADDITIONAL)	CRACKED	85.00	85.00
	LESS 20% DISCOUNT		-1,281.18	-956.58
			5,124.72	3,826.32
SPECIAL NETT ITEMS				
1	ROLL REAR WINDSCREEN GUM (SN)	NECESSARY	40.00	40.00
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	35.00	-
1	REVERSE SENSORS (SN)	NOT WORKING	280.00	200.00
			355.00	240.00

Report Ref No. CS/INC19018169/T1sf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO DISMANTLE AND REASSEMBLE OF REAR WINDSCREEN.		120.00	120.00
	TO DISMANTLE AND REASSEMBLE OF PETROL TANK.	NOT NECESSARY	100.00	-
	TO KNOCKING AND STRAIGHTENING OF ALL NECESSARY DAMAGED PARTS.TO CHANGING OF ABOVE PART.INCLUSIVE OF THE REPAIR OF FLOOR PANEL.		1,600.00	700.00
	TO PUTTY AND SPRAY PAINTING ON ACCIDENT DAMAGED PARTS.		1,200.00	900.00
			3,020.00	1,720.00
	GRAND TOTAL		8,499.72	5,786.32
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			4,600.00

Report Ref No. CS/INC19018169/T1sf3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.