22/03/2002 REF: CS MSG 19018172 /RGf 3 pecial Instruction: ASS. REC. BY: Survajor: Rosul ASSIGNMENT (Office) Date/Time: 15.10.19 14.04.10 From (Person); Choson Wom MS1G Estimated Cost: Bill to: OD TP WS TP RES Skt 4297x To Inspect Vehicle No: SFP 8496U Insured: at Workshop m/s ACe Autolution Tel: 68 441184 of 13 Kaki Butit Road 4, # 03-29/ Policy No: 29 120362 a my 608272 Claim No: Sum Insured: Excess: Make of Veh: D.O.A. 11.10.2019 (Client's Record) (upi) CA / REV / REP. / REV 24 HRS H.O.D. Endorsement: Date/Time: 15.10.19 1300.10 Anna Person Contacted: Vehicle IN OUT Date/Time Action/Instruction Estimate SKK 4297 X X SFP 8496U:X 10.20as informed churching wong, we are pending extinute from vegin Passel finalised with Anny is & 4300, 6 days. 1 verised to Chastina Wong via Mevimen.

# ...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Oct 2019 11:34		15 Oct 2019 14:02 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETA	ILS		[Created by	insurer]
Insured:	CHONG CHIN YONG (ZH	IANG JUNYONG), ID: S7625253	Z	
Main Claimant:		S1233170C		
Vehicle Reg. No.:	SFP8496U	Date of Loss:	11/10/2019 ( [ <b>118</b> Months Reg Date (Ma	and 8 Days From LTA
Claim Type:	ТР	Policy/Cover Note No.:	29120362QM Coverage: 13 12/05/2020	Y (Comprehensive) 1/05/2019 -
Vehicle Reg. No. (Insured):	SKK4297X	Policy No. (Claimant):		
		Excess:		
Repairer:	Ace Autolution Pte Ltd ( Bukit - Tel: 68441184	(KAKI BUKIT) 13 Kaki Bukit Road	4, #03-29/30 Bartley Biz	Centre, 417807 Kaki
Handling Insurer:	6643 1311]	pore) Pte. Ltd. (HQ) - Tel: +65 6		
Adjuster:	LKK Auto Consultants P	te Ltd (HQ) - Tel: 6256-3561 [	Imm.Advice due 16/	10/2019]
Driver/Custodian (Insured):	CHONG CHIN YONG (ZHAI	NG JUNYONG) () , NRIC: S76252	53Z Email:	
Adj Asg. Remarks:	on WP. Liab: clear. Agree 2134.	on SJE. Assign: LKK Auto Consulta	nts Pte Ltd. Contact: Anna	@ 6844 1184 / 9657
ASSOCIATED MAIL RECE	IVED		View All	Compose Case Mail
There are no mail for this cas	se.			
ALL ASSOCIATED TASKS  Due Date Priority 1  No results.	Type Task Group Subject		ch Tasks Create New Completed On Cr	Task   Complete reated On Done?

# Rasul (LKKAuto)

From:

Rasul (LKKAuto)

Sent:

Thursday, 19 December, 2019 9:37 AM

To:

admin@aceauto.com.sg

Subject:

SFP 8496U DOA: 11/10/19

Hi Anna,

As spoken, finalised amount of \$ 4300 / 6 days lump sum repair for this case is confirmed Kindly forward to me the resurvey after repair photos

Best Regards,

Rasul | Assessor

#### LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Save the Earth Print only when necessary

# Note: This document has not been finalised.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Pava Ubi Industrial Park Singapore 408933

Attn:

Christina Wong

Date:

19 Dec 2019

# **Preliminary Advice**

Insured Vehicle No : SKK4297X

TP Vehicle No

: SFP8496U

Accident Date

: 11/10/2019

Make

: TOYOTA ALLION

Assignment Date

: 15/10/2019

: 6.00

Date of Inspection

: 15/10/2019

Est. Duration of Repair

Inspection At

: ACE AUTOLUTION PTE LTD (KAKI BUKIT)

13 KAKI BUKIT ROAD 4, #03-29/30 BARTLEY BIZ CENTRE

SINGAPORE 417807

# Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,547.34
Revised Amount	:S\$	5,373.85
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,373.85
Lump Sum Repair	:S\$	4,300.00

#### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

#### Remarks

			9 9	-	100
1	The webiele	is economical/not	economical	for	renair
	 The vehicle	is economical/not	CCOHOHICAI	101	1 CPUII.

( X ) The above survey was conducted on a 'without prejudice' basis.

# Shiau Chan (LKKAuto)

From:

Do-Not-Reply <do-not-reply@merimen.com>

Sent:

Friday, 18 October 2019 10:20 AM

To:

do-not-reply@merimen.com

Cc:

SUR

Subject:

TP VEHICLE SFP 8496U (YOUR REF: 608272)

This mail is associated with: \*SFP8496U (608272) [SKK4297X]

TP

LIM PHECK LIAN
Oct 11 2019 9:00AM
[CHONG CHIN YONG (ZHANG JUNYONG)]
Ace Autolution Pte Ltd

Dear Christina,

Please be informed that we have inspected the vehicle SFP 8496U on 15/10/2019.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms) LKK Auto Consultants Pte Ltd Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by: SHIAU CHAN (LKK Auto Consultants Pte Ltd)

## > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Singapore NRIC	
Owner ID: Vehicle Details	099B	
Vehicle No.:	SFP8496U	
Vehicle to be Exported:	Yes	
Intended Deregistration Date:	02 Dec 2019	
Vehicle Make:	TOYOTA	
Vehicle Model:	ALLION 1.5 A	
Primary Colour:	Silver	
Manufacturing Year:	2008	
Engine No.:	1NZD334364	
Chassis No.:	NZT2603040409	
Maximum Power Output:	81.0 kW (108 bhp)	
Open Market Value:	\$18,819.00	
Original Registration Date:	03 Dec 2009	
First Registration Date:	03 Dec 2009	
Transfer Count:	1	
Actual ARF Paid: Intended PARF Rebate Details	\$11,373.00	
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	02 Dec 2019	
PARF Rebate Amount: Intended COE Rebate Details	\$5,686.00	
COE Expiry Date:	30 Nov 2024	
COE Category:	A - Car (1600cc & below)	
COE Period(Years):	5	
PQP Paid:	\$16,208.00	
COE Rebate Amount:	\$16,189.00	
Total Rebate Amount: Message	\$21,875.00	

its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 02 Dec 2019

ОК

33,000



10 Sin Ming Drive Singapore 575701 www.lta.gov.sg

19 Nov 2019

Our ref 1911190901N036157168

AUTOHAVEN PTE. LTD. 201 HENDERSON ROAD #06-05 APEX @ HENDERSON SINGAPORE 159545

երկլյալեկլյարկելուրիկ

Dear MR CHIA JIN YEE


#### RENEWAL OF CERTIFICATE OF ENTITLEMENT (COE) FOR VEHICLE NO. SFP8496U

We refer to your application on 19 Nov 2019 to renew COE for the above vehicle.

- You may be pleased to know that the COE for this vehicle has been renewed until 30 Nov 2024. Further COE renewal is not allowed. The vehicle will be deregistered when the COE expires on 30 Nov 2024.
- 3. The road tax for this vehicle will expire/has expired on 02 Dec 2019. Please renew the road tax promptly as it is an offence to use or keep a vehicle without valid road tax and insurance. Late renewal fee will be imposed if road tax is renewed after its expiry.
- Please visit www.onemotoring.com.sg for more vehicle-related information and services or contact our customer service officers on tel: 1800-CALL LTA (1800-2255 582) if you have any questions.


Yours sincerely

Assistant Registrar of Vehicles
Vehicle Quota & Registration Division
Land Transport Authority
[This is a computer-generated letter, no signature is required.]





Connect



sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, spo sgramar is the number one car classificas for parallel import cars, Toyota, Honda, Nessan, Pilesuppini or private are prentry or cars for sale, from varie, brocks, section cars, invaring tables, spot cars. Sulforwagens, SUV, MPV, Italchback, to COE cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & insurance. Find buy used Toyota Allion, Toyota Allion Singapore, used Toyota Allion, used vehicles Singapore or even buy used Toyota Allion Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sit for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current, sgCarMart.com does not assume any responsibility for errors or only ins or warrant the accuracy of this information.

Follow sgCarMart.com











©2004-2019 sgCarMart. All rights reserved.



#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver,
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aforesaid,	
	ACCIDENT STATEMENT
Date Of Report	11/10/2019 16:21
Date Of Accident	11/10/2019 08:50
Exact Location Of Accident	ALONG JALAN IBRAHIM EXIT 18(PIONEER ROAD)
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SFP8496U
Insured/Policyholder	
Name Of Registered Owner	LIM PHECK LIAN
NRIC No	S1233170C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96256899
Alternative Phone No	OTHERS-96256899
Vehicle Particulars	
Manufacturer	ТОУОТА
Model	ALLION 1.5 A (BI-FUEL)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5040626547-09
Cover Note Number	
Driver	
Name of Driver	LIM PHECK LIAN
NRIC No	S1233170C

 NRIC No
 \$1233170C

 Date Of Birth
 03/12/1957

 Occupation
 INDOOR

 Date Of Driving Pass
 23/01/1997

Driving Experience 22 YEARS AND 8 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-96256899

Fax Number

Contact Number OTHERS-96256899

EMail Address NOEMAIL

Address BLK 729 #02-344 CLEMENTI WEST STREET 2

Postcode 120729

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own

Vehicle

erricie

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles (including own vehicle)

involved in the accident

3 NO

NO

Was any body injured in the Accident?

Was any injured conveyed to hospital by ambulance?

NO YES

Was any other material or property damaged?

I have been approached by unknown person(s)

s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

**Details of Police Action** 

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO EBLOW STATEMENT/SKETCH PLAN ATTACHED;

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SKK4297X

Vehicle Make/Model/Colour

TOYOTA / VIOS E AUTO

**Details Of Properties** 

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 2** 

Vehicle Registration Number

SFW4439A

Vehicle Make/Model/Colour

**Details Of Properties** 

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

TOYOTA / VIOS 1.5E M

PRIVATE CAR

#### Accident Sketch Plan

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the ladgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

l understand, acknowledge, agree and consent that:

- My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary Investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mall packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, Investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

**Driver's Signature** 


(If driver is not the policyholder) Date & Time

IDAC KAKI BUKIT (VAC) 23 Kaki Bukit Ave 4 #02-02 Singapore 415933 Tel: 67416697 Fax: 67492305

Email: vacida@vicom.com.eg Reporting Centre Personnel's Signature Name

#### Accident Sketch Plan

SKETCH PLAN



Vehicle A: SFP8496U Vehicle B: SFK4297X Vehicle C: SFW4439A

#### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

	on 11 oct 2019 at around 8:50 cm, I was travelling along Jalan Ahmad Ibrahim
foward	Pioneer Road Suddenly, vehicle B (SKX4797X) collided of my vehicle rear
portion.	
	a involving 3 vehicle
	I realised it was chain accident when I alighted my vehicle . that was
vehic	le involve this accident

DECLARATION

We declare the foregoing particulars are true in every respect.

和风处

Policyholder's Signature Date & Time: THE IN EVERY CESPECT.

Driver's Signature (If driver is not the policyholder) Date & Time: IDAC KAKI BUKIT (VAC) 23 Kaki Bukit Ave 4 #02-02 Bingapore 415933 Tel: 67416697 Fax: 67492305

Email: vaokib@vicom.com.sg Reporting Centre Personnel's Signature

Name: NRIC/FIN No.:



# ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Tel:6702 4282 Fax:6702 4202 - Anna (Hi Anna to findise Page No. 1 amount)

Vehicle No. SFP8496U TOYOTA ALLION

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR ADJUSTMENT
	PARTS (LIST ITEMS)			
1	REAR BOOTLID 64		1092.00	950
1	REAR BOOTLID LOGO NO		75.00	-
1	REAR BOOTLID " ALLION " EMBLEM NU		71.00	
1	REAR BOOTLID "A1.5" EMBLEM AL		71.00	
1	REAR BOOTLID TOP LOCK 64		395.00	30(
1	REAR BOOTLID LOWER LOCK XSVC		48.00	
1	REAR BOOTLID RUBBER NEC		230.80	
2	REAR BOOTLID HINGE LH & RH @\$216.00	Sire	432.00	
2	REAR BOOTLID RUBBER STOPPER LH & RH @	\$53.90 Nec /	107. 80	
2	REAR BOOTLID LAMP LH & RH @\$494.10	sic	988. 20	15.2
1	REAR BOOTLID CHROME X5~C		223. 20	X /
1	REAR BUMPER de	6vc	1490.00	000
12	REAR BUMPER SIDE RETAINER LH & RH @\$1	15.00 LH-X RH	-nu (1PC1230:00	083
12	REAR BUMPER SIDE BRACKET LH & RH @\$14	7. 20 LA-X[RH	- nec/ (1pc)294.40	(25)
2	REAR BUMPER LEAR BUMPER SIDE RETAINER LH & RH @\$1 REAR BUMPER SIDE BRACKET LH & RH @\$14 REAR BUMPER REFLECTOR LH & RH @\$191.8	O LH => (in consisten	383.60	221
1	KEAR BUMPER KEYLESS ANTENNA COA		285.00	271
1	REAR END PANEL 54		627. 90	
1	REAR END PANEL TOP GARNISH de		211. 10	
1	REAR SPARE TYRE PANEL XX		921.30	
1	REAR SPARE TYRE PANEL SPONGE		306.00	
1	REAR TAILLAMP LH & RH @\$510.00 CA	P415	227. 60 1020. 00	03/1
2 2	REAR TAILLAMP PANEL LH & RH @\$292.60	× su	243. 00	2
2	REAR TAILLAMP BRACKET LH & RH @\$63.60	XSVL	127. 20	Ç
1	REAR FENDER LH X 500.00	/_	981.30	
2	REAR FENDER TRIM LH & RH @\$314.10 × 5	n	628. 12	
2	REAR FENDER COWLING LH & RH @\$119.30	Xon	238. 60	
2	REAR FENDER AIR VENT LH & RH @\$58.00	× sn	116.00	10.2
1	REAR EXHAUST PIPE X SW		980.00	5.7
1	REAR EXHAUST PIPE MOUNTING		98.00	
	The moent in a		13143. 12	
		less	makesati sawasanan sama	
		1000	9857. 34	
	SPECIAL NETT ITEMS			
1	REAR WINDSCREEN GLASS SEALANT		100.00	Xo
1	IREAR WINDSCREEN SEAL		100.00	The state of the s
1	REAR WINDSCREEN SPONGE TAPE		40.00	X 140
1 SET	REAR BUMPER CLIPS New/		100.00	50
	REAR END PANEL TOP GARNISH CLIPS Ne.		100.00	40
	REAR CAR PLATE WITH HOLDER X		70.00	*/
1	REAR END PANEL SEALANT New		70.00 80.00	50
		Total Parts	590.00	



#### ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29 Singapore 417807 Tel:6702 4282 Fax:6702 4202

Page No. 2

Vehicle No. SFP8496U TOYOTA ALLION

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT
	LABOUR	1000/00 /00	
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	1600.00 600	
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1200.00 600	
3	To remove and refix wiring at damaged areas	120.00 60 200.00 80 150.00 X 11 150.00 .40 120.00 30 150.00 60	1520
4	To perform anti rust treatment on affected areas	200.00 80	
5	To remove and refix rear bootlid windscreen	150.00 X AN	)
6	To remove rear boot mechanism	150.00 40	/
7	To conduct water seepage test	120.00 30	
8	To remove and refix cushion and inner trim	150.00 60	
	Labour Total :		
	TOTAL (PARTS & LABOUR):	13547.34	

LKK Auto Consultants hence notify the Repairer of the following:

To resurvey before/after spray painting

- To display damaged part(s) during resurvey
- \* Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

(13547.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177.34)

(14177

enail: rasul@1kkauto.com 37/3.85

140.50 15 20.00 15 20.00 20%

4300

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rg	ot	Adj Submitted	Ins Auth'ed	Status
Main	14 Oct 2019 11:34		15 Oct 2019 14:02 Edit Adj Rpt	100000000000000000000000000000000000000	Estimates	\$\$4,300.00 View Rpt		Pending for Survey Report Cancel Case
	Main	Refe	erence		Claim Detail:		Documents	Show All
CLAIM SU	BFOLDER DET	TAILS				[Created b	y insurer]	
Insured:	CHONG CH	IN YONG (ZHANG	JUNYONG), ID:	S76252	53Z			
Main Claimant:	LIM PHECE	( LIAN, ID: S123	3170C					
Vehicle Reg No.:	SFP8496	U			Date of Los	[118 Months	s and 8 Days From L	TA Reg Date (Man Yr)]
Claim Type	: <b>TP</b> / 6082	272			Policy/Cove Note No.:		QMY (Comprehensive) 3/05/2019 - 12/05/2	
Vehicle Reg No. (Insured):	SKK4297X				Policy No. (Claimant):			
					Excess:	S\$500.00		
Repairer:	Ace Autolu	ition Pte Ltd (KAR	CI BUKIT) 13 Kaki	Bukit Ro	ad 4, #03-29	/30 Bartley Biz 0	Centre, 417807 Kaki I	Bukit - Tel: 68441184
Handling Insurer:	The state of the s						Christina Wong - 66	
Adjuster:	LKK Auto	Consultants Pte L	td (HQ) - Tel: 625	6-3561	. [Handled by	MOHD RASUL	] [Final Rpt du	e 14/11/2019]
Driver/Cus dian (Insured):	CHONG CH	IN YONG (ZHANG J	UNYONG) () , NR	IC: S762	5253Z Email:			
Adj Asg. Remarks:	on WP. Liab	o: clear. Agree on S	JE. Assign: LKK Au	to Consu	Itants Pte Ltd	Contact: Anna	@ 6844 1184 / 9657	2134.
ASSOCIA	TED MAIL REG	CEIVED					View Al	Compose Case Ma
There are	no mail for this	case.						
ALL ASS	OCIATED TAS	KS⊟				View All S	earch Tasks Creat	e New Task Complet
Due Dat	e Priority	Type Task G	roup Subject	Han	dler Ass	igned By	Completed On	Created On Done

Page 1 of 2 Merimen e-Claims

## **Claim Documents**

# \*SFP8496U (608272) [SKK4297X] TP LIM PHECK LIAN Oct 11 2019 9:00AM [CHONG CHIN YONG (ZHANG JUNYONG)] Ace Autolution Pte Ltd

Ass	essment Reports		1 per page	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbna	
1	19/12/19 10:58	Adjuster Immediate Advice	1 Load HTM	
Pho	tos/Images		3 per page ✓	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbna  Load JPG	
1	19/12/19 10:32	Odometer Reading	Load JPG  Load JPG	-
2	19/12/19 10:32	Chassis Number	1 Load JPG	
3	19/12/19 10:32	General View	1 Load JPG	-
4	19/12/19 10:32	General View	1 Load JPG	
5	19/12/19 10:32	General View		
6	19/12/19 10:32	General View	Load JPG	_
7	19/12/19 10:32	General View	1 Load JPG	
8	19/12/19 10:32	General View	1 Load JPG	_
9	19/12/19 10:32	General View	1 Load JPG	_
10	19/12/19 10:32	General View	Load JPG	_
11	19/12/19 10:32	General View	1 Load JPG	_
12	19/12/19 10:32	General View	1 Load JPG	_
13	19/12/19 10:32	General View	1 Load JPG	_
14	19/12/19 10:32	General View	1 Load JPG	_
15	19/12/19 10:32	General View	1 Load JPG	
16	19/12/19 10:32	General View	1 Load JPG	
17	19/12/19 10:32	General View	1 Load JPG	-
18	19/12/19 10:32	General View	1 Load JPG	₽
19	19/12/19 10:32	General View	1 Load JPG	\ \
20	19/12/19 10:32	General View	1 Load JPG	_
21	19/12/19 10:32	General View	Load JPG	
22	19/12/19 10:32	General View	Load JPG	
23	19/12/19 10:32	General View	■ Load JPG	<u> </u>
24	19/12/19 10:32	General View	■ Load JPG	
25	19/12/19 11:02	General View	1 Load JPG	
26	19/12/19 11:02	General View	1 Load JPG	
27	19/12/19 11:02	General View	1 Load JPG	₽
28	19/12/19 11:02	General View	1 Load JPG	₩ 2
29	19/12/19 11:02	General View	1 Load JPG	- E
30	19/12/19 11:06	DISMANTLE PHOTOS	1 Load JPG	E
31	19/12/19 11:06	DISMANTLE PHOTOS	1 Load JPG	- E
32	19/12/19 11:06	DISMANTLE PHOTOS	1 Load JPG	
33	19/12/19 11:06	DISMANTLE PHOTOS	1 Load JPG	1 -
34	19/12/19 11:06	DISMANTLE PHOTOS	Load JPG	1 -
35	19/12/19 11:06	DISMANTLE PHOTOS	1 Load JPG	-
36	19/12/19 11:06	DISMANTLE PHOTOS	Load JPG	1 -
37	19/12/19 11:06	DISMANTLE PHOTOS	Load JPG	
38	19/12/19 11:06	DISMANTLE PHOTOS	1 Load JPG	1 -
				1 -
39	19/12/19 11:06	DISMANTLE PHOTOS	1 Load JPG	_ ~

Assessment Reports 1 per		age 🗸	V		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	
				Commission (Section	V
41	19/12/19 11:06	DISMANTLE PHOTOS	0	Load JPG	V
42	19/12/19 11:06	DISMANTLE PHOTOS	0	Load JPG	V
43	19/12/19 11:06	DISMANTLE PHOTOS	0	Load JPG	Ø
44	19/12/19 11:06	DISMANTLE PHOTOS	0	Load JPG	V
45	19/12/19 11:06	DISMANTLE PHOTOS	0	Load JPG	$\mathbf{Z}$
46	19/12/19 11:06	DISMANTLE PHOTOS	0	Load JPG	☑
47	19/12/19 11:06	DISMANTLE PHOTOS	0	Load JPG	$\overline{\mathbf{Z}}$
48	19/12/19 11:06	DISMANTLE PHOTOS	0	Load JPG	$\overline{\mathbf{Z}}$
49	19/12/19 11:06	DISMANTLE PHOTOS	0	Load JPG	V
50	19/12/19 11:06	DISMANTLE PHOTOS	0	Load JPG	V
200	19/12/19 11:06	DISMANTLE PHOTOS	0	Load JPG	V
51	19/12/19 11:06	DISMANTLE PHOTOS	0	Load JPG	V
52		DISMANTLE PHOTOS	0	Load JPG	V
53	19/12/19 11:06		0	Load JPG	V
54	19/12/19 11:07	DISMANTLE PHOTOS	0	Load JPG	
55	19/12/19 11:08	DISMANTLE PHOTOS	0	Load JPG	V
56	19/12/19 11:08	DISMANTLE PHOTOS	0	Load JPG	Ø
57	19/12/19 11:08	DISMANTLE PHOTOS		2 1/20/20/20	-
58	19/12/19 11:08	DISMANTLE PHOTOS	0	Load JPG	V
_			1 per	page V	
-	cumentation	101 111 (110)	Грс	Thumbnai	_
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	0	Load PDF	
1	14/10/19 11:36	OI SKK4297X GIA REPORT 2/3	ŏ	Load PDF	
2	14/10/19 11:36	TP SFP8496U GIA REPORT 1/3	0	Load PDF	
3	14/10/19 11:36	TP SFW4439A GIA REPORT 3/3	0	Load PDF	+
4	14/10/19 11:36	PRI from ACE Autolution Pte Ltd			-
5	14/10/19 14:35	Agree on SJE	0	Load PDF	

# **Documents Checklist**

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			^
			~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.			

# LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

# VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/MSG19018172/R1QF3E2

Date:

10/01/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

A29120362QMY

Claimant Vehicle No:

SFP8496U

Insured Vehicle No:

SKK4297X

Date of Loss:

11/10/2019

Nature of Claim:

TP

Claim No: 608272

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

SFP8496U

Make & Model:

TOYOTA ALLION, 1.5 (A) 03/12/2009 (Man. Year: 2008) Engine No: Chassis No: 1NZD334364 NZT2603040409

Reg. Date: Colour:

Grey

Odometer:

288968 km

Engine Capacity:

1496 cc

Market Value/New Car Price: N/A Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition: No

CONDITION OF TYRES

Front Tyre Size:

185/70 R14

Rear Tyre Size:

185/70 R14

Front Left Side:

Michelin 5 mm

Rear Left Side:

Michelin 5 mm

Front Right Side:

Michelin 5 mm

Rear Right Side:

Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,447.34	3,853.85	6,593.49	63.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,690.00	1,520.00	2,170.00	58.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,137.34	5,373.85	8,763.49	61.99
Approved Total (Overridden) (S\$)		4,300.00		
Nett Amount (S\$)	14,137.34	4,300.00	9,837.34	69.58

INSPECTION

Date of Assignment:

15/10/2019

Date Inspected:

15/10/2019 Inspected At:

Ace Autolution Pte Ltd (KAKI BUKIT)

13 Kaki Bukit Road 4, #03-29/30

Bartley Biz Centre Singapore 417807

Estimated Period of Repair:

6.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 4

# **REPAIR DETAILS**

Referen	ce			
Part Source:	: MRM-SG	Version: 1.0 (Last Synchronised: 10 Jan 2020)		
Parts:	143	TOYOTA ALLION 1.5 (A) (Catalogue:Merimen Singapore 1.0)		
Labour:	Repairer's	(Price-denominated Standard List)		
Print Code:	(Unsubmitted, no print-code for SFP8496U)			
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page			
Further Info	: Items/values n	ot in reference catalogue are prefixed with an asterisk *.		

# Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Bent	1,092.00 FL	*950.00 FL
2	1		*REAR BOOTLID LOGO	Necessary	75.00 FL	*75.00 FL
3	1		*REAR BOOTLID ALLION EMBLEM	Necessary	71.00 FL	*71.00 FL
1	1		*REAR BOOTLID A1.5 EMBLEM	Necessary	71.00 FL	*71.00 FL
5	1		*REAR BOOTLID TOP LOCK	Bent	395.00 FL	*301.00 FL
3	1		*REAR BOOTLID LOWER LOCK	Serviceable	48.00 FL	*-Fl
7	1		*REAR BOOTLID RUBBER	Necessary	230.80 FL	*210.00 FL
3	2		*REAR BOOTLID HINGE LH & RH	Serviceable	432.00 FL	*-FL
9	2		*REAR BOOTLID RUBBER STOPPER LH & RH	Necessary	107.80 FL	*107.80 FL
10	2		*REAR BOOTLID LAMP LH & RH	Serviceable	988.20 FL	*-FL
11	1		*REAR BOOTLID CHROME	Serviceable	223.20 FL	*-FL
12	1		*REAR BUMPER	Deformed	1,490.00 FL	*1,126.00 FL
13	1		*REAR BUMPER SIDE RETAINER LH & RH	N/S Serviceable /O/S Necessary	230.00 FL	*85.00 FL
14	1		*REAR BUMPER SIDE BRACKET LH & RH	N/S Serviceable/O/S Necessary	294.40 FL	*55.00 FL
15	2		*REAR BUMPER REFLECTOR LH & RH (N/S NOT NECESSARY / O/S SERVICEABLE)	N/SNotConsistentWithTheImpact	383.60 FL	*-FL
16	1		*REAR BUMPER KEYLESS ANTENNA	Cracked	285.00 FL	*231.00 FL
17	1		*REAR END PANEL	Bent	627.90 FL	*627.90 FL
18	1		*REAR END PANEL TOP GARNISH	Deformed	211.10 FL	*211.10 FL
19	1		*REAR SPARE TYRE PANEL	Serviceable	921.30 FL	*-FL
20	1		*REAR SPARE TYRE PANEL SPONGE	Serviceable	306.00 FL	*-FL
21	1		*REAR SPARE TYRE INNER SPONGE	Serviceable	227.60 FL	*-FL
22	2		*REAR TAILLAMP LH & RH	Cracked	1,020.00 FL	*830.00 FL
23	2		*REAR TAILLAMP PANEL LH & RH	Serviceable	243.00 FL	*-FL
24	2		*REAR TAILLAMP BRACKET LH & RH	Serviceable	127.20 FL	*-FL
25	1		*REAR FENDER LH	Serviceable	981.30 FL	*-FL
26	2		*REAR FENDER TRIM LH & RH	Serviceable	628.12 FL	*-FL
27	2		*REAR FENDER COWLING LH & RH	Serviceable	238.60 FL	*- FL
28	2		*REAR FENDER AIR VENT LH & RH	Serviceable	116.00 FL	*- FL
29	1		*REAR EXHAUST PIPE	Serviceable	980.00 FL	*-FL
30	1		*REAR EXHAUST PIPE MOUNTING	Serviceable	98.00 FL	*- FL
31	1		*REAR WINDSCREEN GLASS SEALANT	Not Necessary	100.00 FS	*- FS
32	1		*REAR WINDSCREEN SEAL	Not Necessary	100.00 FS	*- FS
33	1		*REAR WINDSCREEN SPONGE TAPE		40.00 FS	*- FS
34	1		*SET REAR BUMPER CLIPS	Necessary	100.00 FS	*50.00 FS
35	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	100.00 FS	*40.00 FS
36	1		*SET REAR CAR PLATE WITH HOLDER	Serviceable	70.00 FS	*-FS

 $https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster\&fuseaction=g...\ \ 10/1/2020$ 

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
37	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*50.00 FS
F=Fra	nchise	part S=	SpcNett. L=ListItemDisc.			
				Sub Total (S\$)	13,733.12	5,091.80
			- List Item Dis	scount on L Items 25.00/25.00% (S\$)	3,285.78	1,237.95
				Total Parts (S\$)	10,447.34	3,853.85
			Report was unsul	omitted during this print-out.		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS AND REPLACE DAMAGED PARTS	New	1,600.00	650.00
2	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED	New	1,200.00	600.00
3	TO REMOVE AND REFIX WIRING AT DAMAGED AREAS	New	120.00	60.00
4	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS	New	200.00	80.00
5	TO REMOVE AND REFIX REAR BOOTLID WINDSCREEN	New	150.00	0.00
6	TO REMOVE REAR BOOT MECHANISM	New	150.00	40.00
7	TO CONDUCT WATER SEEPAGE TEST	New	120.00	30.00
8	TO REMOVE AND REFIX CUSHION AND INNER TRIM	New	150.00	60.00
	Gross Labou	r Cost (S\$)	3,690.00	1,520.00
	Gross Labou		3,090.00	1,520

< END OF ESTIMATES >

Report was unsubmitted during this print-out.