

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 15714

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1233/2019/NS
Date : 4-Jul-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Wu Wenxian
Address : Blk 425 Bedok North Road
#06-555
Singapore 460425
Telephone : (HP) +65 81211292
Type of Claim : Own Damage Claims
Policy No. : 1800128688-01
Vehicle No : **SMF 1531 S**
Model Code : Audi Q2 1.4 TFSI COD S TR
Model / Year : 29/10/2018
Engine No : CZE 841731
Chassis No : WAUZZZGAXKA004650
Mileage :
Date In :
Estimated By : Johnny Boo / Allan Wu
Accident Date : 13-Oct-19
Place of Accident : East Coast Caltex

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMF 1531 S

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	✓ ✓
2	To remove and renew aircon condenser, to reinstall radiator and additional radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,400.00	✓ ✓
3	To dismantle and renew front bumper, rhs front fender, and rhs headlight. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$ 5,200.00	2000 ✓
4	To respray front bumper, bonnet and rhs front fender. ✓	\$ 3,200.00	1100 ✓
5	To carry out diagnostic check.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ <u>10,352.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMF 1531 S

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>Distorted</i>	\$ 1,706.00	✓ 1364
2	FRONT BUMPER FIXING PARTS <i>broken? m</i>	\$ 314.00	? X
3	FRONT BUMPER GRILLE - CENTER <i>could</i>	\$ 179.00	✓ 143.20
4	FRONT BUMPER AIR GUIDE GRILLE - RH <i>Distorted</i>	\$ 154.00	✓ 122.80
5	FRONT BUMPER END CAP - RH <i>? Broken</i>	\$ 31.00	? 24.40
6	FRONT BUMPER SPOILER <i>Del'd</i>	\$ 273.00	✓ 218
7	FRONT BUMPER CLOSING ELEMENT <i>new</i>	\$ 142.00	+ 113.20
8	FRONT WHEEL SPOILER - RH <i>new</i>	\$ 31.00	+ X
9	FRONT BUMPER ADAPTER - RH <i>new</i>	\$ 38.00	+ ✓ 30.32
10	RADIATOR GRILLE <i>could</i>	\$ 1,301.00	✓ 1040.80
11	RADIATOR GRILLE STRIKER PLATE <i>? Broken</i>	\$ 114.00	? 91.20
12	FRONT BUMPER CARRIER <i>? Dented</i>	\$ 625.00	? 499.60
13	FRONT BUMPER FOAM FILLER PIECE <i>? cva</i>	\$ 71.00	? 56.08
14	FRONT BUMPER TOP COVER <i>Del'd</i>	\$ 91.00	✓ 72.56
15	FRONT BUMPER GUIDE SECTION - RH <i>new</i>	\$ 32.00	+
16	AC STICKER <i>new</i>	NEC \$ 7.00	✓ 5.12
17	CAUTION SIGN STICKER <i>new</i>	NEC \$ 13.00	✓ 9.76
18	SIGNAL HORN - RH HIGH TONE <i>could</i>	\$ 180.00	✓ 143.60
19	SPRING SHACKLE - RH <i>new</i>	\$ 29.00	+ 22.72
20	FRONT FENDER - RH <i>Not new</i>	\$ 1,047.00	X
SUB TOTAL SPARE PARTS		: \$ 6,378.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMF 1531 S

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
41	REFRIGERANT LINE A/C COMPRESSOR > A/C CONDENSER <i>? BT</i>	\$ 461.00	? <i>368.80</i>
42	EXTERNAL TEMPERATURE SENSOR <i>? BT</i>	\$ 54.00	? <i>X</i>
43	RADIATOR AIR GUIDE - RH <i>? Bent Broken</i>	\$ 27.00	? <i>21.36</i>
44	RADIATOR AIR GUIDE - UPPER CENTRE <i>? nn</i>	\$ 19.00	? <i>X</i>
45	FRONT WHEEL COVER - LH / RH <i>nee</i>	2 \$ 588.00	✓ <i>469.60</i>
46	FRONT NO PLATE <i>Dented</i>	S/N \$ 40.00	✓ <i>40</i>
47	SUNDRIES <i>? ncc</i>	\$ 400.00	? <i>9.28</i>
TOTAL SPARE PARTS		\$ 17,375.00	
TOTAL LABOUR CHARGES		\$ 10,352.00	
GRAND TOTAL		\$ 27,727.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 15/10/19. ✓
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 08 Pags.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

Steve 30/10/19

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No. PA/OD/1233/2019/NS
Date 30-Oct-19
Service Advisor Glory Tan
Pages 1 of 1
Regn No SMF 1531 S
Model No Audi Q2 1.4 TFSI COD S TR

Quantity	Description	Unit Price	Amount
----------	-------------	------------	--------

Parts


1	Additional radiator / DO	\$ 858.00	702.40
2	Upper bracket for radiator / APC	\$ 77.00	61.28
3	Bowden cable centre / BR	\$ 53.00	41.68
4	Bowden cable cover / BR	\$ 9.00	7.12
5	Bonnet release element / BR	\$ 53.00	41.68
6	Noise insulation / BR	\$ 239.00	191.20
		<u>\$ 1,289.00</u>	

Labours

1	To repair and respray both front fenders.	\$ 2,800.00	1100 ✓ S.S.
---	---	-------------	-------------

Labours total \$ 2,800.00
Parts total \$ 1,289.00
GRAND TOTAL \$ 4,089.00

For Premium Automobiles Pte Ltd



Authorised Signature