

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 15714

## Telefax

Estimate : Accident Repairs  
Workshop : Ubi Road 1  
Contact No : 6366 2323  
Fax No : 6841 1183  
Reference : PA/OD/1233/2019/NS  
Date : 4-Jul-19

Vehicle IN workshop. Kindly arrange for survey.

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept  
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Wu Wenxian  
Address : Blk 425 Bedok North Road  
#06-555  
Singapore 460425  
Telephone : (HP) +65 81211292  
Type of Claim : Own Damage Claims  
Policy No. : 1800128688-01  
Vehicle No : **SMF 1531 S**  
Model Code : Audi Q2 1.4 TFSI COD S TR  
Model / Year : 29/10/2018  
Engine No : CZE 841731  
Chassis No : WAUZZZGAXKA004650  
Mileage :  
Date In :  
Estimated By : Johnny Boo / Allan Wu  
Accident Date : 13-Oct-19  
Place of Accident : East Coast Caltex

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle. SMF 1531 S

S/n	Nature of Jobs	Estimated Charges	Surveyor's Reccomendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	✓
2	To remove and renew aircon condenser, to reinstall radiator and additional radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,400.00	✓
3	To dismantle and renew front bumper, rhs front fender, and rhs headlight. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$ <del>5,200.00</del>	2000 ✓
4	To respray front bumper, bonnet and rhs front fender. X	\$ <del>3,200.00</del>	1100 ✓
5	To carry out diagnostic check.	S/N \$ 192.00	✓
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 10,352.00</b>	

## Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

### Telefax

### Material List for Accident Vehicle Regn No. SMF 1531 S

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>Distorted.</i>	\$ 1,706.00	✓ 1364
2	FRONT BUMPER FIXING PARTS <del>None</del> <i>None</i>	\$ 314.00	? X
3	FRONT BUMPER GRILLE - CENTER <i>could</i>	\$ 179.00	✓ 143.20
4	FRONT BUMPER AIR GUIDE GRILLE - RH <i>Distorted</i>	\$ 154.00	✓ 122.80
5	FRONT BUMPER END CAP - RH <i>Broken.</i>	\$ 31.00	? 24.40
6	FRONT BUMPER SPOILER <i>Del'd</i>	\$ 273.00	✓ 218
7	FRONT BUMPER CLOSING ELEMENT <del>None</del> <i>Broken.</i>	\$ 142.00	+ 113.20
8	FRONT WHEEL SPOILER - RH <i>new</i>	\$ 31.00	+ X
9	FRONT BUMPER ADAPTER - RH <del>None</del> <i>Broken.</i>	\$ 38.00	+ ✓ 30.32
10	RADIATOR GRILLE <i>could</i>	\$ 1,301.00	✓ 1040.80
11	RADIATOR GRILLE STRIKER PLATE <i>Broken.</i>	\$ 114.00	? 91.20
12	FRONT BUMPER CARRIER <i>Sealed.</i>	\$ 625.00	? 499.60
13	FRONT BUMPER FOAM FILLER PIECE <i>Sealed.</i>	\$ 71.00	? 56.08
14	FRONT BUMPER TOP COVER <i>Del'd</i>	\$ 91.00	✓ 72.50
15	FRONT BUMPER GUIDE SECTION - RH <i>None</i>	\$ 32.00	+ X
16	AC STICKER <i>new</i>	NEC \$ 7.00	✓ 5.12
17	CAUTION SIGN STICKER <i>None</i>	NEC \$ 13.00	✓ 9.76
18	SIGNAL HORN - RH HIGH TONE <i>could</i>	\$ 180.00	✓ 143.60
19	SPRING SHACKLE - RH <del>None</del> <i>Best.</i>	\$ 29.00	+ 22.72
20	FRONT FENDER - RH <i>None</i>	\$ 1,047.00	+ X
<b>SUB TOTAL SPARE PARTS</b>		<b>\$ 6,378.00</b>	

**Premium Automobiles**

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

**Telefax**

Material List for Accident Vehicle Regn No. SMF 1531 S

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
21	FRONT FENDER ATTACHMENT PARTS 9	\$ 36.00	X
22	FRONT FENDER BRACKET - RH	\$ 43.00	X
23	FRONT FENDER TOP BRACKET - RH	\$ 14.00	X
24	FRONT FENDER BRACE - RH	\$ 29.00	X
25	FRONT FENDER BRACKET	\$ 21.00	X
26	FRONT WHEEL HOUSING LINER - RH	\$ 183.00	X 146.00
27	FRONT WHEEL HOUSING ATTACHMENT PARTS	\$ 52.00	X 41.20
28	HEADLIGHT MOUNTING - RH <i>cracked,</i>	\$ 107.00	? 85.60
29	LED HEADLIGHT - RH <i>cut</i>	\$ 4,491.00	✓ 3502.80
30	MAIN LIGHT ELECTRONIC POWER MODULE	\$ 693.00	+
31	LED WITH HEAT SINK - RH	\$ 666.00	+
32	LIGHT CONTROL SYSTEM CONTROL UNIT	\$ 508.00	+
33	HEADLIGHT COMPENSATING PIECE	2 \$ 87.00	+
34	HEADLIGHT HOSE - RH	\$ 26.00	+
35	LIFT CYLINDER - RH <i>embd.</i>	\$ 128.00	? 102
36	HEADLIGHT HOSE - RH <i>all</i>	\$ 170.00	+
37	LOCK CARRIER <i>cracked</i>	\$ 907.00	✓ 725
38	READY MIX COOLANT <i>all</i>	4 \$ 165.00	✓ 131.84
39	A/C CONDENSER <i>Dented</i>	\$ 503.00	✓ 402
40	REFRIGERANT LINE A/C CONDENSER > CUT-OFF POINT	\$ 579.00	✓ 463.20
	<b>SUB TOTAL SPARE PARTS</b> <i>Bent</i>	<b>\$ 9,408.00</b>	

**Premium Automobiles**

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

**Telefax**

Material List for Accident Vehicle Regn No. SMF 1531 S

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
41	REFRIGERANT LINE A/C COMPRESSOR > A/C CONDENSER	<i>But.</i> \$	461.00 → 368.80
42	EXTERNAL TEMPERATURE SENSOR	<i>Not M.</i> \$	54.00 ? X
43	RADIATOR AIR GUIDE - RH	<i>Broken.</i> \$	27.00 ? 21.36
44	RADIATOR AIR GUIDE - UPPER CENTRE	<i>Not M.</i> \$	19.00 ? X
45	FRONT WHEEL COVER - LH / RH	<i>See</i> 2 \$	588.00 ✓ 469.60
46	FRONT NO PLATE	<i>Dented</i> S/N \$	40.00 ✓ 40
47	SUNDRIES	<i>See.</i> \$	400.00 ? 9.28
<b>TOTAL SPARE PARTS</b>		\$	<b>17,375.00</b>
<b>TOTAL LABOUR CHARGES</b>		\$	<b>10,352.00</b>
<b>GRAND TOTAL</b>		\$	<b>27,727.00</b>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name : Adrian King  
Surveyed Date : 15/10/19 ✓  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks : Not Authorised, 12 days.  
08 days.

## Please Note

: This estimate is based on visual inspection of the affected vehicle  
Should we require further labour charges and spare parts in the  
progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before repairs, painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party surveys on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplemental work must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant

# Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

## Supplementary Estimate 1

GST Reg No. 19-9902271-W

Steve 30/10/19

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No. PA/OD/1233/2019/NS

Date 30-Oct-19

Service Advisor Glory Tan

Pages 1 of 1

Regn No SMF 1531 S

Model No Audi Q2 1.4 TFSI COD S TR

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Additional radiator / <i>DD</i>	\$ 858.00	<i>702.40</i>
2	Upper bracket for radiator / <i>APC</i>	\$ 77.00	<i>61.28</i>
3	Bowden cable centre / <i>BR</i>	\$ 53.00	<i>41.68</i>
4	Bowden cable cover / <i>BR</i>	\$ 9.00	<i>7.12</i>
5	Bonnet release element / <i>BR</i>	\$ 53.00	<i>41.68</i>
6	Noise insulation / <i>BR</i>	\$ 239.00	<i>191.20</i>
			<u>\$ 1,289.00</u>

### Labours

1	To repair and respray both front fenders.	\$ <del>2,800.00</del>	<i>1100</i> ✓ <i>SL</i>
---	---	------------------------	-------------------------

Labours total \$ 2,800.00

Parts total \$ 1,289.00

**GRAND TOTAL** \$ 4,089.00

For Premium Automobiles Pte Ltd

  
\_\_\_\_\_  
Authorised Signature

# Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

## Supplementary Estimate 1

CST Reg No. 19-9902271-W

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No. PA/OD/1233/2019/NS

Date 30-Oct-19

Service Advisor Glory Tan

Pages 1 of 1

Regn No SMF 1531 S

Model No Audi Q2 1.4 TFSI COD S TR

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Lid lock with micro switch <i>Damaged</i>	\$ 184.00	✓

GRAND TOTAL \$ 184.00

For Premium Automobiles Pte Ltd

Authorised Signature

*Adrian Ling*  
*ALS*