

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 15742

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1232/2019/NS
Date	:	14-Oct-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms Leong Hui Min Joie
Address	:	24 Bayshore Road #10-04 Singapore 469971
Telephone	:	(HP) +65 97661869
Type of Claim	:	Own Damage Claim
Policy No.	:	2100376499-05
Vehicle No	:	SKN 5049 Z
Model Code	:	Audi A4 1.8 TFSI MU (A)
Model / Year	:	Jun-14
Engine No	:	CJE 075936
Chassic No.	:	WAUZZZ8K8EA112308
Mileage	:	
Date In	:	
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	13-Oct-19
Place of Accident	:	Bayshore Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKN 5049 Z

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	✓
2	To remove and reinstall aircon condenser, radiator and charged air cooler. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,200.00	?
3	To dismantle and renew front bumper, lhs front fender, bonnet and lhs headlight. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$ 5,250.00	Without Lock Carrier 1750 With Lock Carrier 3000.
4	To respray front bumper, bonnet, lhs front fender and hinges. x	\$ 3,200.00	1650
5	To carry out diagnostic check	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 10,202.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKN 5049 Z

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	REMARKS
1	FRONT BUMPER <i>Distorted</i>	\$ 2,100.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 234.00	+
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$ 207.00	+
4	FRONT BUMPER GRILLE - LOWER CENTRE <i>new</i>	\$ 123.00	+
5	FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE <i>new</i>	\$ 177.00	+
6	FRONT BUMPER SUPPORT ELEMENT - UPPER ?	\$ 54.00	?
7	RADIATOR GRILLE <i>new</i>	\$ 1,005.00	+
8	FRONT BUMPER AIR GUIDE GRILLE - LH <i>cut</i>	\$ 123.00	✓
9	FRONT WHEEL SPOILER - LH <i>new</i>	\$ 45.00	+
10	SIGNAL HORN - LH HIGH TONE ?	\$ 184.00	?
11	SPRING SHACKLE - LH HIGH TONE ?	\$ 23.00	?
12	FRONT FENDER - LH <i>Distorted</i>	\$ 904.00	✓
13	FRONT FENDER ATTACHMENT PARTS ?	\$ 52.00	?
14	FRONT FENDER BRACKET - LH FRONT <i>Bent</i>	\$ 48.00	✓
15	DEFORMATION ELEMENT BRACKET - LH REAR ?	\$ 45.00	?
16	FRONT FENDER BRACE - LH LOWER <i>Bent</i>	\$ 107.00	✓
17	FRONT WHEEL HOUSING LINER - LH ?	\$ 223.00	?
18	WHEEL HOUSING LINER ATTACHMENT PARTS ?	\$ 41.00	?
19	BONNET <i>Distorted</i>	\$ 2,549.00	✓
20	BONNET PROTECTIVE FILM - FRONT <i>new</i>	\$ 42.00	✓
SUB TOTAL SPARE PARTS CHARGES :		<u>\$ 8,286.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKN 5049 Z

S/N	Parts Description	Damaged Parts & Prices		REMARKS
		S/Nett		
21	BONNET ATTACHMENT PARTS ?	\$	152.00	?
22	BONNET LID HINGE - LH / RH <i>new</i>	2 \$	136.00	+
23	BONNET CATCH HOOK	\$	127.00	+
24	BONNET GAS FILLED STRUT <i>new</i>	\$	109.00	+
25	BONNET SEAL - LH <i>new</i>	\$	25.00	✓
26	BONNET EDGE PROTECTION - FRONT <i>new</i>	\$	25.00	✓
27	BONNET LID LOCK <i>new</i>	\$	196.00	X
28	MICRO SWITCH <i>new</i>	\$	67.00	X
29	BONNET LOCK COVER <i>new</i>	\$	21.00	X
30	HEADLIGHT MOUNTING - LH <i>cond</i>	\$	107.00	✓
31	HEADLIGHT BRACE - LH ?	\$	41.00	?
32	HEADLAMP BRACKET - LH ?	\$	96.00	?
33	GAS DISCHARGE LAMP HEADLIGHT - LH <i>Smashed</i>	\$	2,152.00	✓
34	GAS DISCHARGE LAMP CONTROL UNIT ?	\$	1,051.00	?
35	DAY DRIVING LIGHTS POWER MODULE ?	\$	520.00	?
36	GAS DISCHARGE LAMP ?	\$	398.00	?
37	HEADLAMP COUPLING ELEMENT ?	\$	29.00	?
38	HEADLIGHT HOSE - LH <i>new</i>	\$	32.00	X
39	HALOGEN FOG LAMP - LH <i>cut</i>	\$	242.00	✓
40	HEADLIGHT LIFT CYLINDER - LH <i>cond</i>	\$	192.00	✓
SUB TOTAL SPARE PARTS CHARGES		:	\$ 5,718.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKN 5049 Z

S/N	Parts Description	Damaged Parts & Prices		REMARKS
		S/Nett		
41	HEADLIGHT HOSE <i>new</i>	\$	170.00 <i>+</i>	
42	LOCK CARRIER <i>?</i>	\$	928.00 <i>?</i>	
43	READY MIX COOLANT <i>?</i>	4 \$	84.00 <i>?</i>	
44	RADIATOR AIR GUIDE - LH <i>?</i>	\$	24.00 <i>?</i>	
45	RADIATOR SEALING STRIP <i>?</i>	\$	15.00 <i>?</i>	
46	STONE CHIP GUARD <i>?</i>	\$	67.00 <i>?</i>	
47	ADHESIVE TAPE <i>?</i>	\$	50.00 <i>?</i>	
48	FRONT NO PLATE <i>new</i>	S/N \$	40.00 <i>+</i>	
49	SUNDRIES <i>?</i>	\$	500.00 <i>?</i>	
TOTAL SPARE PARTS CHARGES		:	\$ 15,882.00	
TOTAL LABOUR CHARGES		:	\$ 10,202.00	
GRAND TOTAL CHARGES		:	\$ 26,084.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Name : *Adrian Lim*
Surveyed Date : *15/10/19*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, Without Lock Carrier 06 Days.
With Lock Carrier 09 Days.*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant