

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.
TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

12,OCT 2019

Lonpac Insurance BHD
100 Beach Road #19-00
Shaw Tower
S 189702

*Not authorized
11 Rm @ 1750h
Murray after Palm
3 days*

Attn : Motor claim dept-3rd party claim
Claiming against your insured vehicle no: GBB8485Y
Accident involving vehicle no: SJW8025L/GBB8485Y
DOA: 10/10/2019 AT Moulmein Road exit TO CTE

Dear officer incharge
Re: Estimate cost of repair to SJW8025L
To supply—

Description	Qty	Amount
Rear bumper	1 <i>CM</i>	862.00 N ✓
Rear bumper reflector	1 <i>R</i>	76.00 N X
Rear bumper retainer @23N	2 <i>R</i>	46.00 N X
End panel	1 <i>R</i>	506.00 N X
Rear bumper tow cover	1 <i>Mit</i>	46.00 N ✓
Rear bumper lower	1 <i>Red/Bu</i>	392.00 N ✓
Parts		1,928.00 N
Nett parts less 10%		192.80
		1,735.20

Reverse sensor
Rear number plate w bracket
To remove damaged parts and attachments
Repair/reshape dented areas
Replace/align all parts into position
To spray paint

*CM 220.00 2005N
B1 60.00 455N

700.00 350L
500.00 450L*

3,215.20

****Please arrange to survey the vehicle-ASAP,thank you**



*Karen
6456 9830*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: