

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

KNA FX411MH568574

TAN KIAT LIN, ANNE CLAUDINE
BLK 570 HOUGANG ST 51
#16-99
S 530570

TP China
Jia Le

Date :18.10.2019
Vehicle No :SLJ 1879 E
Make/Model :KIA CERATO K3
Accident date :09.10.2019

No	DESCRIPTION	Qty	Amount (S\$)
<u>List Items</u>			
1	Front bumper <i>Deformed.</i>	1	\$ 702.9 ✓
2	Front bumper side holder @ \$ 42.40 LH <i>Damaged.</i>	2	\$ 84.8 42.40 ✓
3	Front bumper reinforcement <i>He m</i>	1	\$ 545.6 +
4	Front bumper LH lower side garnish <i>Deformed.</i>	1	\$ 47.1 ✓
5	Front bumper LH fod lamp <i>crushed</i>	1	\$ 266 ✓
6	Front bumper LH fod lamp garnish <i>crushed</i>	1	\$ 32.8 ✓
7	Front bumper lower centre grille <i>He m</i>	1	\$ 134 x
8	Front bumper sponge <i>crushed</i>	1	\$ 134.2 ✓
9	Front bumper bracket @ \$ 80.10 <i>He m</i>	2	\$ 160.2 +
10	Front grille <i>He m</i>	1	\$ 393.8 +
11	Front grille clips (1 set) <i>He m</i>	1	\$ 66 +
12	Front LH headlamp <i>ut</i>	1	\$ 1766.4 ✓
13	Front LH fender <i>Buckled.</i>	1	\$ 400.2 ✓
14	Front LH fender inner shield <i>Deformed</i>	1	\$ 108.5 ✓
15	Front LH fender inner shield clips (1 set) <i>He m</i>	1	\$ 66 30
16	Front LH knuckle arm <i>Bent</i>	1	\$ 374 ✓
17	Front LH knuckle arm bearing <i>He m</i>	1	\$ 132 ✓
18	Front LH lower arm <i>Bent</i>	1	\$ 405.2 ✓
19	Front LH drive shaft <i>He m</i>	1	\$ 990 +
20	Front LH shock absorber <i>Bent</i>	1	\$ 308 ✓
21	Front LH linkage <i>He m</i>	1	\$ 86.4 +
22	Steering rack <i>He m</i>	1	\$ 1012 +
23	Headlamp lower Bracket. <i>crushed</i>	1	\$ 68.50 ✓
Less 10% Disc			\$ 8216.1
Total			\$ 821.6
			\$ 7394.5

Special Nett Items

1	Front LH sport rim <i>ut</i>	550	\$ 800 550.
2	Front LH tyre <i>He m</i>		\$ 300 x
Total			\$ 1100

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

TAN KIAT LIN, ANNE CLAUDINE
BLK 570 HOUGANG ST 51
#16-99
S 530570

Date :18.10.2019
Vehicle No :SLJ 1879 E
Make/Model :KIA CERATO K3
Accident date :09.10.2019

No	DESCRIPTION	Qty	Amount (S\$)
----	-------------	-----	--------------

Labour Cost

- 1 To check wheel alignment
- 2 Remove & reinstall front LH suspension
- 3 Remove, replace & repair consistent to the accident
- 4 Respray painting
- 5 Tuff kote

	\$	100 ⁸⁰
	\$	400 ²²⁰
1850	\$	1300 ⁶⁰⁰
	\$	1000 ⁴⁰⁰
	\$	100 ⁵⁰
Total	\$	2900

Grand Total \$ 11394.5

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total 6236.38

L/S: SK

05 Days.

SK