

Surveyor Steve

REF: CC3 / AIG 19001807 / E4f3

Minimum

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

\$0/-

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

| | |
|-----|-----|
| | |
| N/S | O/S |
| | |

Bal. or Market Value:

85K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SDH 381K

Yr Regn: 24/7/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: Audi Q2

c.c 999

Colour Red

A/C: Insured / Std / NI / NA

Sp. Reading 32121

T/Radio: Insured / Std / NI / NA

Eng/No:

CiNo: W4UZZZGA3HA059997

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

215/60 R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

29/8/19

D.O.I.

15/10/19

Survey held at

Premises, ARX-ada Rd.

Des. of Damages Frnt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Mk- 85K

SDH 381K - CC3 / LPI 16003465 / RH 632-1 D.O.A - 22/02/2014

16/10@12:34 - Revert via preli advise.
22/10@9:37 - authorise repair by victor kon
07/10@10:18am - email to workshop authorise repair excess \$0

Submit preli Report, withdrawal claim OD

Date/Time, File Pass to?



Preli. Report

Days Of Repair:

3

1) 515 Typist



Final Report

Resurvey No. of Trip:

Survey Fee:

Date/Time, File Return to?

Transportation:

2)

Add Fee:



Site Insp (\$

) S + RS. SI



Interview (\$

) Photos



Tech. Invs (\$

) Others



Weekend (\$

)

Report Format :

OD

Lump Sum / I.B.I: (\$

TOTAL

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Tuesday, 22 October 2019 10:18 AM
To: Admin-D (LKKAUTO); 'Claims'; SUR; assignments
Subject: RE: OD CLAIMS SDH 381 K

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SDH 381K (Excess \$0/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Tuesday, 15 October 2019 1:15 PM
To: 'Claims' <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: RE: OD CLAIMS SDH 381 K

Dear George,

Received with thanks.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>
Sent: Tuesday, 15 October, 2019 1:09 PM
To: 'SUR' <sur@lkkauto.com>; 'assignments' <assignments@lkkauto.com>
Subject: OD CLAIMS SDH 381 K

Dear all,

View Received Message

This mail is associated with :

***SDH381K (3767185175SG)**

OD

Aug 29 2019 7:15AM

[LIM MEI LING, JENNY(LIN MEILING, JENNY)]
Premium Automobiles Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on **22/10/2019 09:37 AM**.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$8659.00) - SDH381K - Claim Handler: Azlan, Syazairdina

Approved:8659.00:Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 16 Oct 2019

Preliminary Advice

| | | | |
|--------------------|--|-------------------------|-----------------|
| Vehicle No | : SDH381K | Accident Date | : 29/08/2019 |
| Make | : AUDI Q2 | Policy No. | : 1700030033-02 |
| Assignment Date | : 16/10/2019 | Excess | : S\$0.00 |
| Date of Inspection | : 15/10/2019 | Est. Duration of Repair | : 3.00 |
| Inspection At | : PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699 | | |

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 15,252.00 |
| Revised Amount | :S\$ | 8,659.00 |
| Check Items (Estimated) | :S\$ | 597.00 |
| Total | :S\$ | 9,256.00 |
| Lump Sum Repair | :S\$ | |

Total Loss Consideration

| | | |
|--------------------|------|-----------|
| New for Old Value | :S\$ | |
| Pre-Accident Value | :S\$ | 85,000.00 |
| COE / PARF Rebate | :S\$ | 47,153.00 |
| Salvage Value | :S\$ | |
| Margin for Repair | :S\$ | 37,847.00 |

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 16 Oct 2019

Preliminary Advice

| | | | |
|--------------------|--|-------------------------|-----------------|
| Vehicle No | : SDH381K | Accident Date | : 29/08/2019 |
| Make | : AUDI Q2 | Policy No. | : 1700030033-02 |
| Assignment Date | : 16/10/2019 | Excess | : S\$0.00 |
| Date of Inspection | : 15/10/2019 | Est. Duration of Repair | : 3.00 |
| Inspection At | : PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699 | | |

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 15,252.00 |
| Revised Amount | :S\$ | 8,659.00 |
| Check Items (Estimated) | :S\$ | 597.00 |
| Total | :S\$ | 9,256.00 |
| Lump Sum Repair | :S\$ | |

Total Loss Consideration

| | | |
|--------------------|------|-----------|
| New for Old Value | :S\$ | |
| Pre-Accident Value | :S\$ | 85,000.00 |
| COE / PARF Rebate | :S\$ | 47,153.00 |
| Salvage Value | :S\$ | |
| Margin for Repair | :S\$ | 37,847.00 |

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| | |
|-------------------------------------|--------------------------------------|
| Vehicle Owner Particulars | |
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 170F |
| Vehicle Details | |
| Vehicle No.: | SDH381K |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 15 Oct 2019 |
| Vehicle Make: | AUDI |
| Vehicle Model: | Q2 1.0 TFSI S TRONIC |
| Primary Colour: | Red |
| Manufacturing Year: | 2017 |
| Engine No.: | CHZ390643 |
| Chassis No.: | WAUZZZGA3HA059997 |
| Maximum Power Output: | 85.0 kW (113 bhp) |
| Open Market Value: | \$26,087.00 |
| Original Registration Date: | 24 Jul 2017 |
| First Registration Date: | 24 Jul 2017 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$18,522.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 23 Jul 2027 |
| PARF Rebate Amount: | \$13,891.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 23 Jul 2027 |
| COE Category: | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years): | 10 |
| QP Paid: | \$42,801.00 |
| COE Rebate Amount: | \$33,262.00 |
| Total Rebate Amount: | \$47,153.00 |

The information contained herein is correct as at 15 Oct 2019

OK

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 10489

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1038/2019/NS
Date : 30-Aug-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no : FBE 5645 G

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Lim Mei Ling
Address : Blk 254 Bangkit Road
#08-216
Singapore 670254
Telephone : HP +65 97849097
Type of Claim : Own Damage Claims
Policy No. : 1700030033-02
Vehicle No : **SDH 381 K**
Model Code : Q2 1.0 TFSI S Tronic
Model / Year : Jul-17
Engine No : CHZ 390643
Chassis No : WAUZZZGA3HA059997
Mileage :
Date In :
Estimated By : Johnny Boo / Allan Wu
Accident Date : 29-Aug-19
Place of Accident : Along Road 1 Travelling Towards Road 2 Bangkit Rd

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SDH 3

| S/n | Nature of Jobs | Es C |
|-----------------------------|--|-----------|
| 1 | To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer Assy. s/n \$ | |
| 2 | To dismantle and renew front bumper and lhs headlight. Re-organise rear crash management components. Reinstall all parts removed. \$20 | \$ |
| 3 | To respray front bumper and lhs front fender. \$10 | \$ |
| 4 | To carry out diagnostic checks. S/N \$ | \$ |
| TOTAL LABOUR CHARGES | | \$ |

0•c
360•+
750•+
550•+
192•+
=
1,852•*
0•c
154•+
273•+
1,301•+
4,491•+
588•+
=
6,807•*
0•c
1,852•+
6,807•+
=
8,659•*
0•c
32•+
114•+
12•+
32•+
107•+
300•+
=
597•*
0•c

16/10
t

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SDH 381 K

| S/n | Nature of Jobs | Estimated Charges | Surveyor's Recommendation |
|----------------------|---|-------------------|---------------------------|
| 1 | To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy. | s/n \$ 360.00 / | |
| 2 | To dismantle and renew front bumper and lhs headlight. Re-organise rear crash management components. Reinstall all parts removed. <i>\$20</i> | \$ 1,600.00 | <i>750</i> |
| 3 | To respray front bumper and lhs front fender. <i>\$10</i> | \$ 2,000.00 | <i>550</i> |
| 4 | To carry out diagnostic checks. | S/N \$ 192.00 | <i>750</i> / |
| TOTAL LABOUR CHARGES | | : \$ 4,152.00 | |

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDH 381 K

| S/N | Parts Description | Damaged Parts & Prices | |
|--------------------------------------|--|------------------------|-----------------|
| | | S/Nett | Remark |
| 1 | FRONT BUMPER ASSY X R | 3 \$ | 1,706.00 |
| 2 | FRONT BUMPER FIXING PARTS X nn | \$ | 314.00 |
| 3 | FRONT BUMPER GRILLE-CENTER X nn | \$ | 179.00 |
| 4 | FRONT BUMPER AIR GUIDE GRILLE-LH / CUT | \$ | 154.00 |
| 5 | FRONT BUMPER END CAP-LH X nn | \$ | 31.00 |
| 6 | FRONT BUMPER SPOILER / CUT | \$ | 273.00 |
| 7 | FRONT BUMPER CLOSING ELEMENT X nn | \$ | 142.00 |
| 8 | FRONT WHEEL SPOILER-LH X nn | \$ | 31.00 |
| 9 | FRONT ADAPTER-LH ? | \$ | 32.00 |
| 10 | RADIATOR GRILLE / CUT | \$ | 1,301.00 |
| 11 | RADIATOR GRILLE STRIKER PLATE ? | \$ | 114.00 |
| 12 | FRONT BUMPER CARRIER X nn | \$ | 625.00 |
| 13 | FRONT BUMPER FOAM FILLER PIECE X nn | \$ | 71.00 |
| 14 | FRONT BUMPER COVER X nn | \$ | 91.00 |
| 15 | FRONT BUMPER DISTANCE PIECE ? | \$ | 12.00 |
| 16 | FRONT BUMPER GUIDE SECTION-LH ? | \$ | 32.00 |
| 17 | HORN - LH LOW TONE X nn | \$ | 262.00 |
| 18 | HORN SPRING SHACKLE - LH X nn | \$ | 29.00 |
| 19 | MAIN BEAM HEADLIGHT MOUNTING | \$ | 107.00 |
| 20 | LED HEADLIGHT - LH / CUT | \$ | 4,491.00 |
| SUB-TOTAL SPARE PARTS CHARGES | | \$ | 9,997.00 |

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDH 381 K

| S/N | Parts Description | Damaged Parts & Prices | |
|----------------------------------|---------------------------------------|------------------------|---------------------|
| | | S/Nett | Remark |
| 21 | LED HEADLIGHT LIFT CYLINDER - LH X nn | \$ | 128.00 |
| 21 | FRONT WHEEL COVER - LH / RH / APC | 2 \$ | 588.00 |
| 22 | RADIATOR AIR GUIDE - LH X nn | \$ | 27.00 |
| 23 | CAUTION SIGN X nn | NEC \$ | 13.00 |
| 24 | AIRCON STICKER X nn | NEC \$ | 7.00 |
| 25 | FRONT NO. PLATE X nn | S/N \$ | 40.00 |
| 26 | SUNDRIES ? | \$ | 300.00 |
| TOTAL SPARE PARTS CHARGES | | : | \$ 11,100.00 |
| TOTAL LABOUR CHARGES | | | \$ 4,152.00 |
| GRAND TOTAL | | | \$ 15,252.00 |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Telefax

Name


Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks


Steve (LKK) 00 - Not Author (Revat)
3 dy
PIP
Ry Rel sy
Excess - ?

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant