

ASS. REC. BY:

REF: CS/FCI 19018 228/ Agf3

Special Instruction:

Surveyor: Adnan

ASSIGNMENT (Office)

From (Person): Sathara

of FCI

Date/Time: 16.10.19 11.16a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGH 7886P

Insured: SHC 7021H

at Workshop m/s MG Solution

Tel: 67444165

of 23 Kabi Bukit Ave 4 # 02-03

Policy No:

Claim No: D19006573MFSH

Sum Insured:

Excess:

Make of Vch:

D.O.A. 13.10.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 16.10.19 11.34p.m

Person Contacted: ms Hong

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SGH 7886P - CS/III 18003605 / R/b342 ROA - 22/10/2018
	SHC 7021H - CS/FCI 17015682 / Lxx ROA - 06/02/2017
17/10/19 @	Has informed Sathara, we are pending estimate from repairer.
18/11/19 @	Estimate revised to Sathara by email.
	US \$1600, 4 days CRed \$3570.68, 69% (o)

ASS. REC. BY:

REF: **FC1****ASSIGNMENT**From: _____ Date: **16.10.2019**

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: **SGH 7886P**at Workshop m/s **MG Solution**of **23 Kaki Bukit Ave 4 #02-03**

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: **4** days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: **SGH 7886P** Yr Regn: **2016, May**Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Mit Attrage** c.c. **1193**Colour: **Black** A/C: Insured / Std / NI / NASp. Reading: **67107** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **MMBSTA13AHH000404**Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim orTyre Size: F: **185/55R15**R: **185/55R15**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO or

Front

Rear

R/Bal. **06** mm R/Bal. **06** mmL/Bal. **06** mm L/Bal. **46** mmD.O.A. _____ D.O.I. **16/10/19**Survey held at **MG Solution**Des. of Damages: Frt / Rear / ☒ O/S / N/S / U/C / Rooftop or .

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP 1st Cap.

RECEIVED 15 NOV 2019

Date/Time, File Pass to?

1) **15/11/2019** ☐ : Prel. Report2) **15/11/2019** ☐ : Final Report

Date/Time, File Return to?

2)

Rep. Format: **TP**Lump Sum / **1600**Days Of Repair: **4**Resurvey No. of Trip: **1**Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Inve (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, \$

Photos:

Others:

TOTAL

140**50****50****16****256**



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19006573MFSH

Date: 15 November 2019

Our Ref: CS/FCI19018228/Aqf3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SGH 7886P .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 16/10/2019 at the premises of M/s MG SOLUTION . and have the following to report:-

Workshop Estimate Amount	: S\$ <u>5,170.68</u> .
Revised Estimate Amount	: S\$ <u>1,600.00 (Lump Sum)</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages
at the o/s portion.



Yours faithfully

ADRIAN LING WAI PING
B.Eng. AMSOE, AMIRTE, AMSAE-A, M.MATAI
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	14-10-2019	Our Ref No. D19006573MFSH
Accident Date	13-10-2019	Claim Type. Third Party
Insured Vehicle	SHC7021H	Third Party Vehicle. SGH7886P
Survey Location	23 KAKI BUKIT AVE 4 AAS KAKI BUKIT CENTRE#02-03	
Contact Person.	MS HONG	
Contact No.	67444165/ 0	Fax No. 0
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MG SOLUTION PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 15 November 2019 10:06 AM
To: 'CWS Motor Claims'; SUR
Cc: 'Sithara'
Subject: RE: SURVEY ASSESSMENT - D19006573MFSH/1
Attachments: CSFCI19018228Aqf3.pdf

Dear Sithara,

Enclosed herewith preliminary advice of SGH 7886P.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Thursday, 17 October 2019 11:00 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19006573MFSH/1

Dear Sithara,

Please be informed that we have inspected the vehicle SGH 7886P on 16/10/19.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Wednesday, 16 October 2019 11:35 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19006573MFSH/1

Dear Sir/Madam,

Thank you for your assignment.

Best Regards,

Summer Lee | Admin

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 17 October 2019 11:00 AM
To: 'CWS Motor Claims'; SUR
Cc: 'Sithara'
Subject: RE: SURVEY ASSESSMENT - D19006573MFSH/1

Dear Sithara,

Please be informed that we have inspected the vehicle SGH 7886P on 16/10/19.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Wednesday, 16 October 2019 11:35 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19006573MFSH/1

Dear Sir/Madam,

Thank you for your assignment.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Sent: Wednesday, 16 October, 2019 11:16 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19006573MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: FIRST CAPITAL	DATE	: 13/10/2019
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<i>xiao Chan</i>			
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SGH7886P		
MODEL	: MITSUBISHI ATTRAGE 1.2		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 13-Oct-19
		TIME	: 13:00HRS
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT DOOR RH <i>Dented</i>	1	\$ 1,355.20	\$ 1,355.20 <i>986</i>
2	FRONT DOOR POWER WINDOW REGULATION <i>Regis</i>	1	\$ 280.00	\$ 280.00 ✓
3	FRONT DOOR POWER WINDOW MOTOR <i>the new</i>	1	\$ 520.00	\$ 520.00 ✓
4	ROCKER PANEL RH <i>Regis</i>	1	\$ 890.00	\$ 890.00 ✓

1266 TOTAL PRICE \$ 3,045.20
1139 40 LESS 10% \$ 304.52
SUB TOTAL PRICE \$ 2,740.68

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,000.00	<i>300</i>
2	TO SPRAY PAINT ON AFFECTED AREA	\$ 1,000.00	<i>400</i>
3	TUFF COAT	\$ 150.00	<i>50</i>
4	WIRING CHECK	\$ 100.00	<i>30</i>
3	TO REMOVE AND REFIX FRONT DOOR MECHANISM	\$ 180.00	<i>80</i>

TOTAL \$2,430.00

860

ESTIMATE REPORT

TOTAL PARTS COST : \$ 2,740.68
TOTAL LABOUR COST : \$ 2,430.00
TOTAL REPAIR COST : \$ 5,170.68

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

Adrian Ling
L/S 16/10/19.
04 days.
Total: 1999.40
L/S: 1.61K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19018228/Aqf3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 18-11-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 7021H	Veh. Inspected	SGH 7886P
Policy No.		Coverage (\$)	0.00
Claim No.	D19006573MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	16/10/2019
2. Vehicle Particulars & Condition			
Make & Model	MITSUBISHI ATTRAGE	c.c	1193
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MMBSTA13AHH000404	Colour	BLACK
Odometer	67107	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/55 R15	YOKOHAMA	6 mm
L/H Front Tyre	185/55 R15	YOKOHAMA	6 mm
R/H Rear Tyre	185/55 R15	YOKOHAMA	6 mm
L/H Rear Tyre	185/55 R15	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	13/10/2019	Inspection Date	16/10/2019
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGH 7886P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT DOOR RH	DENTED	1,355.20	986.00
1	FRONT DOOR POWER WINDOW REGULATION	DAMAGED	280.00	280.00
1	FRONT DOOR POWER WINDOW MOTOR	NOT NECESSARY	520.00	-
1	ROCKER PANEL RH	TO REPAIR SEE LABOUR	890.00	-
	LESS 10% DISCOUNT		-304.52	-126.60
			2,740.68	1,139.40
	LABOUR			
	PANEL BEATING, REMOVAL AND REPLACING PARTS. INCLUSIVE OF THE REPAIR OF ROCKER PANEL RH.		1,000.00	300.00
	TO SPRAY PAINT ON AFFECTED AREA.		1,000.00	400.00
	TUFF COAT.		150.00	50.00
	WIRING CHECK.		100.00	30.00
	TO REMOVE AND REFIX FRONT DOOR MECHANISM.		180.00	80.00
			2,430.00	860.00
	GRAND TOTAL		5,170.68	1,999.40
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,600.00

Report Ref No. CS/FC119018228/Aqf3n2

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.