

ASS. REC. BY:

REF:

CS/FC19018240/09.4312

Special Instruction:

Surveyor:

Marcus

ASSIGNMENT (Office)

From (Person): Marina Chia San San of PCI

Date/Time: 16.10.19 9.239.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: WTR 912

Insured: SHD 8865C

at Workshop m/s Exclusive Enterprise

Tel: 62459655

of B koki Bukit Ave 4 707-50

Policy No:

Claim No:

D19006578 mFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 14.10.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 16.10.19 10.28A.m

Person Contacted:

ICE

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHD 8865C NA/GA1900366103 DCA 26/10/2019
	WTR 912 : X
15/10/19 @ 12.03pm	Informed Marina Chia, we are pending estimate from repair
31/10/19 @ 2.01pm	revised to Marina Chia by email.

(08/11/13) wof

ASS. REC. BY: Marcus

REF:

La 1

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: WTR912at Workshop m/s Exohm

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: RM

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 15 days Res.: Yes or NoLum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: WTR912 Yr Regn: 3 10Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: Toyota Innova C.O. 1998Colour: Beige A/C: Insured / Std / NI / NASp. Reading: 137752 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: PN111NV 4008620757

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/65 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIO / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 6 mm Rear: 6 mmR/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 14/10/19 D.O.I. 18/10/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & R/L

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

30/10/19 4/5 \$10,000 confirmed with AH Xiong (Red 89557.13, 49%)

RECEIVED 31 OCT 2019

Date/Time, File Pass to?

31/10 10:15☐ : Preli. Report☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 15Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)Report Format: TPLump Sum / L.S.I. (\$) (10000)9x15=135170+1355050+50100648



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19006578MFSH

Date: 31 October 2019

Our Ref: CS/FCI19018240/Uqf3

The Motor Claims Department
MS First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. WTR 912

Please be informed that we had conducted the inspection of the abovementioned vehicle on 16/10/2019 at the premises of M/s EXCLUSIVE ENTERPRISE, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>19,557.23</u>
Revised Estimate Amount	: S\$ <u>10,000.00 (Lump Sum)</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:
The vehicle sustained damages
at the rear & front portion.



Yours faithfully

CHUA KANG SENG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	15-10-2019	Our Ref No. D19006578MFSH
Accident Date	14-10-2019	Claim Type. Third Party
Insured Vehicle	SHD8865C	Third Party Vehicle. WTR912
Survey Location	8 KAKI BUKIT AVENUE 4#03-50 PREMIER @ KAKI BUKIT	
Contact Person.	ICE	
Contact No.	62459655/ 0	Fax No. 62459678
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	EXCLUSIVE ENTERPRISE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MERINA CHIA SAN SAN	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 31 October 2019 2:01 PM
To: 'CWS Motor Claims'; SUR
Cc: 'Merina Chia'
Subject: RE: SURVEY ASSESSMENT - D19006578MFSH/1
Attachments: CSFCI19018240Uqf3.pdf

Dear Merina,

Enclosed herewith preliminary advice of WTR 912.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Friday, 18 October 2019 12:03 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Cc: 'Merina Chia' <MerinaChia@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19006578MFSH/1

Dear Merina,

Please be informed that we have inspected the vehicle WTR 912 on 16/10/2019.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Wednesday, 16 October 2019 10:27 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Merina Chia' <MerinaChia@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19006578MFSH/1

Dear Sir/Madam,

Thank you for your assignment.

Best Regards,

Summer Lee | Admin

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 18 October 2019 12:03 PM
To: 'CWS Motor Claims'; SUR
Cc: 'Merina Chia'
Subject: RE: SURVEY ASSESSMENT - D19006578MFSH/1

Dear Merina,

Please be informed that we have inspected the vehicle WTR 912 on 16/10/2019.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Wednesday, 16 October 2019 10:27 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Merina Chia' <MerinaChia@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19006578MFSH/1

Dear Sir/Madam,

Thank you for your assignment.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Sent: Wednesday, 16 October, 2019 9:23 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Merina Chia <MerinaChia@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19006578MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.



SIJIL PEMILIKAN KENDERAAN

JABATAN PENGANGKUTAN JALAN

W4Y4TG61

No. Pendaftaran	: WTR912
No. ID	: 650817085366
Nama Pemunya Berdaftar	: NG SOOK CHIN
Alamat	: NO 41 JALAN KEMAJUAN 15 TAMAN UNIVERSITI 81300 SKUDAI JOHOR
No. Chasis/No. Enjin	: PH111NV4008620767 / 1TR6861084
Buatan/Nama Model	: TOYOTA / INNOVA 2.0 G (AT)
Keupayaan Enjin	: 1998
Bahan Bakar	: PETROL
Status Asal	: PEMASANGAN TEMPATAN
Kelas Kegunaan	: PERSENDIRIAN-MOTOKAR INDIVIDU
Jenis Badan/Tahun Dibuat	: MOTOKAR PELBAGAI UTILITI / 2010
Tarikh Pendaftaran	: 15/03/2010
B. D. M/B. G. K/BTM	: -
Syarat Pendaftaran 1	: -
Syarat Pendaftaran 2	: -
Syarat Pendaftaran 3	: -



Please call KAA Toll Free 1-800-88-3833 for breakdown or accident assistance

PRIVATE CAR SCHEDULE / JADUAL KERETA PERSENDIRIAN

STAMP DUTY PAID

LANPWS000EXMT
REV: 2
RTD Code 09
PRIVATE CAR EX GOODS
M.X.1

The Insured / Pemegang Polisi NG SOOK CHIN		Policy No. / No. Polisi JVD7272112 01-01	
NO 41 JALAN KEMAJUAN 15 TAMAN UNIVERSITI 81300 JOHOR BAHRU 81300 JOHOR BAHRU		Account No. / No. Akaun P30000-00	
Occupation / Pekerjaan OTHERS		Type of Cover / Jenis Perlindungan COMPREHENSIVE	
I.C. No. / No. Kad Pengenalan 650817085366		Period of Insurance / Tempoh Insurans From / Dari 00:00:01 AM 04-06-2019 To / Hingga 03-06-2020	
Bus. Regn. No / No Pendaftaran Perniagaan -		Premium / Premium All Rider / Semua Penunggang RM 1,169.62 0.00	
Hire Purchase Owner / Pemilik Sewa Bell -		NCD / Diskaun Tanpa Tuntutan 0.00% Wef / Berkuatkuasa dari 04-06-2019 0.00 1,169.62	
Make & Type of Body / Buatn & Jenis Badan TOYOTA INNOVA G / 4D WAGON		Optional Cover Add Named Driver / Pemandu Tambahan 10.00 Legal Liability Of Passengers / Liabiliti Penumpang Di Sisi Undang-Undang Kerana Perbuatan Cua 7.50 Legal Liability To Passengers / Liabiliti Dnt Sepg Undang-Undang Kepada Penumpang 57.80 Windscreen Damage (Tempered/Laminated Glass inclusive Labour Cost) / Kerosakan Cermin Kenderaan (Penggubahan Cermin / Cermin Bertapis Termasuk Kos Buruh) RM 150.00 1,000.00	
Registration No. / No. Pendaftaran WTR912	Excess / Lebihan 0.00	Regn. Card No. / No. Kad Pendaftaran -	Gross Premium / Premium Kasar 1,394.92
Carrying or Seating Capacity Incl. Driver / Muatan Tempat Duduk Termasuk Pemandu 7	Tonnage / C.C / Watt Tan / Keupayaan Enjin 1998.00 CC Year of Manufacture / Tahun Diperbuat 2010	Sum Insured / Jumlah Diinsuranskan (RM) 30,000.00	Service Tax / Cukai Perkhidmatan 6% Stamp Duty / Duti Setem 83.70 10.00
Engine/Motor No. / No. Enjin/Motor 1TR6861084	Chassis No. / No. Casis PN111NV4008620757		Trailer / Treler -
Only The Extensions, Endorsement And / Or Warranties Indicated Below Apply To This Policy. / Hanya Laajutan, Endorsemen dan / atau Warranti sepertimana yang dinyatakan di bawah ini boleh diguna pakai dalam polisi ini. 2, 100, 72, 89			Total Due / Jumlah Berbayar RM 1,488.62
Subject to IMPORTANT NOTICE: Your duty as the Owner of the vehicle as attached Named Driver / Pemandu Yang Dinamakan THE POLICYHOLDER, LIEW YUK SUN, WONG YU CHANG			Total Due (OTC) / Jumlah Berbayar Di Kaunter RM 1,488.60
Geographical Area : Malaysia , Republic of Singapore and Negara Brunei Darussalam. / Kawasan Geografi : Malaysia, Republik Singapura dan Negara Brunei Darussalam Limitations as to Use / Authored Driver : As described in the Certificate of Insurance. / Had Penggunaan / Pemandu Yang Dibek Kuasa : Seperti yang tercatat dalam Sijil Insurans			
Replacing Cover Note No. / Gantian No. Nota Perlindungan Renewal of Policy No. / Pembaharuan No. Polisi Date of Proposal or Declaration / Tarikh Cadangan atau Pengisytiharan 03-06-2019	Issued By / Dikeluarkan Oleh : DS BEST ENTERPRISE NO 301 JLN PERSIARAN PERLING TAMAN PERLING 81200 JOHOR BAHRU JOHORE Tel : 0167712969 Fax :		For / untuk AmGeneral Insurance Berhad <i>AmGeneral Insurance</i> Authorised Signature / Tandatangan Yang Diberi Kuasa
Date of Issue / Time Tarikh Dikeluarkan / Waktu 03-06-2019 05:28:19 PM			

Note / Nota: No refund of premium for any cancellation of policy if premium is charged on instalment premium / Tidak bayaran balik premium bagi sebarang pembatalan polisi sekiranya premium yang dikenakan adalah premium minima.
03/V11TPH60415-1

AmGeneral Insurance Berhad 4412147

A member of the AmBank Group

Monara Street, No 211, Jalan Tan Sri Rumbengan, 50475 Kuala Lumpur, Malaysia. PO Box 11225, 50512 Kuala Lumpur, Malaysia

Tel : 1-800-88-3833 Email: customer@amgeneral.com.my Web: www.amgeneral.com.my

[Home](#) / [Used Cars](#) / [Toyota](#) / [Innova](#) / [E](#)

Updated on: October 17, 2019

2010 Toyota Innova 2.0 E MPV -- WELL MAINTAINED

RM 473/month

RM 36,500

Seller Information

 Sales Agent 

 Johor » Johor Bahru

Updated on: October 17, 2019

 Sales Agent 

 Johor » Johor Bahru »



Key details

 Car type Used Car

 Make Toyota

 Model Innova

 Variant E

 Year 2010

 Engine Capacity
1998 cc

 Transmission
Automatic

 Seat Capacity 8

 Mileage 90 - 95K

 Colour Silver

[View All 396 Cars From This](#)

Seller's comments

Say Carlist.my for the best deal

[Home](#) / [Used Cars](#) / [Toyota](#) / [Innova](#) / [G](#)

Updated on: October 17, 2019

**10 FULSVC UMW TRUE MIL
GUARANTEED CARKING
FULLKIT LKNEW Innova 2.0
G MPV ONLY 1 IN
MALAYSIA MACAM BARU**

Updated on: October 17, 2019

 Dealer 
 Selangor » Klang »



RM 501/month
RM 38,666

Seller Information

 Dealer 

 Selangor » Klang

Key details

 Car type Used Car

 Make Toyota

 Model Innova

 Variant G

 Year 2010

 Engine Capacity
1998 cc

 Transmission
Automatic

 Seat Capacity 8

 Mileage 90 - 95k

 Colour Brown

[View All 342 Cars From This](#)

Seller's comments

[Home](#) / [Used Cars](#) / [Toyota](#) / [Innova](#) / [G](#)

Updated on: October 16, 2019

RM 516/month

RM 39,800

2010 Toyota Innova 2.0 G (A) FACELIFT

Updated on: October 16, 2019

 Sales Agent Penang » Georgetown »

Seller Information

 Sales Agent Penang »

Georgetown

Key details

 Car type
Used Car Make Toyota Model Innova Variant G Year 2010 Engine
Capacity 1998 cc Transmission
Automatic Seat Capacity
8 Mileage
145 - 150K Colour White

Seller's comments

Exclusive Enterprise Pte Ltd

8 Kaki Bukit Ave 4 , #03-50 , Premier @ KB , Singapore 415875

Tel : 62459655 / 9735 6016 (Tony) Fax : 6245 9678

Email : exclusiveenterprise50@gmail.com

TP INS : First Capital

Veh No. : WTR 912

PN1111NV

Veh Model : Toyota Innova 2.0

16/10/19

N. of Allowed
L/S \$ 10,000

Take up the After Repair
15 days.

No. List items

QTY

Amount

1 Bonnet	1	huc	\$739.10 ✓
2 Bonet Lock	1	surf	\$93.10 ✓
3 Bonnet Outer Chrome Moulding 166.50	1	cre	\$267.30 ✓
4 Bonnet Rubber Seal	1	na	\$39.10 X
5 Bonnet Hinge L/R	2	na	\$114.20 X
6 Frt Bumper	1	Dis	\$573.10 ✓
7 Frt Bumper Side Retainer L/R 65 X 2 = 130	2	surf	\$146.20 ✓
8 Frt Bumper Fog Lamp Garnish L/R	2	na	\$178.40 X
9 Frt Bumper Lower Grille 145.20	1	to. n	\$188.30 ✓
10 Frt Bumper Reinforcement 339.10	1	Dis	\$437.10 ✓
11 Frt Bumper Bracket	1	na	\$113.40 X
12 Frt Grille	1	cre	\$362.10 ✓
13 Frt Grille Logo	1	na	\$48.80 ✓
14 Headlamp L/R	2	cre	\$986.20 ✓
15 Support Panel	1	surf	\$519.30 ✓
16 Brace Panel 157.00	1	twi	\$221.90 ✓
17 Radiator	1	surf/pur	\$939.10 ✓
18 A/C Condenser	1	surf/pur	\$1,163.90 ✓
19 Radiator Upper Hose	1	na	\$69.30 X
20 Radiator Lower Hose	1	Dis	\$69.10 X
21 Radiator Spare Tank	1	Dis	\$183.90 ✓
22 Radiator Fan Blade	1	cu	\$277.90 ✓
23 Radiator Fan Blade Shourd	1	cre	\$143.60 ✓
24 Radiator Fan Motor	1	gm	\$189.10 ✓
25 Front Fender L/R	2	na	\$926.20 X
26 Front Fender Under Cowling L/R	2	na	\$336.20 X
27 Tailgate 1043.00	1	body	\$1,391.60 ✓
28 Tailgate Lock 285.00	1	ro/gm	\$476.10 ✓
29 Tailgate W/strip	1	to. n	\$197.60 ✓
30 Tailgate Outer Garnish	1	na	\$119.30 X
31 Tailgate Logo 45.00	1	na	\$69.30 ✓
32 Emblem " 2.0 "	1	na	\$53.10 ✓

33 Emblem " G "
 34 Emblem " Toyota "
 35 Emblem " Innova "
 36 Tailgate Glass Moulding L/R
 37 Tailgate Inner Trimboard 485.10
 38 Tailgate Stopper L/R
 39 Rear Bumper
 40 Rear Bumper Side Retainer L/R
 41 Rear Bumper Side Holder L/R
 42 Rear Bumper Side Reflector L/R 35.00
 43 Taillamp L/R
 44 End Panel 665.10
 45 End Panel Top Garnish 266.50
 46 Rear Fender Inner Trim L/R @ \$392.10
 47 Rear Compartment Board
 48 Rear Exhaust 699.10
 49 Rear Exhaust Chrome
 50 Rear Exhaust Moulding

1	rec	\$48.30	/
1	me	\$55.20	/
1	me	\$51.30	/
2	me	\$79.20	/
1	de/cne	\$587.10	/
2	11	\$78.80	X
1	dis	\$561.90	/
2	sat	\$178.60	/
2	ns	\$187.20	X
2	MS B/W	\$183.60	12C
2	cne	\$579.20	/
1	body	\$811.60	/
1	Trim	\$363.70	/
2	11	\$784.20	X
1	11	\$893.60	X
1	Buf dis	\$899.30	/
1	dis	\$108.20	505.2
2	11	\$192.40	X

Sub-Total : \$18276.30 12479.20
 Less 25%
 Total : \$13707.22

S/N

Frt Bumper Clips
 Frt Grille Clips
 Coolant
 Frt Number Plate
 Rear Bumper Clips
 Rear W/S Sealant
 Tailgate Inner Trim Clips
 Rear Number Clips
 Reverse Sensor

1Set	me	\$50	40
1Set	11	\$50	X
1	11	\$80	X
1	cne	\$50	14
1Set	me	\$50	40
1	me	\$80	40
1	11	\$50	X
1Set	11	\$50	X
1	MF	\$300	X

S/N Total : \$760

Labour

R&R Front Aircon Condenser & Radiator
 Top up aircon gas
 Wire-Checking (Front)
 Labour (Front)
 Painting (Front)
 R&R Rear Windscreen
 R&R Reverse Sensor
 Wire-Checking (Rear)
 R&R Rear Compartment & Trims
 Transfer Rear Gate Component from old to new

\$180	100
\$150	
\$50	15
\$1,000	800
\$1,000	800
\$150	120
11 \$60	X
\$50	15
\$150	80
\$100	50

R&R Rear Exhaust Pipe

\$200 60

Labour (Rear)

\$1,000 900

Painting (Rear)

\$1,000 950

Labour Total : \$5090

13433.4

10746.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

19557.73



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19018240/Uqf3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 04-11-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 8865C	Veh. Inspected	WTR 912
Policy No.		Coverage (\$)	0.00
Claim No.	D19006578MFSH	Excess (\$)	0.00
Assign From	MERINA CHIA SAN SAN	Assign Date	16/10/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA INNOVA (A)	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	PN111NV4008620757	Colour	BEIGE
Odometer	137752	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/65 R15	MICHELIN	6 mm
L/H Front Tyre	205/65 R15	MICHELIN	6 mm
R/H Rear Tyre	205/65 R15	MICHELIN	6 mm
L/H Rear Tyre	205/65 R15	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	14/10/2019	Inspection Date	16/10/2019
Survey held at	EXCLUSIVE ENTERPRISE PTE. LTD. 8 KAKI BUKIT AVENUE 4 #03-49 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		15 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. WTR 912

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BONNET	BUCKLED	739.10	739.10
1	BONNET LOCK	BENT	93.10	93.10
1	BONNET OUTER CHROME MOULDING	CRACKED	267.30	166.50
1	BONNET RUBBER SEAL	NOT NECESSARY	39.10	-
2	BONNET HINGE L/R	NOT NECESSARY	114.20	-
1	FRT BUMPER	DISTORTED	573.10	573.10
2	FRT BUMPER SIDE RETAINER L/R	BENT	146.20	130.00
2	FRT BUMPER FOG LAMP GARNISH L/R	NOT NECESSARY	178.40	-
1	FRT BUMPER LOWER GRILLE	TORN	188.30	145.20
1	FRT BUMPER REINFORCEMENT	DISTORTED	437.10	339.10
1	FRT BUMPER BRACKET	NOT NECESSARY	113.40	-
1	FRT GRILLE	CRACKED	362.10	362.10
1	FRT GRILLE LOGO	NECESSARY	48.80	48.80
2	HEADLAMP L/R	CRACKED	986.20	986.20
1	SUPPORT PANEL	BENT	519.30	519.30
1	BRACE PANEL	TWISTED	221.90	151.00
1	RADIATOR	BENT / PUNCTURE	939.10	939.10
1	A/C CONDENSER	BENT / PUNCTURE	1,163.90	1,163.90
1	RADIATOR UPPER HOSE	NOT NECESSARY	69.30	-
1	RADIATOR LOWER HOSE	NOT NECESSARY	69.10	-
1	RADIATOR SPARE TANK	DISTORTED	183.90	183.90
1	RADIATOR FAN BLADE	CUT	277.90	277.90
1	RADIATOR FAN BLADE SHROUD	CRACKED	143.60	143.60
1	RADIATOR FAN MOTOR	JAMMED	189.10	189.10
2	FRONT FENDER L/R	TO REPAIR SEE LABOUR	926.20	-
2	FRONT FENDER UNDER COWLING L/R	NOT NECESSARY	336.20	-
1	TAILGATE	BADLY DENTED	1,391.60	1,043.00
1	TAILGATE LOCK	DENTED / JAMMED	476.10	285.00
1	TAILGATE OUTER GARNISH	NOT NECESSARY	119.30	-
1	TAILGATE LOGO	NECESSARY	69.30	45.00

Report Ref No. CS/FCI19018240/Uqf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	EMBLEM 2.0	NECESSARY	53.10	53.10
1	EMBLEM "G"	NECESSARY	48.30	48.30
1	EMBLEM "TOYOTA"	NECESSARY	55.20	55.20
1	EMBLEM "INNOVA"	NECESSARY	51.30	51.30
2	TAILGATE GLASS MOULDING L/R	NECESSARY	79.20	79.20
1	TAILGATE INNER TRIMBOARD	DEFORMED / CRACKED	587.10	485.10
2	TAILGATE STOPPER L/R	NOT NECESSARY	78.80	-
1	REAR BUMPER	DISTORTED	561.90	561.90
2	REAR BUMPER SIDE RETAINER L/R	BENT	178.60	178.60
2	REAR BUMPER SIDE HOLDER L/R	NO SUCH PARTS	187.20	-
2	REAR BUMPER SIDE REFLECTOR L/R	N/S BROKEN	183.60	35.00
2	TAILLAMP L/R	CRACKED	579.20	579.20
1	END PANEL	BADLY DENTED	811.60	665.10
1	END PANEL TOP GARNISH	TORN	363.70	266.50
2	REAR FENDER INNER TRIM L/R @\$392.10	NOT NECESSARY	784.20	-
1	REAR COMPARTMENT BOARD	NOT NECESSARY	893.60	-
1	REAR EXHAUST	BENT / DISTORTED	899.30	699.10
2	REAR EXHAUST MOULDING	NOT NECESSARY	192.40	-
1	TAILGATE W/STRIP	TORN	197.60	197.60
	LESS 25% DISCOUNT		-4,542.03	-3,119.80
			13,626.07	9,359.40
1	REAR EXHAUST CHROME (SN)	DISTORTED	108.20	50.00
	LESS 25% DISCOUNT		-27.05	-
			81.15	50.00
	SPECIAL NETT ITEMS			
1	SET FRT BUMPER CLIPS (SN)	NECESSARY	50.00	40.00
1	SET FRT GRILLE CLIPS (SN)	NOT NECESSARY	50.00	-
1	COOLANT (SN)	NOT NECESSARY	80.00	-
1	FRT NUMBER PLATE (SN)	CRACKED	50.00	14.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	40.00
1	REAR W/S SEALANT (SN)	NECESSARY	80.00	40.00

Report Ref No. CS/FCI19018240/Uqf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAILGATE INNER TRIM CLIPS (SN)	NOT NECESSARY	50.00	-
1	SET REAR NUMBER CLIPS (SN)	NOT NECESSARY	50.00	-
1	REVERSE SENSOR (SN)	NOT FITTED	300.00	-
			760.00	134.00
	LABOUR			
	R&R FRONT AIRCON CONDENSER & RADIATOR. }		180.00	100.00
	TOP UP AIRCON GAS. }		150.00	-
	WIRE-CHECKING (FRONT)		50.00	15.00
	LABOUR (FRONT).INCLUSIVE OF THE REPAIR OF FRONT FENDER L/R.		1,000.00	800.00
	PAINTING (FRONT).		1,000.00	800.00
	R&R REAR WINDSCREEN.		150.00	120.00
	R&R REVERSE SENSOR.	NOT NECESSARY	60.00	-
	WIRE-CHECKING (REAR)		50.00	15.00
	R&R REAR COMPARTMENT & TRIMS.		150.00	80.00
	TRANSFER REAR GATE COMPONENT FROM OLD TO NEW.		100.00	50.00
	R&R REAR EXHAUST PIPE.		200.00	60.00
	LABOUR (REAR).		1,000.00	900.00
	PAINTING (REAR).		1,000.00	950.00
			5,090.00	3,890.00
	GRAND TOTAL		19,557.22	13,433.40
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			10,000.00

Report Ref No. CS/FC19018240/Uqf3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.