

ASS. REC. BY:

REF: CS/MSG/19018242/125F302

Special Instruction:

Surveyor: Taufikn

ASSIGNMENT (Office)

From (Person): Ng Chen How

of MSI 9

Date/Time: 16.10.19 9.59

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBK 6143A

Insured: SML 55985

at Workshop m/s Leong Seng

Tel: 62737469

of BIK 1006 Bukit Merah Lane 2 A01-06

Policy No:

Claim No: 608512

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 12.10.2019

CA / REV / REP. / REV 24 HRS

Date/Time: 16.10.19 10.43A.m

Person Contacted:

CS Teo

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SML 55985: CF/MSG/19014363/Dqf3 DCA: 23/09/2019
	FBK 6143A: X
18/10/19	@ 14:55 pm revised PA to Ng Chen How via noinner.

ASS. REC. BY: Tausi K

REF: MS19

ASSIGNMENT

From: _____ Date: 17.10.2019

Estimated Cost: _____

OD: TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBK 6143A

at Workshop m/s: Leong Seng Motor

of BK 1006 Bukit Merah Lane 2 #01-08

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: FBK 6143A Yr Regn: 2015, Nov

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda CB400X C.C. 329

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 58767 T/Radio: Insured / Std / NI / NA

Eng/No: SH2NC47915K00048

C/No: _____


Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120 / 70 R17
R: 160 / 60 R17



(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS mp'

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Front: 5 mm R/Bal. 5 mm

L/Bal. _____ mm

D.O.A. _____

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or .

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

08/11/19 Confirmed 4S \$3,300/- @ 4 days
(\$1,831.00 Red - 36%)

8/11/2019

RECEIVED 08 NOV 2019

Date/Time, File Pass to?

1) 08/11/19
Typ: 4

Date/Time, File Return to?

2)

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 4
Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Survey Fee:
Transportation: 150
S + RS: 11
Photos:
Others:

TOTAL

150
11
161

Rep. Contact:

Lump Sum / L.S. \$3,300/- 4S

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: NG CHEN HOW

Date: 18 Oct 2019

Preliminary Advice

Insured Vehicle No	: SML5598S	Accident Date	: 12/10/2019
TP Vehicle No	: FBK6143A	Assignment Date	: 16/10/2019
Make	: HONDA CB400X	Est. Duration of Repair	: 4 days
Date of Inspection	: 17/10/2019		
Inspection At	: Leong Seng Motor Pte Ltd (HQ) BLK 1006 Bukit Merah Lane 2, 2 Alexandra Village #01-08 Singapore 159762		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s & n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,131.00
Revised Amount	:S\$	3,950.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,950.50
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Oct 2019 17:43		16 Oct 2019 09:59 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G								
Main Claimant:	CERTIS CISCO AUXILIARY POLICE, Co. Reg. No.: 200900882K								
Vehicle Reg. No.:	FBK6143A	Date of Loss:	12/10/2019 18:00 - :59 [47 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 608512	Policy/Cover Note No.:	D29114745MKF (Comprehensive) Coverage: 01/02/2019 - 31/01/2020						
Vehicle Reg. No. (Insured):	SML5598S	Policy No. (Claimant):	MOMVM000001011-02-000						
		Excess:							
Repairer:	Leong Seng Motor Pte Ltd (HQ) BLK 1006 Bukit Merah Lane 2, 2 Alexandra Village #01-08, 159762 Alexandra - Tel: 62737469								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by NG CHEN HOW - 6643 1391]								
Claimant's Insurer:	Great American Insurance Company (HQ) - Tel: 6804 6047								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 17/10/2019]								
Driver/Custodian (Insured):	IAN TAY ZHIWEN (38 / Male), NRIC: S8118074A, Tel: +6586992967 Email:								
Adj Asg. Remarks:	on WP, Manual assigned to LKK via email on 15/10/19. (Manual Assign). OI:Grab. Liab: clear. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: C S Teo @ 6273 7469.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Friday, 8 November 2019 4:42 pm
To: leongseng
Cc: SUR
Subject: RE: FBK6143 marked estimate

Dear Teo,

Finalize amount confirmed.

Final invoice and all supporting documents sent over to MSIG Insurance (Singapore) Pte. Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: leongseng <leongsen@singnet.com.sg>
Sent: Monday, 4 November 2019 2:16 pm
To: SUR <sur@lkkauto.com>
Subject: Re: FBK6143 marked estimate

Dear Sir

Kindly check and update us on your recommended COR.

Thanks

c s teo

From: leongseng
Sent: Tuesday, October 22, 2019 5:25 PM
To: Lkk survey
Subject: FBK6143 marked estimate

Dear Taufikh

Pls find enclosed FBK6143 marked estimate,

Shirley Hiew (LKK Auto)

From: leongseng <leongsen@singnet.com.sg>
Sent: Tuesday, 22 October 2019 5:25 pm
To: SUR
Subject: FBK6143 marked estimate

Dear Taufikh

Pls find enclosed FBK6143 marked estimate,

Kindly check and advice us on your recommended COR.

Pls find below are our working on COR

parts	\$1380.00
less 10%	(\$ 138.00)
	\$1242.00
net item & labour	\$2920.00
sub total	\$4162.00
less 20%	(\$ 832.40)
total	\$3329.60

Based on our working, we will like to request for Lump Sum repair of \$3300.00

Kindly check and update us on your recommendation.

Thanks

c s teo

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

882K

Vehicle Details

Vehicle No.:

FBK6143A

Vehicle to be Exported:

No

Intended Deregistration Date:

11 Nov 2019

Vehicle Make:

HONDA

Vehicle Model:

CB400X

Primary Colour:

White

Manufacturing Year:

2015

Engine No.:

NC47E5000434

Chassis No.:

JH2NC4791EK000438

Maximum Power Output:

-

Open Market Value:

\$6,659.00

Original Registration Date:

05 Nov 2015

First Registration Date:

05 Nov 2015

Transfer Count:

1

Actual ARF Paid:

\$999.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

04 Nov 2025

COE Category:

D - Motorcycle

COE Period(Years):

10

QP Paid:

\$6,158.00

COE Rebate Amount:

\$3,683.00

Total Rebate Amount:

\$3,683.00

The information contained herein is correct as at 11 Nov 2019

OK

Leong Seng Motor Pte Ltd

Blk 1006 Bukit Merah Lane 2

#01-08 Singapore 159762

Tel: 62737469 Fax: 62727669

Veh No : FBK6143A

Model : CB400X

S/N	Parts Description	QTY	List Price	Nett Price	Remark
1	Front wind shield		\$ 285.00		crs ✓
2	Top cowling stay		\$ 260.00		bt ✓
3	Front side cowling (L)		\$ 365.00		Rx
4	Front fender		\$ 225.00		cut ✓
5	Handle bar		\$ 235.00		? bt ✓
6	Handle balancer		\$ 45.00		X nn
7	Clutch lever		\$ 45.00		cut ✓
8	Mirror		\$ 95.00		cut ✓
9	Gear pedal		\$ 150.00		ddl ✓
10	Front foot rest		\$ 85.00		at ✓
11	Front blinker lamp (R)			\$ 155.00	crs ✓
12	Front blinker lamp (L)			\$ 155.00	crs ✓
13	Top crash bar			\$ 450.00	bt ✓
14	Bottom crash bar			\$ 350.00	bt ✓
15	Rear crash bar			\$ 280.00	Rx
16	Siren assy			\$ 780.00	cut ✓
17	Rear blinker post			\$ 350.00	bt ✓
18	Co logo sticker			\$ 180.00	150 nec
19	Respray top side, front fender			\$ 250.00	200
20	Towing 2 way			\$ 120.00	80
21	Labour			\$ 450.00	250
22					2720
23			1380		
24		10%	1242		
25			2920		
26			4162		
27		4/5%	3300		
28			4 days		
29					
30					
31					
32					
33					
34					
35					
36					
37					
38					
39					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Less 10%
Date:

\$ 1,790.00 \$ 3,520.00
\$ 179.00
\$ 1,611.00

5131

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19018242/T1SF3N2

Date: 11/11/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	D29114745MKF
Claimant Vehicle No :	FBK6143A	Insured Vehicle No :	SML5598S
Date of Loss:	12/10/2019	Nature of Claim:	TP
		Claim No:	608512

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBK6143A	Engine No:	NC47E5000434
Make & Model:	HONDA CB400X, 399cc	Chassis No:	JH2NC4791EK000438
Reg. Date:	05/11/2015 (Man. Year: 2015)	Odometer:	58767 km
Colour:	White		
Engine Capacity:	399 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/70R17	Rear Tyre Size:	160/60R17
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,311.00	3,632.00	679.00	15.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	820.00	530.00	290.00	35.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,131.00	4,162.00	969.00	18.89
Approved Total (Overridden) (S\$)		3,300.00		
Nett Amount (S\$)	5,131.00	3,300.00	1,831.00	35.69

INSPECTION

Date of Assignment:	16/10/2019
Date Inspected:	17/10/2019 Inspected At:

Leong Seng Motor Pte Ltd (HQ)
BLK 1006 Bukit Merah Lane 2, 2
Alexandra Village #01-08
Singapore 159762

Estimated Period of Repair:	4.0 days
------------------------------------	----------

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 11 Nov 2019)	
Parts:	N/A	HONDA CB400X 399cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBK6143A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WIND SHIELD	Cracked	285.00 FL	*285.00 FL
2	1		*TOP COWLING STAY	Bent	260.00 FL	*260.00 FL
3	1		*FRONT SIDE COWLING (L)	Repair	365.00 FL	*- FL
4	1		*FRONT FENDER	Cut	225.00 FL	*225.00 FL
5	1		*HANDLE BAR	Bent	235.00 FL	*235.00 FL
6	1		*HANDLE BALANCER	Not Necessary	45.00 FL	*- FL
7	1		*CLUTCH LEVER	Cut	45.00 FL	*45.00 FL
8	1		*MIRROR	Cut	95.00 FL	*95.00 FL
9	1		*GEAR PEDAL	Dented	150.00 FL	*150.00 FL
10	1		*FRONT FOOT REST	Cut	85.00 FL	*85.00 FL
11	1		*FRONT BLINKER LAMP (R)	Cracked	155.00 FS	*155.00 FS
12	1		*FRONT BLINKER LAMP (L)	Cracked	155.00 FS	*155.00 FS
13	1		*TOP CRASH BAR	Bent	450.00 FS	*450.00 FS
14	1		*BOTTOM CRASH BAR	Bent	350.00 FS	*350.00 FS
15	1		*REAR CRASH BAR	Repair	280.00 FS	*- FS
16	1		*SIREN ASSY	Cut	780.00 FS	*780.00 FS
17	1		*REAR BLINKER POST	Bent	350.00 FS	*350.00 FS
18	1		*CO LOGO STICKER	Necessary	180.00 FS	*150.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,490.00	3,770.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	179.00	138.00
Total Parts (\$\$)	4,311.00	3,632.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RESPRAY TOP SIDE,FRONT FENDER	New	250.00	200.00
2	TOWING 2 WAY	New	120.00	80.00
3	LABOUR	New	450.00	250.00
Gross Labour Cost (\$\$)			820.00	530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >