Tenneth	ASSIGNMENT 19018247/Egf3n2
From:	D. LAD T.
Estimated Cost:	Veh No: \$1+187-56614 Yr Regn: 03, 18
ODYTP/WS/TP RES/OD RES/EVA/INV/	Type: M.Car / M.Cycle / Bus / Van / Lorry (Taxl) Prime Mover /
To Inspect Vehicle No:	Truck / Traller or
	Make: Toy Privi) ac 1798
at Workshop m/s Trans	Cab Colour M. Elwhite / Re AC: Insured / Std / NI / NA
	C- C
Insured SJP 74960	Eng/No: T/Radio: Insured / Std / NI / NA
Policy No. MIC 000 808	
Claims No. M1908059	Gen. Cond: Good   Fair   Poor   Burnt
Sum Insured: Excess:	
(Client's Record)	Steering: Inorder / Jammed / Leaked / Burnt or
Make of Veh;	Brake: Inorder / Jammed / Leaked / Burnt or
	Modi: Nil / S/Rim / STD MRim or
(Policy Condition)	Tyre Size: F: 185/65R 15
Remark: The veh had commenced its	R:
repair at the time of inspection.	N/S O/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUM! /
	TOYO LYOKO or
Bal. or Market Value:	Erons O Rear
IDAC Accident Rport: Consistent? : Yes	Or Ho R/Bal. O mm B/Bal
GIA / PR Seen: Consistent? : Yes	or No L/Bai. 8 mm
Est. Repairs: 02 days Res.: Yes	or No 0.0A. /3/11/19
Lum Sum: 1.B./% 3 Val.: Yes	or No Survey held at 0.0.1.75 /10/19
CA / REV / REP. / 24 HRS	
	Vehicle: IN / OUT Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Person Contacted:	The U/C / Chasals frame / Body Structure affected due to collision.
The state of the s	The state of Body Structure affected due to collision.
16/10/19 @ 3.04p enail GIA B	
82922 02 1000	estimate and newsed to TMI.
82927.93 (Red &	(6936.87, 85%)
STR FUND - X - COUNTY SES	106132/ 11153/2 PER-25/13/2011
* alfforent 80.01	
111111111111111111111111111111111111111	RECEIVED 1 7 OCT 2019
a/Tene, File Pass to? : Prell. Report	Days Of Repair:
7/10 Muist : Final Report	KOSHITYOV No. of T.
7/10 Muist : Final Report	Resurvey No. of Trip: Survey Fee:
7/10 Muist : Final Report	Add Fac: Transportation 250
7/10 Muist : Final Report	Add Fee: : Site Insp (\$ ) _ 5 - RS _ SI 11
17/10 Must : Final Report	Add Fee: : Site Insp (\$ ) _ 5 - RS _ SI 11
17015 84-141	Add Fee: : Site Insp (\$ ) _ 5 - RS _ Si 11



51 UBLAVE 1, #61-25 PAYA UBLINDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: TBA

Date: 16th October 2019

Our Ref: CC3/TMI19018247/Kqf3

The Motor Claims Department
TOKIO MARINE INSURANCE SINGAPORE LTD

Attn: Ms Shirley Too

Dear Sirs/Mdm

# PRELIMINARY ADVICE OF VEHICLE NO. SHB 7566H .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 15/10/2019 at the premises of M/s TRANS-CAB and have the following to report:-

Workshop Estimate Amount	: S\$	19,864.80	12
Revised Estimate Amount	: S\$	2,927.93	
"Check" Items Amount	: S\$		
Market Value	: S\$		
LTA Reimbursement Value	: <u>S\$</u>	- V	
Nett Value	: S\$	-	

Description of Damage:

The vehicle sustained damages at the o/s front portion.

rear from

Comments/ Present Status: Damages consistent.

Yours faithfully

KONG SENG CHEONG Licensed Appraiser

#### Shiau Chan (LKKAuto)

From:

Ng Wai Yin <waiyin.ng@transcab.com.sg>

Sent:

Thursday, 17 October 2019 3:27 PM

To:

Shiau Chan (LKKAuto)

Subject:

RE: TP VEHICLE SHB 7566H (DOA: 13/10/2019) -- AAD1910-094

Attachments:

image001.wmz

Hi Shiau Chan

Amount confirmed \$ 2,927.93 (before GST).

Thank You Best Regards, Ng Wai Yin Finance Department TEL: 6603 1265 Ext.308

\*\*\* Please be reminded that all claims correspondence to be send to claims@transcab.com.sg



#### TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111 Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764 Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Shiau Chan (LKKAuto) [mailto:siewsc@lkkauto.com]

Sent: Thursday, 17 October, 2019 11:20 AM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Subject: TP VEHICLE SHB 7566H (DOA: 13/10/2019)

Dear Wai Yin,

#### WITHOUT PREJUDICE

Based on our surveyor, the calculation of repair cost will be at final fig \$2,927.93 before GST and 2 repair days.

Kindly check.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



This email has been checked for viruses by AVG antivirus software. www.avg.com

# Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Wednesday, 16 October 2019 3:04 PM

To:

motorclaims@tokiomarine.com.sg

Cc:

SUR

Subject:

DIRECT SURVEY INSPECTION ON WORKSHOP - TRANS-CAB AUTO SERVICES PTE

LTD, DOA: 13/10/2019, SHB 7566H (TP VEHICLE), SJP 7496D (OI VEHICLE)

Attachments:

CC3TMI19018247Kqf3.pdf; SHB7566 GIA.pdf; SHB7566 EST.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHB 7566H at M/s: TRANS-CAB AUTO SERVICES PTE LTD, 2 ANG MO KIO ST 63 SINGAPORE 569111 on 15/10/2019.

Enclosed herewith a copy of TP's GIA report, preliminary advice and estimated cost of repair.

Meanwhile, kindly create claim in merimen for our necessary action.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

# > Back to OneMotoring

	11 400 000 00000
wner ID Type:	Company
wner ID:	878K
ehicle Details	CUPTCOM
ehicle No.:	SHB7566H
ehicle to be Exported:	Yes
stended Deregistration Date:	14 Oct 2019
ehicle Make:	TOYOTA
ehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
rimary Colour:	Red
fanufacturing Year:	2018
ngine No.:	2ZR2C02471
hassis No.:	JTDKB3FU203079457
faximum Power Output:	90.0 kW (120 bhp)
pen Market Value:	\$26,605.00
riginal Registration Date:	11 Mar 2019
irst Registration Date:	11 Mar 2019
ransfer Count:	0
ctual ARF Paid: ntended PARF Rebate Details	\$14,247.00
ARF Eligibility:	Yes
ARF Eligibility Expiry Date:	10 Mar 2027
ARF Rebate Amount:	\$10,685.00
ntended COE Rebate Details	
OE Expiry Date:	10 Mar 2027
OE Category:	A - Car up to 1600cc & 97kW (130bhp)
OE Period(Years):	8
QP Paid:	\$20,420,00
OE Rebate Amount:	\$16,336.00
otal Rebate Amount: Message	\$27,021.00

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 14 Oct 2019

OK

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any witful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT
Date Of Report	14/10/2019 09:01
Date Of Accident	13/10/2019 14:10
Exact Location Of Accident	ECHELON CONDOMINIUM 7 ALEXANDRA VIEW
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SHB7566H
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	N 2000 CHANGE (CHANGE MICHAEL AND CHANGE CHANGE CHANGE AND CHANGE
Alternative Phone No	OFFICE-62866666
Vehicle Particulars	
Manufacturer	ТОУОТА
Model	PRIUS-1.8 HYBRID CVT (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VFX/P2203857
Cover Note Number	
Driver	
Name of Driver	LIM SWEE SENG
NRIC No	S6825727A
Date Of Birth	11/08/1968
Occupation	OUTDOOR
Date Of Driving Pass	18/12/1989
Driving Experience	29 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	+65-97542355
Fax Number	
Contact Number	

NOEMAIL

Address

1.10

BLK 613 WOODLANDS AVENUE 4

#08-483

Postcode

730613

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own

Vehicle

•

Insurance Company of Driver's Own Vehicle

.

#### General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

#### Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

.

involved in the accident

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

0000

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

#### **Details of Police Action**

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

#### Circumstances of Accident

On 13.10.2019 at about 1410hours, I was heading towards ECHELON Condominium, 7 Alexandra Road to alight my passenger, while stationary, suddenly I felt an impact. Vehicle B (SJP7496D) made a reverse without checking rear and hit onto my taxi's right side front portion.

#### Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

FILE TOO BIG

Was there any audio recorded?

NO

#### **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number

SJP7496D

Vehicle Make/Model/Colour

**Details Of Properties** 

Vehicle Category

PRIVATE CAR

Name of Driver

CHONG DAVID

NRIC/Passport Number

S1683331B

Contact Number

92265395

Address Postcode

Insurance Company Name

Nature Of Damage

2.705

Postcode

# Name LIM SWEE SENG Approximate Age Injuries Sustain Injured person in which vehicle? SHB7566H Were seat belts worn? YES Was this injured conveyed to hospital by ambulance? Address 2 DAYS MC

#### Sketch Plan Pg. 1

#### SKETCH PLAN

#### **IMPORTANT NOTICE**

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time: Driver's Signature (If driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

GIARMC SketchPlanForm\_V3

# Sketch Plan #2 Pg. 1

KETCH PLAN						
		++++				
<del></del>		++++				
		++++	<del>+++++</del> +	++++		+++
	1913	200	madrient			
		++++			++++	+++
		++++				
						++++
		<del>                                      </del>				++++
					10	
	DLE	Ece	attach	61A	Report	
	1					
W						
CLARATION Ve declare the foregoing par	ticulars are true in ev	ery respect.				>
	Jak.				(d.	<u> </u>
licyholder's Signature ite & Time:	Oriver's Sign (if driver is n Oate & Time	ot the policyhold	er)	Reporting ( Name: NRIC/FIN N	Centre Personnel	's Signature

GIARMS Statch Francisco. VI

Page 5 of 12

2

#### Trans-cab Auto Services Pte Ltd Not Nothanin' Resurry BEpaint No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No.: 6287 6666 Fax No.: 6257 1330 CO./GST Reg. No. 201019626G SHB 7566H 8 2927.93 SHB 7566H Vehicle No.: Chassis No.: JTDKB3FU203079457 Vehicle Make: 15 CUT 2018 TOYOTA Vehicle Model: PRIUS Date of Accident: 13.10.19 Third Party Insurer: TOKIO MARINE Date of Registration: 11/3/2019 PART LIST Bux 1011 516.00 -FRONT BUMPER \$ 1 1 P1 82.30 W 2 \$ FRONT BUMPER SIDE RETAINER RH √ 132.70 X 3 ABSORBER, FRONT BUMPER, LOWER 5 1 ABSORBER, FRONT BUMPER ENERGY 4 \$ 79.60 X 1 5 951.40 X 5 FRONT LED LAMP (LOWER) RH \$ 1 MyoM 2,637.60 Z 6 1 FRONT HEADLAMP RH \$ ∫<sub>4</sub> 960.50 7 COMPUTER SUB-ASSY, HEADLAMP, RH NO.1 \$ 1 √~ 487.50 8 MOTOR, HEADLAMP LEVELING, RH \$ 1 M 977.80 9 \$ 1 FRONT FENDER RH 10 \$ 202.50 1 LINER, FRONT FENDER, RH \$ 11 54.60 1 FRONT FENDER EMBLEM RH 346.00 12 GRILLE SUB-ASSY, RADIATOR \$ 1 5m 170.10 13 1 GRILLE, RADIATOR, LOWER NO.1 5 FRONT BONNET \$ 7 983.10 14 1 Sa 58.90 15 HINGE ASSY, HOOD, RH \$ 1 TOTAL \$ 8,640.60 25% \$ 2,160.15 \$ 6.480.45 Special Nett 1,570.55 X FRONT WHEEL RIM \$ 1 1 5 175.80 X 2 1 FRONT WHEEL RIM COVER \$ JL 350.00 X 3 \$ FRONT TYRE 195/65/15 4 1 CLIP, FRONT FENDER LINER \$ Na 22.00 / 200.00 X 5 1 FRONT NUMBER PLATE WITH MOULDING \$ 6 1 BUMPER CLIP FRT 66.00 4

TOTAL \$

TOTAL PARTS \$

2.384.35

8,864,80

. 1

### Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7566H

LABOUR

LKK Able Co (PART-BY-PART) Repair Days Use Repairer of the following:  To resurvey between a pray por the  To display day upon the resulting of the proof of of th	25 days 2day	
Over All Total	\$ 19,864.80	=
TOTAL	 11,000.00	
To transfer of Front Bonnet fittings, attachments and perform water seepage test.	\$ 1 ~ 170.00	×
To Check Electrical Lighting Concerned.	\$ 170.00	15/
To Rust-Proofing Of The Affected Areas.	\$ ~~ 170.00	X
To check steering geometry and computer wheel alignment	\$ مم <sub>220.00</sub>	<
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$ ~~ 380.00	<
To transfer of tire, rim and on wheel balancing.	\$ <b>ル</b> 170.00	X
To transfer of Front Bumper fittings, attachments and perform water seepage test.	\$ <b>ル</b> ~ 170.00	×
To transfer of Fender fittings, attachments and perform water seepage test.	\$ ~~ 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$ ~~ 380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$ 4,500.00	200
Putty And Spray Painting Of The Affected Portion.	\$ 4,500.00	220

AAD1910-094

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI19018247/KQF3N2

Date:

23/10/2019

REFERENCE

Handling Insurer:

Tokio Marine Insurance Singapore Ltd

Policy No:

MK000808

Claimant Vehicle No:

SHB7566H

Insured Vehicle No:

SJP7496D

Date of Loss:

13/10/2019

Nature of Claim:

TP

Claim No: M1908059

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SHB7566H

Make & Model:

TOYOTA PRIUS, 1.8 HYBRID CVT (A)

Engine No:

2ZR2C02471

Reg. Date: Colour:

11/03/2019 (Man. Year: 2018) Metallic White/Red

Chassis No: Odometer:

JTDKB3FU203079457 65201 km

Engine Capacity:

1798 cc

Market Value/New Car

N/A

Price: Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

195/65R15

Rear Tyre Size:

195/65R15

Front Left Side:

Yokohama 8 mm

Rear Left Side:

Yokohama 8 mm

Front Right Side: Yokohama 8 mm Rear Right Side:

Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts Miscellaneous Items	Repairer's 8,864.80 0.00	Adjuster's 2,492.93 0.00	5,371.87 0.00	Diff % 71.88
Labour Paintwork Labour	11,000.00	435.00 0.00	10,565.00 0.00	96.05
Towing Gross Total (S\$)	0.00 19,864.80	0.00 2,927.93	16,936.87	85.26
+ GST 7.00/7.00% (S\$)	1,390.54	204.96	1,185.58	85.26
Nett Amount (S\$)	21,255.34	3,132.89	18,122.45	85.26

INSPECTION

Date of Assignment:

17/10/2019

Date Inspected:

15/10/2019 Inspected At:

Trans Cab Auto Services Pte Ltd - Amk

(HQ)

No 2 Ang Mo Kio St 63 Singapore 569111

Estimated Period of Repair:

2.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# REPAIR DETAILS

Referen	ce	
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Oct 2019)
Parts:	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted	, no print-code for SHB7566H)
Validity:	로마 1903 - Common 프로그램 전 1903 - 1903	
Further Info:		not in reference catalogue are prefixed with an asterisk *.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Buckled/Distorted	516.00 FL	*516.00 FL
2	1	*ABSORBER,FRONT BUMPER,LOWER	Serviceable	132.70 FL	*-FL
3	1	*ABSORBER,FRONT BUMPER ENERGY	Serviceable	79.60 FL	*-FL
4	1	*FRONT LED LAMP (LOWER) RH	Serviceable	951.40 FL	*-FL
5	1	*FRONT HEADLAMP RH	Mtg Cracked	2,637.60 FL	*2,637.60 FL
6	1	*COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	Serviceable	960.50 FL	*-FL
7	1	*MOTOR, HEADLAMP LEVELING, RH	Serviceable	487.50 FL	*-FL
8	1	*FRONT FENDER RH	Repair	977.80 FL	
9	1	*LINER,FRONT FENDER RH	Serviceable	202.50 FL	*-FL
10	1	*FRONT FENDER EMBLEM RH	Not Necessary	54.60 FL	*-FL
11	1	*GRILLE SUB-ASSY, RADIATOR	Serviceable	346.00 FL	*-FL
12	1	*GRILLE RADIATOR, LOWER NO 1	Serviceable	170.10 FL	*-FL
13	1	*FRONT BONNET	Repair	983.10 FL	*-FL
14	1	'HINGE ASSY, HOOD, RH	Serviceable	58.90 FL	*-FL
15	1	*FRONT WHEEL RIM	Serviceable	1,570.55 FS	
16	1	*FRONT WHEEL RIM COVER	Serviceable	175.80 FS	*-FS
17	1	*FRONT TYRE 195/65/15	Serviceable	350.00 FS	*-F8
18	1	*CLIP,FRONT FENDER LINER	Not Necessary	22.00 FS	*-FS
19	1	*FRONT NUMBER PLATE WITH MOULDING	Serviceable	200.00 FS	*-F8
20	1	*BUMPER CLIP FRT	Necessary	66.00 FS	*66.00 FS
21 F=Fr	1 anchise	*FRONT BUMPER SIDE RETAINER RH part. S=SpcNett, L=ListItemDisc.	Distorted	61.73 FS	*61.73FS
1.00111		Personal Per	Sub Total (S\$)	11,004.38	3,281.33
		- List Item Discount on L Item	and the second s		788.40
			Total Parts (S\$)	8,864.80	2,492.93

# Recommended Miscellaneous Items There are no new miscellaneous items selected.

Red	Recommended Labour							
No	Particulars	Lab.Type	Repairer's	Amount				
Labo	our Items							
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	4,500.00	220.00				
2	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	New	4,500.00	200.00				
3	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	New	380.00	0.00				
4	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00				
5	TO TRANSFER OF FRONT BUMPER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00				
6	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	Repair	170,00	0.00				
7	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	Repair	380.00	0.00				
8	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	Repair	220.00	0.00				
9	TO RUST-PROOFING OF THE AFFECTED AREAS.	Repair	170.00	0.00				
10	TO CHECK ELECTRICAL LIGHTING CONCERNED.	Repair	170.00	15.00				
11	TO TRANSFER OF FRONT BONNET FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	Repair	170.00	0.00				
	Gross Labou	r Cost (S\$)	11,000.00	435.00				
	Report was unsubmitted during	g this print-out.						

< END OF ESTIMATES >