

ASS. REC. BY:

REF:

TMI/CC3/TML K018248/tcf3n2

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

1.13.1%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S11096434

Yr Regn:

12, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Tug Pmt

c.c

1798

Colour:

M. White/Pw

A/C:

Insured / Std / NI / NA

Sp. Reading

48147

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB37U 3.0 30 77362

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F:

R:

195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

3

mm

L/Bal.

4

mm

L/Bal.

3

mm

D.O.A.

11/10/19

D.O.I.

15/10/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 File pass to

8 1206-68 2226-68 to Summit

SHD 9643 U - CC3 / AIG 130704 B3 / b1 a 392

SKY 4894 - X

D.O.A - 30/10/2019

(\$ 19,686.17 Red - 90%)

RECEIVED 05 NOV 2019

Date/Time, File Pass to?

1) 08/11/19

Date/Time, File Return to?

2)



: Prell. Report



: Final Report

Days Of Repair:

2

Resurvey No. of Trip:

1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

250

11

261

Report Format:

Lump Sum / I.B.I. (\$

2,226.68 p/p

Shirley Hiew (LKK Auto)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Friday, 8 November 2019 1:10 pm
To: Shirley Hiew (LKK Auto)
Cc: SUR
Subject: FW: TCS REF: AAD1910-116--Accident involving SHD 9643U & SKV 439Y on 11/10/2019
Attachments: ESTIMATE MARKED.pdf; IMG_0821.JPG; IMG_0819.JPG; IMG_0820.JPG

Hi Shirley

Amount confirmed \$ 2,226.68 (before GST).

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**

TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63
Singapore 569111
Tel: 6287 6666 Fax: 6287 7764

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Thursday, 7 November, 2019 3:13 PM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: TCS REF: AAD1910-116--Accident involving SHD 9643U & SKV 439Y on 11/10/2019

Dear Wai Yin,

Please confirm final fig \$ 2,226.68 @ 2 days of repairs before GST.

Kindly provide us before paint photo.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

DIRECT SURVEY INSPECTION ON WORKSHOP -TRANS-CAB AUTO SERVICES PTE LTD, DOA:12/10/2019, SHD 9643U (TP VEHICLE), SKV 439Y (OI VEHICLE)

Shirley Hiew (LKK Auto)

Wed 16/10/2019 3:51 PM

To: motorclaims@tokiomarine.com.sg <motorclaims@tokiomarine.com.sg>

Cc: SUR <sur@lkkauto.com>

📎 3 attachments (1 MB)

TP GIA REPORT.pdf; ESTIMATE.pdf; PRELI ADVISE - SHD 9643U.pdf;

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHD 9643U at M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63 SINGAPORE 569111 on 15/10/2019

Enclosed herewith a copy of TP's GIA report, estimated cost of repair and preliminary revised.

Kindly create claim in merimen for our necessary action.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	878K
Vehicle Details	
Vehicle No.:	SHD9643U
Vehicle to be Exported:	Yes
Intended Deregistration Date:	14 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	2ZR2B80290
Chassis No.:	JTDKB3FU303077362
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,605.00
Original Registration Date:	12 Dec 2018
First Registration Date:	12 Dec 2018
Transfer Count:	0
Actual ARF Paid:	\$14,247.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Dec 2026
PARF Rebate Amount:	\$10,685.00
Intended COE Rebate Details	
COE Expiry Date:	11 Dec 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$22,057.00
COE Rebate Amount:	\$17,645.00
Total Rebate Amount:	\$28,330.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 14 Oct 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GlA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/10/2019 16:49
Date Of Accident	12/10/2019 21:30
Exact Location Of Accident	CTE TOWARDS ANG MO KIO
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD9643U
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS-1.8 HYBRID CVT (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VFX/P1680520
Cover Note Number	

Driver

Name of Driver	DANIEL H K ANG
NRIC No	S1721049A
Date Of Birth	24/09/1965
Occupation	OUTDOOR
Date Of Driving Pass	16/10/1984
Driving Experience	34 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82829438
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 334D YISHUN STREET 31 #12-135
Postcode	764334
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 12.10.2019 at about 2130hours, I was stationary on the extreme right lane along CTE towards Ang Mo Kio due to congestion ahead. Suddenly I felt an impact. Vehicle B (SKV439Y) hit onto my taxi's rear portion.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKV439Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHOW MEI YIN
NRIC/Passport Number	S6911728G
Contact Number	97882877
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN

CTE towards
Ang Mo Kio

A
B

A= SMO 9643U
B= SKV 431Y

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

pls see attach GA Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9643U

AAD1910-116

*Not Notarized
Resuming B4 paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

15 OCT 2019

SHD 9643U

JTDKB3FU303077362

TOYOTA

PRIUS

12.10.19

TOKIO MARINE

12/12/2018

*8+200.00
2226.68***PART****LIST**

1	1	REAR BUMPER	\$	<i>Am</i>	442.60	✓
2	1	REAR BUMPER RE-INFORCEMENT	\$	<i>Am</i>	332.70	✓
3	1	REAR BUMPER TOWING COVER	\$	<i>Am</i>	15.40	✓
4	1	REAR BUMPER UNDER COVER (BLACK)	\$	<i>BT/Am</i>	576.30	✓
5	1	ANTENNA, ELECTRICAL KEY	\$	<i>Am</i>	72.00	X
6	1	REAR BUMPER SIDE RETAINER LH	\$	<i>Am</i>	116.50	X
7	1	REAR BUMPER SIDE RETAINER RH	\$	<i>Am</i>	117.70	X
8	1	REAR TAILGATE	\$	<i>Am</i>	1,147.80	X
9	1	REAR TAILGATE OUTER GARNISH	\$	<i>Am</i>	925.60	X
10	1	COVER, REAR COMBINATION LAMP, RH	\$	<i>Am</i>	64.50	} X
11	1	COVER, REAR COMBINATION LAMP, LH	\$	<i>Am</i>	64.50	
12	1	GARNISH, BACK DOOR SIDE, LH	\$	<i>Am</i>	95.60	
13	1	GARNISH, BACK DOOR SIDE, RH	\$	<i>Am</i>	95.60	
14	1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER RH	\$	<i>Am</i>	56.50	
15	1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER LH	\$	<i>Am</i>	56.50	
16	1	BOARD ASSY, BACK DOOR TRIM	\$	<i>Am</i>	259.20	
17	1	PANEL ASSY, BACK DOOR TRIM, UPPER	\$	<i>Am</i>	52.10	
18	1	REAR TAILGATE WEATHERSTRIP	\$	<i>Am</i>	372.30	
19	1	PANEL SUB-ASSY, BODY LOWER BACK	\$	<i>Am</i>	650.30	
20	1	TAILLAMP LOWER RH	\$	<i>Am</i>	502.00	
21	1	TAILLAMP UPPER RH	\$	<i>Am</i>	451.80	
22	1	REAR BUMPER SIDE RH	\$	<i>Am</i>	123.70	
23	1	REAR BUMPER SIDE LH	\$	<i>Am</i>	123.70	
24	1	TAILLAMP LOWER LH	\$	<i>Am</i>	502.00	
25	1	TAILLAMP UPPER LH	\$	<i>Am</i>	443.30	
26	1	BOARD, BACK DOOR TRIM	\$	<i>Am</i>	225.20	
27	1	PANEL ASSY, DECK TRIM SIDE, RH	\$	<i>Am</i>	355.90	
28	1	PANEL ASSY, DECK TRIM SIDE, LH	\$	<i>Am</i>	355.90	
29	1	COVER, DECK TRIM, REAR	\$	<i>Am</i>	126.70	
30	1	COVER, FLOOR UNDER, NO 1	\$	<i>Am</i>	175.10	

Trans-cab Auto Services Pte Ltd

AAD1910-116

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9643U

31	1	COVER, FLOOR UNDER, NO 2
32	1	COVER, REAR FLOOR

	\$	<i>Return</i> 241.90 ✓
	\$	<i>nn</i> 229.90 X
TOTAL	\$	9,370.80
25%	\$	2,342.70
	\$	7,028.10

Special Nett

1	1SET	PARKING AID
2	1SET	REAR BUMPER CLIP
3	2	REAR WINDSCREEN SEALANT
4	1	WINDSCREEN MOULDING
5	1	REAR WINDSCREEN INNER SPONGE SEAL
6	1	REAR TAILGATE TOYOTA LOGO
7	1	REAR TAILGATE WORDING 'PRIUS'
8	1	REAR TAILGATE WORDING 'HYBRID'
9	1	REAR TAILGATE STICKER 'TRANS-CAB'
10	1	REAR TAILGATE STICKER '6555-3333'
11	1	REAR BUMPER PROTECTOR
12	1	REAR WHEEL RIM
13	1	REAR TYRE 195/65/15
14	1	REAR WHEEL RIM COVER

\$	<i>nd</i> 700.00	
\$	<i>nn</i> 55.00	✓
\$	<i>nn</i> 80.00	
\$	<i>nn</i> 100.00	
\$	<i>nn</i> 100.00	
\$	<i>nn</i> 47.00	
\$	<i>nn</i> 52.90	
\$	<i>nn</i> 53.50	
\$	<i>nn</i> 80.00	
\$	<i>nn</i> 80.00	
\$	<i>nn</i> 100.00	<i>4000</i>
\$	<i>SL</i> 1,570.55	X
\$	<i>SL</i> 350.00	X
\$	<i>nn</i> 175.80	X
TOTAL	\$	3,544.75

TOTAL PARTS \$ 10,572.85**LABOUR**

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$ *nn* 170.00 X

Putty And Spray Painting Of The Affected Portion.

\$ 4,500.00 *4400*

To transfer of Rear Bumper fittings, attachments and perform water seepage test.

\$ *nn* 170.00 X

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ *nn* 170.00 X

To transfer of rear windscreen glass to facilitate bodywork repair.

\$ *nn* 170.00 X

Trans-cab Auto Services Pte Ltd**AAD1910-116**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9643U

To Rust-Proofing Of The Affected Areas.	\$	~ 170.00 X
To reinstall rear bumper parking sensor.	\$	170.00 50/
To check steering geometry and computer wheel alignment	\$	~ 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	~ 170.00 X
To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	~ 380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	~ 380.00 X
To Check Electrical Lighting Concerned.	\$	170.00 15/
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,500.00 200/
TOTAL	\$	11,340.00
Over All Total	\$	21,912.85

(PART-BY-PART) Repair Days**15 Days****2 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary (or (s)) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI19018248/KSF3N2
Date: 15/11/2019**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MS003090
Claimant Vehicle No :	SHD9643U	Insured Vehicle No :	SKV439Y
Date of Loss:	11/10/2019	Nature of Claim:	TP
		Claim No:	M1908038

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD9643U	Engine No:	2ZR2B80290
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FU303077362
Reg. Date:	12/12/2018 (Man. Year: 2018)	Odometer:	48147 km
Colour:	Metallic White/Red		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Goodyear 4 mm	Rear Left Side:	Goodyear 3 mm
Front Right Side:	Goodyear 4 mm	Rear Right Side:	Goodyear 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,572.85	1,521.67	9,051.18	85.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,340.00	705.00	10,635.00	93.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	21,912.85	2,226.67	19,686.18	89.84
+ GST 7.00/7.00% (\$\$)	1,533.90	155.87	1,378.03	89.84
Nett Amount (\$\$)	23,446.75	2,382.54	21,064.21	89.84

INSPECTION

Date of Assignment:	17/10/2019	
Date Inspected:	15/10/2019	Inspected At:
		Trans Cab Auto Services Pte Ltd - Amk (HQ) No 2 Ang Mo Kio St 63 Singapore 569111
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Different 1 cents -Finalise confirm amount: \$2,226.68

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Nov 2019)
Parts:	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD9643U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	442.60 FL	*442.60 FL
2	1		*REAR BUMPER RE-INFORCEMENT	Bent	332.70 FL	*332.70 FL
3	1		*REAR BUMPER TOWING COVER	Missing	15.40 FL	*15.40 FL
4	1		*REAR BUMPER UNDER COVER (BLACK)	Bent/Cracked	576.30 FL	*576.30 FL
5	1		*ANTENNA,ELECTRICAL KEY	Serviceable	72.00 FL	*- FL
6	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	116.50 FL	*- FL
7	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	117.70 FL	*- FL
8	1		*REAR TAILGATE	Repair	1,147.80 FL	*- FL
9	1		*REAR TAILGATE OUTER GARNISH	Serviceable	925.60 FL	*- FL
10	1		*COVER,REAR COMBINATION LAMP,RH	Serviceable	64.50 FL	*- FL
11	1		*COVER,REAR COMBINATION LAMP,LH	Serviceable	64.50 FL	*- FL
12	1		*GARNISH,BACK DOOR SIDE,LH	Serviceable	95.60 FL	*- FL
13	1		*GARNISH,BACK DOOR SIDE,RH	Serviceable	95.60 FL	*- FL
14	1		*MOULDING,BACK DOOR OUTSIDE GARNISH,LOWER RH	Serviceable	56.50 FL	*- FL
15	1		*MOULDING,BACK DOOR OUTSIDE GARNISH,LOWER LH	Serviceable	56.50 FL	*- FL
16	1		*BOARD,ASSY BACK DOOR TRIM	Serviceable	259.20 FL	*- FL
17	1		*PANEL ASSY,BACK DOOR TRIM,UPPER	Serviceable	52.10 FL	*- FL
18	1		*REAR TAILGATE WEATHERSTRIP	Serviceable	372.30 FL	*- FL
19	1		*PANEL SUB-ASSY,BODY LOWER BACK	Repair	650.30 FL	*- FL
20	1		*TAILLAMP LOWER RH	Serviceable	502.00 FL	*- FL
21	1		*TAILLAMP UPPER RH	Serviceable	451.80 FL	*- FL
22	1		*REAR BUMPER SIDE RH	Serviceable	123.70 FL	*- FL
23	1		*REAR BUMPER SIDE LH	Serviceable	123.70 FL	*- FL
24	1		*TAILLAMP LOWER LH	Serviceable	502.00 FL	*- FL
25	1		*TAILLAMP UPPER LH	Serviceable	443.30 FL	*- FL
26	1		*BOARD,BACK DOOR TRIM	Serviceable	225.20 FL	*- FL
27	1		*PANEL ASSY,DECK TRIM SIDE,RH	Serviceable	355.90 FL	*- FL
28	1		*PANEL ASSY,DECK TRIM SIDE,LH	Serviceable	355.90 FL	*- FL
29	1		*COVER,DECK TRIM,REAR	Serviceable	126.70 FL	*- FL
30	1		*COVER,FLOOR UNDER,NO 1	Serviceable	175.10 FL	*- FL
31	1		*COVER,FLOOR UNDER,NO 2	Deformed	241.90 FL	*241.90 FL
32	1		*COVER,REAR FLOOR	Serviceable	229.90 FL	*- FL
33	1		*SET PARKING AID	Dented	700.00 FS	*220.00 FS
34	1		*SET REAR BUMPER CLIP	Necessary	55.00 FS	*55.00 FS
35	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
36	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
37	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
38	1		*REAR TAILGATE TOYOTA LOGO	Not Necessary	47.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*REAR TAILGATE WORDING PRIUS	Not Necessary	52.90 FS	*- FS
40	1		*REAR TAILGATE WORDING HYBRID	Not Necessary	53.50 FS	*- FS
41	1		*REAR TAILGATE STICKER TRANS-CAB	Not Necessary	80.00 FS	*- FS
42	1		*REAR TAILGATE STICKER 6555-3333	Not Necessary	80.00 FS	*- FS
43	1		*REAR BUMPER PROTECTOR	Necessary	100.00 FS	*40.00 FS
44	1		*REAR WHEEL RIM	Serviceable	1,570.55 FS	*- FS
45	1		*REAR TYRE 195/65/15	Serviceable	350.00 FS	*- FS
46	1		*REAR WHEEL RIM COVER	Serviceable	175.80 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,915.55	1,923.90
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,342.70	402.23
Total Parts (\$\$)	10,572.85	1,521.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER OF TAILGATE FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	4,500.00	440.00
3	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
4	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
5	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	0.00
6	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
7	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
8	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
9	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00
10	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR	New	380.00	0.00
11	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR	New	380.00	0.00
12	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	15.00
13	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	4,500.00	200.00
Gross Labour Cost (S\$)			11,340.00	705.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >