

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5628X**AAD1910-114***Not Notified*
1/1 Sep 8

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

15 OCT 2019

SHC 5628X

VF1ABL15AUC279627

RENAULT

LATITUDE

11.10.19

TOXIO

4/11/2014

		PART		LIST	
1	1	BUMPER COVER REAR	\$	B 561.70	✓
2	1	BUMPER LOWER REAR	\$	B 411.90	✓
3	1	BUMPER BRACKET CTR REAR	\$	CM 98.10	✓
4	1	BUMPER BRACKET SIDE RH REAR	\$	D 82.10	✓
5	1	BUMPER RETAINER RH REAR	\$	D 59.80	✓
6	1	BUMPER REFLECTOR RH	\$	CM 16.60	✓
7	1	BUMPER BRACKET SIDE LH REAR	\$	L 80.80	X
8	1	BUMPER RETAINER LH REAR	\$	D 54.20	✓
9	1	BUMPER REFLECTOR LH	\$	L 16.60	X
10	1	BUMPER BEAM REAR	\$	B 547.80	✓
11	1	BUMPER BEAM BRACKET LH REAR	\$	D 114.50	✓
12	1	BUMPER BEAM BRACKET RH REAR	\$	B 100.90	✓
13	1	BUMPER BLOCK LH REAR	\$	L 75.70	X
14	1	BUMPER BLOCK RH REAR	\$	L 76.50	X
15	1	BOOT REAR	\$	B 1,677.20	✓
16	1	BOOT FINISHER	\$	L 344.70	X
17	1	BOOT WHEATERSTRIP	\$	CV 178.20	509m
18	1	BOOT REFLECTOR LAMP LH	\$	B 277.70	X
19	1	BOOT REFLECTOR LAMP RH	\$	CM 277.70	✓
20	1	BOOT BADGE 'RENAULT'	\$	MC 82.40	✓
21	1	BOOT BADGE	\$	MC 95.80	✓
22	1	BOOT STRUT LH	\$	L 145.10	X
23	1	BOOT STRUT RH	\$	L 145.10	X
24	1	BOOT HINGE LH	\$	N 254.20	X
25	1	BOOT HINGE RH	\$	N 253.80	X
26	1	BOOT INNER TRIM BOARD	\$	Return 611.00	✓
27	1	BOOT SWITCH	\$	L 113.00	X
28	1	BOOT LOCK	\$	N 246.60	X

Trans-cab Auto Services Pte Ltd**AAD1910-114**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5628X

29	1	BOOT LOCK CATCH	\$	<i>N</i>	41.70	X
30	2	LICENCE PLATE LAMP	\$	<i>SL</i>	26.30	X
31	2	BOOT RUBBER PLUG	\$	<i>SL</i>	139.30	X
32	2	BOOT BUFFER	\$	<i>SL</i>	26.80	X
33	1	BOOT LOCK LINKAGE	\$	<i>SL</i>	20.60	X
34	1	BOOT LOCK LINKAGE HOLDER	\$	<i>SL</i>	99.50	X
35	1	FENDER PANEL INNER TRIM REAR RH	\$	<i>Reform</i>	671.45	✓
36	1	FENDER PANEL REAR RH	\$	<i>Re</i>	1,933.20	✓
37	1	WHEELARCH REAR RH	\$	<i>SL</i>	275.40	X
38	1	FENDER PANEL INNER REAR RH	\$	<i>N</i>	952.50	X
39	1	FENDER INNER BOARD LH	\$	<i>SL</i>	561.40	X
40	1	FENDER INNER BOARD RH	\$	<i>SL</i>	561.40	X
41	1	SPARE TYRE BOARD	\$	<i>SL</i>	680.90	X
42	1	TAILLAMP RH	\$	<i>CM</i>	313.10	✓
43	1	TAILLAMP PANEL RH	\$	<i>Re</i>	401.40	✓
44	1	TAILLAMP LH	\$	<i>mgem</i>	401.40	✓
45	1	TAILLAMP PANEL LH	\$	<i>N</i>	401.40	X
46	1	AIR VENT LH	\$	<i>SL</i>	59.40	X
47	1	AIR VENT RH	\$	<i>SL</i>	59.40	X
48	1	OUTER PANEL REAR (End Panel)	\$	<i>Re</i>	745.80	✓
49	1	OUTER PANEL REAR (End Panel) TRIM	\$	<i>mg DI</i>	404.56	✓
50	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	<i>BTIR</i>	1,229.40	✓
51	1	SPARE WHEEL PANEL TRIM	\$	<i>SL</i>	612.21	X
52	1	EXHAUST REAR	\$	<i>N</i>	5,263.60	
53	1	EXHAUST CAP REAR	\$	<i>N</i>	125.40	
54	1	BUMPER HARNESS REAR	\$	<i>N</i>	301.10	
55	1	FUEL TANK	\$	<i>SL</i>	2,748.95	
56	1	FUEL TANK PUMP	\$	<i>SL</i>	1,266.53	
57	1	FUEL PIPE SHORT	\$	<i>SL</i>	611.80	
58	1	FUEL PIPE LONG	\$	<i>SL</i>	1,148.12	
59	1	TUBE- FUEL SUPPLY	\$	<i>SL</i>	370.01	X
60	1	TUBE- FUEL RETURN	\$	<i>SL</i>	201.29	
61	1	FUEL TANK NECK	\$	<i>SL</i>	686.55	
62	1	TUBE- FILLER	\$	<i>SL</i>	297.19	
TOTAL			\$		30,638.76	
10%			\$		3,063.88	
			\$		27,574.88	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5628X**AAD1910-114****Special Nett**

1	1SET PARKING AID	\$	Short 700.00	400.00
2	1SET REAR BUMPER CLIP	\$	na 66.00	—
3	1SET BUMPER BRACKET CTR CLIP	\$	na 33.00	—
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na 10.00	X
5	1SET BUMPER RETAINER RH CLIP RR	\$	na 20.00	X
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	na 10.00	X
7	1SET BUMPER RETAINER CLIP LH RR	\$	na 20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	na 22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	na 66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	na 16.00	X
11	1 EXHAUST PIPE CLAMP	\$	na 68.80	X
12	1SET BOOT FINISHER CLIP	\$	na 24.20	X
13	1 BOOT STICKER "Trans-cab"	\$	na 30.00	✓
14	1 BOOT STICKER "6555-3333"	\$	na 30.00	—
15	1 BOOT INNER TRIM CLIP	\$	na 45.00	—
16	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	na 385.00	X
17	1 SPARE TYRE	\$	na 330.00	X
18	1 FENDER INNER TRIM CLIP LH	\$	na 28.00	X
19	1 TAILLAMP CLIP RH	\$	na 5.00	✓
20	2 REAR WINDSCREEN SEALANT	\$	na 80.00	40.00
21	1 WINDSCREEN MOULDING	\$	na 100.00	—
22	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na 100.00	30.00
23	1 TAILLAMP CLIP LH	\$	na 5.00	✓
24	1 Rear Bumper Protector	\$	na 100.00	} X
25	1 REAR LEFT TYRE	\$	na 300.00	
26	1 REAR LEFT TYRE RIM	\$	na 380.00	
27	1 REAR RIGHT TYRE	\$	na 300.00	
28	1 REAR RIGHT TYRE RIM	\$	na 380.00	
29	1SET FENDER WHEELARCH REAR RH CLIP	\$	na 35.00	
30	1 FENDER INNER TRIM CLIP RH	\$	na 28.00	
TOTAL		\$	3,717.00	

TOTAL PARTS \$ 31,291.88

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5628X**AAD1910-114****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	9,000.00	1100
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	9,000.00	1800
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	800
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	600
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	} 1000
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To Rust-Proofing Of The Affected Areas.	\$	170.00	1200
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	600
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	170.00	1200

Trans-cab Auto Services Pte Ltd**AAD1910-114**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5628X

To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	X
Towing Fees	\$	170.00	501
To drop diesel tank, pipes, hoses and renew the necessary parts and final checking and testing for leak.	\$	440.00	601
TOTAL	\$	22,810.00	
Over All Total	\$	54,101.88	

(LUMP SUM) Repair Days**30 DAYS**

14 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: