

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7905M**AAD1910-098**

Not Notified
Recovery B4 paint
81976.83

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

15 OCT 2019

SHB 7905M

JTDKB3FU803079625

TOYOTA

PRIUS

14.10.19

AIG

29/3/2019

		PART	LIST	
1	1	REAR BUMPER	\$ <i>Bu</i> 442.60	✓
2	1	REAR BUMPER RE-INFORCEMENT	\$ <i>R</i> 332.70	X
3	1	REAR BUMPER TOWING COVER	\$ <i>SL</i> 15.40	X
4	1	REAR BUMPER UNDER COVER (BLACK)	\$ <i>Diy</i> 576.30	✓
5	1	REAR BUMPER SIDE RETAINER LH	\$ <i>Diy</i> 116.50	✓
6	1	REAR BUMPER SIDE RETAINER RH	\$ <i>SL</i> 117.70	X
7	1	REAR TAILGATE	\$ <i>R</i> 1,147.80	} X
8	1	REAR TAILGATE OUTER GARNISH	\$ <i>SL</i> 925.60	
9	1	COVER, REAR COMBINATION LAMP, RH	\$ <i>SL</i> 64.50	
10	1	COVER, REAR COMBINATION LAMP, LH	\$ <i>SL</i> 64.50	
11	1	GARNISH, BACK DOOR SIDE, LH	\$ <i>SL</i> 95.60	
12	1	GARNISH, BACK DOOR SIDE, RH	\$ <i>SL</i> 95.60	
13	1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER RH	\$ <i>SL</i> 56.50	
14	1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER LH	\$ <i>SL</i> 56.50	
15	1	BOARD ASSY, BACK DOOR TRIM	\$ <i>SL</i> 259.20	
16	1	PANEL ASSY, BACK DOOR TRIM, UPPER	\$ <i>SL</i> 52.10	
17	1	REAR TAILGATE WEATHERSTRIP	\$ <i>SL</i> 372.30	
18	1	PANEL SUB-ASSY, BODY LOWER BACK	\$ <i>SL</i> 650.30	
19	1	TAILLAMP LOWER RH	\$ <i>SL</i> 502.00	
20	1	TAILLAMP UPPER RH	\$ <i>SL</i> 451.80	
21	1	REAR BUMPER SIDE RH	\$ <i>SL</i> 123.70	
22	1	REAR BUMPER SIDE LH	\$ <i>mgent</i> 123.70	✓
23	1	TAILLAMP LOWER LH	\$ <i>CM</i> 502.00	✓
24	1	TAILLAMP UPPER LH	\$ <i>SL</i> 443.30	X
25	1	REAR LH FENDER PANEL	\$ <i>R</i> 854.80	X
26	1	LINER, REAR WHEEL HOUSE, LH	\$ <i>n</i> 139.80	X
27	1	BOARD, BACK DOOR TRIM	\$ <i>SL</i> 225.20	X

Trans-cab Auto Services Pte Ltd**AAD1910-098**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7905M

28	1	PANEL ASSY, DECK TRIM SIDE, RH	\$	SH	355.90	}	X
29	1	PANEL ASSY, DECK TRIM SIDE, LH	\$	SH	355.90		
30	1	COVER, FLOOR UNDER, NO.1	\$	SH	175.10		
31	1	COVER, FLOOR UNDER, NO.2	\$	SH	241.90		
32	1	COVER, REAR FLOOR	\$	SH	229.90		
33	1	COVER, DECK TRIM, REAR	\$	SH	126.70		
34	1	DUCT ASSY, QUARTER VENT, LH	\$	SH	67.00		
35	1	TROUGH, BACK DOOR OPENING, LH	\$	SH	103.40		
TOTAL			\$		10,463.80		
25%			\$		2,615.95		
			\$		7,847.85		

Special Nett

Special Net					
1	1SET	PARKING AID	\$	SH	700.00 X
2	1SET	REAR BUMPER CLIP	\$	na	66.00
3	2	REAR WINDSCREEN SEALANT	\$	na	80.00
4	1	WINDSCREEN MOULDING	\$	na	100.00
5	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00
6	1	REAR TAILGATE TOYOTA LOGO	\$	na	47.00
7	1	REAR TAILGATE WORDING 'PRIUS'	\$	na	52.90
8	1	REAR TAILGATE WORDING 'HYBRID'	\$	na	53.50
9	1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	na	80.00
10	1	REAR TAILGATE STICKER '6555-3333'	\$	na	80.00
11	1	REAR BUMPER PROTECTOR	\$	na	100.00 400.00
12	1	REAR WHEEL RIM	\$	SH	1,570.55 X
13	1	REAR TYRE 195/65/15	\$	SH	350.00 X
14	1	REAR WHEEL RIM COVER	\$	SH	175.80 X
15	1SET	FENDER WHEELARCH REAR LH CLIP	\$	na	35.00 X
TOTAL			\$		3,590.75
TOTAL PARTS			\$		11,438.60

LABOUR

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$ na 170.00 X

Trans-cab Auto Services Pte Ltd

AAD1910-098

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7905M

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	2801
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	2001
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To Rust-Proofing Of The Affected Areas.	\$	nn 170.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	nn 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	501
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 170.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201

TOTAL \$ 14,720.00**Over All Total \$ 26,158.60****(PART-BY-PART) Repair Days****20 Days****2 days**

LKK Auto Consultants hence notify

To Check Electrical Lighting Concerned.

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: