

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

15-Oct-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8073 G

1 pc	Front o/s wheel cover <i>X repair</i>	\$	116.00
1 pc	Front bumper <i>cut</i>	\$	531.00
1 pc	Front bumper emblem <i>X m</i>	\$	44.00
1 pc	Front bumper o/s side retainer <i>X see</i>	\$	16.00
1 pc	Front bumper o/s protector <i>X see</i>	\$	51.00
1 pc	Front bumper o/s fog lamp cover <i>X see</i>	\$	66.00
2 pcs	Front bumper o/s & n/s upper bracket @ \$16.00 <i>X see</i>	\$	32.00
2 pcs	Front bumper o/s & n/s support bracket @ \$16.00 <i>X see</i>	\$	32.00
1 pc	Front o/s fender <i>X repair</i>	\$	384.00
		\$	1,272.00
Less 10%		\$	127.20
		\$	1,144.80

S/NETT

1 pc	Front bumper clips <i>see</i>	\$	48.00
1 pc	Front o/s fender sticker <i>X m</i>	\$	30.00
1 set	Front o/s fender inner shield clips <i>X m</i>	\$	28.00

Sundry

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair reshape and adjust of the same

To putty and spray painting on front bumper, front o/s fender

To apply rustproofing on the repaired and replaced panels.

LKK Auto Consult is hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No insurance claim(s) is allowed
- Supplier of item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

	\$	50.00 20
	\$	300 360
	\$	650.00 360
	\$	400.00 360
	\$	120.00 120.00
	\$	2,470.80

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

24/10/19
Contract 415 \$ 950 / 3 Dg.

Kalvin Ullery
15/10/19 10:26h
3 Dg
4/5
Attu Rep photo