

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC8543L

DATE: 15. Oct. 2019

MAKE : HYUNDAI

MODEL : i40

DOA: 15. Oct. 2019

NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Rear Bumper <i>cut CRA</i>			\$553.00
10	Rear Bumper Clips <i>rec</i>		\$2.20	\$22.00
1	Rear Bumper Sponge <i>xnn</i>			\$103.50
1	Rear Bumper Reinforcement <i>xnn</i>			\$428.40
1	Rear Bumper Undercover <i>scv cut</i>			\$225.00
1	Rear Reinforcement Bracket - RH <i>xnn</i>			\$80.30
SUB TOTAL				\$1,412.20
LESS 20%				\$282.44
DISCOUNTED TOTAL				\$1,129.76
1	Reverse Sensor <i>scv cut</i>			\$135.70
1	Rear Bumper Rubber Mat <i>rec</i>			\$50.00
Labour Charge				
1	Panel Beating			\$300.00
1	Spray Painting Charge			\$250.00
1	Remove/refix Reverse Sensor			\$100.00
TOTAL LABOUR				\$650.00
ESTIMATE TOTAL				\$1,965.46
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

800
8160
8640

Nett
Nett

\$280
\$200
\$30

\$510
\$1335.7

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

16/10/19
Ram (LKK)
15/10/19 1300hrs
2 repair days
L/S
qqd repair photo required
Parasuram@lkk.com
8862277hip

Larry Ng