

SKF5993P.  
 BMW X1  
 WBAH5720405G65683

TP III  
 Cecilia.

- Front Bumper <sup>delivered</sup> 875 ✓
- Front Bumper Lips. <sup>new</sup> 50 ✓
- Front Bumper Side Holder x 02 <sup>RH dmgd</sup> 78x2 = 156. 78.
- Front Bumper Low Cover <sup>Missy</sup> 38 ✓
- Front Bumper Reinforcement <sup>NP</sup> <sup>new</sup> 515.40 +
- Front Bumper Sponge. <sup>could</sup> 198.40 ✓
- Front Bumper Fog Lamp RH. <sup>could</sup> 285. ✓
- Front Bumper Side Cover RH. <sup>NP</sup> <sup>new</sup> 132.40 +
- Front Bumper Side Cover Chrome Garnish RH <sup>lit</sup> 65.10. ✓
- Front Bumper Sensor x 02 <sup>1 piece dmgd</sup> 255x2 = 510. 255.
- Front wheel Reim RH. <sup>lit</sup> ~~1007~~ 750(SN).
- Front Tyre RH. <sup>new</sup> 350(SN) +
- Front RH knuckle Arm. 1850 +
- Front RH wheel Hub c/w Bearing <sup>NP</sup> 612.40 +
- Front RH lower Arm. <sup>NEC</sup> 418.40 +
- Front RH Shock Absorber 685. +
- Headlamp RH. <sup>lit</sup> 2675 ✓

4519.50  
 4293.52  
 S.N: 750

SKF5993P.

Panel Beating

~~800~~ 400

Spray Painting

~~800~~ 400

Wiring

~~50~~ 30

To underseal.

150 +

To remove front undercarriage.

380 + 910

To perform wheel alignment.

~~150~~ 80.

Total: 5953.52.

H/S: 4750.

04 Days.

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: