



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SEDGWICK SINGAPORE PTE. LTD

Ref : CS/SGK19018266/R1vd3e2

c/o SEDGWICK SINGAPORE PTE LTD
30 CECIL STREET, LEVEL 12
PRUDENTIAL TOWER
SINGAPORE 049712

Date : 06-01-2020



Code : SGK

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PSA 417C	Veh. Inspected	YN 1469E
Policy No.		Coverage (\$)	0.00
Claim No.	511046275327/ARI	Excess (\$)	0.00
Assign From	ABRAHAM RAJADURAI	Assign Date	15/10/2019

2. Vehicle Particulars & Condition

Make & Model	mitsubishi FE83BEOSRDEA	c.c	2977
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	FE83BEA20370	Colour	WHITE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	7.00 R16LT	AUSTONE	7 mm
L/H Front Tyre	7.00 R16LT	AUSTONE	7 mm
R/H Rear Tyre	185 R15 (D)	AUSTONE	6/6 mm
L/H Rear Tyre	185 R15 (D)	AUSTONE	6/6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	12/10/2019	Inspection Date	30/12/2019
Survey held at	8 TUAS AVE 18		
Repairer	SIN SHENG ENGINEERING SERVICES		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **10 Working Days**