

Form 100

REC BY:

Signature: RJSU1

REP: CS/SQK19018266/RV d302

Special Instructions:

ASSIGNMENT (Office)

From (Person): Northcom Reproduci of Sedgwick Date/Time: 15/10/2019 @ 2:10pm

Estimated Cost: _____ Bill to: _____

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No: YN 1469E Incident: Public liability PSA 417C

at Workshop no: GoldBUI Tel: 649 4 2897

of 59 Snoko Road

Policy No: _____ Claim No: 51104625327 / ARX

Sum Insured: _____ Percent: _____

Make of Veh: _____ D.O.A. 12/10/19

(Client's Record)

CA / REV / REP. / REV 24 HRS NP

H.O.D. Endorsement: _____

Date/Time: 3:50pm @ 15/10/19 Person Contacted: ISSUC Vehicle-IN (OUT) (OUT)

Date/Time	Action/Instruction
	Insp: <u>8 fuae Ave 18</u> Contact: <u>6863 9545</u>
	<u>INITIALS - MA/AC/1604/15/19</u>

6/1/2020 Submit preli report -
 Note: \$14K (Est) LTA: \$ 2174 NV: \$ 11,826

11/3/20 LS \$ 11,000 confirmed by email (Real 19,811, 649)

To re-open and submit final report, pass to typist Celine 12/3/2020
12/3/20 re-open ref only, let doc 13/1/20 ↓

SIN SHENG ENGINEERING SERVICES

NO 8, TUAS AVE 18,
 (Level 3), SINGAPORE 638892
 Tel No. : 6863-9595 Fax No. : 6863-6477
 E-Mail : sinsheng1981@gmail.com
 Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD
 59 SENOKO ROAD
 SINGAPORE 758123

Attention : Motor Claim Department
 Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES003040

Date : 27/12/2019
 Vehicle Num. : YN1469E
 Make/Model : MITSUBISHI FE 83-2010
 Chassis/Eng# : FE83BEA20370/4M42A77491
 Accident Date : 12/10/2019
 Claim No. :
 Reference : PSA417C
 Policy No. : 29131844

S/N	Quantity	Particular	Unit Price	Amount S\$
		NETT ITEMS :		
1.	1	CABIN ? <i>bt</i>		¹²⁰⁰⁰ 14,500.00
2.	1	CABIN BRACKET ? <i>XSM</i>	18490	950.00 X
3.	1	FRONT BUMPER <i>bt</i>		350.00
4.	1	NUMBER PLATE <i>bt</i>	10%	20.00
5.	1	AIR BAG <i>bt</i>		1,200.00
6.	2	SEAT BELT ? <i>bt</i>	600.00	1,200.00
7.	1	WOODEN BODY <i>ca</i>	³⁰⁰⁰ 120.00	8,500.00 ?
8.	6	U BOLT <i>bt</i>		720.00
9.	1	CABIN REAR BRACKET ? <i>XSM</i>		850.00 X
		Nett Total S\$:		28,290.00
		10.00% Discount S\$:		2,829.00
				25,461.00
		LABOUR :		
		TO DISMANTLE/REPLACE CABIN	600	1,500.00
		TO CHECK WIRING	200	350.00
		TO SERVICE AIR-CON	120	150.00
		TO SPRAY PAINTING	1200	1,600.00

CONTINUE / ...

SIN SHENG ENGINEERING SERVICES

NO 8, TUAS AVE 18,
 (Level 3), SINGAPORE 638892
 Tel No. : 6863-9595 Fax No. : 6863-6477
 E-Mail : sinsheng1981@gmail.com
 Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD
 59 SENOKO ROAD
 SINGAPORE 758123

Attention : Motor Claim Department
 Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES003040

Date : 27/12/2019
 Vehicle Num. : YN1469E
 Make/Model : MITSUBISHI FE 83-2010
 Chassis/Eng# : FE83BEA20370/4M42A77491
 Accident Date : 12/10/2019
 Claim No. :
 Reference : PSA417C
 Policy No. : 29131844

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

		TO DISMANTLE/REPLACE WOODEN BODY	700	1,200.00
		TO APPLY NEW LOGO	350	450.00
		TOWING CHARGES	70	100.00
		LOSS OF USE : 18 DAYS @ S\$150/DAY		2,700.00
		Labour Total S\$:		5,350.00

[Handwritten signature]
 21/12/2019

[Handwritten signature]
 Hp 90010068
 10 days
 L/S
 30/12/19 @ 1600
 Resurvey after repair

Total S\$: 30,811.00

SIN SHENG ENGINEERING SERVICES

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

16,641
 3240
 19881
 202
 15,904.50
 43-15,900

10 days Repair limit = \$11,000

Veron Chen (LKKAuto)

From: Rasul (LKKAuto)
Sent: Wednesday, 11 March 2020 9:24 AM
To: sinsheng engineering services
Cc: Veron Chen (LKKAuto)
Subject: RE: Accident Involving YN1469E with PSA417C on 12/10/2019

Hi Peijin,

Repair limit of \$11000 / 10 days lump sum is confirmed


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: sinsheng engineering services [mailto:sinsheng1981@gmail.com]
Sent: Tuesday, 10 March, 2020 12:06 PM
To: Rasul (LKKAuto)
Subject: Re: Accident Involving YN1469E with PSA417C on 12/10/2019

Hi Mr. Rasul,

I have confirmed with Mr. Hoe that the repair limit is \$11,000.00

**** KINDLY NOTE THAT WE ARE ALLOCATED AT NO 8 TUAS AVE 18 (LEVEL 5), SINGAPORE 638892 WITH IMMEDIATE EFFECT ****

Thank You

Regards

Pei Jin

Sin Sheng Engineering Services

No 8 Tuas Ave 18

Singapore 638892

(Level 3 Office)

(Level 5 Workshop)

Tel: 6863 9595

Fax: 6863 6477

On Tue, 10 Mar 2020 at 11:07, Rasul (LKKAuto) <Rasul@lkkauto.com> wrote:

Hi Peijin,

Can you check with Mr Ho what is the repair limit?

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK Auto Consultants Pte Ltd *Save the Earth. Print only when necessary.*

From: sinsheng engineering services [mailto:sinsheng1981@gmail.com]

Sent: Monday, 9 March, 2020 5:47 PM

To: Rasul (LKKAuto)

Subject: Accident Involving YN1469E with PSA417C on 12/10/2019

Hi Mr. Rasul,

Please find attached the after repair photos and have your finalize.

**** KINDLY NOTE THAT WE ARE ALLOCATED AT NO 8 TUAS AVE 18 (LEVEL 5), SINGAPORE 638892 WITH IMMEDIATE EFFECT ****

*Thank You
Regards*

Pei Jin
*Sin Sheng Engineering Services
No 8 Tuas Ave 18*

Singapore 638892

(Level 3_Office)

(Level 5_Workshop)

Tel: 6863 9595

Fax: 6863 6477

Veron Chen (LKKAuto)

From: sinsheng engineering services <sinsheng1981@gmail.com>
Sent: Wednesday, 11 March 2020 4:54 PM
To: Rajadurai, Abraham
Cc: Admin-D (LKKAuto); Yeo, Jackson Peck Hong
Subject: Re: Accident Involving YN1469E & PSA417C Inside Pasir Panjang Terminal Berth 11 on 12/10/2019
Attachments: YN1469E_LOC.pdf; YN1469E_ATA.pdf

Hi Mr. Abraham,

Attached LOC document and ATA for your attention please.

Kindly assist to revert us with the liability issue/offer if direct settlement is in order.

**** KINDLY NOTE THAT WE ARE ALLOCATED AT NO 8 TUAS AVE 18 (LEVEL 5), SINGAPORE 638892 WITH IMMEDIATE EFFECT ****

Thank You
Regards

Pei Jin
Sin Sheng Engineering Services
No 8 Tuas Ave 18
Singapore 638892
(Level 3_Office)
(Level 5_Workshop)
Tel: 6863 9595
Fax: 6863 6477

On Thu, 16 Jan 2020 at 11:29, sinsheng engineering services <sinsheng1981@gmail.com> wrote:
Hi Mr. Taufiq,

Please be informed that we have ask the liability on dated 02/01/2020.
Have any update for this?

**** KINDLY NOTE THAT WE ARE ALLOCATED AT NO 8 TUAS AVE 18 (LEVEL 5), SINGAPORE 638892 WITH IMMEDIATE EFFECT ****

Thank You
Regards

Pei Jin
Sin Sheng Engineering Services
No 8 Tuas Ave 18
Singapore 638892
(Level 3_Office)
(Level 5_Workshop)

Tel: 6863 9595
Fax: 6863 6477

On Fri, 3 Jan 2020 at 09:53, CLA - Mr Taufiq <taufiq@calllade.com> wrote:

Hi Pei Jin,

I understand that the surveyor had come down to your workshop on the 30th Dec 2019 to view the vehicle. (see attachment)

We will wait for their update.

cc - Nivitha

Thank you

Regards

On 2/1/2020 3:48 pm, sinsheng engineeringservices wrote:

Hi Mr. Taufiq,

We would like to ask is it this accident case liability clear ?

**** KINDLY NOTE THAT WE ARE ALLOCATED AT NO 8 TUAS AVE 18 (LEVEL 5), SINGAPORE 638892 WITH IMMEDIATE EFFECT ****

*Thank You
Regards*

Pei Jin
*Sin Sheng Engineering Services
No 8 Tuas Ave 18
Singapore 638892
(Level 3_Office)
(Level 5_Workshop)
Tel: 6863 9595
Fax: 6863 6477*

On Sun, 29 Dec 2019 at 09:24, CLA - Mr Taufiq <taufiq@calllade.com> wrote:

Hi Pei Jin,

As spoken, we will arrange with our surveyor and keep you posted on the date for the joint inspection.

cc - Abraham Rajadurai and team

Thank you

Regards

On 27/12/2019 10:52 am, sinsheng engineering services wrote:

Hi Mr. Taufiq,

Please be informed that YN1469E at our premises and please arrange your surveyor for joint inspection.

Thanks

**** KINDLY NOTE THAT WE ARE ALLOCATED AT NO 8 TUAS AVE 18 (LEVEL 5), SINGAPORE 638892 WITH IMMEDIATE EFFECT ****

Thank You

Regards

Pei Jin

Sin Sheng Engineering Services

No 8 Tuas Ave 18

Singapore 638892

(Level 3_Office)

(Level 5_Workshop)

Tel: 6863 9595

Fax: 6863 6477

On Tue, 10 Dec 2019 at 09:21, Ethan Toh Xiao Xin
<EthanTohXX@gbl.com.sg> wrote:

Dear Taufiq,

Well noted with thanks.

Dear Pei Jin,

For your follow up with Mr Jackson.

Regards.

Ethan Toh Xiao Xin | Goldbell Leasing Pte Ltd
Assistant, Operations Admin (FIM)

From: CLA - Mr Taufiq <taufiq@calllade.com>
Sent: Monday, 9 December 2019 10:54 PM
To: Ethan Toh Xiao Xin
<EthanTohXX@gbl.com.sg>; sinsheng
engineeringservices <sinsheng1981@gmail.com>
Cc: Isaac Ng Cheng Long
<IsaacNgCL@gbl.com.sg>; Jacqueline Han Kwee
Ling <JacquelineHanKL@gbl.com.sg>; Eileen Ngan
Yi Ling <EileenNganYL@gbl.com.sg>; Yeo, Jackson
Peck Hong <Jackson.Yeo@sg.sedgwick.com>;
Denon <denon@pensley.com.sg>; Call Lade
Admin - (C) <admin@calllade.com>; Lee Han
Meng <hmlee@calllade.com>;
fahmi@calllade.com; william@calllade.com;
Steven Soh <bksoh@globalpsa.com>
Subject: Re: Accident Involving YN1469E &
PSA417C Inside Pasir Panjang Terminal Berth 11
on 12/10/2019

Hi,

Appreciate if you could arrange for a Joint
inspection to view the vehicle YN1469E with our
surveyor (Jackson Yeo of Sedgwick) at your
repairer's premises.

Mr Jackson Yeo of Sedgwick will be representing
our Insurers from Lonpac.

Do update us on the date and time of the
inspection.

cc - Jackson Yeo and Denon

Thank you

Best Regards

On 9/12/2019 3:23 pm, Ethan Toh Xiao Xin wrote:

Afternoon Taufiq,

As spoken, we refer to the accident involving our vehicle YN1469E and your PSA417C on 12/10/2019.

Sin Sheng Engineering is our authorised workshop, and will be handling this case.

Kindly provide us with your insurer's details.

Dear Pei Jin,

For your attention and action.

Thank you both.

Regards.

Ethan Toh Xiao Xin | Goldbell Leasing Pte Ltd
Assistant, Operations Admin (FIM)

DID: +65 6494 2942 | Tel: +65 6861 0007 | Fax: +65 6807 0431 |
Mobile: +65 9348 4218 |



新盛机械工程服务

SIN SHENG ENGINEERING SERVICES

REGISTRATION NO : 312029/00D

No 8 Tuas Ave 18, Singapore 638892

Tel : 6863 9595 Fax : 6863 6477 Email : sinsheng1981@gmail.com

11-Mar-20

Lonpac Insurance Berhad
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

Fax: 6741 4108

Tel: 6256 3561

Our ref: SSES/L2020/0081

Your ref: PSA417C

Attn: Case Handler

Dear Sir/Mdm,

VEHICLE: YN1469E (DoA: 12/10/2019)

We refer to the above and append herewith our costings for your perusal: -

Final Repair Bill	:	11,770.00
Loss of Use: 12 days @ S\$ 150/day (including 2 day for PRI)	:	1800.00
Survey Fee	:	N/A
Third Party Vehicle Insurance Search Fee	:	-
Total	:	<u>13,570.00</u>

Thank You

Yours faithfully

Pei Jin

OPERATIONS EXECUTIVE

Encl

SIN SHENG ENGINEERING SERVICES

NO 8, TUAS AVE 18,
(Level 3), SINGAPORE 638892
Tel No. : 6863-9595 Fax No. : 6863-6477
E-Mail : sinsheng1981@gmail.com
Tax Reg. No. : M90010014J Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD
59 SENOKO ROAD
SINGAPORE 758123

Attention : Motor Claim Department
Contact : 6861 0007 Fax No. : 6753 7780

Tax Invoice : TI003040

Date : 11/03/2020
Vehicle Num. : YN1469E
Make/Model : MITSUBISHI FE 83-2010
Chassis/Eng# : FE83BEA20370/4M42A77491
Accident Date : 12/10/2019
Claim No. :
Reference : PSA417C
Policy No. : 29131844

	Amount S\$
LUMP SUM REPAIR	11,000.00



SIN SHENG ENGINEERING SERVICES

M9-0010014-J

Total S\$:	11,000.00
GST @ 7% S\$:	770.00
Amount Due S\$:	11,770.00
	=====

AUTHORIZATION TO ACT

I, GOLDBELL LEASING PTE LTD ("The Third Party Claimant") of

NO 59, SENOKO ROAD, SINGAPORE 758123 (address),

being the owner of YN1469E (vehicle no.) hereby authorize

SIN SHENG ENGINEERING SERVICES ("the workshop") to act for me

with respect to my claim for repair cost and / or rental and / or loss of use ("claim") for my

vehicle bearing registration no. YN1469E that was damaged pursuant to the accident

which occurred on 12/10/2019 along INSIDE PASIR PANJANG TERMINAL BERTH 11

involving vehicle's YN1469E / PSA417C ("the accident")

I further authorize the workshop to settle my above mentioned claim in a manner they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability in so far as the driver/owner/insurers of the other vehicle is concerned.

Dated this 11 day of MAR (month) 2020 (year)



Signed by "the Third Party claimant"



Signed by "the workshop"



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CS/SGK19018266/R1vd3e2	
C/O: SEDGWICK SINGAPORE PTE LTD 30 CECIL STREET, LEVEL 12 PRUDENTIAL TOWER SINGAPORE 049712		Date : 06-01-2020	
		Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	PSA 417C	Veh. Inspected
	Policy No.		Coverage (\$)
	Claim No.	511046275327/ARI	Excess (\$)
	Assign From	ABRAHAM RAJADURAI	Assign Date
			15/10/2019
2. Vehicle Particulars & Condition			
	Make & Model	MITSUBISHI FE83BEOSRDEA	c.c
	Engine No.	HIDDEN	Year of Reg.
	Chassis No.	FE83BEA20370	Colour
	Odometer	-	Steering
	Brakes	IN ORDER	Modification
	General	FAIR	NIL
3. Conditions of Tyres			
		Size	Make
	R/H Front Tyre	7.00 R16LT	AUSTONE
	L/H Front Tyre	7.00 R16LT	AUSTONE
	R/H Rear Tyre	185 R15 (D)	AUSTONE
	L/H Rear Tyre	185 R15 (D)	AUSTONE
			Balance
			7 mm
			7 mm
			6/6 mm
			6/6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
	Accident Date	12/10/2019	Inspection Date
	Survey held at	8 TUAS AVE 18	
	Repairer	SIN SHENG ENGINEERING SERVICES	
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YN 1469E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	CABIN (N)	BENT	14,500.00	12,000.00
1	CABIN BRACKET (N)	SERVICEABLE	950.00	-
1	FRONT BUMPER (N)	BENT	350.00	350.00
1	NUMBER PLATE (N)	BENT	20.00	20.00
1	AIR BAG (N)	ACTIVATED	1,200.00	1,200.00
2	SEAT BELT @\$600.00 (N)	ACTIVATED	1,200.00	1,200.00
1	WOODEN BODY (N)	CRACKED	8,500.00	3,000.00
6	U BOLT @\$120.00 (N)	BENT	720.00	720.00
1	CABIN REAR BRACKET (N)	SERVICEABLE	850.00	-
	LESS 10% DISCOUNT		-2,829.00	-1,849.00
			25,461.00	16,641.00
LABOUR				
	TO DISMANTLE / REPLACE CABIN.		1,500.00	600.00
	TO CHECK WIRING.		350.00	200.00
	TO SERVICE AIR-CON.		150.00	120.00
	TO SPRAY PAINTING.		1,600.00	1,200.00
	TO DISMANTLE / REPLACE WOODEN BODY.		1,200.00	700.00
	TO APPLY NEW LOGO.		450.00	350.00
	TOWING CHARGES.		100.00	70.00
			5,350.00	3,240.00
GRAND TOTAL			30,811.00	19,881.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				11,000.00

Report Ref No. CS/SGK19018266/R1vd3e2

MARKET VALUE: \$14,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$2,174.00=NETT VALUE: \$11,826.00

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.