

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.
TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

14, OCT 2019

China Taiping Insurance (S) PI
105 Cecil Street #18-00
The Octagon
S 069534

Attn: motor claim dept-3rd party claim

Claiming against your insured vehicle no: SMD8063R

Accident involving vehicle No; SMN8120G/SMD8063R/SMJ856R/NA/SMA8453P/SMN8605A

DOA: 12/10/2019 AT AYE (MCE) 10KM

*Not Authorized
Resony Bepain
7 days
U/Sy @ 8200hr*

Dear officer incharge

Re: estimate cost of repair for vehicle no: SMN8120G

To supply—

| Description | Qty | Amount | |
|-----------------------------------|-----|--------------------|---|
| Tailgate <i>1100-90</i> | 1 | <i>Bu</i> 1,472.40 | ✓ |
| Tailgate absorber @129.80 | 2 | <i>Su</i> 259.60 | X |
| Tailgate lock | 1 | <i>su</i> 174.90 | ✓ |
| End panel | 1 | <i>Bu</i> 474.10 | ✓ |
| End panel top garnish | 1 | <i>su</i> 84.90 | ✓ |
| Rear bumper | 1 | <i>Bu</i> 508.80 | ✓ |
| Rear bumper side @118.50 | 2 | <i>Su</i> 237.00 | R |
| Rear bumper tow cover | 1 | <i>Su</i> 37.50 | X |
| Front bumper | 1 | <i>Bu</i> 891.10 | ✓ |
| Front bumper foglamp | 1 | <i>Su</i> 273.90 | R |
| Front grille base | 1 | <i>CM</i> 374.20 | ✓ |
| Front grille chrome | 1 | <i>Su</i> 283.30 | R |
| Front bumper side moulding @49.30 | 2 | <i>CM</i> 98.60 | ✓ |
| Front bumper H logo | 1 | <i>su</i> 45.10 | X |
| Tailgate H logo | 1 | <i>su</i> 45.10 | ✓ |
| Tailgate Vezel emblem | 1 | <i>su</i> 52.50 | ✓ |
| Boot weather strip | 1 | <i>CM</i> 186-90 | ✓ |
| Front bumper lower grille | 1 | <i>su</i> 137-50 | ✓ |
| Boot tool compartment <i>loan</i> | 1 | <i>CM</i> 226-90 | R |
| Bonnet | 1 | <i>Bu</i> 988-80 | ✓ |
| Front & Rr bumper clip | | <i>su</i> 76-00 | ✓ |
| Rear bumper reflector, RH | | <i>CM</i> 92-20 | ✓ |

208

*090
260
180
340
180*

Vehicle no: SMN8120G

| | | |
|---|----------|---------------|
| Reverse sensor | 220,00 | <i>200,00</i> |
| To remove/replace rear windscreen glass | 150,00 | <i>120</i> |
| To transfer tailgate doorboard, rear wiper motor and all attachments to new door. | 160,00 | <i>60</i> |
| To remove damaged parts and attachments-front n rear | | |
| Repair/reshape dented areas. | | |
| Straighten rear chassis frames where necessary. | | |
| To replace/align all parts into position. | 1,200.00 | <i>900</i> |
| To spray paint | 1,100.00 | <i>1000</i> |

威利摩托

WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.
TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

China Taiping Insurance (S) Pl

CC: LKK Kenneth

Vehicle no: SMN8120G

Supplementary parts for vehicle no: ^{SMN}SDM8120G

To supply---

| Description | Qty | Amount |
|--|---|------------|
| Headlamp,Rh 3518.20 | 1 CM | 3,840.00 ✓ |
| Spare tyre panel | 1 | R 962.30 X |
| Front bumper enforcement | 1 | R 274.30 ✓ |
| Headlamp lower bracket @53.70 | 2 CM | 107.40 ✓ |
| Buzzer assy,Rear | 1 CM | 96.10 ✓ |
| Parts | | 5,280.10 |
| Parts less 20% | | 1,056.02 |
| | | 4,224.08 |
| | | |
| | | |

To check wiring and all related connectors,replace/focus headlamp

120.00 400

Cut n weld badly damaged spare tyre panel,replace panel.

450.00 2500

To apply rust proofing

180.00 900

4,974.08