

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.
TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

Not Authorised
Resurvey B4 painting
7 days

14, OCT 2019

China Taiping Insurance (S) PI
105 Cecil Street #18-00
The Octagon
S 069534

Attn: motor claim dept-3rd party claim
Claiming against your insured vehicle no: SMD8063R
Accident involving vehicle No; SMN8120G/SMD8063R/SMJ856R/NA/SMA8453P/SMN8605A
DOA: 12/10/2019 AT AYE (MCE) 10KM

Dear officer incharge
Re: estimate cost of repair for vehicle no: SMN8120G
To supply—

Description	Qty	Amount	
Tailgate	1	<i>RM</i> 1,472.40	✓
Tailgate absorber @129.80	2	<i>RM</i> 259.60	X
Tailgate lock	1	<i>RM</i> 174.90	✓
End panel	1	<i>RM</i> 474.10	✓
End panel top garnish	1	<i>RM</i> 84.90	✓
Rear bumper	1	<i>RM</i> 508.80	✓
Rear bumper side @118.50	2	237.00	?
Rear bumper tow cover	1	<i>RM</i> 37.50	X
Front bumper	1	<i>RM</i> 891.10	✓
Front bumper foglamp	1	273.90	?
Front grille base	1	<i>CM</i> 374.20	✓
Front grille chrome	1	283.30	?
Front bumper side moulding @49.30	2	<i>CM</i> 98.60	✓
Front bumper H logo	1	<i>RM</i> 45.10	X
Tailgate H logo	1	<i>RM</i> 45.10	✓
Tailgate Vezel emblem	1	<i>RM</i> 52.50	✓
Boot weather strip	1	<i>RM</i> 186-90	✓
Front bumper lower grille	1	<i>RM</i> 137-50	✓
Boot tool compartment <i>Loan</i>	1	<i>CM</i> 226-90	✓
Bonnet	1	<i>RM</i> 988-80	✓
Front & Rr bumper clip	1	<i>RM</i> 76-00	✓
Rear bumper reflector, RH	1	<i>CM</i> 92-20	✓

209

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Vehicle no: SMN8120G

Reverse sensor

Nd 220,00 *200sn*

To remove/replace rear windscreen glass

150.00 *120d*

To transfer tailgate doorboard, rear wiper motor and all attachments to new door.

160.00 *60d*

To remove damaged parts and attachments-front n rear

Repair/reshape dented areas.

Straighten rear chassis frames where necessary.

To replace/align all parts into position.

1,200.00 *900d*

To spray paint

1,100.00 *1000d*