



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	M/s Beni Warehousing Pte Ltd 29 Tuas Avenue 11 Singapore 639089 Home: 68724358
	Document No 0	
	Document Date 15/10/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	GFXSK E1	ACR50R	03/03/2017	SLL6447A	0	49402	5DS/SLL6447A/11101
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTEGDS6M307146485	2A24A74877	60	Francis Cher T S	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
26	5	T75441-28730 REAR "TOYOTA" EMBLEM, AN	1.00	44.10		44.10
27	6	T75441-28720 "PREVIA" EMBLEM, AN	1.00	57.20		57.20

RARE
Hq 90010088
8 days
23/10/19 @ 1420
Rear before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 6,547.90	16,047.90
		Labour 9,150.00	GST 7.00% 1,123.35
		Materials 350.00	Less: 0.00
		Lubrication/Fluid 0.00	
		Others 0.00	Amount Due 17,171.25

PLEASE TEAR ALONG PERFORATED LINE

4039832

TO SECURITY GUARD

4039832

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 15/10/2019
TIME 14:26

VEHICLE NO SLL6447A

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Attn: Rasul

8 days Final Bill

TAX INVOICE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyota.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 129462
Tel no: 6631-1188

Account Detail	Account No	Customer Detail
Longpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia	S1000007/ICLPI1 Document No 38044636 Document Date 16/12/2019	M/s Beni Warehousing Pte Ltd 29 Tuas Avenue 11 Singapore 639089 Home: 68724358

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	GFXSK E1	ACR50R	03/03/2017	SLL6447A	117850	49402	5DS/SLL6447A/11101
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTEGD56M307146485	2AZ4A74877	60	Francis Cher T S	11/12/2019	9.37	11/12/2019	9.37

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES T/P INS. : LOMPAC INS. T/P VEH. : YL9292E ACC DATE : 11.10.19 BY : RASUL (LKK)				50.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT)				200.00
3	B	BP-LAB2 DRILL HOLE TO INSTALL REVERSE SENSOR.				180.00
4	B	BP-LAB2 CHK REAR WIRING SYSTEM AND CONDUCT WATER TEST.				180.00
5	B	BP-LAB2 REMOVE TAIL-GATE COMPONENTS TO TRANSFER ONTO NEW DOOR.				360.00
6	B	BP-LAB2 REMOVE BOOT INTERIOR TO ASSIST REPAIR.				360.00
7	B	BP-LAB2 REPLACE REAR W/SCREEN GLASS TO ASSIST REPAIR.				450.00
8	S	BP-SUBLET SUPPLY AND INSTALL REAR W/SCREEN SOLAR FILM. PO 25227	M30			350.00
9	B	BP-MECH2 RESET AND REPROGRAMME ECU.	18			180.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE MAIL YOUR CHEQUE TO 2 PANDAN CRESCENT, LEVEL 10 INCHCAPE CENTRE, SINGAPORE 129462 4136195

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 16/12/2019
TIME 15:34

4136195

VEHICLE NO SLL6447A

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

TAX INVOICE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyota.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631-1188

Account Detail	Account No	Customer Detail
Longpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia	S1000007 / ICLPI1	M/s Beni Warehousing Pte Ltd 29 Tuas Avenue 11 Singapore 639089 Home: 68724358
	Document No	
	38044636	
	Document Date	
	16/12/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	GFXSK E1	ACR5OR	03/03/2017	SLL6447A	117850	49402	5DS/SLL6447A/11101
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTEGD56M307146485	2A24A74877	60	Francis Cher T S	11/12/2019	9.37	11/12/2019	9.3

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
10	B	BP-LAB2 REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE, REPAIR, STRAIGHTEN REAR BUMPER, TAIL-LAMP PANEL, TAIL-GATE AND AFFECTED PORTION OF CAR.	*			2880.0
11	B	BP-RES2 SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.	*			1770.0
12	1	T76801-28460 GARNISH SUB-ASSY,	1.00	336.80		336.8
13	2	T21000-22 SIKA 210002-2 G+P-207 ADHESIVE. PRIM	1.00	200.00		200.0
14	3	T52159-28959 COVER, RR BUMPER AERAS	1.00	596.90		596.9
15	4	T52156-28050 L/REAR BUMPER SUPPORT,	1.00	57.70		57.7
16	5	T52156-28060 L/REAR SIDE BUMPER SUPPORT,	1.00	40.40		40.4
17	6	S52161-0K040 PIECE, RR BUMPER	4.00	4.10		16.4
18	7	T67005-28D10 PANEL ASSY, BACK DOOR	1.00	1753.60		1753.6
19	8	T21000-20 SIKA 210002-0 TACK GOI (BLACK) SG	2.00	108.00		216.0
20	9	T04562-12010 DAM KIT, WINDOW GLASS	1.00	121.00		121.0
21	0	T58307-28110 PANEL, LAMP LOWER	1.00	755.40		755.4
22	1	T90975-02064 EMBLEM, SYMBOL	1.00	72.20		72.2
23	2	T75441-28730 PLATE, LUGGAGE	1.00	44.10		44.1
24	3	T68105-28680 GLASS, BACK DOOR	1.00	1265.90		1265.9
25	4	T75441-28720 PLATE, LUGGAGE	1.00	57.20		57.2

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	
	Please acknowledge receipt of vehicle	Parts	5,533.60	
		Labour	6,610.00	
		Materials	350.00	
		Lubrication/Fluid	0.00	
		Others	0.00	
			GST 7.00%	874.5
			Less	0.00
			Amount Due	13,368.10

PLEASE MAIL YOUR CHEQUE TO 2 PANDAN CRESCENT, LEVEL 10 INCHCAPE CENTRE, SINGAPORE 128462 4136191

TO SECURITY GUARD 4136191

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 16/12/2019
TIME 15:34

VEHICLE NO SLL6447A

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Moto



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	M/s Beni Warehousing Pte Ltd
	Document No	29 Tuas Avenue 11
	Document Date	Singapore 639089
		Home: 68724358

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	GFXEK	E1	03/03/2017	SLL6447A	0	49402	5DS/SLL6447A/11101
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTEGD56M307146485	2AZ4A74877	60	Francis Cher T S	--/--/--	0.00	--/--/--	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	X	BP-SUNDRY SUNDRIES				100.00
		T/P INS. : Lompac Ins				
		T/P VEH. : YL92928				
		ACC DATE : 11.10.19				
		BY :				
2	X	BP-SLANT SUPPLY SEALANT (NETT)				200.00
3	B	BP-LAB2 DRILL HOLE TO INSTALL REVERSE				180.00
		SENSOR.				
4	B	BP-LAB2 CHK REAR WIRING SYSTEM AND				180.00
		CONDUCT WATER TEST.				
5	B	BP-LAB2 REMOVE TAIL-GATE COMPONENTS TO				360.00
		TRANSFER ONTO NEW DOOR.				
6	B	BP-LAB2 REMOVE BOOT INTERIOR TO ASSIST				360.00
		REPAIR.				
7	B	BP-LAB2 REPLACE REAR W/SCREEN GLASS				450.00
		TO ASSIST REPAIR.				
8	S	BP-SUBLET SUPPLY AND INSTALL REAR W/SCREEN				350.00
		SOLAR FILM.				
9	B	BP-MECH2 RESET AND REPROGRAMME ECU.				180.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 5 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
		Lubricant	
		Materials	
		Lubrication/Fluid	
		Others	
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4039830

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 15/10/2019
TIME 14:26


VEHICLE NO SLL6447A

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 1967000862
GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :

www.toyota.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	M/e Beni Warehousing Pte Ltd 29 Tuas Avenue 11 Singapore 639089 Home: 68724358
	Document No 0	
	Document Date 15/10/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	GFXSK	E1	03/03/2017	SLL6447A	0	49402	5DS/SLL6447A/11101

Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On
JTRGD56M307146485	2AZ4A74877	60	Francis Cher T S	--/--/--	0.00 --/--/-- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
10	B	BP-LAB2 REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE, REPAIR, STRAIGHTEN REAR BUMPER, TAIL-LAMP PANEL, TAIL-GATE AND AFFECTED PORTION OF CAR.				2880 3608.00
11	B	BP-RBS2 SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.				1770 3540.00
12	1	T52159-28959 COVER, RR BUMPER <i>de</i>	1.00	596.90		596.90 ✓
13	2	T52156-28050 L/R SIDE BPR SUPPORT, <i>ne</i>	1.00	57.70		57.70 ✓
14	3	T52156-28060 L/RR BUMPER SUPPORT, <i>ne</i>	1.00	40.40		40.40 ✓
15	4	S52161-0K040 PIECE, RR BUMPER <i>ne</i>	4.00	4.10		16.40 ✓
16	5	T68105-28680 GLASS SUB-ASSY, BACK <i>ne (photo)</i>	1.00	1265.90		1265.90 ✓
17	6	T67005-28D10 BACK DOOR <i>W</i>	1.00	1753.60		1753.60 ✓
18	7	T76801-28460 GARNISH SUB-ASSY, <i>? ca</i>	1.00	336.80		336.80 ✓
19	8	T21000-20 SINK 182010 SINK TACK GOI (BLA <i>ne</i>	2.00	108.00		216.00 ✓
20	9	T21000-22 SINK 207. G+P ADHESIVE PRIMER <i>ne</i>	1.00	200.00		200.00 ✓
21	0	T04562-12010 W/SCREEN GLS DAM KIT, <i>ne</i>	1.00	121.00		121.00 ✓
22	1	T58307-28110 REAR LOWER FLR PANEL, <i>W photo</i>	1.00	755.40		755.40 ✓
23	2	T76802-28070 GARNISH SUB-ASSY <i>? X-ray photo</i>	1.00	229.40		229.40 ✓
24	3	T81591-28300 LENS & BODY, RR <i>X-ray</i>	1.00	784.90		784.90 ✓
25	4	T90975-02064 EMBLEM, SYMBOL <i>ne</i>	1.00	72.20		72.20 ✓

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Oil Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE.

4039831

TO SECURITY GUARD

4039831

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 15/10/2019
TIME 14:26

VEHICLE NO SLL6447A

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 1967000862
GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail		Account No	Customer Detail	
THIRD PARTY CLAIM		S1000020 / TPCLAIM	H/o Beni Warehousing Pte Ltd	
		Document No 0	29 Tuam Avenue 11	
		Document Date 15/10/2019	Singapore 635089	
			Homes: 68724358	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	GFXSK	81	03/03/2017	SLL6447A	0	49402	5DS/SLL6447A/11101
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTEGD56M307144485	2A24A74877	60	Francis Cher T S	--/--/----	0.00 --/--/----	0.00	

L	Ed	Job/Parts Description	Qty	Unit Price	Disc %	Amount
26	5	T75441-28730 REAR "TOYOTA" EMBLEM, AA	1.00	44.10		44.10
27	6	T75441-28720 "PREVIA" EMBLEM, AA	1.00	57.20		57.20

Done
Hy 9/10/2018
8 days
23/10/19 @ 1420
Regy before part

L&K Auto Consultants hence notify the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Receiver
Signature: _____
Date: _____

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 6,547.90	16,047.90
		Labour 9,150.00	GST 7.00%
		Materials 350.00	1,123.25
		Lubrication/Fluid 0.00	Less 0.00
		Others 0.00	Amount Due 17,171.25

PLEASE REAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SLL6447A

CUSTOMER

DATE 15/10/2019
TIME 14:26

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

4039832

4039832

Nivitha (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Wednesday, 16 October 2019 8:39 AM
To: assignments@lkkauto.com
Cc: MT_Claim_SG; chng@inchcape.com.sg
Subject: FW: Direct Settlement (FC) - Accident involving SLL6447A & YL9292E DOA 11/10/2019 [External Confidential]
Attachments: SLL6447A_EST INV.pdf; SLL6447A_EFILE.pdf

11.57am 16/10/19


P: Francis
vehicle not in

Lonpac External - Confidential
Our Ref :19/19/19/VC00/022495

Dear Nivitha,

Kindly proceed to survey and revert to them on liability.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: Ashlyn Chng [mailto:Ashlyn.Chng@inchcape.com.sg]
Sent: Tuesday, 15 October, 2019 5:47 PM
To: MT_Claim_SG; GERALD POH WEE BIN
Cc: Suraidah B Saidi PTCBC
Subject: Direct Settlement (FC) - Accident involving SLL6447A & YL9292E DOA 11/10/2019

Hi,

Reference to the above-mentioned.

Please find attached herein a copy of our client's Accident Report, Damaged Photos & Estimate Invoice for your kind perusal.

As our client is claiming against your insured **YL9292E** thus would appreciate if you could revert to us on the liability urgently or we could settle the case under Direct Settlement with **Car Rental of @ \$150 per day x no. of days** as recommended by your appointed surveyor.

Kindly have your surveyor to contact our Motor Claim Assessor, **Francis Cher @ 9847 6179 / 6631 1863** is located at **2 Pandan Crescent / Level 4** for an appointment to inspect our client's vehicle (currently vehicle NOT in workshop).

As for liability clearance, kindly revert to this email.

Your kind attention into the above is greatly appreciated.

Thank you!

Regards,

Ashlyn Chng

D: 6631 1874 | F: 6872 7260 | E: Ashlyn.chng@inchcape.com.sg

Inchcape Centre

Level 4, Bodycare Centre

2 Pandan Crescent

Singapore 128462

www.borneomotors.com.sg | www.lexus.com.sg | www.toyotasingapore.com.sg | www.hino.com.sg | www.suzukicar.com.sg



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC19018286/R1da3n2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 06-03-2020



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YL 9292E	Veh. Inspected	SLL 6447A
Policy No.	Z/19/VC00/102842	Coverage (\$)	0.00
Claim No.	19/19/19/VC00/022495	Excess (\$)	0.00
Assign From	GERALD	Assign Date	16/10/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PREVIA AERAS 2.4	c.c	2362
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTEGD56M307146485	Colour	WHITE
Odometer	115054	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50 R18	PIRELLI	6 mm
L/H Front Tyre	225/50 R18	PIRELLI	6 mm
R/H Rear Tyre	225/50 R18	PIRELLI	6 mm
L/H Rear Tyre	225/50 R18	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	11/10/2019	Inspection Date	23/10/2019
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 6447A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	COVER,RR BUMPER (SN)	DEFORMED	596.90	596.90
1	L/R SIDE BPR SUPPORT (SN)	NECESSARY	57.70	57.70
1	L/RR BUMPER SUPPORT (SN)	NECESSARY	40.40	40.40
4	PIECE,RR BUMPER (SN)	NECESSARY	16.40	16.40
1	GLASS SUB-ASSY,BACK (SN)	NECESSARY	1,265.90	1,265.90
1	BACK DOOR (SN)	BENT	1,753.60	1,753.60
1	GARNISH SUB-ASSY (SN)	CRACKED	336.80	336.80
2	SIKA 182010 SIKA TACK GOI BLA (SN)	NECESSARY	216.00	216.00
1	SIKA 207.G+P ADHESIVE PRIMER (SN)	NECESSARY	200.00	200.00
1	W/SCREEN GLS DAM KIT (SN)	NECESSARY	121.00	121.00
1	REAR LOWER FLR PANEL (SN)	BENT	755.40	755.40
1	GARNISH SUB-ASSY (SN)	REPEATED	229.40	-
1	LENS & BODY,RR (SN)	SERVICEABLE	784.90	-
1	EMBLEM,SYMBOL (SN)	NECESSARY	72.20	72.20
1	REAR "TOYOTA" EMBLEM (SN)	NECESSARY	44.10	44.10
1	"PREVIA" EMBLEM (SN)	NECESSARY	57.20	57.20
1	SUNDRIES (SN)	NECESSARY	100.00	50.00
1	SEALANT (SN)	NECESSARY	200.00	200.00
			6,847.90	5,783.60
LABOUR				
DRILL HOLE TO INSTALL REVERSE SENSOR.			180.00	180.00
CHK REAR WIRING SYSTEM AND CONDUCT WATER TEST.			180.00	180.00
REMOVE TAIL-GATE COMPONENTS TO TRANSFER ONTO NEW DOOR.			360.00	360.00
REMOVE BOOT INTERIOR TO ASSIST REPAIR.			360.00	360.00
REPLACE REAR W/SCREEN GLASS TO ASSIST REPAIR.			450.00	450.00
SUPPLY AND INSTALL REAR W/SCREEN SOLAR FILM.			350.00	350.00
RESET AND REPROGRAMME ECU.			180.00	180.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE,REPAIR,STRAIGHTEN REAR BUMPER,TAIL-LAMP PANEL,TAIL-GATE AND AFFECTED PORTION OF CAR.		3,600.00	2,880.00
	SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.		3,540.00	1,770.00
			9,200.00	6,710.00
GRAND TOTAL			16,047.90	12,493.60
RECOMMENDED COST OF REPAIRS				12,493.60

Report Ref No. CC4/LPC19018286/R1da3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.