

INS. CASE OWNER:

Jaime

CC 3/EQ1901

8295, Kp639

LKK:
IDAC

Surveyor:

Kenneth

DOI:

ASSIGNMENT
15/10/19

Date / Time:

15/10/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. : SJH 45165

Claim No. : _____

Name of Insured : _____

Policy No. : _____

Insured Tel No. : _____ HP: _____

Make / Model : _____

Excess Sec II : \$5 D.O.A. : 12/10/19

Place of Accident : _____

Is driver the owner? (YES / NO) Nature of Accident : _____

If NO, Driver Name / Age : _____

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No. : _____ (V/L: YES / NO)

Insured Liability : % Final ? Yes / No

SHB 99085

INSRS:
WSP: Trans
Tel: Cuh
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

SJH 45165 - 11/10/19 10:00 AM - 10:15 AM
SJH 45165 - A

- EQ handling (up)

12/11/19 - RE-ASSURANCE to close (up)

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$5

(days) Reduction:

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with

Email ☐ Call ☐

Final Liability:

%

(Agreed / Assessed) BOLA S/N No. :

If NO or B 28, Ass. Lia :

Repair Cost:

\$5

Loss of Rental (LOR):

\$5

(days)

Loss of Use (LOU):

\$5

(\$ x days)

Loss of Income (LOI):

\$5

(\$ x days)

LOR only ☐LOU only ☐LOR + LOU ☐LOR + LO ☐

[Tick only one]

GIA/LTA Search

\$5

Medical:

\$5

Disbursement:

\$5

(e.g. Tow/ Independent)

Legal Cost

\$5

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$ 300.00

Total:

\$5

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

\$5

Name 1:

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

ASS. REC. BY:

REF: EQ1Kenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

03 days

Res.: Yes or No

Lum Sum: _____

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: S14B 9P08SYr Regn: 08, 13Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Perodua Latitudec.c. 1995Colour: M. White / R

A/C: _____

Insured / Std / NI / NA

Sp. Reading: 58879

T/Radio: _____

Insured / Std / NI / NA

Eng/No: _____

C/No: V1-1A3L15AUC273467Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: MI / S/Rlm / STD A/Rlm or

Tyre Size: F: _____

R: _____

215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Giti

Front

Rear

R/Bal. 9 mmR/Bal. 9 mmL/Bal. 9 mmL/Bal. 9 mmD.O.A. 12/10/19D.O.I. 15/10/19

Survey held at _____

Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 File post to11 Day @ 3950h(Red # 20966.13 / 84%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S - RS, SI

Fees:

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/EQI19018295/Kpb3

Date: 16.10.2019

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHB9908S


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 15.10.2019 at the premises of M/s Trans-cab Auto Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	24,916.23
Revised Estimate Amount	: S\$	3,950.00
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9908S**AAD1910-096***Not Authored
21 Sep 8 3850h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

15 OCT 2019

SHB 9908S

VF1ABL15AUC273467

RENAULT

LATITUDE

12.10.19

EQ

30/8/2013

PART

1	1	BUMPER COVER REAR
2	1	BUMPER LOWER REAR
3	1	BUMPER BRACKET CTR REAR
4	1	BUMPER BRACKET SIDE RH REAR
5	1	BUMPER RETAINER RH REAR
6	1	BUMPER REFLECTOR RH
7	1	BUMPER BRACKET SIDE LH REAR
8	1	BUMPER RETAINER LH REAR
9	1	BUMPER REFLECTOR LH
10	1	BUMPER BEAM REAR
11	1	BUMPER BEAM BRACKET LH REAR
12	1	BUMPER BEAM BRACKET RH REAR
13	1	OUTER PANEL REAR (End Panel)
14	1	OUTER PANEL REAR (End Panel) TRIM
15	1	TAILLAMP RH
16	1	TAILLAMP PANEL RH
17	1	TAILLAMP LH
18	1	TAILLAMP PANEL LH
19	1	BOOT REAR
20	1	BOOT FINISHER
21	1	BOOT WHEATERSTRIP
22	1	BOOT REFLECTOR LAMP LH
23	1	BOOT REFLECTOR LAMP RH
24	1	BOOT BADGE 'RENAULT'
25	1	BOOT BADGE
26	1	BOOT STRUT LH

LIST

\$	<i>BY/CM</i>	561.70	✓
\$	<i>CM</i>	411.90	✓
\$	<i>SL</i>	98.10	X
\$	<i>SL</i>	82.10	X
\$	<i>SL</i>	59.80	X
\$	<i>SL</i>	16.60	X
\$	<i>SL</i>	80.80	X
\$	<i>SL</i>	54.20	X
\$	<i>CM</i>	16.60	✓
\$	<i>RS</i>	547.80	✓
\$	<i>N</i>	114.50	} X
\$	<i>N</i>	100.90	
\$	<i>N</i>	745.80	
\$	<i>SL</i>	404.56	
\$	<i>SL</i>	313.10	
\$	<i>N</i>	401.40	} X
\$	<i>SL</i>	401.40	
\$	<i>N</i>	401.40	
\$	<i>RS</i>	1,677.20	✓
\$	<i>SL</i>	344.70	X
\$	<i>SL</i>	178.20	X
\$	<i>SL</i>	277.70	X
\$	<i>SL</i>	277.70	X
\$	<i>N</i>	82.40	✓
\$	<i>N</i>	95.80	✓
\$	<i>SL</i>	145.10	X

Trans-cab Auto Services Pte Ltd

AAD1910-096

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9908S

27	1	BOOT STRUT RH	\$	Sm	145.10	}	X
28	1	BOOT HINGE LH	\$	na	254.20		
29	1	BOOT HINGE RH	\$	na	253.80		
30	1	BOOT INNER TRIM BOARD	\$	Sm	611.00		
31	1	BOOT SWITCH	\$	na	113.00		
32	1	BOOT LOCK	\$	na	246.60		
33	1	BOOT LOCK CATCH	\$	na	41.70		
34	1	EXHAUST CAP REAR	\$	Sm	125.40		
TOTAL			\$		9,682.26		
10%			\$		968.23		
			\$		8,714.03		

Special Nett

1	1SET	PARKING AID	\$	Shan	700.00	400.00	
2	1SET	REAR BUMPER CLIP	\$	na	66.00		✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	na	33.00		✓
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00		X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	na	20.00		X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00		X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	na	20.00		X
8	1SET	BUMPER LOWER REAR RIVET	\$	na	22.00		X
9	1SET	BUMPER LOWER REAR CLIP	\$	na	66.00		✓
10	1	BOOT STICKER "Trans-cab"	\$	na	30.00		✓
11	1	BOOT STICKER "6555-3333"	\$	na	30.00		✓
12	1	EXHAUST MOUNTING REAR	\$	na	16.00	}	X
13	2	REAR WINDSCREEN SEALANT	\$	na	80.00		
14	1	WINDSCREEN MOULDING	\$	na	100.00		
15	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00		
16	1	BOOT INNER TRIM CLIP	\$	na	45.00		
17	1SET	BOOT FINISHER CLIP	\$	na	24.20		
18	1	TAILLAMP CLIP LH	\$	na	5.00		
19	1	TAILLAMP CLIP RH	\$	na	5.00		
20	1	Rear Bumper Protector	\$	na	100.00		
TOTAL			\$		1,482.20		

Trans-cab Auto Services Pte Ltd

AAD1910-096

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 99085

TOTAL PARTS	\$	10,196.23
--------------------	-----------	------------------

LABOUR

To Rust-Proofing Of The Affected Areas.	\$	170.00	301
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	5001 6001
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	na X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	170.00	na X
To check steering geometry and computer wheel alignment	\$	220.00	na X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	380.00	na X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	na X

Trans-cab Auto Services Pte Ltd

AAD1910-096

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 99085

Putty and spray painting of the affected portion. \$ 6,000.00 6000

To repair and realign rear exhaust pipe. \$ 170.00 X

TOTAL \$ 14,720.00**Over All Total \$ 24,916.23****LUMP SUM (REPAIR DAY)**

20 DAYS

3 day

L&K Auto Consultants hence notify the Repairer of the following:

- To return vehicle after repair
- To display damaged parts during return
- Parts prices are subject to market
- This party is not a "Fixed Price" quote
- For detail and terms, please refer to the contract
- Repairs are done by the company and the company is not responsible for any damage to the vehicle

Acknowledged by Repairer
Signature: _____
Date: _____

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	878K

Vehicle Details

Vehicle No.:	SHB99085
Vehicle to be Exported:	Yes
Intended Deregistration Date:	14 Oct 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C000407
Chassis No.:	VF1A8L15AUC273467
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	30 Aug 2013
First Registration Date:	30 Aug 2013
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Aug 2021
PARF Rebate Amount:	\$8,123.00

Intended COE Rebate Details

COE Expiry Date:	29 Aug 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$54,952.00
COE Rebate Amount:	\$12,870.00
Total Rebate Amount:	\$20,993.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 14 Oct 2019

OK

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Tuesday, 19 November 2019 8:10 AM
To: 'jasminetan@transcab.com.sg'; 'Ng Wai Yin'; claims@transcab.com.sg
Cc: Admin A
Subject: Your Ref: AAD1910-096 (SHB9908S) *Our Ref: CC3/EQI19018295/Kpb3 [ACCIDENT INVOLVING SJH 4516S(EQ) AND SHB 9908S ON 12/10/2019]

Your Ref: **AAD1910-096 (SHB9908S)**
Our Ref: CC3/EQI19018295/Kpb3

Without Prejudice

Dear Sirs/Mdm,

ACCIDENT INVOLVING SJH 4516S(EQ) AND SHB 9908S ON 12/10/2019

We refer to the above matter.

Please be informed that EQ claim officer will handle the matter at their end.

Kindly submit your LOD & document to EQ directly.

Email Address: egiprs@eqinsurance.com.sg
Fax Number: 65 6223 4190

Thank you.

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shu Pei (LKKAUTO)

From: Jaime Tay <jaime.tay@eqinsurance.com.sg>
Sent: Friday, 8 November 2019 10:12 AM
To: Shu Pei (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving SJH4516S (OI : EQI - DM19HO02799) and SHB9908S (TP : LKK REF - CC3/EQI19018295/Kpb3) on 12.10.2019

Dear Shu Pei,

Please let us have your survey report and invoice when available and advise workshop to send their letter of claim directly to our office for our handling.

Thank you.

Regards,

Jaime Tay
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9882 | tel 65 6223 9433 ext 882 | fax 65 6223 4190
www.eqinsurance.com.sg



A Member of Citystate



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of it.

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: 08 November 2019 09:42
To: EQI PRS <EQIPRS@eqinsurance.com.sg>
Subject: RE: Direct Settlement - Accident Involving SJH4516S (OI : EQI - TBA) and SHB9908S (TP : LKK REF - CC3/EQI19018295/Kpb3) on 12.10.2019

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Thank you.

Best Regards,

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC3/EQI19018295/Kpb3q2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 11-12-2019



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJH 4516S	Veh. Inspected	SHB 9908S
Policy No.		Coverage (\$)	0.00
Claim No.	DM19HO02799	Excess (\$)	0.00
Assign From		Assign Date	15/10/2019

2. Vehicle Particulars & Condition

Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	VF1ABL15AUC273467	Colour	METALLIC WHITE / RED
Odometer	588791	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	GITI	9 mm
L/H Front Tyre	215/60 R16	GITI	9 mm
R/H Rear Tyre	215/60 R16	GITI	9 mm
L/H Rear Tyre	215/60 R16	GITI	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	12/10/2019	Inspection Date	15/10/2019
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 9908S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER COVER REAR	BENT / CRACKED	561.70	561.70
1	BUMPER LOWER REAR	CRACKED	411.90	411.90
1	BUMPER BRACKET CTR REAR	SERVICEABLE	98.10	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	82.10	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	59.80	-
1	BUMPER REFLECTOR RH	SERVICEABLE	16.60	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	80.80	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	54.20	-
1	BUMPER REFLECTOR LH	CRACKED	16.60	16.60
1	BUMPER BEAM REAR	BENT	547.80	547.80
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	114.50	-
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	100.90	-
1	OUTER PANEL REAR (END PANEL)	TO REPAIR SEE LABOUR	745.80	-
1	OUTER PANEL REAR (END PANEL)TRIM	SERVICEABLE	404.56	-
1	TAILLAMP RH	SERVICEABLE	313.10	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	401.40	-
1	TAILLAMP LH	SERVICEABLE	401.40	-
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	401.40	-
1	BOOT REAR	BENT	1,677.20	1,677.20
1	BOOT FINISHER	SERVICEABLE	344.70	-
1	BOOT WEATHERSTRIP	SERVICEABLE	178.20	-
1	BOOT REFLECTOR LAMP LH	SERVICEABLE	277.70	-
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	277.70	-
1	BOOT BADGE 'RENAULT'	NECESSARY	82.40	82.40
1	BOOT BADGE	NECESSARY	95.80	95.80
1	BOOT STRUT LH	SERVICEABLE	145.10	-
1	BOOT STRUT RH	SERVICEABLE	145.10	-

Report Ref No. CC3/EQ19018295/Kpb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	254.20	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	253.80	-
1	BOOT INNER TRIM BOARD	SERVICEABLE	611.00	-
1	BOOT SWITCH	SERVICEABLE	113.00	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	246.60	-
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	41.70	-
	LESS 10% DISCOUNT		-955.69	-339.34
			8,601.17	3,054.06
	<u>SPECIAL NETT ITEMS</u>			
1	SET PARKING AID (SN)	SHORTED	700.00	400.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	BOOT STICKER 'TRANS-CAB' (SN)	NECESSARY	30.00	30.00
1	BOOT STICKER '6555-3333' (SN)	NECESSARY	30.00	30.00
1	EXHAUST MOUNTING REAR (SN)	NOT NECESSARY	16.00	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	BOOT INNER TRIM CLIP (SN)	NOT NECESSARY	45.00	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	24.20	-
1	TAILLAMP CLIP LH (SN)	NOT NECESSARY	5.00	-
1	TAILLAMP CLIP RH (SN)	NOT NECESSARY	5.00	-
1	REAR BUMPER PROTECTOR (SN)	NOT NECESSARY	100.00	-
			1,482.20	625.00

Report Ref No. CC3/EQI19018295/Kpb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO REINSTALL REAR BUMPER PARKING SENSOR .		170.00	60.00
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BUMPER BEAM BRACKET LH REAR,BUMPER BEAM BRACKET RH REAR,OUTER PANEL REAR (END PANEL),TAILLAMP PANEL RH,TAILLAMP PANEL LH,BOOT HINGE LH,BOOT HINGE RH,BOOT LOCK AND BOOT LOCK CATCH.		6,000.00	500.00
	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF REAR BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION .		6,000.00	600.00
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
			14,720.00	1,270.00
	GRAND TOTAL		24,803.37	4,949.06
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,950.00

Report Ref No. CC3/EQ19018295/Kpb3q2



Report Ref No. CC3/EQ119018295/Kpb3q2

A handwritten signature in black ink, consisting of the letters 'KSC' in a cursive, stylized font.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part does so at his or her own risk.