

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9908S**AAD1910-096***Not Notarized
21 Sep 8 3950h*

Vehicle No.:

Chassis No.:

Vehicle Make:

15 OCT 2019

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHB 9908S

VF1ABL15AUC273467

RENAULT

LATITUDE

12.10.19

EQ

30/8/2013

		PART			LIST
1	1	BUMPER COVER REAR	\$	<i>B47/cm</i>	561.70 ✓
2	1	BUMPER LOWER REAR	\$	<i>CM</i>	411.90 ✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>SL</i>	98.10 X
4	1	BUMPER BRACKET SIDE RH REAR	\$	<i>SL</i>	82.10 X
5	1	BUMPER RETAINER RH REAR	\$	<i>SL</i>	59.80 X
6	1	BUMPER REFLECTOR RH	\$	<i>SL</i>	16.60 X
7	1	BUMPER BRACKET SIDE LH REAR	\$	<i>SL</i>	80.80 ✓
8	1	BUMPER RETAINER LH REAR	\$	<i>SL</i>	54.20 X
9	1	BUMPER REFLECTOR LH	\$	<i>CM</i>	16.60 ✓
10	1	BUMPER BEAM REAR	\$	<i>B2</i>	547.80 ✓
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>N</i>	114.50
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>N</i>	100.90
13	1	OUTER PANEL REAR (End Panel)	\$	<i>N</i>	745.80
14	1	OUTER PANEL REAR (End Panel) TRIM	\$	<i>SL</i>	404.56
15	1	TAILLAMP RH	\$	<i>SL</i>	313.10
16	1	TAILLAMP PANEL RH	\$	<i>N</i>	401.40
17	1	TAILLAMP LH	\$	<i>SL</i>	401.40
18	1	TAILLAMP PANEL LH	\$	<i>N</i>	401.40
19	1	BOOT REAR	\$	<i>B1</i>	1,677.20 ✓
20	1	BOOT FINISHER	\$	<i>SL</i>	344.70 X
21	1	BOOT WHEATERSTRIP	\$	<i>SL</i>	178.20 X
22	1	BOOT REFLECTOR LAMP LH	\$	<i>SL</i>	277.70 X
23	1	BOOT REFLECTOR LAMP RH	\$	<i>SL</i>	277.70 X
24	1	BOOT BADGE 'RENAULT'	\$	<i>N</i>	82.40 ✓
25	1	BOOT BADGE	\$	<i>N</i>	95.80 ✓
26	1	BOOT STRUT LH	\$	<i>SL</i>	145.10 X

Trans-cab Auto Services Pte Ltd**AAD1910-096**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9908S

27	1	BOOT STRUT RH	\$	Sm	145.10	}	X
28	1	BOOT HINGE LH	\$	na	254.20		
29	1	BOOT HINGE RH	\$	na	253.80		
30	1	BOOT INNER TRIM BOARD	\$	Sm	611.00		
31	1	BOOT SWITCH	\$	Sm	113.00		
32	1	BOOT LOCK	\$	na	246.60		
33	1	BOOT LOCK CATCH	\$	na	41.70		
34	1	EXHAUST CAP REAR	\$	Sm	125.40		
TOTAL			\$		9,682.26		
10%			\$		968.23		
			\$		8,714.03		

Special Nett

1	1SET	PARKING AID	\$	Shan	700.00	400.00	
2	1SET	REAR BUMPER CLIP	\$	na	66.00	—	
3	1SET	BUMPER BRACKET CTR CLIP	\$	na	33.00	—	
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X	
5	1SET	BUMPER RETAINER RH CLIP RR	\$	na	20.00	X	
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X	
7	1SET	BUMPER RETAINER CLIP LH RR	\$	na	20.00	X	
8	1SET	BUMPER LOWER REAR RIVET	\$	na	22.00	X	
9	1SET	BUMPER LOWER REAR CLIP	\$	na	66.00	✓	
10	1	BOOT STICKER "Trans-cab"	\$	na	30.00	✓	
11	1	BOOT STICKER "6555-3333"	\$	na	30.00	✓	
12	1	EXHAUST MOUNTING REAR	\$	na	16.00		
13	2	REAR WINDSCREEN SEALANT	\$	na	80.00		
14	1	WINDSCREEN MOULDING	\$	na	100.00		
15	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00		
16	1	BOOT INNER TRIM CLIP	\$	na	45.00		
17	1SET	BOOT FINISHER CLIP	\$	na	24.20		
18	1	TAILLAMP CLIP LH	\$	na	5.00		
19	1	TAILLAMP CLIP RH	\$	na	5.00		
20	1	Rear Bumper Protector	\$	na	100.00		
TOTAL			\$		1,482.20		

Trans-cab Auto Services Pte Ltd**AAD1910-096**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9908S

TOTAL PARTS	\$	10,196.23
--------------------	-----------	------------------

LABOUR

To Rust-Proofing Of The Affected Areas.	\$	170.00	301
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	5001 6001
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	na 170.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	na 170.00	X
To check steering geometry and computer wheel alignment	\$	na 220.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	na 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	na 380.00	X

Trans-cab Auto Services Pte Ltd**AAD1910-096**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9908SPutty and spray painting of the affected portion. \$ 6,000.00 *6000*To repair and realign rear exhaust pipe. \$ *nn* 170.00 *X***TOTAL \$ 14,720.00****Over All Total \$ 24,916.23****LUMP SUM (REPAIR DAY)***20 DAYS*
3 day

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: