

INS. CASE OWNER:

CC³ /AIG1901 8296, *PKL*

LKK
IDAC

Surveyor: *M. Jones* DOI: *4/11/19* Date / Time: *16/10/19*
Registered in Merimen: *16/10/19*

Pre-assign / CCU / FTE



Insured Vehicle No. : *SMN2ET* Claim No. : _____
Name of Insured : *MR TOH SHI JIE* Policy No. : _____
Insured Tel No. : _____ HP: _____ Make / Model : _____
Excess Sec II :SS D.O.A : *11/10/19* Place of Accident : _____
Is driver the owner? (YES / NO) Nature of Accident : _____
If NO, Driver Name / Age : _____ OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO
Driver Tel No. : _____ (V/L) YES / NO Insured Liability : % Final ? Yes / No

SMG 7925M



INSRS: *Performance*
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time	STAGE	DATE / PIC
<i>4/12/19</i>	File pass to type mandate	<i>Chenchen</i>
<i>22/1/2020</i>	File pass to MK to close.	<i>Chenchen</i>
	Documentation Check List:	Handler Type
	Notification ltr (if non-pickup)	<input type="checkbox"/>
	After call ltr to OI:	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/>
	LTA / GIA :	<input type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____

Repair Cost: *P/P* \$5,048.50; 5 days) Reduction: 19 % Email Call

FINAL SETTLEMENT Date/Time: *2/11/2019* Confirm with: *Caroline* Email Call

Final Liability: % *100* (Agreed / Assessed) BOLA S/N No. : *27* If NO or B 28, Ass. Lia : _____

Repair Cost: *(w/ GST)* \$5,611.90

Loss of Rental (LOR) *(w/ GST)* \$5 *428* (5 days) x \$ 80

Loss of Use (LOU): \$5 - (\$ - x - days)

Loss of Income (LOI): \$5 - (\$ - x - days)

LOR only LOU only LOR + LOU LOR + LO [Tick only one]

GIA/LTA Search \$5 -

Medical: \$5 -

Disbursement: \$5 - (e.g. Tow/ Independent)

Legal Cost \$5 -

Total: \$5 *9,039.90* Global Sum \$5: _____

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email Call

Payee 1: \$5 *8,611.90* Name 1: *PERFORMANCE MOTOR LIMITED*

Payee 2: (Strike if N.A.) \$5 *428* Name 2: *Bkw RENT A CAR PTE LTD*

Payee 3: (Strike if N.A.) \$5 _____ Name 3: _____

COPY SENT
Milner

- 1) Claim status: Normal/Reject/Private Settle
- 2) Report Format: *TP*
- 3) Survey fee: *\$320*

Acc. No. 2018 ALG 626C

ASSIGNMENT

From _____ Date: 4.11.2019

Estimated Cost _____

CD: IP / VS / TP RES / OD RES / EVA / INV / MV

To inspect vehicle No: SMG 7925 U

at Workshop No: Performance 2

at 303 Alexander Road

Insured _____

Policy No. _____

Claims to _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Sub. or Market Value _____

IDAC Accident Report: _____ Consistent?: Yes or No


GA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 5 days Res: Yes or No

Liab Lim: 118 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS nwp

Date: _____ Person Contacted: _____ Vehicle: IN / OUT



Veh No: SMG 7925U Vt Reg: 2018 / Dec

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: B.M.W 2167 G.T CC: 1499

Colour: WHITE A/C: Insured / Std / Nil / NA

Sp. Reading: 16838 T/Radio: Insured / Std / Nil / NA

EngNo: _____

C/Nr: WDA6V12060E005578

Gen. Cond: Good / Fair / Poor / Burnt

Steering: None / Jammed / Leaked / Burnt or _____

Brake: None / Jammed / Leaked / Burnt or _____

Mod: Nil / SPRim / STD A/Rim or _____

Tyre Size: F: 205/55R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____

Front	Wheel	Back
R/Bal: <u>6</u> mm	R/Bal: <u>6</u> mm	
L/Bal: <u>6</u> mm	L/Bal: <u>6</u> mm	
D.O.A: <u>11/10/19</u>	D.O.I: <u>08/11/19</u>	

Survey held at: PERFORMANCE

Des. of Damages: Ft / Roof / O/S / N/S / U/C / Rooftop ✓

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	<u>C/P \$ 8,048.50 / Red \$ 1,881.90 / 19.1%</u>

Dist/Trac. File Pass List

: Preli. Report

: Final Report

Dist/Trac. File Return List

File Contact

File Copy

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

- Site Insp: \$
- Interview: \$
- Tech. trip: \$
- Wheel and: \$

Survey Fee

Transportation

Other

Konkrit Hara

Varrange mahl car from BKW

Survey & repair
4/10 @ 10am

MS Dealer

Performance Motors Limited

A Stone Derby Motors Company
Co. Reg. No. 19742339W GST Reg. No. M3-1000001-9
Toll-Free Number: 1800-2711249

101, Alexandra Road
Stone Derby Performance Centre
Singapore 119941
Fax: 64747772

241, Kallang Road
East Coast Centre
Singapore 338189
Fax: 63448773

311, Alexandra Road
Stone Derby Business Centre
Singapore 119948
Fax: 64786600 (AfterHours)
64786622 (Merkury)



GST REG. NO : M2 - 0020081 - X

16 OCT 2019

ESTIMATE

Estimate No. : b1 53107	Page No. : 1 of 5
Date Estimated : 16/10/2019	
Prepared By : Inthiran A/L Thurasamy	

- ESTIMATE REPAIR FOR - Lee Chong Meng, Benjamin (Li Zongmi) 81 Pasir Ris Grove #03-48 Singapore 518210	- ACCOUNT - 121 AIG Asia Pacific Insurance Pte. Ltd. 78 Shenton Way #08-16 Chartis Building Singapore 079120
---	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMS7925U	WBA6V12000ED05578	31/12/2018	216i GT	0

DESCRIPTION	VALUE
To replace rear bumper, tailgate and attachments	1700 2580.00
Painting rear bumper and tailgate	1770 1923.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 17.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150 17.00
To remove and install rear windscreen glass to facilitate the repair job.	574.00
To conduct water leak tests.	75.00
To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking system for proper function.	457 531.00
To carry out body cavity preservation (Per panel).	100 118.00
Sundries. <i>N/A</i>	80/? 150.00
Total Labour :	6,275.00

DESCRIPTION	QTY	PRICE	VALUE
TAILPIPE TRIM BRIGHT CHROME <i>? XM</i>	1	116.05	116.05
BOOTLID <i>st</i>	1	1,204.35	1,204.35
SUPPORT <i>? ca</i>	1	45.30	45.30
RR BUMPER LH INNER SIDE GUIDE <i>? ca</i>	1	67.55	67.55
RR BUMPER RH INNER SIDE GUIDE <i>? ca</i>	1	67.55	67.55
REAR BUMPER TOWING FLAP EYE PRIMED <i>X M</i>	1	42.85	42.85
REAR BUMPER TRIM STRIP (BLACK) <i>cat</i>	1	72.20	72.20

✓
 1210.35 ✓
 15.25 ✓
 67.55 ✓
 67.55 ✓
 42.85 ✓
 72.20 ✓

Performance Motors Limited

A Siam Dairy Motors Company
 Co. Reg. No. 177452199R GST Reg. No. M2 0020081-X
 Toll Free Number: 1800 2252281

101, Alexandra Road
 Siam Dairy Performance Centre
 Singapore 119941
 Fax: 63767710

201, Selegie Road
 Siam Dairy Centre
 Singapore 118182
 Fax: 63448173

111, Alexandra Road
 Siam Dairy Business Centre
 Singapore 119999
 Fax: 63764011 (AfterSales)
 63764010 (Motorhall)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Page No. : 2 of 5

Estimate No. : b1 53107
 Date Estimated : 16/10/2019
 Prepared By : Inthiran A/L Thurasamy

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMG7925U	WBA6Y12000ED05578	31/12/2018	216i GT	0

DESCRIPTION	QTY	PRIC	VALUE
REAR BUMPER PANEL PRIMED (LINES PDC de -	1	1,045.45	1,045.45
GROMMET ~	2	0.80	1.60
REAR BUMPER HEAT INSULATION ? XAN	1	63.20	63.20
PLAQUE 82MM ~	1	71.25	71.25
DECOUPLING RING PDC TORQUE CONVERTER ? Xsu	4	5.05	20.20
ULTRASONIC SENSOR MINERALWEISS(WA96 ? Xsu	1	368.80	368.80
Total Parts :			3,186.35

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts price will be subject to confirmation
- Third party survey will be on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary items must be resurveyed and
- subject to final approval from Insurance Company

Claim ID: 08/11/19 @ 1020

Claim No: _____

Estimate No: _____

Signature: [Signature]

Date: _____

5 days

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts price will be subject to confirmation
- Third party survey will be on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary items must be resurveyed and
- subject to final approval from Insurance Company

Labour 1	6,275.00
Parts	3,186.35
Labour 2	0.00
Excess	0.00
Total GST @ 7%	662.29
Grand Total	10,123.64

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **
 ** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
 Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



Final Report

Estimate No. : b1 53107
 Date Estimated : 16/10/2019
 Prepared By : Inthiran A/L Thurasamy

- ESTIMATE REPAIR FOR -
Lee Chong Meng, Benjamin (Li Zongmi
81 Pasir Ris Grove
#03-48

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 518210

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMG7925U	WBA6V12000ED05578	31/12/2018	216i GT	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper end attachments, bootlid and attachments including knock out dented area caused by the accident.	1,700.00		1,700.00 ✓
To respray rear bumper and bootlid.	1,730.00		1,730.00 ✓
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00 ✓
To remove old PDC assembly and reconnect to new bumper including conduct checks for proper function.	150.00		150.00 ✓
To remove and install rear windscreen glass to facilitate repairs.	574.00		574.00 ✓
To conduct water leak tests.	75.00		75.00 ✓
To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking system for proper function.	451.00		451.00 ✓
To carry out body cavity preservation. (Per panel).	100.00		100.00 ✓
Sundries.	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
BOOTLID	1,210.35	1.00		1,210.35 ✓
# EXPANDING NUT	1.00	2.00		2.00 (1) ✓
# REAR BUMPER CARRIER SUPPORT	460.40	1.00		460.40 (1) ✓
RR BUMPER LH INNER SIDE GUIDE	45.55	1.00		45.55 ✓
RR BUMPER RH INNER SIDE GUIDE	61.35	1.00		61.35 ✓
REAR BUMPER TRIM STRIP (BLACK)	61.35	1.00		61.35 ✓
REAR BUMPER PANEL PRIMED (LINES PDC)	72.20	1.00		72.20 ✓
GROMMET	1,045.45	1.00		1,045.45 ✓
PLAQUE 74MM	0.80	2.00		1.60 ✓
# PLUG BLACK D=5MM	71.60	1.00		71.60 ✓
	0.95	7.00		6.65 (1) ✓

Performance Motors Limited

A member of the Smead Debits Group
Co. Reg. No. 18740153BNW / GST Reg. No. M2-0020081-8



Final Report

SUPPLEMENTARY ITEMS

Total Labour :	5,010.00
Total Parts :	3,038.50
Total Labour & Parts :	8,048.50
Deduction for Excess :	0.00
Total Repair Costs less Excess:	8,048.50
GST @7%:	563.40
<u>Grand Total :</u>	<u>8,611.90</u>

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 101401559W GST Reg No. M2-0020081-K



Supplementary

Estimate No. : b1 53107
Date Estimated : 16/10/2019
Prepared By : Inthiran A/L Thurasamy

- ESTIMATE REPAIR FOR -
Lee Chong Meng, Benjamin (Li Zongmi)
81 Pasir Ris Grove
#03-48

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 518210

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMG7925U	WBA6V12000ED05578	31/12/2018	216i GT	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING NUT <i>nc</i>	1.00	2.00		2.00
# REAR BUMPER CARRIER <i>bt</i>	460.40	1.00		460.40
# PLUG BLACK D=5MM <i>nc</i>	0.95	7.00		6.65

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	469.05
Total Labour & Parts :	469.05

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

260, Kaepong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64736601 (AfterSales)
64796634 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

16 OCT 2019

Estimate No. : b1 53107 Page No. : 1 of 5
Date Estimated : 16/10/2019
Prepared By : Inthiran A/L Thurasamy

- ESTIMATE REPAIR FOR -

Lee Chong Meng, Benjamin (Li Zongmi)
81 Pasir Ris Grove
#03-48

Singapore 518210

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMG7925U	WBA6V12000ED05578	31/12/2018	216i GT	0

DESCRIPTION

To replace rear bumper, tailgate and attachments.

VALUE

2,550.00

Painting rear bumper and tailgate.

1,923.00

To check electrical wiring systems and lightings at the rear section for proper function.

177.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.

177.00

To remove and install rear windscreen glass to facilitate the repair job.

574.00

To conduct water leak tests.

75.00

To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking system for proper function.

531.00

To carry out body cavity preservation.
(Per panel).

118.00

Sundries.

150.00

Total Labour 1: 6,275.00

DESCRIPTION

TAILPIPE TRIM BRIGHT CHROME

QTY

PRIC

VALUE

BOOTLID

1

116.05

116.05

SUPPORT

1

1,204.35

1,204.35

RR BUMPER LH INNER SIDE GUIDE

1

45.30

45.30

RR BUMPER RH INNER SIDE GUIDE

1

67.55

67.55

REAR BUMPER TOWING FLAP EYE PRIMED

1

67.55

67.55

REAR BUMPER TRIM STRIP (BLACK)

1

42.85

42.85

REAR BUMPER TRIM STRIP (BLACK)

1

72.20

72.20



303, Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941
 Fax: 64747770

289, East Coast Road
 East Coast Centre
 Singapore 438180
 Fax: 63449773

215, Alexandra Road
 Sime Darby Business Centre
 Singapore 159944
 Fax: 64796601 (AfterSales)
 64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 53107	Page No. : 2 of 5
Date Estimated : 16/10/2019	
Prepared By : Inthiran A/L Thurasamy	

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMG7925U	WBA6V12000ED05578	31/12/2018	216i GT	0

DESCRIPTION	QTY	PRIC	VALUE
REAR BUMPER PANEL PRIMED (LINES PDC	1	1,045.45	1,045.45
GROMMET	2	0.80	1.60
REAR BUMPER HEAT INSULATION	1	63.20	63.20
PLAQUE 82MM	1	71.25	71.25
DECOUPING RING PDC TORQUE CONVERTER	4	5.05	20.20
ULTRASONIC SENSOR MINERALWEISS(WA96	1	368.80	368.80
Total Parts :			3,186.35

Labour 1	:	6,275.00
Parts	:	3,186.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	662.29
Grand Total	:	10,123.64

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Certificate of Insurance

ORIGINAL

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.1
Individual Ownership

**Prestige Drive - PPSL
Comprehensive**

Certificate No. A 29131007 APO

Excess : SGD500
Windscreen Excess : SGD0

1. Index Mark and Registration Number of Vehicle

SMG7925U

2. Name of Policyholder

Lee Chong Meng Benjamin (Li Zongming)

3. Effective Date of the Commencement of Insurance for the purposes of the Act

22/07/2019

4. Date of Expiry of Insurance

31/12/2020

5. Persons or Classes of Persons entitled to drive*

Lee Chong Meng Benjamin (Li Zongming)

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business.

The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR CAN BE CARRIED OUT AT PERFORMANCE MOTORS LIMITED OR AT ANY MSIG AUTHORISED WORKSHOP LISTED IN THE ATTACHED.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.
Approved Insurers



Amy Ler
Senior Vice President, Agencies

Claim Audit

AUDIT TRAIL				
No.	On	Action	Remarks	By
1	16 Oct 2019 16:47	Cim Dtl Modified	Claimant's Name: -> BENJAMIN LEE CHONG MENG. Claimant's ID: -> S7813686C.	[A] Lau Shu Pei
2	16 Oct 2019 16:47	Cim Veh Model Changed	(205130) BMW 216I 1.5 D GT LED (A).	[A] Lau Shu Pei
3	16 Oct 2019 16:47	Cim Created	Reg No: SMG7925U, Acct Date: 2019/10/11. Claim Type: TP, Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG), TP Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ), Workshop: Performance Motors Limited (Alexandra)	[A] Lau Shu Pei
4	16 Oct 2019 16:47	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pei
5	16 Oct 2019 16:47	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/10/25	[A] Lau Shu Pei
6	16 Oct 2019 16:47	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] Lau Shu Pei
7	16 Oct 2019 16:47	Cim Ins Co Changed	[200005] AIG Asia Pacific Insurance Pte. Ltd. (SG) -> [203630] AIG Asia Pacific Insurance Pte. Ltd. (Express)	[I] Merimen Administrator
8	16 Oct 2019 16:47	Label Added	(23):Express.	[A] Lau Shu Pei
9	16 Oct 2019 16:47	Adj Adjuster Assigned	[None] -> MOHD RASUL	[A] Lau Shu Pei
10	22 Oct 2019 10:52	Video Downloaded	Downloaded Video - Accident	[A] Khanchna Pothura
11	22 Oct 2019 14:56	Video Downloaded	Downloaded Video - Accident	[A] Khanchna Pothura
12	22 Oct 2019 15:03	Video Downloaded	Downloaded Video - Accident TP	[A] Khanchna Pothura
13	10 Dec 2019 16:49	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN
14	10 Dec 2019 16:49	Cim Dtl Modified	IPJ Reg. Date: -> 2018/12/31.	[A] JOANNE LEE KHANG MIN
15	10 Dec 2019 16:49	Cim Details Notified		[A] JOANNE LEE KHANG MIN
16	02 Jan 2020 17:04	Adj Mandate Request	Cur.Reg:9039.90:BOLA 27, Head to rear end collision, Liability down against Insured.	[A] Khanchna Pothura

Date From



Date To



Audit Type None



Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Insurer	TP Insurer (Branch)	Acc No	Ref No	Amount
2316078	17 Oct 2019 10:16:46	TP Case (Insurer)	Motor	LKK Auto Consultants Pte Ltd	AIG Asia Pacific Insurance Pte. Ltd. (Express)	SMG7925U	SMN28T	11.77
2320777	22 Oct 2019 10:33:28	Video Upload	Motor	AIG Asia Pacific Insurance Pte. Ltd.	AIG Asia Pacific Insurance Pte. Ltd. (SG)	SMG7925U	Hor, Yinrul	xx.xx
2321336	22 Oct 2019 15:03:23	Video Upload	Motor	AIG Asia Pacific Insurance Pte. Ltd.	AIG Asia Pacific Insurance Pte. Ltd. (SG)	SMG7925U	Khanchna Pothura	xx.xx
2372918	10 Dec 2019 16:49:13	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SMG7925U	SMN28T	11.77

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Tuesday, 21 January 2020 10:29 AM
To: PBSP
Cc: Admin A
Subject: Confirm settlement + Request for LOA - SMG7925U & SMN28T ON 11/10/2019 ***LKK REF:CC3/AIG19018296/kb3

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We confirm settlement as follows:

1. Cost of Repair (w/GST)	\$ 8,611.90
2. Loss of Rental (5 days x \$80)(W/GST) (PAYABLE TO BKW RENT A CAR PTE LTD)	\$ 428.00
Total	\$ 9,039.90

Please forward us a copy of the Letter of Authorisation with company chop for our further action.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Wishing you a Happy and Prosperous Lunar New Year



Best Regards,
Khanchna | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Tuesday, 14 January 2020 10:22 AM
To: Khanchna (LKK Auto) <khanchna@lkkauto.com>; Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Subject: PAYMENT REMINDER - SMG7925U & SMN28T ON 11/10/2019 ***LKK REF:CC3/AIG19018296/kb3

Dear Sirs

Print Received Message

This mail is associated with :

***SMG7925U (8273251526SG)**
[SMN28T]

TP
BENJAMIN LEE CHONG MENG
Oct 11 2019 4:00PM
[TOH SHI JIE]
Performance Motors Limited

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 20/01/2020 10:41 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$9039.90) - SMG7925U - Claim Handler: MdNoor, Norsiah

Approved:9039.90.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Oct 2019 Edit Reg		04 Nov 2019 00:00 Edit Adj Rpt	S\$8,048.50 Edit Estimates	S\$8,048.50 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	TOH SHI JIE , ID: S9331520J								
Main Claimant:	BENJAMIN LEE CHONG MENG , ID: S7813686C								
Vehicle Reg. No.:	SMG7925U	Date of Loss:	11/10/2019 16:00 - :59 [9 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 8273251526SG	Policy/Cover Note No.:	1900189535 (Comprehensive) Coverage: 09/10/2019 - 08/10/2021						
Vehicle Reg. No. (Insured):	SMN28T	Policy No. (Claimant):	A29131007APO						
Repaier:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 25/10/2019]								
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail				
• AIG_SG_EXPRESS (20/01/2020): Alert - Adj Mandate Approved (S\$9039.90) - SMG7925U - Claim Handler: MdNoor, Nor...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMG7925U (8273251526SG)**
[SMN28T]
TP
BENJAMIN LEE CHONG MENG
Oct 11 2019 4:00PM
[TOH SHI JIE]
Performance Motors Limited

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View <input type="button" value="View in Browser"/>		
Video															1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print				
1	22/10/19 15:03	Video - Accident TP											Load MOV	<input type="checkbox"/>			
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)										Thumbnail	Print				
1	22/10/19 10:33	Video - Accident											Load AVI	<input type="checkbox"/>			
Letters/Correspondences															1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print				
1	(Draft)	Third Party Express Settlement - Payment Breakdown											Edit	<input type="checkbox"/>			
Photos/Images															3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print				
1	02/01/20 16:58	General View											Load JPG	<input checked="" type="checkbox"/>			
2	02/01/20 16:58	Chassis Number											Load JPG	<input checked="" type="checkbox"/>			
3	02/01/20 16:58	General View											Load JPG	<input checked="" type="checkbox"/>			
4	02/01/20 16:58	General View											Load JPG	<input checked="" type="checkbox"/>			
5	02/01/20 16:58	General View											Load JPG	<input checked="" type="checkbox"/>			
6	02/01/20 16:58	General View											Load JPG	<input checked="" type="checkbox"/>			
7	02/01/20 16:58	General View											Load JPG	<input checked="" type="checkbox"/>			
8	02/01/20 16:58	General View											Load JPG	<input checked="" type="checkbox"/>			
9	02/01/20 16:58	General View											Load JPG	<input checked="" type="checkbox"/>			
10	02/01/20 16:58	General View											Load JPG	<input checked="" type="checkbox"/>			
11	02/01/20 16:58	General View											Load JPG	<input checked="" type="checkbox"/>			
12	02/01/20 16:58	General View											Load JPG	<input checked="" type="checkbox"/>			
13	02/01/20 16:58	General View											Load JPG	<input checked="" type="checkbox"/>			
14	02/01/20 16:58	General View											Load JPG	<input checked="" type="checkbox"/>			
15	02/01/20 16:58	General View											Load JPG	<input checked="" type="checkbox"/>			
16	02/01/20 16:58	General View											Load JPG	<input checked="" type="checkbox"/>			
17	02/01/20 16:58	General View											Load JPG	<input checked="" type="checkbox"/>			
18	02/01/20 16:58	General View											Load JPG	<input checked="" type="checkbox"/>			
19	02/01/20 16:58	General View											Load JPG	<input checked="" type="checkbox"/>			
20	02/01/20 16:58	General View											Load JPG	<input checked="" type="checkbox"/>			
21	02/01/20 16:58	General View											Load JPG	<input checked="" type="checkbox"/>			
22	02/01/20 16:59	General View											Load JPG	<input checked="" type="checkbox"/>			
23	02/01/20 16:59	General View											Load JPG	<input checked="" type="checkbox"/>			
24	02/01/20 16:59	General View											Load JPG	<input checked="" type="checkbox"/>			
25	02/01/20 16:59	General View											Load JPG	<input checked="" type="checkbox"/>			
26	02/01/20 16:59	General View											Load JPG	<input checked="" type="checkbox"/>			
27	02/01/20 16:59	General View											Load JPG	<input checked="" type="checkbox"/>			
28	02/01/20 16:59	General View											Load JPG	<input checked="" type="checkbox"/>			
29	02/01/20 16:59	General View											Load JPG	<input checked="" type="checkbox"/>			
30	02/01/20 16:59	General View											Load JPG	<input checked="" type="checkbox"/>			
31	02/01/20 16:59	General View											Load JPG	<input checked="" type="checkbox"/>			
32	02/01/20 16:59	General View											Load JPG	<input checked="" type="checkbox"/>			
33	02/01/20 16:59	General View											Load JPG	<input checked="" type="checkbox"/>			
34	02/01/20 16:59	General View											Load JPG	<input checked="" type="checkbox"/>			
35	02/01/20 16:59	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>			

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
36	02/01/20 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	02/01/20 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	02/01/20 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	02/01/20 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	02/01/20 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	02/01/20 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	02/01/20 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	02/01/20 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	02/01/20 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	02/01/20 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	02/01/20 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	02/01/20 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	02/01/20 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	02/01/20 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	02/01/20 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/10/19 16:48	TP ESTIMATE	 Load PDF	
2	16/10/19 16:48	TP GIA REPORT	 Load PDF	
3	22/10/19 10:58	EMAIL TO OI	 Load PDF	
4	23/10/19 09:27	BKW CAR RENTAL	 Load PDF	
5	06/11/19 17:35	TP ESTIMATE- MARKED	 Load PDF	
6	19/11/19 09:22	RENTAL RECEIPT	 Load PDF	
7	02/01/20 14:04	LOD	 Load PDF	
8	23/01/20 10:33	WORKSHOP INVOICE	 Load PDF	
9	23/01/20 10:33	AUTHORISATION TO ACT FORM	 Load PDF	
10	23/01/20 10:33	Release Voucher	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	17/10/19 10:13	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SMN28T (Insd veh)	Model:	BMW 216I 1.5 D GT LED (A)
	SMG7925U (TP veh)		
Date of Accident:	11/10/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	10,632.59
Final Repair Cost	:	\$	8,611.90
Loss of Use	:	\$	_____ days at \$0.00 per day
Rental (if any)	:	\$	428.00 5 days
LTA / GIA Search Fee	:	\$	0.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	9,039.90
Is Third Party Workshop GIA Registered? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____(%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No —BOLA Scenario No: _____	
BOLA Liability: _____100_____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:	\$ 8,611.90
2)	BKW Rent-A-Car Pte Ltd	:	\$ 428.00

JOANNE LEE KHANG MIN

23 Jan
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19018296/R1KA3Q2

Date: 23/01/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900189535
 Claimant: SMG7925U Insured Vehicle No: SMN28T
 Vehicle No: SMG7925U Nature of Claim: TP Claim No: 8273251526SG
 Date of Loss: 11/10/2019

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMG7925U
 Make & Model: BMW 216I, 1.5 D GT LED (A) Engine No: 34935443B38A15A
 Reg. Date: 31/12/2018 (Man. Year: 2018) Chassis No: WBA6V12000ED05578
 Colour: White Odometer: 16838 km
 Engine Capacity: 1499 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R17 Rear Tyre Size: 205/55 R17
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,812.00	3,118.50	693.50	18.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,125.00	4,930.00	1,195.00	19.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,937.00	8,048.50	1,888.50	19.00
+ GST 7.00/7.00% (S\$)	695.59	563.40	132.19	19.00
Nett Amount (S\$)	10,632.59	8,611.90	2,020.69	19.00
+ Car Rental (5.0 x S\$80.00/day + 7.00% GST) (S\$)		428.00		
		9,039.90		
		9,039.90		

INSPECTION

Date of Assignment: 04/11/2019
 Date Inspected: 04/11/2019 Inspected At: Performance Motors Limited
 (Alexandra)
 303 Alexandra Road, Sime Darby
 Performance Centre
 Singapore 159941
 Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*TAILPIPE TRIM BRIGHT CHROME	Not Necessary	116.05 FS	*- FS
3	1		*BOOTLID	Bent	1,210.35 FS	*1,210.35 FS
4	1		*SUPPORT	Cracked	45.55 FS	*45.55 FS
5	1		*RR BUMPER LH INNER SIDE GUIDE	Cracked	67.55 FS	*61.35 FS
6	1		*RR BUMPER RH INNER SIDE GUIDE	Cracked	67.55 FS	*61.35 FS
7	1		*REAR BUMPER TOWING FLAP EYE PRIMED	Not Necessary	42.85 FS	*- FS
8	1		*REAR BUMPER TRIM STRIP (BLACK)	Cut	72.20 FS	*72.20 FS
9	1		*REAR BUMPER PANEL PRIMED (LINES PDC)	Deformed	1,045.45 FS	*1,045.45 FS
10	2		*GROMMET	Necessary	1.60 FS	*1.60 FS
11	1		*REAR BUMPER HEAT INSULATION	Not Necessary	63.20 FS	*- FS
12	1		*PLAQUE 82MM	Necessary	71.60 FS	*71.60 FS
13	4		*DECOUPONG RING PDC TORQUE CONVERTER	Serviceable	20.20 FS	*- FS
14	1		*ULTRASONIC SENSOR MINERALWEISS (WA96)	Serviceable	368.80 FS	*- FS
15	2		*EXPANDING NUT	Necessary	2.00 FS	*2.00 FS
16	1		*REAR BUMPER CARRIER	Bent	460.40 FS	*460.40 FS
17	7		*PLUG BLACK D=5MM	Necessary	6.65 FS	*6.65 FS
Total Parts (\$\$)					3,812.00	3,118.50

F=Franchise part, S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER ,TAILGATE AND ATTACHMENTS	New	2,550.00	1,700.00
2	PAINTING REAR BUMPER AND TAILGATE	New	1,923.00	1,730.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
4	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION	New	177.00	150.00
5	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE THE REPAIR JOB	New	574.00	574.00
6	TO CONDUCT WATER LEAK TESTS	New	75.00	75.00
7	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOTLID INCLUDING CONDUCT CHECKS ON NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	531.00	451.00
8	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
Gross Labour Cost (S\$)			6,125.00	4,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >