

V arrange metal car from BKW

Survey & repair
 4/11 @ 10am

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
 Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
 Toll-Free Number (1800-2255269)



303, Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941
 Fax. 64747770

280, Kampong Arang Road
 East Coast Centre
 Singapore 438180
 Fax. 63449773

315, Alexandra Road
 Sime Darby Business Centre
 Singapore 159944
 Fax. 64796601 (AfterSales)
 64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

16 OCT 2019

E S T I M A T E

| | |
|--------------------------------------|-------------------|
| Estimate No. : b1 53107 | Page No. : 1 of 5 |
| Date Estimated : 16/10/2019 | |
| Prepared By : Inthiran A/L Thurasamy | |

| | |
|--|---|
| - ESTIMATE REPAIR FOR - Lee Chong Meng, Benjamin (Li Zongmi) 81 Pasir Ris Grove #03-48 Singapore 518210 | - ACCOUNT - 121 AIG Asia Pacific Insurance Pte. Ltd. 78 Shenton Way #08-16 Chartis Building Singapore 079120 |
|--|---|

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL | MILEAGE |
|-----------|-------------------|------------|---------|---------|
| SMG7925U | WBA6V12000ED05578 | 31/12/2018 | 216i GT | 0 |

| DESCRIPTION | VALUE |
|--|--------------------------|
| To replace rear bumper, tailgate and attachments. | 1700 2,550.00 |
| Painting rear bumper and tailgate. | 1730 1,923.00 |
| To check electrical wiring systems and lightings at the rear section for proper function. | 150 177.00 |
| To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function. | 150 177.00 |
| To remove and install rear windscreen glass to facilitate the repair job. | 574.00 |
| To conduct water leak tests. | 75.00 |
| To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking system for proper function. | 457 531.00 |
| To carry out body cavity preservation. (Per panel). | 100 118.00 |
| Sundries. | ? 150.00 |
| Total Labour 1: 6,275.00 | |

| DESCRIPTION | QTY | PRIC | VALUE |
|--------------------------------------|-----|----------|----------|
| TAILPIPE TRIM BRIGHT CHROME ? | 1 | 116.05 | 116.05 |
| BOOTLID bt | 1 | 1,204.35 | 1,204.35 |
| SUPPORT ? | 1 | 45.30 | 45.30 |
| RR BUMPER LH INNER SIDE GUIDE ? | 1 | 67.55 | 67.55 |
| RR BUMPER RH INNER SIDE GUIDE ? | 1 | 67.55 | 67.55 |
| REAR BUMPER TOWING FLAP EYE PRIMED X | 1 | 42.85 | 42.85 |
| REAR BUMPER TRIM STRIP (BLACK) cut | 1 | 72.20 | 72.20 |

Performance Motors Limited

A Sime Darby Motors Company
 Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
 Toll-Free Number (1800-2255269)



303, Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941
 Fax. 64747770

280, Kampong Arang Road
 East Coast Centre
 Singapore 438180
 Fax. 63449773

315, Alexandra Road
 Sime Darby Business Centre
 Singapore 159944
 Fax. 64796601 (AfterSales)
 64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 53107** Page No. : 2 of 5
 Date Estimated : **16/10/2019**
 Prepared By : **Inthiran A/L Thurasamy**

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL | MILEAGE |
|-----------|-------------------|------------|---------|---------|
| SMG7925U | WBA6V12000ED05578 | 31/12/2018 | 216i GT | 0 |

| DESCRIPTION | QTY | PRIC | VALUE |
|---|-----|----------|-----------------|
| REAR BUMPER PANEL PRIMED (LINES PDC de ✓) | 1 | 1,045.45 | 1,045.45 |
| GROMMET ne ✓ | 2 | 0.80 | 1.60 |
| REAR BUMPER HEAT INSULATION ? | 1 | 63.20 | 63.20 |
| PLAQUE 82MM ne ✓ | 1 | 71.25 | 71.25 |
| DECOUPLING RING PDC TORQUE CONVERTER ? | 4 | 5.05 | 20.20 |
| ULTRASONIC SENSOR MINERALWEISS(WA96 ?) | 1 | 368.80 | 368.80 |
| Total Parts : | | | 3,186.35 |

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 04/11/19 @ 10.20 Excess S\$ _____

Surveyor's Name RASUL Sign _____

Surveyor's Tel 96010068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

| | | |
|--------------------|---|------------------|
| Labour 1 | : | 6,275.00 |
| Parts | : | 3,186.35 |
| Labour 2 | : | 0.00 |
| Excess | : | 0.00 |
| Total GST @ 7% | : | 662.29 |
| Grand Total | : | 10,123.64 |

**** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY****
**** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE ****