

Kanc Hpa

Arrange metal car from BKW

Survey & repair
4/11 @ 10am

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559M GST Reg. No. M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

16 OCT 2019

ESTIMATE

Estimate No. : b1 53107	Page No. : 1 of 5
Date Estimated : 16/10/2019	
Prepared By : Inthiran A/L Thurasamy	

- ESTIMATE REPAIR FOR - Lee Chong Meng, Benjamin (Li Zongmi) 81 Pasir Ris Grove #03-48 Singapore 518210	- ACCOUNT - 121 AIG Asia Pacific Insurance Pte. Ltd. 78 Shenton Way #08-16 Chartis Building Singapore 079120
---	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMG7925U	WBA6V12000ED05578	31/12/2018	216i GT	0

DESCRIPTION	VALUE
To replace rear bumper, tailgate and attachments.	1700 2,580.00
Painting rear bumper and tailgate.	1730 1,923.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150 177.00
To remove and install rear windscreen glass to facilitate the repair job.	574.00
To conduct water leak tests.	75.00
To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking system for proper function.	457 534.00
To carry out body cavity preservation. (Per panel).	100 116.00
Sundries.	80 ? 150.00
Total Labour 1: 6,275.00	

DESCRIPTION	QTY	PRIC	VALUE
TAILPIPE TRIM BRIGHT CHROME ? XM	1	118.05	118.05
BOOTLID st	1	1,204.35	1,204.35
SUPPORT ? ca	1	45.30	45.30
RR BUMPER LH INNER SIDE GUIDE ? ca	1	67.55	67.55
RR BUMPER RH INNER SIDE GUIDE ? ca	1	67.55	67.55
REAR BUMPER TOWING FLAP EYE PRIMED XM	1	42.85	42.85
REAR BUMPER TRIM STRIP (BLACK) cut	1	72.20	72.20

1210.35
45.30
67.55
(1.75)

BMM Dealer

Performance Motors Limited

A Sime Darby Motors Company
 Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
 Toll-Free Number (1800-2255269)

303, Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941
 Fax: 64747770

280, Kampong Arang Road
 East Coast Centre
 Singapore 438180
 Fax: 61449773

315, Alexandra Road
 Sime Darby Business Centre
 Singapore 159944
 Fax: 64796601 (AfterSales)
 64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 53107 Page No. : 2 of 5
 Date Estimated : 16/10/2019
 Prepared By : Inthiran A/L Thurasamy

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMG7925U	WBA6V12000ED05578	31/12/2018	216i GT	0

DESCRIPTION	QTY	PRIC	VALUE
REAR BUMPER PANEL PRIMED (LINES PDC de -	1	1,045.45	1,045.45
GROMMET	2	0.80	1.60
REAR BUMPER HEAT INSULATION ? XAN	1	63.20	63.20
PLAQUE 82MM	1	71.25	71.25
DECOUPLING RING PDC TORQUE CONVERTER ? Xsu	4	5.05	20.20
ULTRASONIC SENSOR MINERALWEISS(WA96 ? Xsu	1	368.80	368.80
Total Parts :			3,186.35

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No _____ Claim No _____
 Date & Time 04/11/19 @ 10:20 Excess S\$ _____
 Surveyor's Name R. S. S. Sign _____
 Surveyor's Tel 92010068 Authorised Yes / No _____
 Time _____
 Surveyor's E-mail _____
 No. of Working Days Recommended 5 days

LMA Group Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal modification(s) is allowed
- Any secondary item(s) must be resurveyed and approved by the surveyor's final approval from Insurance Company.

Approved by Repairer _____

Labour 1	:	6,275.00
Parts	:	3,186.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	662.29
Grand Total	:	10,123.64

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
 ** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 53107**
Date Estimated : **16/10/2019**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -
Lee Chong Meng, Benjamin (Li Zongmi
81 Pasir Ris Grove
#03-48

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 518210

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMG7925U	WBA6V12000ED05578	31/12/2018	216i GT	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments, bootlid and attachments including knock out dented area caused by the accident.	1,700.00		1,700.00 ✓
To respray rear bumper and bootlid.	1,730.00		1,730.00 ✓
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00 ✓
To remove old PDC assembly and reconnect to new bumper including conduct checks for proper function.	150.00		150.00 ✓
To remove and install rear windscreen glass to facilitate repairs.	574.00		574.00 ✓
To conduct water leak tests.	75.00		75.00 ✓
To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking system for proper function.	451.00		451.00 ✓
To carry out body cavity preservation. (Per panel).	100.00		100.00 ✓
Sundries.	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
BOOTLID	1,210.35	1.00		1,210.35 ✓
# EXPANDING NUT	1.00	2.00		2.00 (S) ✓
# REAR BUMPER CARRIER SUPPORT	460.40	1.00		460.40 (S) ✓
RR BUMPER LH INNER SIDE GUIDE	45.55	1.00		45.55 ✓
RR BUMPER RH INNER SIDE GUIDE	61.35	1.00		61.35 ✓
REAR BUMPER TRIM STRIP (BLACK)	61.35	1.00		61.35 ✓
REAR BUMPER PANEL PRIMED (LINES PDC)	72.20	1.00		72.20 ✓
GROMMET	1,045.45	1.00		1,045.45 ✓
PLAQUE 74MM	0.80	2.00		1.60 ✓
# PLUG BLACK D=5MM	71.60	1.00		71.60 ✓
	0.95	7.00		6.65 (S) ✓

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

SUPPLEMENTARY ITEMS

Total Labour :	5,010.00
Total Parts :	3,038.50
Total Labour & Parts :	8,048.50
Deduction for Excess :	0.00
Total Repair Costs less Excess:	8,048.50
GST @7%:	563.40
Grand Total :	8,611.90

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 53107**
Date Estimated : **16/10/2019**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -
Lee Chong Meng, Benjamin (Li Zongmi
81 Pasir Ris Grove
#03-48

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 518210

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMG7925U	WBA6V12000ED05578	31/12/2018	216i GT	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING NUT <i>new</i>	1.00	2.00		2.00
# REAR BUMPER CARRIER <i>bt</i>	460.40	1.00		460.40
# PLUG BLACK D=5MM <i>new</i>	0.95	7.00		6.65

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	469.05
Total Labour & Parts :	469.05