From	(Person): Virmala D/O	Raja Soyamof	msta	Date/Tim	e: 16.10.2014	7 16.11
Estin	ialed Cost:		Bill to:			
To In	TP / WS / TP RES / OI spect Vehicle No:	GBF 8800A		_ Insured;		
	orkshop m/s Auto mob		d	Tel: 9L3	90102	
of D	& Sin miny Lane	707-147				
Polic	y No: 2892584L		Claim No:	608432	× ++	
Sum	Insured:	1	Excess:	9600.00		
	of Veh:				11.10.0019	
CA	REV / REP. / REV Time: 16.10.15 5.4	24 HRS Person Con	ntacted: kevin	H.O.D.I	endorsement:	
Date		1	D 1 1	12 Mari Ruk	of live 4 a	104-01
-	Time Action/Instruc	tion (J) ts	timate Inspection.	22 MIN 041		
-	Time Action/Instruc		timate "spection".	22 MIN 2011		

Tech. Invs (\$

Weel end (\$

Reputationnal:

Lump 2000/10:00 5906-90

Officers

TOTAL

211

...CLAIM SUBFOLDER...(New Assignment)

ase	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Oct 2019		16 Oct 2019 16:11 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS	S		[Created by in	nsurer]
Insured:	FENG SHENG ENGINEER	RING PTE LTD, Co. Reg. No.: 20	00900097C	
Vehicle Reg. No.:	GBF8800A	Date of Loss:	11/10/2019 10: [45 Months and Reg Date (Man	10 Days From LT
Claim Type:	OD / 608432	Policy/Cover Note No.:	28925846 (Com Coverage: 07/0- 06/04/2020	
		Excess:	5\$600.00	
Repairer:	Automobile Intergrated Sin Ming - Tel:	Management Pte Ltd (HQ) 28	Sin Ming Lane, #07-147, Midvi	iew City, 573972
Handling Insurer:	MSIG Insurance (Singar Singam - 65942471]	pore) Pte. Ltd. (HQ) - Tel: +65	6827 7888 [Handled by Vin	nmala D/O Raja
Adjuster:	LKK Auto Consultants P	te Ltd (HQ) - Tel: 6256-3561	[Imm.Advice due 17/10	/2019]
Driver/Custodian:	TOH KOK PENG (51 / Male), NRIC: S1831299I, Tel: +6	590034119 Email: NOEMAIL	
Adj Asg. Remarks:		ease contact us ASAP if you cannot h Wing) Singapore 415933 (PIC: H		vey at 23 Kaki
ASSOCIATED MAIL RECEIVE	ED .		View All Cor	mpose Case Mail
There are no mail for this case.				
E ALL ASSOCIATED TASKS		View All Sea	rch Tasks Create New Tas	sk Complete
Due Date Priority Typ	e Task Group Subject	Handler Assigned By	Completed On Crea	ted On Done?

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID: Vehicle Details	097C
Vehicle No.:	GBF8800A
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Oct 2019
Vehicle Make:	NISSAN
Vehicle Model:	NV350 PANEL VAN 2.5 5AT 5DR EURO V
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	YD25393825A
Chassis No.:	JN1MC2E26Z0006443
Maximum Power Output:	
Open Market Value:	\$23,944.00
Original Registration Date:	07 Apr 2016
First Registration Date:	07 Apr 2016
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$1,198.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	•
PARF Rebate Amount: Intended COE Rebate Details	\$0.00
COE Expiry Date:	06 Apr 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$37,499.00
COE Rebate Amount:	\$24,265.00
Total Rebate Amount:	\$24,265.00

The information contained herein is correct as at 17 Oct 2019

View Received Message

This mail is associated with:

*GBF8800A (608432)
OD
Oct 11 2019 10:00AM
[FENG SHENG ENGINEERING PTE LTD]
Automobile Intergrated Management Pte Ltd

Reply	Reply All Mark as Unread Print Message Delete Message Forward	
From	MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 17/10/2019 17:16 PM.	
То	LKK HO	
Subject	Alert - Adj Mandate Approved (S\$5906.50) - GBF8800A - Claim Handler: Vimmala D/O Raja Singam	
росим	MENTS SUMMARY	
There ar	are no documents.	

Bal: 6-5.9m ths.

> Back to OneMotoring

Enquire PARF/COE Rebate for	Registered Vehicle
-----------------------------	--------------------

Vehicle Owner Particulars	Mark translation
Owner ID Type:	Company
Owner ID: Vehicle Details	097C
Vehicle No.:	GBF8800A
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Oct 2019
Vehicle Make:	NISSAN
Vehicle Model:	NV350 PANEL VAN 2.5 5AT 5DR EURO V
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	YD25393825A
Chassis No.:	JN1MC2E26Z0006443
Maximum Power Output:	
Open Market Value:	\$23,944.00
Original Registration Date:	07 Apr 2016
First Registration Date:	07 Apr 2016
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$1,198.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	•
PARF Rebate Amount: Intended COE Rebate Details	\$0.00
COE Expiry Date:	06 Apr 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$37,499.00
COE Rebate Amount:	\$24,265.00
Total Rebate Amount:	\$24,265.00

The information contained herein is correct as at 17 Oct 2019

OK

m_1, \$45 K

Site Insp (\$

Interview (\$

S+RS SI

Photos

MVA319134955 / VAC - Kaki Bukit ENTRY DATE & TIME: 11/10/2019 14:16 SUBMITTED BY: NorhainI Bte Abdul Majid

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCI	DENT	CTA	-	
ACCI	DENI	SIA	- 17	

Date Of Report 11/10/2019 14:16
Date Of Accident 11/10/2019 10:55

Exact Location Of Accident WEST COAST CRESCENT / WEST COAST LINK

Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBF8800A

Insured/Policyholder

Name Of Registered Owner FENG SHENG ENGINEERING PTE LTD

 Co Reg No
 200900097C

 Email Address
 NOEMAIL

Mobile Phone No

Alternative Phone No OFFICE-90034119

Vehicle Particulars

Manufacturer NISSAN

Model NV350 PANEL VAN 2.5 5AT 5DR EURO V

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

YES

If No, Please state action to be taken

Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number A 28925846 MKC (COMP)

Cover Note Number

Driver

 Name of Driver
 TOH KOK PENG

 NRIC No
 \$1831299I

 Date Of Birth
 23/11/1967

 Occupation
 OUTDOOR

 Date Of Driving Pass
 30/01/1988

Driving Experience 31 YEARS AND 8 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-90034119

Fax Number

Contact Number

EMail Address NOEMAIL

Address BLK 122 TECK WHYE LANE #10-842

Postcode 680122

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident SIDE SWIPE
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)

involved in the accident

2

Was any body injured in the Accident?

Was any injured conveyed to hospital by

ambulance?

NO NO

YES

NO

2

Was any other material or property damaged?

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

Passenger 1

NAME:

: TAN YONG SHENG

GENDER:

: MALE

Details of Police Action

Was the accident reported to the police?

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

WITH DRIVER

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GBE5880T

Vehicle Make/Model/Colour

TOYOTA / DYNA 3.0 DIESEL TURBO M/T 2WD LORRY

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

ONG WEE KOON

NRIC/Passport Number

S1336114B

Contact Number

Address Postcode

Insurance Company Name

Nature Of Damage

Page 2 of 11

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (I) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, Investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

Driver's Signature (If driver is not the policyholder)

Date & Time:

IDAC KAKI BUKIT (VAC) 23 Kaki Bukit Ave 4 #02-02 Singapore 415933 Tel: 67416697 Fax: 67492305

Email services. -m.com.sq

Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

1 1 OCT 2019

No. Of Passenger (Including Driver)

Sketch Plan #2

SKETCH PLAN		GBESPRO		
	-	A	\rightarrow	
- West C	oast with			
	-			
		9 7	FRRADA	
		1 6	0.00	
		6		
		1 V		
		10		
		100		
		0		
		8		
		8		
DESCRIBE CIRCUMSTAN	CES OF THE ACCIDENT	2		
DA Walana				
0" 11/10/14 (8)	10.53 an J 200	driving my vehice	6 GBFP800A	from clast
chaot cracent.	toward Nest Con	ast cink Alten	becking there	WAR OF 101-
reliek on the lef	+ & proceed to	turn right to want	0. + (1 - 01	FORE 110 OFFEE
fast never yet	ille no GBE Soft	ht III	cour Look o After	e turney a
O. V.	CCC NO. DEC SUN	sudderly .	All my rehide	and cut
with my lane		,	/	
the my line				
the my lane				
atto my lane		/		
wite my come				
wite my cone				
were my cone				
were my cone				
THE MY LINE				
were my cone				
The My Cone				
acto my cone				
were my cone				
toto my line				
were my cone				
atte my lane				
toto my lane				
acto my cone				
toto my lane				
toto my lane				
ECLARATION				
ECLARATION				
ECLARATION We declare the foregoing part	ticulars are true in every re-		IDAC KA 23 Kaki Bui	KI DUKIT (VAC)
ECLARATION We declare the foregoing part		spect.	IDAC KA 23 Kaki Bu Sinaan	Ki DUKIT (VAC) kit Ave 4 #02-02
ECLARATION We declare the foregoing particular	ticulars are true in every re	spect.	IDAC KAI 23 Kaki Bui Singap Tel: 6741669	KI BUKIT (VAC) kit Ave 4 #02-02 ore 41 #393
ECLARATION We declare the foregoing part	ticulars are true in every re-	spect. 1 1 00T 20	IDAC KA 23 Kaki Bu Sinaan	KI BUKIT (VAC) kit Ave 4 #02-02 ore 41 #393







Automobile Integrated Management Re Lt Co. & G.S.T. Reg no. 201605297G
Office: 28 Sin Ming Lane #07-147 Midview
Workshop: 23 Kaki Bukit Ave 5 #04-01 (Sou

LKK Auto Consultants hence notify the Repairer of the following: Automobile Integrated Management Re Ltd rowsy before/after spray painting

Co. & G.S.T. Reg no. 201605297G

Office: 28 Sin Ming Lane #07-147 Midylew City Singapore 573972

Workshop: 23 Kaki Bukit Ave 5 #04-01 (South Wing) Singapore 573978

**Third party survey is on a "Without Prejudice" basis Email: automim.claim@gmail.com Tel: 911983710d.fcation.s) is allowed

 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATE

Our Ref: AC2019041/OD/GBF8800A-11.10.2019

Vehicle number: GBF8800A Vehicle Made & Model: NISSAN URVAN NV350

<u>Items</u>	Qty	List Ite	ems an		Amount \$
1	1		bumper / OK OP		380.00
2	1	Front	bumper fog lamp - LH		260.00
3	1	Front	(17) (10) (1) (10) (1) (1) (1) (1) (1) (1) (1) (1) (1) (1		95.00
4	1	Front	bumper bracket / AHT B		95.00
5	1	Front	bumper side bracket - LH		110.00
6	10	Front	bumper clips @ 2.50 / //(25.00 /
7	1		corner panel - LH / //		280.00
8	1	Front	cab panel assy / //		750.00
9	1	Front	door pillar - LH - Outer X		850.00
10	1	Front	door pillar - LH - Inner X K		620.00
11	1	Front	grille / MII CRA		330.00
12	1	Front	grille logo		75.00
13	1		headlamp - LH / //(285.00
14	1	Front	wiper panel garnish 🗴		195.00
15	1		windshield X		820.00
16	1		step garnish - LH X K		85.00
17	1	Oil coo	oler / ///	_	580.00
				Sub-total	5,835.00
				Additional 10%	583.50
				Total Cost	6,418.50
		Specia	Nett Items		
18	1 set	Front	windscreen sealant / /		40 80.00
19	1 set	Front	no. plate with holder RV		75 60.00
20	1	I.U bra	cket / Mg		20.00
21	1	R.O.V :	sticker / n/C		45.00
				Total Special Nett	215.00
		Labou	r charges_		
22	To che	ck front	electrical wiring		30 50.00
23	To rem	ove, ref	ix front windscreen		121 180.00
24	To rem	ove, ref	ix front dashboard		150 300.00
25	To rem	ove, ref	ix A/C cooling sytems & refill A/C gas		124 180.00
26			iting and etc		800 1,200.00
27	Panel b	eating,	cut, weld remove & replacing above parts		1,500.00
			W 89 W	Total Labour	3,410.00
	ESTIMA	ATE PAR	TS AND LABOUR GRAND TOTAL \$		10,043.50



Steve (LKK) 00 - Not Author (Pevid) 17/10/19/12-90/ph

EXCESS - 600

EXCESS - 600

Automobile integrated Management for esurvey before/after co. & 6.5.T. Reg no. 20160529 G. To display damaged par Workshop: 23 Kalling.

PIP Workshop: 23 Kalling.

Office: 28 Sin Ming Lane #07-1-7 Midview City Singapore 573972 Office: 28 Sin Ming Lane #07-1 7 Midylew City Singapore 573972
Workshop: 23 Kaki Bukit Ave 5 104-01 Gdom Wing Singapore a "Without Prejudice" basis 415933

LKK Auto Consultants hence notify the Repairer of the following:

reNe l'egas godification s) is allowed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATE

Our Ref: AC2019041/OD/GBF8800A-11.10.2019

Vehicle number: GBF8800A

Vehicle Made & Model: NISSAN URVAN NV350

				An	nount \$
Items	Qty	List Items 10			380.00
1	1	Front bumper / UK AP			260.00
2	1	Front bumper fog lamp - LH MIS			95.00
3	1	Front humper fog lamp cover			95.00
4	1	Front human bracket / [111]			110.00
5	1	Front bumper side bracket - Ln			25.00/
6	10	Front bumper clips @ 2.50 / 1/C			280.00
7	1	Front corner panel - LH / DD		V	750.00 V
8	1	Front cab panel assy / NO P		X	850.00
9	1	Front door pillar - LH - Outer X P			620.00
10	1	Front door pillar - LH - Inner X K			330.00
11	1	Front grille / MIJ			75.00 V
12	1	Front grille logo / MI)			285.00
13	1	Front headlamp - LH / DR			195.00 X
14	1	Front wiper panel garnish X			820.00
15	1	Front windshield X ///			85.00 X
16	1	Front step garnish - LH X K			580.00
17	1	Oil cooler / ())		- OILL	
			Sub-total		5,835.00
			Additional 10% _	7	583.50
			Total Cost		6,418.50
		Special Nett Items			
18	1 set			TILA	20.00
19	1 set	Front windscreen sealant / //K		71	80.00
20	1	Front no. plate with holder / CRM I.U bracket / MX		10	60.00
21	1	P.O.V. etickor		4	30.00
21		R.O.V sticker × prc nn			45.00
			Total Special Nett		215.00
		Labour charges			
22	Toch	eck front electrical wiring		21	
23		nove, refix front windscreen		30	50.00
24				120	180.00
		nove, refix front dashboard		150	300.00
25	To rer	nove, refix A/C cooling sytems & refill A/C gas		121	180.00
26	10 res	pray painting and etc		800	1,200.00
27	Panel	beating, cut, weld remove & replacing above parts		1000	1,500.00
			Total Labour		3,410.00
	ESTIN	ATE PARTS AND LABOUR GRAND TOTAL \$, Old and Old		10,043.50
					10,043.50

日美汽車私人有限公司

JAE AUTO PTE LTD Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710 TEL: 67453833 FAX: 67454442, 67450616 (Account)

60 JALAN LAM HUAT #B1-05/06 CARROS CENTRE



Arrange By	Driver













SINGAPORE 737869 TEL: 63625226 FAX: 63626977 Email: jaeauto@pacific.net.sg

23 KAKI AVE.4 #04-01 (KELVIN 96890102)

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

ATTN: AUTOMOBILE INTEGRATED MANAGMENT PTE LTD.

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea), -Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made In Japan)

-------CASH SALES

WAREHOUSE:

CASH

TAX INVOICE : AR201910-12217 DATE CUSTOMER ID:

24/10/2019 **CAS001**

VEH REG. NO. TERMS

GBF8800A

PO NO.

CASH

PAGE NO.

Page 1 of 3

CURR.

SGD

SQ_STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
N62022-3XA0H E26 14'LR	FRT BUMPER	WH FR	1	380.00	380.00
Z. N26150-3XA0A E26	FOG LAMP RH & LH	WH FR	1	260.00	260.00
8. N62257-3XA0B E26	FOG LAMP COVER LH W/HOLE	WH FR	1	95.00	95.00
N62211-3XA0A/62210-3XA 0A	FRT BUMPER BRACKET RH@LH	WH	1	95.00	95.00
E26		FR			
/s. N62221-3XA0A/B	FRT BUMPER SIDE BRACKET LH	WH	1	110.00	110.00
E26		FR			
6. N01553-09321/05933 B16 N16 M11 A33 J31	CLIP FENDER SHIELD CLIP	WH FR	10	2.50	25.00
7. N61261-3XA0A E26	SIDE PANEL LH	WH FR	1	280.00	280.00

CONTINUE NEXT PAGE

[P] 24/10/2019 3:25:22PM Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL

[E] 24/10/2019 3:13:30PM

日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710 TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

60 JALAN LAM HUAT #B1-05/06 CARROS CENTRE SINGAPORE 737869 TEL: 63625226 FAX: 63626977

Email: jaeauto@pacific.net.sg

23 KAKI AVE.4 #04-01 (KELVIN 96890102)

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

ATTN: AUTOMOBILE INTEGRATED MANAGMENT PTE LTD.



Arrange By	Driver























Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),

Forch (Made in Germany) Spark plug: Nippon Denso, NGK (Made In Japan)

______ CASH SALES

CASH

DATE

TAX INVOICE : AR201910-12217

CUSTOMER ID: VEH REG. NO. : 24/10/2019 CAS001 GBF8800A

TERMS

PAGE NO.

CASH

PO NO.

Page 2 of 3

CLIBB

COD

	COLUC		300
StkLoc	QTY	U/PRICE	AMOUNT
WH		750.00	750.00

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
3	NF1202-3XAMA/F1B02-3; AMA	X FRT PANEL	WH		750.00	750.00
	E26 14' LR		FR			
18.	NG7413-3XAMB E26 LR	SIDE PANEL OUTER LIL YOUNG	WH K	1	850.00	850.00
10.	N76231-3XA0A E26	FRT PILLAR INNER LH VELWIN	WH K	1	620.00	620.00
JX.	N62310-3XA0C E26 CHROME	RAD.GRILLE (CHROME)	WH FR	1	330.00	330.00
12.	N62889-1JA0A E26 C26	EMBLEM	WH FR	1	75.00	75.00
13.	N26075-3XA0D/3XA1D E26 NV350	HEADLAMP LH	WH FR	1	285.00	285.00
14.	N21606-3XV0A E26 A/T	OIL COOLER LH	WH FR	1	580.00	580.00

CONTINUE NEXT PAGE

[P] 24/10/2019 3:25:22PM Goods Sold are not refundable for Cash. Interest Rate of 1.5% per month will be imposed on OverDue Account(s). ORIGINAL

[E] 24/10/2019 3:13:30PM

...CLAIM SUBFOLDER...(Pending for Survey Report)


Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	A	dj Submitted	Ins Auth'ed	Status	
Main	15 Oct 2019		16 Oct 2019 16:11 Edit Adj Rpt	S\$5,906 Edit Est		\$5,906.50 View Rpt		Pending for Survey Report Cancel Case	
	Main	R	eference		laim Detai	ls	Documents		Show All
CLAIM SU	BFOLDER DE	TAILS				[Created	by insurer]		
Insured:	FENG SHE	NG ENGINEERI	NG PTE LTD, Co. I	Reg. No.: 20	0900097C				
Vehicle Reg No.:	GBF880	0A			Date of Lo		9 10:00 - :59 is and 4 Days From L	TA Reg Date (M	an Yr)]
Claim Type	OD / 608	3432			Policy/Cov Note No.:		(Comprehensive) 07/04/2019 - 06/04/	2020	
					Excess:	S\$600.00			
Repairer:	Automob	ile Intergrated M	lanagement Pte L	td (HQ) 28	Sin Ming La	ine, #07-147, I	Midview City, 573972	Sin Ming - Tel:	
Handling Insurer:	MSIG Ins	urance (Singapo	re) Pte. Ltd. (HQ)	- Tel: +65	6827 7888	[Handled by	Vimmala D/O Raja	Singam - 659	42471]
Addisobass	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	56-3561	[Handled b	Y CHEN TSUE	YEE] [Final Rpt	due 15/11/2	2019]
Majuster:				I. Tel: +6	590034119	Email: NOEMA	AIL.		
Adjuster: Driver/Cust dian:	0	PENG (51 / Male)	NRIC: S1831299	- n- n-	Contract to the contract of		2011		
Driver/Cust dian: Adj Asg.	O TOH KOK I	rvey & revert. Plea		if you cann	ot attend th	is assignment.	Survey at 23 Kaki Bu	kit Ave 4 #04-0	01 (South
Driver/Cust dian: Adj Asg. Remarks:	O TOH KOK I	rvey & revert. Plea gapore 415933 (PI	se contact us ASAP	if you cann	ot attend th	is assignment.	Survey at 23 Kaki Bu)1 (South
Driver/Cust dian: Adj Asg. Remarks:	Car in, Sur Wing) Sing	rvey & revert. Plea gapore 415933 (PI	se contact us ASAP C: Kelvin @ 9689 0	if you cann 102)				All Compose	Service Constitution
Driver/Cust dian: Adj Asg. Remarks: ASSOCIAT	Car in, Sur Wing) Sing	rvey & revert. Plea gapore 415933 (PI CEIVED)): Alert - Adj Ma	se contact us ASAP C: Kelvin @ 9689 0	if you cann 102)		00A - Claim H	View A andler: Vimmala D/	All Compose	Service Constitution

Claim Documents


*GBF8800A (608432) OD Oct 11 2019 10:00AM [FENG SHENG ENGINEERING PTE LTD] Automobile Intergrated Management Pte Ltd

Lett	ers/Corresponder	ices	1 per	age 🗸	V
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Prin
1	16/10/19 10:16	Acknowledgement Letter to OI with OD CDT	0	Load HTM	
Ass	essment Reports		1 per	page V	V
No	Finalized On	VAC (Kaki Bukit)	Line Santon	Thumbnail	
1	11/10/19 14:27	Accident Statement	O	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Prin
1	17/10/19 15:07	Adjuster Immediate Advice	0	Load HTM	
Pho	tos/Images		3 per	page 🗸	V
No	Finalized On	VAC (Kaki Bukit)		Thumbnail	Prin
1	11/10/19 14:20	Accident Photo [Linked Accident Report Documents]	0	Load JPG	V
2	11/10/19 14:20	Accident Photo [Linked Accident Report Documents]	0	Load JPG	V
3	11/10/19 14:20	Accident Photo [Linked Accident Report Documents]	0	Load JPG	Z
4	11/10/19 14:20	Accident Photo	0	Load JPG	V
5	11/10/19 14:20	[Linked Accident Report Documents] Accident Photo	6	Load JPG	V
6	11/10/19 14:20	[Linked Accident Report Documents] Accident Photo [Linked Accident Report Documents]	0	Load JPG	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Prin
1	25/11/19 15:57	General View	0	Load JPG	V
2	25/11/19 15:58	General View	0	Load JPG	V
3	25/11/19 15:58	General View	0	Load JPG	V
4	25/11/19 15:58	General View	0	Load JPG	V
5	25/11/19 15:58	General View	0	Load JPG	V
6	25/11/19 15:58	General View	0	Load JPG	V
7	25/11/19 15:58	General View	0	Load JPG	V
8	25/11/19 15:58	General View	0	Load JPG	V
9	25/11/19 15:58	General View	0	Load JPG	V
10	25/11/19 15:58	General View	0	Load JPG	V
11	25/11/19 15:58	General View	0	Load JPG	V
12	25/11/19 15:58	General View	0	Load JPG	V
13	25/11/19 15:58	General View	0	Load JPG	V
14	25/11/19 15:58	General View	0	Load JPG	V
15	25/11/19 15:58	General View	0	Load JPG	V
16	25/11/19 15:58	General View	0	Load JPG	V
17	25/11/19 15:58	General View	0	Load JPG	V
18	Description of the second of t	General View	0	Load JPG	Z
	25/11/19 15:58		0	Load JPG	V
19	25/11/19 15:58	General View			₩ ₩
20	25/11/19 15:58	General View	6	Load JPG	-
21	25/11/19 15:58	General View	6	Load JPG	✓
22	25/11/19 15:58	General View	0	Load JPG	
23	25/11/19 15:58	General View	0	Load JPG	<u>V</u>
24	25/11/19 15:58	General View	0	Load JPG	V
25	25/11/19 15:58	General View	0	Load JPG	V
26	25/11/19 15:58	General View	0	Load JPG	V
27	25/11/19 15:58	General View	63	Load JPG	~

Lett	ers/Corresponder		1 per p	-	✓
No 28	Finalized On 25/11/19 15:58	MSIG Insurance (Singapore) Pte. Ltd. (HQ) General View	0	Thumbnail Load JPG	Prin
9	Company of the company	General View	0	Load JPG	V
	25/11/19 15:58	General View	0	Load JPG	V
0	25/11/19 15:58		0	Load JPG	∀
1	25/11/19 15:58	General View General View	0	Load JPG	V
2	25/11/19 15:58	Control Contro	0	Load JPG	V
3	25/11/19 15:58	General View		Load JPG	₩ ₩
4	25/11/19 15:58	General View	0	TP COSTO	2
35	25/11/19 15:58	General View	0	Load JPG	_
36	25/11/19 15:58	General View	0	Load JPG	2
37	25/11/19 15:58	General View	0	Load JPG	2
38	25/11/19 15:58	General View	0	Load JPG	Z
39	25/11/19 15:58	General View	0	Load JPG	2
10	25/11/19 15:58	General View	0	Load JPG	2
1	25/11/19 15:58	General View	0	Load JPG	2
12	25/11/19 15:58	General View	0	Load JPG	₩.
13	25/11/19 15:58	General View	0	Load JPG	V
4	25/11/19 15:58	General View	0	Load JPG	V
15	25/11/19 15:58	General View	0	Load JPG	E
16	25/11/19 15:58	General View	0	Load JPG	E
7	25/11/19 15:58	General View	0	Load JPG	2
18	25/11/19 15:58	General View	0	Load JPG	E
9	25/11/19 15:58	General View	0	Load JPG	6
50	25/11/19 15:58	General View	0	Load JPG	6
1	25/11/19 15:58	General View	0	Load JPG	6
2	25/11/19 15:59	Photo After Spray	0	Load JPG	5
3	25/11/19 15:59	Photo After Spray	0	Load JPG	6
		Photo After Spray	0	Load JPG	5
54	25/11/19 15:59	Una Uniformità a Seconda del Companione del Compani	0	Load JPG	5
55	25/11/19 15:59	Photo After Spray	0	Load JPG	E
56	25/11/19 15:59	Photo After Spray	0	Load JPG	6
57	25/11/19 15:59	Photo After Spray	0	Load JPG	2
58	25/11/19 15:59	Photo After Spray	0	Load JPG	2
59	25/11/19 15:59	Photo After Spray	0	Load JPG	8
50	25/11/19 15:59	Photo After Spray		11 000000	1
51	25/11/19 15:59	Photo After Spray	6	Load JPG	-
52	25/11/19 15:59	Reinspection Photo	0	Load JPG	8
53	25/11/19 15:59	Reinspection Photo	0	Load JPG	2
54	25/11/19 15:59	Reinspection Photo	0	Load JPG	6
55	25/11/19 15:59	Reinspection Photo	0	Load JPG	8
56	25/11/19 15:59	Reinspection Photo	0	Load JPG	8
57	25/11/19 15:59	Reinspection Photo	0	Load JPG	2
58	25/11/19 15:59	Reinspection Photo	0	Load JPG	2
69	25/11/19 15:59	Reinspection Photo	0	Load JPG	6
70	25/11/19 15:59	Reinspection Photo	0	Load JPG	6
71	25/11/19 15:59	Reinspection Photo	0	Load JPG	6
72	25/11/19 15:59	Reinspection Photo	0	Load JPG	6
73	25/11/19 15:59	Reinspection Photo	0	Load JPG	6
74	25/11/19 15:59	Reinspection Photo	0	Load JPG	6
75	25/11/19 15:59	Reinspection Photo	1	Load JPG	18
76	25/11/19 15:59	Reinspection Photo	0	Load JPG	6
77	25/11/19 15:59	Reinspection Photo	0	Load JPG	6
78	25/11/19 15:59	Reinspection Photo	0	Load JPG	6
79	25/11/19 15:59	Reinspection Photo	0	Load JPG	E
200	NAME OF THE PARTY		0	Load JPG	6
80	25/11/19 15:59	Reinspection Photo	6	Load JPG	6
81	25/11/19 15:59	Reinspection Photo			-
82	25/11/19 15:59	Reinspection Photo	0	Load JPG	6
83	25/11/19 15:59	Reinspection Photo	0	Load JPG	1



Linked Accident Report Documents



Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			^
			~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way, #21-01 SGX Centre 2

Our File No:

CS/MSG19018301/ETF3E2

Singapore 068807

Date:

27/11/2019

REFERENCE

Insured/Claimant: Date of Loss:

FENG SHENG ENGINEERING PTE LTD

Policy No:

Nature of Claim:

28925846

OD

Claim No: 608432

DESCRIPTION & IDENTIFICATION OF VEHICLE

11/10/2019

Reg No:

GBF8800A

Make & Model:

NISSAN NV350, 2.5 (A)

Engine No:

YD25393825A

Reg. Date:

07/04/2016 (Man. Year: 2016)

Chassis No:

JN1MC2E26Z0006443

Colour: Engine Capacity: Silver

Odometer:

105013 km

2488 cc

Market Value/New Car Price:

\$\$45,000.00

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

195 R15C

Rear Tyre Size:

No

195 R15C

Front Tyre Size: Front Left Side:

Hankook 5 mm

Rear Left Side:

Hankook 5 mm

Front Right Side:

Hankook 5 mm

Rear Right Side:

Hankook 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,633.50	3,686.50	2,947.00	44.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,410.00	2,220.00	1,190.00	34.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,043.50	5,906.50	4,137.00	41.19
- Excess (S\$)	600.00	600.00	0.00	0.00
Nett Amount (S\$)	9,443.50	5,306.50	4,137.00	43.81

INSPECTION

Date of Assignment:

16/10/2019

Date Inspected:

17/10/2019 Inspected At:

23 Kaki Bukit Ave 4 #04-01

Repairer: Automobile Intergrated

Management Pte Ltd (HQ)

Estimated Period of Repair:

8.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 27 Nov 2019)

Parts: N/A NISSAN NV350 2.5 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBF8800A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	380.00 F	*380.00 F
2	1		*FRONT BUMPER FOG LAMP - LH	Broken	260.00 F	*260.00 F
3	1		*FRONT BUMPER FOG LAMP COVER	Missing	95.00 F	*95.00 F
4	1		*FRONT BUMPER BRACKET	Missing	95.00 F	*95.00 F
5	1		*FRONT BUMPER SIDE BRACKET - LH	Missing	110.00 F	*110.00 F
6	10		*FRONT BUMPER CLIPS	Necessary	25.00 F	*25.00 F
7	1		*FRONT CORNER PANEL - LH	Dented	280.00 F	*280.00 F
8	1		*FRONT CAB PANEL ASSY	Dented	750.00 F	*750.00 F
9	1		*FRONT DOOR PILLAR - LH - OUTER	Repair	850.00 F	*-F
10	1		*FRONT DOOR PILLAR - LH - INNER	Repair	620.00 F	*- F
11	1		*FRONT GRILLE	Missing	330.00 F	*330.00 F
12	1		*FRONT GRILLE LOGO	Missing	75.00 F	*75.00 F
13	1		*FRONT HEADLAMP - LH	Broken	285.00 F	*285.00 F
14	1		*FRONT WIPER PANEL GARNISH	Not Necessary	195.00 F	*-F
15	1		*FRONT WINDSHIELD	Not Necessary	820.00 F	*-F
16	1		*FRONT STEP GARNISH - LH	Repair	85.00 F	*-F
17	1		*OIL COOLER	Dented	580.00 F	*580.00 F
18	1		*SET FRONT WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
19	1		*SET FRONT NO. PLATE WITH HOLDER	Crushed	60.00 FS	*35.00 FS
20	1		*I.U BRACKET	Necessary	30.00 FS	*20.00 FS
21	1		*R.O.V STICKER	Not Necessary	45.00 FS	*-FS
F=Fra	nchise	part. S=Spcf	Nett.			
				Sub Total (S\$)	6,050.00	3,360.00
			+ Margin on L,N Iten	ns 10.00/10.00% (S\$)	583.50	326.50
				Total Parts (S\$)	6,633.50	3,686.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK FRONT ELECTRICAL WIRING	New	50.00	30.00
2	TO REMOVE, REFIX FRONT WINDSCREEN	New	180.00	120.00
3	TO REMOVE, REFIX FRONT DASHBOARD	New	300.00	150.00
4	TO REMOVE, REFIX A/C COOLING SYSTEMS & REFILL A/C GAS	New	180.00	120.00
5	TO RESPRAY PAINTING AND ETC	New	1,200.00	800.00
6	PANEL BEATING, CUT, WELD REMOVE & REPLACING ABOVE PARTS	New	1,500.00	1,000.00
	Gross Labo	ur Cost (S\$)	3,410.00	2,220.00
	Report was unsubmitted duri		5,410.00	

< END OF ESTIMATES >